

**swissport**   
fueling services  
2350 S. 190<sup>th</sup> Street  
Seattle, WA 98198

CERTIFIED MAIL

September 3, 2014

Mr. David D. Lykken  
Pipeline Safety Director  
Washington Utilities and Transportation Commission  
1300 S. Evergreen Park Dr. S.W  
P.O box 47250  
Olympia, WA 98504

Dear Mr. David D. Lykken,


The following areas of concern of Title 49 CFR Part 195 were noted as a result of WUTC inspection in June 3-4, 2014 of Swissport Fueling Inc.- SeaTac Fuel Facilities LLC.

1. 49 CFR 195.432 Inspection of in-service breakout tanks.

**Finding:** In the last two 5 years in-service API inspections, API 653 inspectors noted that there should be a moisture barrier caulking applied between the foundation and the tank shell.

**Corrective Action:** We followed their recommendation and we applied moisture caulking between the foundation and tank shell of Breakout Tank 115.

Sincerely,



Nestor Soriano  
Operation Manager  
Tel. 206-246-0407

RECEIVED

SEP 17 2014

WASH. UT. & TP. COMM

