

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

NOTES-FIELD INSPECTION

Company: PSE

Date(s): 11/12-13, 2015

Unit: Snohomish

Field Readings									
Line & Location	Line		CP Volts		Rectifier		Pressures		Remarks
	Size	In.	P/S (mV) CSE	Casing (mV) CSE	Volts	Amps	Set (psig)	Actual (psig)	
Port of Edmonds Business District									S&A leak survey
PBS-0132 Sultan Bridge									Bridge patrol
PBS-0110 2600 Firetrail & 140th St NE									
PBS-0352 16324 Marine Dr. Everett									
Kayak Point- Residential Service landslide									Slide Patrol
RS-1168 (farm tap)							22.4 (per PSE record)		Did not perform lockup due to losing 2 customers connected to the farm tap. Farm tap is due for replacement. Job# 109089650
RS-2667							Inlet 800 457 outlet		Delta Gate, turned valve

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

RS-2665							460.4 upstream	350 interstage 255 (monitor)	250 MAOP
RS-2766								36.45 outlet 37 Lockup	50-60psig fracture disc
RS-255, Seattle Hill Rd & 35th							57 set point 2 nd stage monitor sp 62	57.4 Lockup 57.2 as left	MAOP 60 out Eric Cannon performed
PS-0366 on IC- 39156			-2003		6.03 VDC	.19 A			Kevin Anson performed
TS-044488			-1043	-581					
3716 Federal Ave, Everett			-1251 on isolated service, - 356 on Impressed current system						This is addressed as an item of concern in the letter to the operator
Edwards Ave & Federal Ave, Everett			-285						-937mV foreign line crossing This is addressed as an item of concern in the letter to the operator
Sharon Dr. & Holly Dr., Everett			-956						
Valhalla Dr & Gothic Way			-1220	-259					

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

9117 238 th St SW, Edmonds			-1125						
Hwy 2 & 179 th Ave SE, Monroe			-1678	-433					
W Columbia St & Kirby Dr, Monroe			-2229		33.64 VDC	5.14 A			60% on dial
312 N Madison, Monroe			-1281						9 yr isolated service reads