Form A- Annual Review 8249

UTC Standard Annual Review Inspection Report Intrastate Operators FORM A: Annual Review

PHMSA Pipeline Regulations Print Inspection Record PHMSA Advisory Bulletins Print Blank Form

Inspector and Operator Information

Inspection ID Inspection Link Inspector - Lead Inspector - Assist

Dennis Ritter 8249 8249

Operator Unit Records Location - City & State

Avista Corporation Avista Corporation - Headquarters

Inspection Start Date Inspection Exit Interview Date Engineer Submit Date

06-21-2021 06-21-2021

Inspection Summary

You must include the following in your inspection summary: *Inspection Scope and Summary *Facilities visited and Total AFOD

- Summary of Signficant Findings
- * Primary Operator contacts and/or participants

Inspection Scope and Summary:

This inpection will review documents as noted below.

Facilities visited and Total AFODS:

No facilities were visited, there was a MS Teams meeting to review the question with the operator on June 21, 2021. 0.5 AFODs

Summary of Significant Findings:

There were no findings associated with this annual review.

Primary Operator Contacts and/or participants:

Randy Bareither, Avista Corporation, Pipeline Safety Engineer

Instructions and Ratings Definitions

INSPECTION RESULTS: Annual Review

Satisfactory Responses Satisfactory List Number of Unanswered Questions

1,3,5,6,9,10,12,13,14,15,21,22,23,24,25,26,27,28,29,30,31,32,35,37,39,40,

Unsatisfactory List Unsatisfactory Responses

Area of Concern Responses Area of Concern List

Not Applicable List Not Applicable Responses 10 4,7,16,17,18,19,20,42,43,44

Yes Responses Yes List No Responses No List

Not Checked / Evaluated Responses Not Checked / Evaluated List

**If an item is marked Unsat, AOC, N/A, or N/C, an explanation must be included in the "Notes" block for that question and also summarized in the "SUMMARY OF REQUIRED COMMENTS" section at the end of this inspection form.

Crew Inspection History

Click Link for Full List of Crew Inspections

Determination crew inspection Date	Inspector	Operator	Unit	Type of Work	Foreman Name	Contractor Name	Comments / Observations for Operator
05-05-2022	Darren Tinnerstet	Avista Corporation		Main Extension	Justin Hardy		
05-05-2022	Darren Tinnerstet	Avista Corporation		Main Extension	Brett Freeman		
05-05-2022	Darren Tinnerstet	Avista Corporation		Main Replacement	Jake Neilsen		
04-20-2022	Darren Tinnerstet	Avista Corporation	Avista - Spokane - 7897	Main Replacement	Kelly Wallen	Michels	
03-23-2022	Derek Norwood	Avista Corporation	Avista - Pullman/Clarkston -7895	New Service		Curry Inc.	
03-22-2022	Derek Norwood	Avista Corporation	Avista - Ritzville - 7896	New Service			
03-22-2022	Derek Norwood	Avista Corporation	Avista - Ritzville - 7896	Other	Hayden Graham		
10-21-2021	Anthony Dorrough	Avista Corporation	Avista - Ritzville - 7896	Service Repair	Ed Trzcinski	NPL	Staff observed that the location was behind a private drive with gated access - no entry was possible. Was unsure whether or not a crew was on site.
10-21-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	New Service	Andrew Murphy	NPL	Staff observed crew in the process installing a new 3/4-inch PE gas service, tying into an existing 3/4-inch PE stub (2009). On site were: Foreman/Fitter/Andrew Murphy; Fitter/Laborer/Andrew O-Reilly and Operator/Jax Render. Calibration audit: CGI #1641-019545 last 10/11/21 Test Gauge #GPG-626 due 12/10/21 Electrofusion Machine (Genesis) #1032456 12/30/21 Butt Fuse PE Cradle 4-inch last 6/21 PE found on truck: 2-inch 10/31/19 & 2/24/2020; 3/4-inch 6/21/21
10-21-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	New Service	Kyle Lorenzen	NPL	Staff observed crew in the process of installing a new 3/4-inch PE gas service, tying into an existing 2-inch PE main (2013). On site were: Foreman/Kyle Lorenzen; Fitter/Laborer/Aller Brazington and Operator/Judd Gridley. Calibration audit: CGI #1422-018623 last 10/4/21 Test Gauge #GPG-00623 due 12/16/21 Electrofusion Machine (Genesis) #1032196 12/30/22 PE found on truck: 2-inch 11/1/19 and 3/4-inch 6/28/21

Determination crew inspection Date	Inspector	Operator	Unit	Type of Work	Foreman Name	Contractor Name	Comments / Observations for Operator
10-21-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Main Install	Eric Wiedeman	NPL	Staff observed crew in the process of installing new 2-inch PE gas main and 3/4-inch service. Also on site were: Foreman/Eric Wiedeman; Fitter/Operator/Travis Shane a Fitter/Laborer/Ken Brinkley. Calibration audit: CGI #1710-019654 last 10/21/21 Test Gauge #GPG-01012 due 1/27/22 Test Gauge #GPG-00814 1/27/22 Electrofusion Machine (Genesis) #1032727 2/17/23 PE found on truck: 2-inch 10/27/2020; 3/4-inch 6/21/21 and 1/2-inch 1/14/19.
10-21-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	New Service	Chad Leonard		Staff observed that the work had already been completed.
10-21-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Main Install	Travis Ward		Staff observed crew installing new 2-inch PE main, tying into existing 2-inch STW ma (1965). On site were: Foreman/Fitter/Travis Ward; Journeyman Fitter/Josh Radezky a Apprentice/Levi Butler. Calibration audit: CGI #59 due 11/6/21 Electrofusion Machine (Genesis) #328349 due 3/19/24 Test Gauge #GPG-00606 12/18/21 Test Gauge #GPG-01029 12/18/21 Test Gauge #GPG-01029 12/18/21 Fe found on truck: 2-inch 7/29/2020; 3/4-inch 5/18/19 and 1/2-inch 6/14/21.
10-20-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Other	Schuyler Price	NPL	Staff observed crew in the process of raising a riser with a double valve on an existing inch PE gas service and removing one of them that was discovered to be corroded. Owere: Foreman/Schuyler Price and Operator/Fitter/Marty Anderson.
10-20-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Main Install	Jake Struve		Staff observed crew in the process of installing new 2-inch PE gas main to new const. tying into existing 2-inch PE main (2020). On site were: Lead Foreman/Seth Schaeffe Foreman/Jake Struve; Journeyman Fitter/Taylor Sudbrink and Apprentice/Cody VanderZanden. Calibration audit: Multimeter #487602256SV 12/21 Halfcell #WA-049 12/21 Water Manometer #GPG-01036 8/14/22 Gas Scope #98 11/5/21 Jest Gauge #GPG-00383 2/3/22 Jest Gauge #GPG-00383 2/3/22 Fet Gauge #GPG-00383 2/3/22 Fet Gound on truck: 1/2-inch 8/13/2020 and 3/4-inch 3/2/19
04-29-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Other	Tim Hammond		Staff observed crew in the process of installing a new EFV due to increased customer old EFV(2011). Also on site were Fitter/Jake Morris; Apprentice Fitter/Cody Gubler at Crewman/Rory Sager. Calibration audit: CGI #78 3/14/21 Electrofusion Machine #3283501 3/19/24 Halfcell #WA008 12/21 Multimeter #84370418 12/21 Test Gauge #00399 2/3/22 Fef found on the truck: 3/4-inch 5/30/2020
04-29-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Main Extension	Jake Struve		Staff observed crew in the process of installing 6-inch and 2-inch PE main to service n const. commercial building, tying into existing 2-inch main. Also on site were Fitter/Operator/Josh Radezky and Crewman/Brandon Hartill. Calibration audit. Cali #98 6/23/21 Test Gauge #GPG053821/10/22 Multimeter #48760256-SV 12/21 Halfcell #SN/WA049 12/21 UVI #GPG01036 8/14/21 Electrofusion Machine #2846 7/28/22 PE found on trailer: 6-inch 10/2/2020
04-29-2021	Anthony	Avista	Avista - Spokane -	Other	Travis Ward		Staff observed that work had already been completed.
04-29-2021	Dorrough Anthony	Corporation Avista	7897 Avista - Spokane -	Other	Justin Hardy		Staff observed that work had already been completed.
04-29-2021	Anthony Dorrough	Corporation Avista Corporation	7897 Avista - Spokane - 7897	Relocate/Abandon	Hayden Graham		Staff observed crew in the process of relocating an existing 3/4-inch PE service to cle installation of a retaining wall, tying into an existing 6-inch PE main. Also on site were apprentice Fitter/Dylan Huber; Fitter/Dusty Dershom; Apprentice Fitter/Jeremy McK and Crewman/Connor Barber. Calibration audit: Multimeter #40720337-WS 12/21 Halfcell #87 5/14/21 Electrofusion Machine 6/16/21 PE found on truck: 2-inch 4/21/2020; 3/4-inch 3/29/2020 and 1/2-inch 5/17/19
04-28-2021	Anthony Dorrough	Avista Corporation	Avista - Pullman/Clarkston -7895	New Service	Brian Curry	Curry Inc.	Staff observed crew in the process of installing a 3/4-inch PE service, tying into a 3/4 PE stub on a new const. lot. Calibration audit: CGI #R5 4/12/21 Test Gauge #GPG00231 6/26/21 PE found on truck: 3/4-inch 3/30/2020
04-28-2021	Anthony Dorrough	Avista Corporation	Avista - Pullman/Clarkston -7895				Staff observed that apparently work had not been started.
04-28-2021	Anthony Dorrough	Avista Corporation	Avista - Pullman/Clarkston -7895				Staff observed that apparently work had not been started.
04-28-2021	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7897	Relocate/Abandon	Jake Neilsen		Staff observed crew in the process of relocating an MSA after a deck was built over it. on site was Apprentice Fitter/Emily Stannard. Calibration audit: UEI Gauge #0039512/14/21 Test Gauge #GPG0064412/18/21 CGI #94 5/14/21 Electrofusion Machine #FR9930590* Multimeter #39951649-WS 12/20/21 Halfcell #SN/WA054 12/20/21 PE found on the truck: 2-inch 4/21/20/20 and 3/4-inch 5/30/2020 *Staff found out of calibration but learned that the equipment an older version no lon being used and should have been removed from the truck. Since the equipment was involved in the work on site no follow-up investigation is needed.
03-24-2021	Derek Norwood	Avista Corporation	Avista - Spokane - 7897	Main Extension	Hayden Graham		
03-24-2021	Derek	Avista	Avista - Spokane -	Other	Elmo	NPL	
10-07-2020	Norwood David Cullom	Corporation Avista	7897 Avista - Ritzville -	Other	McClean Don Williams	Don Williams	
11-19-2019	Scott	Corporation Avista	7896 Avista - Ritzville -	New Service	Don Williams	Don Williams	
09-05-2019	Anderson Derek	Corporation Avista	7896 Avista - Spokane -	New Service	Trevor Butler		
06-06-2019	Norwood David Cullom	Corporation Avista	7897 Avista - Ritzville -	Main Extension	Don Williams	Don Williams	Great, personable crew
05-08-2019	Scott	Corporation	7896 Avista - Ritzville -	Main Install	Don Williams	Don Williams	No crew on-site, locates present. Job looked to be a main install since there was an ex
	Anderson Derek	Corporation	7896	Main Extension		Contracting	trench on the side of the road and no residences.
05-08-2019	Norwood	Corporation	Avista - Spokane - 7897	Main Extension	Hayden Graham		
10-24-2018	Dennis Ritter	Avista Corporation	Avista - Ritzville - 7637		Hayden Graham		No crew on site
10-24-2018	Dennis Ritter	Avista Corporation	Avista - Ritzville - 7637		Hayden Graham		No crew on site at this address or the other Ritzville address, 102 E Birch.

Determination crew inspection Date	Inspector	Operator	Unit	Type of Work	Foreman Name	Contractor Name	Comments / Observations for Operator
10-23-2018	Dennis Ritter	Avista Corporation	Avista - Ritzville - 7637				No crew on site. No issues noted
08-21-2018	David Cullom	Avista Corporation	Avista - HQ - 7633				
08-21-2018	David Cullom	Avista Corporation	Avista - HQ - 7633				
08-21-2018	David Cullom	Avista Corporation	Avista - HQ - 7633				
08-21-2018	David Cullom	Avista Corporation	Avista - HQ - 7633				
08-20-2018	David Cullom	Avista Corporation	Avista - HQ - 7633				
06-27-2018	Scott Anderson	Avista Corporation	Avista - Ritzville - 7637		Don Williams	Don Williams Contracting	
05-09-2018	David Cullom	Avista Corporation	Avista - Colville - 7634				
05-09-2018	David Cullom	Avista Corporation	Avista - Colville - 7634				
05-03-2018	Anthony Dorrough	Avista Corporation	Avista - HQ - 7633		Davis Critelli	NPL	
05-03-2018	Anthony Dorrough	Avista Corporation	Avista - HQ - 7633		Clayton Coleman	NPL	
05-03-2018	Anthony Dorrough	Avista Corporation	Avista - HQ - 7633		Doug Jacobsen	NPL	
05-03-2018	Anthony Dorrough	Avista Corporation	Avista - HQ - 7633		Mark Plaster	NPL	
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7636		Greg Mattison		
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - HQ - 7633		Al Flaa		
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7636		Doug Jacobsen	NPL	
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7636		Justin Shaw	NPL	
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7636		Kelly Skurupey	NPL	
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7636		Ken Carvalho		
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7636		Ken Carvalho		
05-02-2018	Anthony Dorrough	Avista Corporation	Avista - HQ - 7633		Russ Schupman		
04-26-2018	Derek Norwood	Avista Corporation	Avista - Ritzville - 7637				
03-21-2018	Derek Norwood	Avista Corporation	Avista - Ritzville - 7637		Hayden Graham		
08-24-2017	Derek Norwood	Avista Corporation	Avista - Ritzville - 7383		Don Williams	Don Williams Contracting	
07-19-2017	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7384		Eric Wiedeman	NPL	
07-19-2017	Anthony Dorrough	Avista Corporation	Avista - Spokane - 7384		Steven Fitzner	NPL	
04-19-2017	Derek Norwood	Avista Corporation	Avista - Ritzville - 7383				
04-13-2017	Dennis Ritter	Avista Corporation	Avista - Spokane - 7384		Matt Pooler		
04-13-2017	Dennis Ritter	Avista Corporation	Avista - Spokane - 7384		Russ Schupman		
04-13-2017	Dennis Ritter	Avista Corporation	Avista - Spokane - 7384				
04-13-2017	Dennis Ritter	Avista Corporation	Avista - Spokane - 7384				
04-10-2017	Dennis Ritter	Avista Corporation	Avista - Spokane - 7384		Ken Carvalho	NPL	
03-02-2017	Derek Norwood	Avista Corporation	Avista - Pullman/Clark - 7373		Dylan Curry	Curry Inc.	

Facility Inspection History

Link for Full List of Facility Inspections

Date	Inspection ID	Form A Operator Name	Other Company	Inspector	Type of Inspection	Do you have inspection pictures or file attachments?
04-21-2022				David Cullom	Facility	Yes
04-21-2022				David Cullom	Facility	Yes
03-23-2022				Derek Norwood	Facility	Yes
03-23-2022				Derek Norwood	Facility	Yes
03-22-2022				Derek Norwood	Facility	Yes
02-09-2021			Trans Mountain	Dennis Ritter	Pre-Field	No
08-12-2020				Scott Rukke	Facility	Yes
06-24-2020				Derek Norwood	Facility	Yes
06-24-2020				Derek Norwood	Facility	Yes

Scheduled Inspection History

Annual Review Inspection History

Year of Inspection	Facility - Operator	Unit Name	Inspection ID			Closed Date	Next Inspection Interval	SHAREPOINT
Avista Corp	oration (49 Inspect	ions)			I			I
2021	Avista Corporation	Avista Corporation- Headquarters	8154	CRM - GAS	Complete	04-20-2021	02-17-2025	Documents
2021	Avista Corporation	Avista Utilities Corp - Pullman/Clarkston	8248	Standard Comprehensive - GD	Complete	05-07-2021	04-29-2024	Documents
2021	Avista Corporation	Avista Corporation- Headquarters	8249	Standard - Annual Review	Complete	06-22-2021	06-21-2022	Documents
2021	Avista Corporation	Avista Corporation- Headquarters	8250	Pipe Replacement Plan	Complete	08-26-2021	07-08-2023	Documents

Artist Corporation Anise Corporation Register R	Year of Inspection	Facility - Operator	Unit Name	Inspection ID	Inspection Type	Inspection Status	Closed Date	Next Inspection Interval	SHAREPOINT
Artist Corporation Anise Corporation Register R	2021	Avista Corporation	Avista Utilities Corp - Spokane	8330	Design, Testing & Construction - Gas	In the Workflow		03-02-2022	Documents
Avista Corporation	2021		Avista Corporation-				09-03-2021		
Anisa Corporation Anis	2021	Avista Corporation	Avista Corporation-	8383	Damage Prevention	Complete	09-03-2021	09-03-2021	Documents
Autisa Corporation Autis Utilises Curp - Cowlie 8030 Soundard Comprehensive - GD Complete 10-27-2020 06-97-2023 Documents Complete Complete 10-27-2020 06-97-2023 Documents Complete Complete Complete 10-27-2020 06-97-2023 Documents Complete Co	2021	Avista Corporation	Avista Corporation-	8474	Damage Prevention	Complete	12-15-2021	11-23-2021	Documents
April	2020	Avista Corporation		8030	Standard Comprehensive - GD	Complete	10-26-2020	08-27-2023	Documents
April 10.000 April 10.0000 April 10.0000 April 10.0000 April 10.0000 April 10.0000 April 10.0000 April 10.00000 April 10.000000 April 10.00000 April 10.000000 April 10.00000 April 10.000000 April 10.00000 April 10.000000 April 10.00000 April 10.00000 April 10.00000 April 10.00000 April 10.00000 April 10.00000 April 10.000000 April 10.000000 April 10.000000 April 10.000000 April 10.0000000 April 10.0000000 April 10.00000000000000000000000000000000000	2020		Avista Corporation-		·				
Avita Corporation Avita Difference Corporation B034 Standard - Annual Review Complete 10-26-2020 09-29-2021 Documents Do	2020	Avista Corporation	Avista Utilities Corp -	8032	Standard Comprehensive - GT	Complete	10-27-2020	08-27-2023	Documents
Avita Corporation Avita Diffice Corp. Spokane 7962 Compliance Investigation and Follow Up Complete 021-2/2/18 Documents 1016 Avita Corporation Avita Diffice Corp. Spokane 7962 Documents 7962 Doc	2020	Avista Corporation	Avista Utilities Corp -	8033	TIMP - Gas Transmission Integrity Management	Complete	10-26-2020	08-27-2023	Documents
Autita Corporation Autita	2020	Avista Corporation		8034	Standard - Annual Review	Complete	10-29-2020	09-29-2021	Documents
One Avista Corporation Avista Utilities Corp. Psechane 7778 Standard Comprehensive-OD Complete 092-52019 092-4002 Documents 093-5002 Documents 093-5003 Docum	2020	Avista Corporation	Avista Corporation-	8097		Complete	11-02-2020	09-29-2024	Documents
Avista Corporation	2019	Avista Corporation	·	7779	Standard Comprehensive - GD	Complete	10-17-2019	09-26-2022	Documents
Avista Corporation Avista Utilities Corp. Spokene 7982 Corpolance Investigation and Follow Up Complete 049-52-002 048-2021	2019								
Headquarters	2019								
Headquaries Headquaries Headquaries Avista Corporation Avista Corporation Avista Corporation Avista Corporation Headquaries 7783 Pa. Prug & Alcohol Complete 01-09-2020 06-25-2023 Documents Doc	2019		Headquarters						
Headquarfers	2019		Headquarters						
Headquarters	2019		Headquarters		-				
Headquarters	2019		Headquarters		<u> </u>				
Avista Corporation Avista Utilities Corp - Spokane 7594 Damage Prevention Complete 0.212-2018 0.212-2018 Documents 7602 Damage Prevention Complete 0.226-2018 0.222-2018 Documents 7602 Damage Prevention Complete 0.227-2018 0.222-2018 Documents Documents 0.222-2018 Documents 0.222-2018 Documents	2019	·							
Description									
Natis Corporation					-				
Avista Corporation					9				
Natisal Corporation					-				
Avista Corporation Avista Utilities Corp Spokane Avista Corporation Avista Utilities Corp T557 Standard Comprehensive - GT Complete 09-10-2018 C7-26-2021 Documents D		· ·			-				
Avista Corporation Avista Utilities Corp- Tonsmission									
Avista Corporation Headquarters Avista Corporation Avista Utilities Corp - Spokane Avista Corporation Avista Corporation Avista Corporation Avista Corporation Avista Utilities Corp - Spokane Avista Utilities Corp - Spokane Avista Utilities									
Pullman/Clarkston Natisa Utilities Corp - Colville Avista Corporation Avista Utilities Corp - Colville Avista Corporation Avista Utilities Corp - Ritzville Avista Corporation Avista Corporation Avista Utilities Corp - Ritzville Avista Corporation Avista Utilities Corp - Ritzville Avista Corporation Avista Corporatio			Transmission		·				
Avista Corporation Avista Corporation-Headquarters Avista Corpora	2010	7 Wista Corporation		7500	otaniaara comprenensive ob	Complete	00 20 2010	C) 20 2021	Documents
Headquarters Avista Corporation Avista Corporation-Headquarters Avista Corporation Avista Utilities Corp- Ritzville Avista Corporation Avista Corporation-Headquarters Avista Corporation-Avista Utilities Corp-Spokane Avista Corporation-Avista Utilities Corp-Spokane Avista Corporation-Avista Corporation-Headquarters Avista Corporation-Avista Utilities Corp-Spokane Avista Corporation-Avista Corporation-Headquarters Avista Corporation-Avista Utilities Corp-Spokane Avista Corporation-Avista Utili	2018	Avista Corporation	Avista Utilities Corp - Colville	7558	Standard Comprehensive - GD	Complete	08-20-2018	07-26-2021	Documents
Headquarters O17 Avista Corporation Avista Utilities Corp - Ritzville O18 Avista Corporation Avista Utilities Corp - Spokane O19 Avista Corporation Avista Utilities Corp - Spokane O19 Avista Corporation Avista Corporation- Headquarters O10 Avista Corporation Avista Corporation- Headquarters O10 Avista Corporation Avista Corporation- Headquarters O11 Avista Corporation Avista Corporation- Headquarters O12 Avista Corporation Avista Corporation- Headquarters O13 Avista Corporation Avista Corporation- Headquarters O14 Avista Corporation Avista Corporation- Headquarters O15 Avista Corporation Avista Utilities Corp - Spokane O16 Avista Corporation Avista Utilities Corp - Spokane O17 Standard Comprehensive - GD O18 Avista Corporation Avista Corporation- Avista Corporation Avista Utilities Corp - Spokane O18 Avista Corporation Avista Corporation- Avista Utilities Corp - Spokane O19 Documents O19 Avista Corporation Avista Corporation- Headquarters O19 Documents O	2018	Avista Corporation		7888	Damage Prevention	Complete		12-07-2018	Documents
Avista Corporation Avista Corporation-Headquarters Parcedures Review Procedures Procedu	2018	Avista Corporation		7887	Damage Prevention	Complete		12-03-2018	Documents
Avista Corporation Avista Corporation-Headquarters Parcedures Review Procedures Procedu	2017	Avista Corporation	Avista Utilities Corp - Ritzville	7260	Standard Comprehensive - GD	Complete	09-07-2017	05-17-2020	Documents
Avista Corporation Avista Utilities Corp- Transmission 7259 TIMP - Gas Transmission Integrity Management Complete 12-08-2017 11-14-2020 Documents Avista Corporation Headquarters 7301 PA - Public Awareness Complete 04-21-2017 03-29-2021 Documents 7302 OQ - Operator Qualification Order Avista Corporation Headquarters 7303 CRM - GAS Complete 10-06-2017 09-06-2021 Documents 7304 CRM - GAS Complete 10-06-2017 09-06-2021 Documents 7305 CRM - GAS Complete 10-06-2017 09-06-2021 Documents 7306 CRM - GAS Complete 10-06-2017 09-06-2021 Documents 7307 Pa - Public Awareness Complete 10-06-2017 09-06-2021 Documents 7308 CRM - GAS Complete 10-06-2017 09-06-2021 Documents 7309 CRM - GAS Complete 10-06-2017 09-06-2021 Documents 7300 CRM - GAS Complete 10-06-2017 Documents 7300 CRM - GAS Complete 10-06-2017 Documents 7300 Documents 7300 CRM - GAS Complete 10-06-2017 Documents 7300 Documents 7300 CRM - GAS Complete 10-06-2017 Documents 7300 Documents 7300 CRM - GAS Complete 10-06-2017 Documents 7300 Documents 7300 CRM - GAS Complete 10-06-2017 Documents 7300 Documents 7300 CRM - GAS Complete 7300 CRM - GAS	2017		Avista Corporation-		OM PPR GAS - Operations & Maintenance, Plans &		05-02-2017		
Avista Corporation Avista Corporation-Headquarters Avista Corporation Avista Utilities Corp - Spokane Avista Util	2017	Avista Corporation	Avista Utilities Corp -	7259		Complete	12-08-2017	11-14-2020	Documents
Avista Corporation Avista Corporation-Headquarters Avista Corporation Avista Utilities Corp - Spokane Avista Corporation Avista Utilities Corp - Spokane Avista Corporation Avista Utilities Corp - Spokane Avista Corporation Avista Utilities Corp - Spokane Avista Util	2017	Avista Corporation	Avista Corporation-	7301	PA - Public Awareness	Complete	04-21-2017	03-29-2021	Documents
Headquarters Avista Corporation Avista Corporation Avista Utilities Corp - Spokane 6660 Damage Prevention Complete 10-26-2017 Complete 04-27-2016 02-10-2016 Documents Complete 04-27-2016 08-09-2019 Documents Complete 04-27-2016 08-09-2019 Documents Complete 10-26-2017 Documents Complete 10-26-2017 Documents Complete 10-26-2017 Documents Documents Complete 10-25-2016 Documents Documents Complete 10-25-2016 Documents Documents Complete 10-25-2016 Documents Documents Documents Complete 10-25-2016 Documents	2017	Avista Corporation	Avista Corporation-	7302	OQ - Operator Qualification	Complete	12-04-2017	11-07-2021	Documents
Avista Corporation Avista Corporation- Headquarters 6660 Damage Prevention Complete 04-27-2016 O2-10-2016 Documents 07-2016 Avista Corporation Avista Utilities Corp - Spokane 6770 Standard Comprehensive - GD Complete 10-05-2016 08-09-2019 Documents 07-2016 Avista Corporation Avista Utilities Corp - Spokane 6770 Standard Comprehensive - GD Complete 10-05-2016 08-09-2019 Documents 07-2016 Avista Corporation Avista Utilities Corp - Spokane 6940 Damage Prevention Complete 12-21-2016 06-10-2016 Documents 07-2016 Avista Corporation Avista Utilities Corp - Spokane 67-2016 DIMP - Gas Distribution Integrity Management Complete 08-30-2016 08-09-2019 Documents 07-2015 Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-16-2016 12-21-2015 Documents 07-2015 Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents 07-2015 Avista Corporation Avista Utilities Corp - Gig2 Standard Comprehensive - GT Complete 09-25-2015 07-22-2018 Documents 07-2015 Avista Corporation Avista Utilities Corp - Pullman/Clarkston Avista Comprehensive - GD Complete 02-23-2016 11-20-2018 Documents 07-20-2018 Documents 07-20-2018 Documents 07-20-2016 Documents 07-20-2018 Documents 07-20-2018 Documents 07-20-2016 Documents 07-20-2018 Documents 07-20-20-2018 Documents 07-20-20-2018 Documents 07-20-20-2018 Documents 07-20-20-2018 Documents 07-20-20-2018 Documents 07-20-20-2018 Documents 07-20-20-20-20-20-20-20-20-20-20-20-20-20-	2017	Avista Corporation		7303	CRM - GAS	Complete	10-06-2017	09-06-2021	Documents
Avista Corporation Avista Utilities Corp - Spokane 6770 Standard Comprehensive - GD Complete 10-05-2016 08-09-2019 Documents 016 Avista Corporation Avista Utilities Corp - Spokane 6940 Damage Prevention Complete 12-21-2016 06-10-2016 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-30-2016 08-09-2019 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-16-2016 12-21-2015 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents 015 Avista Corporation Avista Utilities Corp - 6192 Standard Comprehensive - GT Complete 09-25-2015 C7-22-2018 Documents 015 Avista Corporation Avista Utilities Corp - Pullman/Clarkston Avista Utilities Corp - Pullman/Clarkston Documents 015 Docume	2017	Avista Corporation		7454	Pipe Replacement Plan	Complete	10-26-2017		Documents
Avista Corporation Avista Utilities Corp - Spokane 6770 Standard Comprehensive - GD Complete 10-05-2016 08-09-2019 Documents 016 Avista Corporation Avista Utilities Corp - Spokane 6940 Damage Prevention Complete 12-21-2016 06-10-2016 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-30-2016 08-09-2019 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-16-2016 12-21-2015 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents 015 Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents 015 Avista Corporation Avista Utilities Corp - 6192 Standard Comprehensive - GT Complete 09-25-2015 C7-22-2018 Documents 015 Avista Corporation Avista Utilities Corp - Pullman/Clarkston Pullman/Clarkston 015 Avista Corporation Avista Utilities Corp - 6194 Standard Comprehensive - GD Complete 02-23-2016 11-20-2018 Documents 015 Doc	2016	Avista Corporation	Avista Utilities Corp - Spokane	6660	Damage Prevention	Complete	04-27-2016	02-10-2016	Documents
Avista Corporation Avista Utilities Corp - Spokane 6940 Damage Prevention Complete 12-21-2016 06-10-2016 Documents Avista Corporation Avista Corporation Avista Corporation Avista Corporation Avista Corporation Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-16-2016 12-21-2015 Documents Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents Avista Corporation Avista Utilities Corp - 6192 Standard Comprehensive - GT Complete 09-25-2015 07-22-2018 Documents Avista Corporation Avista Utilities Corp - Pullman/Clarkston Avista Comprehensive - GD Complete 02-23-2016 11-20-2018 Documents	2016						10-05-2016		Documents
Avista Corporation Avista Corporation-Headquarters 6746 DIMP - Gas Distribution Integrity Management Complete 08-30-2016 08-09-2019 Documents Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-16-2016 12-21-2015 Documents Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents Avista Corporation Avista Utilities Corp - G192 Standard Comprehensive - GT Complete 09-25-2015 C7-22-2018 Documents Avista Corporation Avista Utilities Corp - Pullman/Clarkston Avista Utilities Corp - Pullman/Clarkston Standard Comprehensive - GD Complete 02-23-2016 Documents	2016	Avista Corporation	Avista Utilities Corp - Spokane	6940	Damage Prevention		12-21-2016	06-10-2016	Documents
Avista Corporation Avista Utilities Corp - Spokane 6623 Damage Prevention Complete 08-16-2016 12-21-2015 Documents Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents Avista Corporation Avista Utilities Corp - G192 Standard Comprehensive - GT Complete 09-25-2015 C7-22-2018 Documents Avista Corporation Avista Utilities Corp - G194 Standard Comprehensive - GD Complete 02-23-2016 11-20-2018 Documents Avista Corporation Avista Utilities Corp - Pullman/Clarkston Documents	2016		Avista Corporation-	6746	DIMP - Gas Distribution Integrity Management				
Avista Corporation Avista Utilities Corp - Spokane 6661 Damage Prevention Complete 04-26-2016 12-07-2015 Documents Avista Corporation Avista Utilities Corp - 6192 Standard Comprehensive - GT Complete 09-25-2015 C7-22-2018 Documents Avista Corporation Avista Utilities Corp - 6194 Standard Comprehensive - GD Complete 02-23-2016 11-20-2018 Documents	2015	Avista Corporation		6623	Damage Prevention	Complete	08-16-2016	12-21-2015	Documents
Avista Corporation Avista Utilities Corp- Transmission Avista Utilities Corp- Pullman/Clarkston Avista Corporation Avista Utilities Corp- Pullman/Clarkston Avista Comprehensive - GD Standard Comprehensive - GD Complete 09-25-2015 C7-22-2018 Documents Documents	2015				-				
Avista Corporation Avista Utilities Corp - Pullman/Clarkston 6194 Standard Comprehensive - GD Complete 02-23-2016 11-20-2018 Documents	2015		Avista Utilities Corp -						
	2015	Avista Corporation	Avista Utilities Corp -	6194	Standard Comprehensive - GD	Complete	02-23-2016	11-20-2018	Documents
	2015	Avista Corporation		6193	Standard Comprehensive - GD	Complete	02-23-2016	11-20-2018	Documents

GAS System Operations History

Annual Rep	ort - Miles of Main		Annual Repor	Annual Report GAS Transmission Miles				
Year	Miles of Main		Miles of Service	SYSTEM TOTAL NO. of Services	Average Service Length	YEAR	Total Total Miles	e. Total tool mileage inspected in calendar year using in-line inspection tools
2021	Avista Corporation	44,211.79	2,633.00	126,810.483	83	2020	76.562	0
2020	Avista Corporation	3507.559	2,598.98	165,333	83	2019	76.562	0
2020	Avista Corporation	3507.559	2,598.98	165,333	83	2018	76.573	0
2019	Avista Corporation	3484.897	2,572.72	163,662	83	2015	72.692	0
2018	Avista Corporation	3457.304	2,562.70	161,084	84	2016	72.591	0
2017	Avista Corporation	3430.169	2,515.10	158,092	84	2017	72.589	0
2016	Avista Corporation	3401.195	2,460.36	154,651	84	тот	447.569	0
2015	Avista Corporation	3374,75	2,437.92	151,438	85			

Annual Report - Leaks

Year	Operator	Cause of Leak Mains Total	Cause of Leak Mains Hazardous Total	Cause of Leak Services Total	Cause of Leak Services Hazardous Total	NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR
2021	Avista Corporation	83	55	495	257	232
2020	Avista Corporation	62	36	507	193	212
2020	Avista Corporation	61.1	36	507	193	212
2019	Avista Corporation	89	61	567	255	162
2018	Avista Corporation	81	51	562	241	47

Year	Operator	Cause of Leak Mains Total	Cause of Leak Mains Hazardous Total	Cause of Leak Services Total	Cause of Leak Services Hazardous Total	NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR
2017	Avista Corporation	77	48	502	235	99
2016	Avista Corporation	68	32	447	215	134
2015	Avista Corporation	77	39	561	243	1779

Annual Report - EFV

Operator	Year	Number of EFV's Installed This Calendar Year on Single Family Residential Services:	Estimated Number of EFV's in the system at the End of The Year:	Total Number of Services with EFV Installed During Year:	Estimated Number of Services with EFV In The System At The End of The Year:	* Total Number of Manual Service Line Shut-off Valves Installed During Year:	* Estimated Number of Services with Manual Service Line Shut-off Valves Installed in the System at End of Year:
Avista Corporation	2021	3012	40,835			164	1715
Avista Corporation	2020			2048	38,071	110	1565
Avista Corporation	2020			2048	38,071	110	1565
Avista Corporation	2019		36,027	3277	1467	115	
Avista Corporation	2018			3644	32,520	138	1364
Avista Corporation	2017	3947	28,718			153	1249
Avista Corporation	2016	4601	24,527				
Avista Corporation	2015	2521	18,448				
Avista Corporation	2014	3407	15,855				
Avista Corporation	2013	3230	12,324				
Avista Corporation	2012	1697	9064				
Avista Corporation	2011	1169	7193				
Avista Corporation	2010	1174	5781				
TOT		24,758	198,772	11,017	110,129	790	7458

HL System Operations History

HL Annual Report - Miles of Pipe by Decade

YEAR	Operator	Commodity Group	Part I - Total Miles of Pipe by Decade	Unknown	Pre- 20s	1920- 1929	1930- 1939	1940- 1949	1950- 1959	1960- 1969	1970- 1979	1980- 1989	
------	----------	--------------------	---	---------	-------------	---------------	---------------	---------------	---------------	---------------	---------------	---------------	--

No reports found

HL Annual Report - HL Miles / HCAs

HL Annual Report - Breakout Tanks

YEAR	Operator	Commodity Group	Crude Oil #5	Refined (non HVL) #5
No reports	found			

No reports found

ANNUAL REPORT: ACCURACY/TRENDS

Question #1.

1. Result

Was the Annual Report reviewed for accuracy and trends? If any trends were discovered, please describe.

Satisfactory

1 Notes

The 2020 annual distribution report submitted on 2/9/2021 was reviewed. Leak history, excavation damage, new installations and percent unaccounted for gas were compared to 2019 values. Other than a significant decrease in the total number of leaks reported-812 in 2019 and 569 in 2020, no obvious trends were noted. It is probable the decrease is due to the impacts of Covid-19 in the building/construction industry. For example, Avista installed 2614 services in 2019 (difference between total services in 2018 and 2019 annul report) and 2048 in 2020.

Reviewed the 2020 Transmission Annual Report submitted 2/9/2021. No change in miles of line 76.562 or HCA mileage 0.113 in class 3. 6.009 total miles Class 3. MAOP a(4) 0.009 miles. No leaks.

Access to Complete Distribution Annual Report

, CCC33 10	Complete Distribu	don Admidal Report			
Year	Operator	SYSTEM TOTAL Miles of Main	Miles of Service	SYSTEM TOTAL NO. of Services	Average Service Length
2021	Avista Corporation	44,211.79	2,633.00	126,810.483	83
2020	Avista Corporation	3507.559	2,598.98	165,333	83
2020	Avista Corporation	3507.559	2,598.98	165,333	83
2019	Avista Corporation	3484.897	2,572.72	163,662	83
2018	Avista Corporation	3457.304	2,562.70	161,084	84
2017	Avista Corporation	3430.169	2,515.10	158,092	84
2016	Avista Corporation	3401.195	2,460.36	154,651	84
2015	Avista Corporation	3374.75	2,437.92	151,438	85

Access to Complete Transmission Annual Report

YEAR	Operator	Commodity Group	Total Total Miles
Avista 0	Corporation (6	Reports)	
2020	Avista Corporation	Natural Gas	76.562
2019	Avista Corporation	Natural Gas	76.562
2018	Avista Corporation	Natural Gas	76.573
2015	Avista Corporation	Natural Gas	72.692
2016	Avista Corporation	Natural Gas	72.591
2017	Avista Corporation	Natural Gas	72.589

Access to Complete Hazardous Liquid Annual

Report

YEAR Operator Commodity Group

No reports found

DAMAGE PREVENTION

Year	Operator	Number of Excavation Tickets	Total Number of Excavation Damages By Apparent Root Cause:	Locating Practices Not Sufficient:	One-Call Notification Practices Not Sufficient:	Excavation Practices Not Sufficient:	Other:	Number of Services	Total Leaks Excavation Damage	Total Main Leaks	Miles of Service MAIN	Number of Leaks per Mile of MAIN	Total Leaks Per 1,000 Locates	
2021	Avista Corporation	49,034	248	37	95	100	16	126,810.48	41	138	44,211.79		0.83615450503732	2
2020	Avista Corporation	46,242	185	14	93	66	12	165,333	134	45	3507.559		2.8977985381255	5
2019	Avista Corporation	47,232	211	17	90	89	15	163,662					O)
2018	Avista Corporation	48,673	199	19	91	74	15	161,084					O	۰ د
2017	Avista Corporation	44,325	213	31	79	88	15	158,092					O)
2016	Avista Corporation	46,871	163	37	47	68	11	154,651					0)
2015	Avista Corporation	46,513	197	31	60	87	19	151,438					0	o .

DIRT data on mismarks for prior year

Company - Name	Avista Corporation	Totals
Damage Cause	Number of Reports	Number of Reports
Facility marked inaccurately due to incorrect facility record/maps	<u>6</u>	6
Facility marked inaccurately due to locator error	4	4
Facility marked inaccurately due to tracer wire issue	<u>6</u>	6
Facility not marked due to incorrect facility records/maps	<u>6</u>	6
Facility not marked due to locator error	<u>5</u>	5
Facility not marked due to tracer wire issue	1	1
Site marked but incomplete at damage location	Z	7
<u>Unlocatable facility</u>	<u>2</u>	2
Totals (8 groups)	37	37

DIRT Timeliness - Prior Year Reports must be submitted within 45 days of	Α
the damage.	

Late	no	yes	Totals
SubmitCompanyID - UTCfinalName	Number of Reports	Number of Reports	Number of Reports
Avista Corporation	<u>248</u>	<u>10</u>	258
Totals (2 gioups)	248	10	258

Annual	Dovious	_ DD	Penalties	

Docket	LDC Operator	InvestigationID - Docket	Service Date	A A
Avista Co	orporation (9	Investigations)		
D-220230	Avista Corporation	8533 - D-220230		
D-220112	Avista Corporation	8496 - D-220112	03-29-2022	\$
D-220111	Avista Corporation	8495 - D-220111	03-29-2022	\$
D-210605	Avista Corporation	8474 - D-210605	12-28-2021	\$
D-210636	Avista Corporation	8383 - D-210636	09-23-2021	\$
D-210635	Avista Corporation	8382 - D-210635	09-23-2021	\$
D-200814	Avista Corporation	8245 - D-200814	03-18-2021	\$
D-180982	Avista Corporation	7887 - D-180982	12-13-2018	\$
D-180666	Avista Corporation	7888 - D-180666	12-20-2018	\$
TOT				\$32

Question #2

Review the following damage prevention items:

Q2. Is the damage prevention information in the annual report complete? http://Yes

Q2.d Does the operator follow a process to evaluate the cause of "locating practices not sufficient" category?

Yes DP Administrator works with locating contractor

Q2.g. What is the number of damages resulting from mismarks? 14 out of 46,242

Q2.j. Are mapping corrections timely and according to written procedures? GSM 4.11-1 Clarkston, 1 Spokane

Q2.b. Is the annual report damages root cause information complete and accurate? Yes

Q2.e. Is the operator or its contractor qualified and following procedures for locating and marking facilities?

ves

the time requirements?

Q2.k. Does the operator follow a process to evaluate causes for damages listed "Excavation Practices Not Sufficient"? DP Administrator works with PA specialist

Q2.c. Does the operator have a process to evaluate the cause of "One-c Yes DP Administrator works with PA specialist

Q2.f. Is the operator appropriately requalifying locators to address perfo

Q2.h. What is the number of damages resulting from not locating within Q2.i. Is the operator appropriately addressing discovered mapping enc yes mapping errors are corrected within 6 months

Q2.L. Is the operator appropriately focusing damage prevention educat

yes PA program is up to date and meets requirements

NPMS SUBMISSIONS/CHANGES

3. Result For transmission operators, has the operator submitted information to the NPMS database, along with changes made after the original submission? Satisfactory

3. Notes

completed 2/8/2021

INCIDENT/SRC/AOC REPORTS REVIEW

Question #4 Were there any federally reportable incidents during the previous year? Are there any discernable trends to these incidents? 4 Results

5. Result

Satisfactory

Not Applicable

No federal reportables in 2020

Q4: Federally reportable incidents

NotificationID	Operator	Company	NRC #	Assigned Engineer	Date & Time of Incident	Street Address of event/incident	Incident Address: City	Closure Date	Reporting Level
3988	Avista Corporation	Avista Corporation	1330648	Darren Tinnerstet	03-03-2022 06:08 PM	E Empire Ave. and N Crestline St.	Spokane	05-09-2022	Federal

Review operator records of previous year's accidents and failures including reported third party damage and leak response. Is the operator ensuring appropriate evaluation and response as required in 192.617 (Gas) or 195.402 (HL) to determine cause of failure? Is the operator taking appropriate steps to minimize the possibility of reoccurrence?

Operator reported 26 incidents in 2020. 30-d reports were timely and received for all required incidents. No issues were noted by oncall engineers. A random review of 10 incidents showed operator provided all required information—3796, 3793,3780,3760,3748,3772,3714,3685,3661,3658

Review incident reports for the previous year for accuracy and identify any trends. If any trends discovered please describe. (Please see list of incident data at end of this report)

Q6: Incident Reports

6. Result Satisfactory

NotificationID	Inspector	Company	Street Address of event/incident	Date & Time of Incident	Is 30-Day Report Received?	Reporting Leve
4013	Derek Norwood	Avista Corporation	502 E 23rd Ave	05-02-2022 05:55 PM		
4012	Darren Tinnerstet	Avista Corporation	9711 E Walton Lane	04-30-2022 03:21 PM		
4011	Darren Tinnerstet	Avista Corporation	26 W 40th Ave.	04-28-2022 11:06 AM		
4005	Derek Norwood	Avista Corporation	4899 E Grace Ave	04-12-2022 09:03 AM		
4003	Derek Norwood	Avista Corporation	923 S Mariam St	04-11-2022 10:45 AM		
3995	David Cullom	Avista Corporation	2829 West Beacon Ave	03-22-2022 12:31 PM		State
	David Cullom	Avista Corporation	2501 West Boone Ave	03-21-2022 06:43 AM	~	State
3988	Darren Tinnerstet	Avista Corporation	E Empire Ave. and N Crestline St.	03-03-2022 06:08 PM	~	Federal
3983	Derek Norwood	Avista Corporation	101 W Beck Way	02-14-2022 10:48 AM		Non-Reportable
3981	Scott Anderson	Avista Corporation	1411 W. Knox Ave. #1	01-23-2022 01:09 AM	~	State
3966	Scott Anderson	Avista Corporation	6812 N. Wiscomb St	12-13-2021 05:50 PM	~	State
3959	Anthony Dorrough	Avista Corporation	10108 Seminole Drive	11-23-2021 01:28 PM	~	State
3950	Darren Tinnerstet	Avista Corporation	412 W. 37th Ave.	11-01-2021 11:29 AM	~	State
	Darren Tinnerstet	Avista Corporation	2623 N Madelia St.	10-08-2021 05:55 PM	~	State
	Darren Tinnerstet	Avista Corporation	111 E Liberty St.	10-06-2021 11:25 AM	Υ.	State
	Dennis Ritter	Avista Corporation	603 N Mamer Rd	09-17-2021 09:04 AM	· ·	State
	Dennis Ritter	Avista Corporation	1st and Lee St	09-17-2021 07:45 AM	<u> </u>	State
	Lex Vinsel	Avista Corporation	6514 N. Sotherland St	09-10-2021 06:15 PM	· ·	0
	David Cullom	Avista Corporation	707 North 8th St	09-05-2021 08:19 AM	· ·	State
	Scott Rukke	Avista Corporation	1111 W Augusta 621 W 3rd Street	08-16-2021 02:42 PM	ž	State
	Lex Vinsel Lex Vinsel	Avista Corporation Avista Corporation	840 E Spokane Falls Blvd	07-08-2021 10:33 AM 07-06-2021 02:00 PM	ž	State
	Derek Norwood	Avista Corporation	347 S Colville Rd	06-17-2021 11:35 AM	Ž	State
3877		Avista Corporation	22787 Road 6 SE	06-17-2021 12:15 AM	Ž	State
	Anthony Dorrough	Avista Corporation	1109 Hwy 395	05-28-2021 05:08 PM	Ž	State
	Scott Anderson	Avista Corporation	508 6th St.	05-26-2021 10:05 AM	~	State
	Scott Rukke	Avista Corporation	828 W Main	04-27-2021 11:49 PM	~	State
3853	Anthony Dorrough	Avista Corporation	612 Phelts	04-25-2021 04:00 PM	~	State
	Lex Vinsel	Avista Corporation	115 N Main	03-26-2021 05:44 PM	~	State
3829	Scott Rukke	Avista Corporation	9919 N. Seminole Dr	03-04-2021 03:15 PM	~	State
3822	Anthony Dorrough	Avista Corporation	Harvard Rd & Wellesely Ave	02-10-2021 10:19 AM	~	Non-Reportable
3811	David Cullom	Avista Corporation	6200 N Division St	01-18-2021 11:01 AM	~	State
3797	Derek Norwood	Avista Corporation	801 N Division St	12-14-2020 12:00 AM		State
3796	Dennis Ritter	Avista Corporation	619 E Cascade PL	12-07-2020 01:11 PM	~	State
3793	Scott Anderson	Avista Corporation	5217 N Adams St	12-03-2020 02:24 PM	~	State
3787	Scott Anderson	Avista Corporation	6301 N. Division St.	11-19-2020 10:49 AM	~	State
	Scott Anderson	Avista Corporation	3009 W Alice Ave	11-17-2020 05:31 PM	~	State
	Scott Anderson	Avista Corporation	20 W North River	11-16-2020 08:22 PM	~	State
	Scott Rukke	Avista Corporation	6311 E Sharpe	11-10-2020 11:07 AM	· ·	State
	Lex Vinsel	Avista Corporation	452 W Shoshone PI	10-06-2020 11:48 AM		State
	David Cullom	Avista Corporation	1900 West 1st Ave	09-30-2020 12:10 PM 09-22-2020 01:06 PM	<u> </u>	State
	Anthony Dorrough Scott Rukke	Avista Corporation	606 E Burke Rd 1231 W 1st St	09-22-2020 01:06 PM 09-20-2020 02:47 PM	Ý	State State
	Darren Tinnerstet	Avista Corporation Avista Corporation	301 S. Cromwell	09-20-2020 02:47 PM	Ť	State
	Derek Norwood	Avista Corporation	209 S Summit Ave	08-26-2020 12:49 PM	Ĵ	State
	David Cullom	Avista Corporation	3818 East 29th	08-09-2020 11:31 AM	Ž	State
	Scott Anderson	Avista Corporation	2603 W Upton Ave	07-27-2020 11:39 AM	~	State
	Scott Rukke	Avista Corporation	2528 W. Queen St	07-26-2020 06:53 PM	~	State
	Scott Rukke	Avista Corporation	3405 Grandview ave	07-20-2020 03:09 PM	~	State
	Derek Norwood	Avista Corporation	2831 W Broad Ave	06-25-2020 11:00 AM	~	State
	David Cullom	Avista Corporation	1905 West Pacific St	06-10-2020 08:58 AM	~	State
3691	Scott Anderson	Avista Corporation	5510 N Haven St.	06-04-2020 07:32 AM	~	State
		Avista Corporation	1110 Westview Ct	06-02-2020 09:01 AM	~	State
3685	Scott Anderson					
3685 3678 3675	Darren Tinnerstet	Avista Corporation	10510 West Richland Rd.	05-23-2020 01:00 PM	~	State
3685 3678 3675 3661	Darren Tinnerstet Derek Norwood	Avista Corporation Avista Corporation	614 E Hartson Ave	04-30-2020 01:07 PM	~	State
3685 3678 3675 3661 3660	Darren Tinnerstet	Avista Corporation				

6. Notes

 $Operator reported\ 26\ incidents\ in\ 2020.\ 30\ d\ reports\ were\ timely\ and\ received\ for\ all\ required\ incidents.\ No\ issues\ were\ noted\ by\ oncall\ engineers.\ No\ trends\ were\ noted.\ A\ random\ review\ of\ 10\ incidents\ showed\ operator\ provided\ all\ required\ information-3796,\ 3793,3780,3760,3748,3772,3714,3685,3661,3658$

 $Were there \, reportable \, or \, unreportable \, safety \, related \, conditions \, during \, the \, previous \, year? \, If \, yes \, please \, describe.$

Q7: Report of SPCs

Car. Report of SRCs							
NotificationID	Company	Safety- Related Condition	SafetyRelatedConditionChoices	Reportable?	Date & Time of Incident	Company Notified Date	Report Date
No incident notificat	ions found						

7. Notes

There were no safety related conditions reported in 2020.

Question #8.

For transmission systems, were there any abnormal operating conditions (as described in 192.605 (c) or 195.402(d)) since the last annual review? If yes please describe.

8. Result

7. Result Not Applicable

Not Checked/Evaluated

192.605(c) does not apply to distribution operators who operate transmission lines (192.605(d).

Question #9.

Operator Manuals on Sharepoint

9. Result Satisfactory

13. Result

Satisfactory

16 Posuite

18. Results

Is the O&M Manual up to date and were changes made in the previous year?

Manual is updated annually. Current manual was issued and became effective 1/1/21, previous manual was effective on 1/1/20. Changes are noted in the front of the Manual

Question #10.

10. Result

If changes to the O&M were made, are changes acceptable?

Satisfactory

Reviewed the 2021 updates as described on pages 5-17 of the manual (physical pages in pdf). Highlights include: Avista has added language for compliance with the new federal codes identified in 49 CFR 192. This includes 4.16-MAOP reconfirmation per 192.619, 624 and 607; 4.41 Changes to the TIMP to include MCAs and other related integrity changes; 4.31 made the OQ program a separate program. 3.22 New weld procedures; 1.1 various changes and additions to Glossary.

Question #11.

Were emergency plans changed during the previous year?

11. Result

Satisfactory

11. Notes

Reviewed the 2021 updates as described on pages 5-7 of the manual (physical pages in pdf).

Question #12.

Were any changes to emergency plans satisfactory?

12. Result

Satisfactory

12. Noies

Reviewed the 2021 updates as described on pages 5-7 of the manual (physical pages in pdf).

INTEGRITY MANAGEMENT PROGRAMS

Question #13

Were there changes to the Integrity Management programs (TIMP, DIMP or both, as applicable)?

DIMP plan was last revised on 8/17/20. TIMP was revised 10/19/2020. Avista updates these manuals annually.

14. Result Satisfactory

Is the DIMP/TIMP up to date? What are the results of the operator's program review (effectiveness evaluation) (DIMP every 5 years)?

14. Notes

DIMP-Revision 9 Issued August 17, 2020. Revision 8 was issued Dec 6, 2019. There were several minor changes to Sections 6.2, 7.4, 8.3 (this relates to Oregon PUC dig law), 9.5 and Appendices A-G--Note Appx E is listing of current accelerated actions and Appx G is year by year historical record.

TIMP-Revision 15 Issued 2020. This revision adds the new requirement from federal code published 10/1/19 relating to MAOP reconfirmation and verification—New section 14, New E&RP #13 and 14 for predicted failure pressure analysis and Critical engineering assessment.

Question #15 15. Result

Are IMP program changes acceptable? Satisfactory

15. Notes Changes to both the DIMP and TIMP plan are acceptable

Was appropriate assessment/repair work conducted during the past year? (monitor progress of IMP activities) Not Applicable

No assessment work was completed in WA in 2020

17. Results Not Applicable

Does the operator's HCA location data correspond to the positional data located in UTC GIS?

17. Notes Avista has no HCAs in WA

Question #18

What assessment work is planned for the upcoming year? Not Applicable

Avista has no planned assessment work for the upcoming year.

Question #19 19. Results Within the operator's DIMP, are low pressure systems evaluated for overpressure threats? Not Applicable

Avista has no low pressure systems.

Question #20 20. Results

Did the operator develop and follow specific procedures for low pressure system construction or maintenance projects? (Note: this question is revisited in greater detail in the ADB review Not Applicable

20. Notes Avista has no low pressure systems.

Question #21

21. Results Are plastic pipe and components that have shown a record of defects/leaks being mitigated through the DIMP plans? Satisfactory

Adyl A pipe is monitored and being replaced in the Avista system as part of Pipeline Replacement Plan. Duraline PE pipe is used in the Avista system. DuraLine notified industry that their small diameter pipe experience manufacturing defects resulting in wall thickness inconsistencies. Avista is monitoring through the DIMP and switched suppliers to Endot for future deliveries.

22. Results Question #22 Satisfactory

 $Has appropriate \ DIMP\ remediation\ work\ occurred\ during\ the\ past\ year?\ (monitor\ progress\ of\ DIMP\ activities)$

Adyl A replacement work, isolated steel riser replacement (to be completed in 2021), utility cross bore post camera inspection pilot.

Question #23

23. Results What DIMP remediation work is anticipated for upcoming year? Satisfactory

isolated steel program wraps up in 2021 and continued Adyl A replacement, deteriorated pipe and utility cross bore pilot.

OQ PROGRAM

Question #24 24. Results

Is the OQ program up to date? Were there changes to the Operator Qualification (OQ) program in the last year? If yes, please describe.

Question #25

Are the OQ plan updates satisfactory?

25. Results Satisfactory

25. Notes

Updates are satisfactory as ther ewere no findings from 2020 inspection.

Question #26

Are personnel performing covered tasks (including contractors) properly qualified and requalified at intervals determined in the operator's plan?

26. Results Satisfactory

26. Notes

During the Pullman/Clarkston unit inspection 2021 reviewed OQs for a number of Avista personnel and contractors. No issues were found.

PUBLIC AWARENESS PROGRAM

Is the PA program up to date? And were there changes to the Public Awareness (PA) program within the last year?

27. Results

Satisfactory

27. Notes

The last revision to the PA plan was completed March 15, 2019. The last PA plan inspection (7782) for Avista was conducted March 29, 2019 by the UTC. No findings were noted during the

Question #28

28. Results

Are changes to the PA program satisfactory?

Satisfactory

28. Notes

No findings were noted from the 2019 inspection.

CONTROL ROOM PROGRAM

Question #29

29. Results

Is the CRM program up to date? And were there changes to the Control Room Management (CRM) program within the last year?

Satisfactory

29. Notes

The WUTC along with Oregon and Idaho PUCs conducted a CRM inspection (8154) in April of 2021. There were 4 areas of concern from this inspection related to procedures. Avista correted the areas of concern and updated the procedures.

Question #30

30. Results

Are the CRM program changes satisfactory?

Satisfactory

30. Notes

The areas of concern were satisfactorily addressed by correcting the appropriate procedures.

SAFETY MANAGEMENT SYSTEM API 1173

Question #31

31. Results

Is the operator developing and implementing an API 1173 Safety Management System? Satisfactory

31. Notes

SMS implemented in 2016 using API RP 1173 as guide.

INSPECTOR ASSESSMENT OF INSPECTION UNITS

Question #32

32. Results

Are inspection units broken down appropriately? Do you recommend any changes to inspection units?

Satisfactory

32. Notes

No concerns with unit break down.

Q32: List of current inspection units

a de la constant de l					
Unit Name	Distribution/Transmission	Intrastate or Interstate?	GAS or LIQUID	UTC Unit ID	UTC Operator ID
Avista Corporation (6 Units)					
Avista Utilities Corp - Colville	Distribution	Intrastate	Gas	1789	112
Avista Utilities Corp - Pullman/Clarkston	Distribution	Intrastate	Gas	1788	112
Avista Utilities Corp - Spokane	Distribution	Intrastate	Gas	1914	112
Avista Utilities Corp - Ritzville	Distribution	Intrastate	Gas	1915	112
Avista Utilities Corp - Transmission	Transmission	Intrastate	Gas	1907	112
Avista Corporation- Headquarters	Distribution	Intrastate	Gas	83	112

OPERATOR'S PUBLIC WEB PAGE

Question #33

33. Results

For informational purposes: Using the drop down selections available in the "Results" block, indicate whether the operator's web page contains the information listed by placing a check in the box adjacent to all items that are present.

Q33.B Damage Prevention; Q33.D How to get additional information; Q33.G Potential Hazards; Q33.H Prevention Measures; Q33.I Leak/Damage Recognition; Q33.J ROW Encroachment; Q33.M Emergency

33. Notes

ADVISORY BULLETIN REVIEW

Question #34

Is there potential for damage to the operator's pipeline facilities caused by flooding, river scour, or channel migration?

ADB 2019-01 ADB 2019-01 Flood Mitigation 34. Results YES

34. Notes

Avista has reviewed PHMSA's Advisory Bulletin on flooding, river scour, and river channel migration. Avista's Gas Standards take into account the threats concerned in this bulletin in its design, reporting, leak survey, and OQ qualifications (Sections 2.12, 2.13, 2.14, 2.15, 4.12, 5.11 and 4.31). Avista continues to improve our Emergency Response plans and has emergency valves in place for zoning off larger portions of the system strategically in case of natural disasters. Between 2016 and 2018, Avista's DIMP program hired outside geological firms to help develop a more detailed and robust natural forces risk model that takes into account waterway crossings, river scour, fault lines, landslide, erosion, liquefaction, and others for all three states we serve. The geological hazards survey performed includes all of Avista's service territory, but was focused in more detail on Avista's transmission pipelines.

As an update to the aforementioned "response to file", the geological hazards survey did confirm waterway crossings of the Kettle Falls Transmission Line (NE Washington) require attention. The crossing of the Colville River at MP 47 will be rebored Summer 2021 due to it being exposed. The WUTC was notified of this pending work on 5/14/21. Another crossing of the Colville River on the outskirts of the city of Kettle Falls, WA has been found to have reduced cover over the pipeline as well and a remediation plan is being developed at present.

Question #35

If "YES" to Q34, did the operator take appropriate action in accordance with the guidance contained ADB 2019-01? Discuss ADB's guidance with operator's representative, and annotate any concerns

ADB 2019-01 ADB 2019-01: Flood Mitigation 35. Results Satisfactory

35. Notes

As an update to the aforementioned response to file, the geological hazards survey did confirm waterway crossings of the Kettle Falls Transmission Line (NE Washington) require attention. The crossing of the Colville River at MP 47 will be rebored Summer 2021 due to it being exposed. The WUTC was notified of this pending work on 5/14/21. Another crossing of the Colville River on the outskirts of the city of Kettle Falls, WA has been found to have reduced cover over the pipeline as well and a remediation plan is being developed at present.

Question #36

Is there potential for the operator's system to be damaged by earth movement or other seismic/geological activities?

ADB 2019-02

ADB 2019-02: Earth Movement/Geological Hazards

36. Results YES

36. Notes

Avista has reviewed PHMSA's Advisory Bulletin on earth movement and other geologic hazards. Avista's Gas Standards take into account the threats concerned in this bulletin in its design, reporting, leak survey, and OQ qualifications (Sections 2.12, 2.13, 2.14, 2.15, 4.12, 5.11 and 4.31). Avista continues to improve our Emergency Response plans and has emergency valves in place for zoning off larger portions of the system strategically in case of natural disasters. Between 2016 and 2018, Avista's DIMP program hired outside geological firms to help develop a more detailed and robust natural forces risk model that takes into account waterway crossings, river scour, fault lines, landslide, erosion, liquefaction, and others for all three states we serve. The geological hazards survey performed includes all of Avista's service territory, but was focused in more detail on Avista's

Question #37

If "YES" to Q36, did the operator take appropriate action according to ADB 2019-02? Discuss suggested actions from ADB with operator's representative and annotate any concerns.

ADB 2019-02

transmission pipelines.

37. Results

ADB 2019-02: Earth Movement/Geological Hazards

Satisfactory

37. Notes

Avista responded with geologal hazards survey

Question #38

Does the operator have any indoor meter sets or regulators in their system?

ADB 2020-01

38. Result

ADB 2020-01 Inside Meter Sets

YES

38. Notes

Avista has inside meter sets / regulators in Washington State. The vast majority are in Spokane Construction District. Avista typically makes a formal "response to file" for PHMSA Advisory Bulletins. On 11/3/20, Avista made the following "response to file" for the noted ADB that came out on 9/29/20:

Avista acknowledges receipt of this bulletin and provides the following response as written by Pipeline Integrity Program Manager, Brian Schultz:

"Avista has reviewed PHMSA's Advisory Bulletin on requirements for inside meters and regulators. Avista currently has approximately 500 inside meter sets in our gas system. Avista also has had a budget in place for several years for meter move-outs and continues to move out the higher risk inside meter sets each year.

In response in the advisory bulletin, Avista is making two updates to the Gas Standards in Specification 2.22 for 2021. The updates to the Gas Standards include a new requirement for approval from Gas Engineering before any new meter or regulator can be installed inside a building, and specifies: "Efforts should be made to move inside meter sets outside anytime work is required on the meter, regulator, or service piping. If it is proposed to leave the meter set inside, contact Gas Engineering. Gas Engineering will review the existing installation and determine if it meets current installation requirements."

Also, in response, Avista has made changes to the consequence scoring of the DIMP risk model to account for additional consequence risk where inside meter sets are currently located. Model updates are currently being performed and will be used in the DIMP risk analysis in 2021.

Question #39

If operator's system has indoor meter sets/regulators, did the operator review ADB 2020-0115? Discuss ADB guidance with operator's representative and annotate any concerns. Particular attention must be given to the operator's plan to conduct leak surveys, AC inspections, and other maintenance activities in locations that are difficult to access, as well as the inclusion of inside meters/regulators within the operator's DIMP plan, as applicable.

 ADB 2020-01
 39. Results

 ADB 2020-01 Inside Meter Sets
 Satisfactory

39. Notes

In response in the advisory bulletin, Avista is making two updates to the Gas Standards in Specification 2.22 for 2021. The updates to the Gas Standards include a new requirement for approval from Gas Engineering before any new meter or regulator can be installed inside a building, and specifies: "Efforts should be made to move inside meter sets outside anytime work is required on the meter, regulator, or service piping. If it is proposed to leave the meter set inside, contact Gas Engineering. Gas Engineering will review the existing installation and determine if it meets current installation requirements."

Avista leak surveys all jurisdictional pipelines to the furthest downstream location. In the case of inside meters / regulators, these get leak surveyed either annually or every five years as required by Federal Codes. Additionally, Avista performs AC Inspections every three years of all jurisdictional pipelines including all meter sets and regulators inside buildings. Avista contracts with Heath Consultants and they conduct our leak survey to include facilities inside buildings. Contractor utilizes the Detecto-Pak IR Device (See GSM 5.11, Sheet 2) which is safe to use indoors.

If the contractor can't gain access inside (just like any "can't gain entry-CGE" order) they will submit the CGE to Avista and then Avista generates a service request for a Gas Serviceman to meet up with them to assist gaining access.

Question #40

Does the operator have a detailed record of locations for all indoor meter sets/regulators within their system?

ADB 2020-01

40. Results Satisfactory

ADB 2020-01 Inside Meter Sets

40. Note:

Avista annotates inside meter sets / regulators in its IBM Maximo Compliance System.

Does the operator have any low pressure systems?

ADB 2020-02 ADB 2020-02 Low Pressure Systems 41. Results

42. Results

44. Results

Not Applicable

Not Applicable

NO

41. Notes

Question #42

If "YES" to Q41, did the operator review ADB 2020-0025 for Overpressure Protection of Low-Pressure Natural Gas Distribution Systems? Review ADB guidance with operator and annotate any concerns.

ADB 2020-02

ADB 2020-02 Low Pressure Systems

42. Notes

Avista has no low pressure systems

For low pressure construction/maintenance projects, does the operator have a process for review of engineering plans and constructibility reviews that are carried out through all applicable departments? Do all applicable departments review project plans for accuracy, completeness and correctness? How are control procedures developed that could identity system threats that could result in a common failure mode? How is the operator mitigating risk in their low presure system?

ADB 2020-02

43. Results ADB 2020-02 Low Pressure Systems Not Applicable

43. Notes

Avista has no low pressure systems

Question #44

Does the operator include all low-pressure system risks in their DIMP program appropriately?

ADB 2020-02

ADB 2020-02 Low Pressure Systems Avista has no low pressure systems

SUMMARY OF REQUIRED COMMENTS

COMMENTS: Required for any ratings other than Satisfactory. Summarize/consolidate entries from the "Notes" blocks above. Ensure you annotate the question number for each comment.

Question 4-No federal reportables in 2020

Question 7-There were no safety related conditions reported in 2020

Question 16-No assessment work was completed in WA in 2020

Question 17-Avista has no HCAs in WA

Question 18-Avista has no planned assessment work for the upcoming year

Question 19-Avista has no low pressure systems

Question 20-Avista has no low pressure systems

Question 42-Avista has no low pressure systems

Question 43-Avista has no low pressure systems

Question 44-Avista has no low pressure systems