Form A- Annual Review 8438

UTC Standard Annual Review Inspection Report Intrastate Operators FORM A: Annual Review

Inspector and Operator Information

Inspection ID Inspection Link Inspector - Lead Inspector - Assist

Tacoma, WA

8438 8438 Darren Tinnerstet

Unit Records Location - City & State Operator

McChord Pipeline McChord Pipeline Inspection Start Date Inspection Exit Interview Date Engineer Submit Date

11-16-2022 11-16-2022 11-17-2022

Inspection Summary

You must include the following in your inspection summary:

- *Inspection Scope and Summary
- *Facilities visited and Total AFOD
- * Summary of Significant Findings
- * Primary Operator contacts and/or participants

Inspection Scope and Summary

Annual Review of McChord Pipeline Company.

The McChord Pipeline is a buried intrastate pipeline 14.25 miles in length, constructed in 1966 with 6-inch nominal steel pipe grade B, wall thickness of 0.188 inch to 0.432 inch. A one mile reroute was performed in 1996. The pipeline has a 720 psig MOP (36% SMYS) with a normal operating pressure at 450 psig (21% SMYS). The pipeline is divided into four sections with isolation valves between each section. The entire pipeline has about 400 foot elevation differential. The pipeline transports jet fuel from US Oil Refinery located in Tacoma near Commencement Bay to the McChord Air Base storage facility, Jurisdiction begins at the pump suction valves (P-1401) and ends at the custody transfer manifold valves downstream of the meters at McChord Air Force Base. The pipeline was hydrostatically tested in 1996, inline inspected in 2004 (GE pig), and MFL runs were completed in 2009, 2014 and 2019. Prior to each run they evaluate the tool to make sure complementary technologies are used. Tuboscope was used in 1996. GE used UT in 2004. In 2005, there was a pressure cycle analysis done by Kiefner and Assoc. along with the LF Pre-70 ERW study. In 2009, a MFL pig was run by Baker Hughes

McChords integrity management program considers all of its pipeline to be in a HCA or a HCA CA given it's location and proximity to HPAs, CNWs, ecological and drinking water USAs.

LF Pre-70 ERW mileage is at 13.25. The remaining 1 mile is not LF Pre-70 ERW.

Facilities visited and Total AFOD

McChord Pipeline administrative offices located at US Oil Refinery

AFOD - 1

Summary of Significant Findings (DO NOT Discuss Enforcement options)

No Violations or areas of concern.

Primary Operator contacts and/or participants

Joel Roppo - Chief Engineer

John Williamson - Chief Pipeline Inspector

Operator executive contact and mailing address for any official correspondence

Andrew Troske - Vice President

McChord Pipeline Company

3001 Marshall Ave.

Tacoma, WA 98421

Instructions and Ratings Definitions

INSPECTION RESULTS: Annual Review

Satisfactory Responses Satisfactory List Number of Unanswered Questions Unanswered List

1,3,8,9,10,12,14,15,17,24,25,26,27,29,30,31,32,35,37,

Unsatisfactory Responses Unsatisfactory List

Area of Concern Responses Area of Concern List

Not Applicable Responses

Not Applicable List 20

4,5,6,7,13,16,18,19,20,21,22,23,28,38,39,40,41,42,43,44

Yes List No Responses No List Yes Responses

Not Checked / Evaluated Responses Not Checked / Evaluated List

**If an item is marked Unsat, AOC, N/A, or N/C, an explanation must be included in the "Notes" block for that question and also summarized in the "SUMMARY OF REQUIRED COMMENTS" section at the end of this inspection form.

Crew Inspection History

Click Link for Full List of Crew Inspections

Determination crew inspection Date	Inspector	Operator	Unit	Type of Work	Foreman Name	Contractor Name	Comments / Observations for Operator
No Crew Inspection recor	ds found						

Facility Inspection History

Link for Full List of Facility Inspections

or file attachments?	Date Inspection ID Form A Operator Name Other Company Inspector Type of Inspection Do you have inspector or file attachments?
----------------------	---

No Facility Inspection records found

Scheduled Inspection History

Annual Review Inspection History

Year of Inspection	Facility - Operator	Unit Name	Inspection ID	Inspection Type	Inspection Status	Closed Date	Next Inspection Interval	SHAREPOIN
McChord Pip	eline Company (16 Ins	spection records)	'		'	'		'
2021	McChord Pipeline Company	McChord Pipeline Company	8275	Standard Comprehensive - HL	Complete	11-30-2021	11-04-2024	Documents
2021	McChord Pipeline Company	McChord Pipeline Company	8276	PA - Public Awareness	Complete	11-30-2021	11-04-2025	Documents
2021	McChord Pipeline Company	McChord Pipeline Company	8277	Standard - Annual Review	Complete	11-30-2021	11-04-2022	Documents
2020	McChord Pipeline Company	McChord Pipeline Company	8016	LIMP - Liquid Transmission Integrity Management	Complete	06-12-2020	06-04-2023	Documents
2020	McChord Pipeline Company	McChord Pipeline Company	8017	DA - Drug & Alcohol	Complete	02-27-2020	02-25-2024	Documents
2020	McChord Pipeline Company	McChord Pipeline Company	8018	Standard - Annual Review	Complete	06-12-2020	06-04-2021	Documents
2019	McChord Pipeline Company	McChord Pipeline Company	7846	OQ - Operator Qualification	Complete	12-02-2019	11-05-2023	Documents
2019	McChord Pipeline Company	McChord Pipeline Company	7847	CRM - LIQUID	Complete	12-20-2019	11-06-2023	Documents
2019	McChord Pipeline Company	McChord Pipeline Company	7848	Standard - Annual Review	Complete	12-20-2019	11-06-2020	Documents
2019	McChord Pipeline Company	McChord Pipeline Company	7924	OM PPR LIQUID - Operations & Maintenance, Plans & Procedures Review	Complete	08-12-2019	07-22-2023	Documents
2018	McChord Pipeline Company	McChord Pipeline Company	7567	Standard Comprehensive - HL	Complete	10-26-2018	10-10-2021	Documents
2017	McChord Pipeline Company	McChord Pipeline Company	7236	LIMP - Liquid Transmission Integrity Management	Complete	10-12-2017	09-26-2020	Documents
2017	McChord Pipeline Company	McChord Pipeline Company	7474	PA - Public Awareness	Complete	12-04-2017	10-31-2021	Documents
2017	McChord Pipeline Company	McChord Pipeline Company	7508	Incident Investigation	Complete	10-20-2017	10-11-2017	Documents
2016	McChord Pipeline Company	McChord Pipeline Company	6754	Standard Comprehensive - HL	Complete	10-19-2016	10-11-2019	Documents
2015	McChord Pipeline Company	McChord Pipeline Company	6208	OM PPR LIQUID - Operations & Maintenance, Plans & Procedures Review	Complete	08-27-2015	08-11-2019	Documents

GAS System Operations History

Annual Report - Miles of Main

Year	Operator	SYSTEM TOTAL Miles of Main	Miles of Service	SYSTEM TOTAL NO. of Services	Average Service Length
No Repor	t records found				

Annual Report GAS Transmission Miles

YEAR	Total Total Miles	e. Total tool mileage inspected in calendar year using in-line inspection tools
No Report re	cords found	

Annual Report - Leaks

Year	Operator	Cause of Leak Mains Total	Cause of Leak Mains Hazardous Total	Cause of Leak Services Total	Cause of Leak Services Hazardous Total	NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR
No Report	records found					

Annual Report - EFV

Annual Report	- LI V						
Operator	Year	Number of EFV's Installed This Calendar Year on Single Family Residential Services:	Estimated Number of EFV's in the system at the End of The Year:	Total Number of Services with EFV Installed During Year:	Estimated Number of Services with EFV In The System At The End of The Year:	* Total Number of Manual Service Line Shut-off Valves Installed During Year:	* Estimated Number of Services with Manual Service Line Shut-off Valves Installed in the System at End of Year:
No Report rec	ords foun	d					

HL System Operations History

HL Annual Report - Miles of Pipe by Decade

No Report records found

HL Annual Report - HL Miles / HCAs

HL Annual	Report -	Breakout	Tanks
-----------	----------	----------	-------

YEAR	Operator	Commodity Group	Miles that	High Population	Other Population	Drinking Water	Ecological Resource	Comm Navigable Water		YEAR	Operator	Commodity Group	Crude Oil #5	Refinec (nor HVL #5
			Could Affect HCAs							No Repor	t records found	1		
No Rep	ort records found	i							1					

ANNUAL REPORT: ACCURACY/TRENDS

Was the Annual Report reviewed for accuracy and trends? If any trends were discovered, please describe.

1. Result Satisfactory

1. Notes

no trends.

Access to	Complete	Distribution	Annual	Report
ACCESS IO	Complete	: Disu ibuuoii	Alliiua:	report

ACCESS 10	Complete Distric	outon Ailitea Kept	,	I							
Year	Operator	SYSTEM TOTAL Miles of Main	Miles of Service	SYSTEM TOTAL NO. of Services	Average Service Length						
No Repo	No Report records found										

Access to Complete Iransmission Annual Report								
YEAR	Operator	Commodity Group	Total Total Miles					
No Report records found								

Access to Complete Hazardous Liquid Annual

YEAR	Operator	Commodity Group
No Report		

DAMAGE PREVENTION

Annual Report Damage Prevention data

Year	Operator	Number of Excavation Tickets	Total Number of Excavation Damages By Apparent Root Cause:	Locating Practices Not Sufficient:	One-Call Notification Practices Not Sufficient:	Excavation Practices Not Sufficient:	Other:	Number of Services	Total Leaks - Excavation Damage	Total Main Leaks	Miles of Service MAIN	Number of Leaks per Mile of MAIN	Total Leaks Per 1,000 Locates	N R€
------	----------	------------------------------------	--	---	---	---	--------	--------------------------	--	------------------------	--------------------------------	---	---	---------

No Damages records found

DIRT data on mismarks for prior year

Damage Cause	Number of Reports				
No Report records found					

DIRT Timeliness - Prior Year Reports must be submitted within 45 days of the damage.

SubmitCompanyID - UTCfinalName	Number of Reports
No Report records found	

Question #2

Review the following damage prevention items:

Q2. Is the damage prevention information in the annual report complete? http://N/A

Q2.d Does the operator follow a process to evaluate the cause of

"Locating practices not sufficient" category? Yes, Maintenance Manual, Section I-6

Q2.g. What is the number of damages resulting from mismarks?

Q2.j. Are mapping corrections timely and according to written procedures?

N/A

2. Notes

Q2.b. Is the annual report damages root cause information complete and accurate?

N/A

Q2.e. Is the operator or its contractor qualified and following procedures for locating and marking facilities?

Yes. Seven qualified in house locators.

Q2.h. What is the number of damages resulting from not locating within the time requirements?

Q2.k. Does the operator follow a process to evaluate causes for damages listed "Excavation Practices Not Sufficient"?

Q2.c. Does the operator have a process to evaluate practices not sufficient" category?

Yes. Maintenance Manual, Section J-6

Q2.f. Is the operator appropriately requalifying loca deficiencies?

N/A. No requalifications were required.

Q2.i. Is the operator appropriately addressing disc excavation damage?

N/A

Q2.L. Is the operator appropriately focusing damas address the causes of excavation damage?

Damages have been minimal. Last excavation dama was caused by improper excavation practices

NPMS SUBMISSIONS/CHANGES

Question #3. 3. Result

For transmission operators, has the operator submitted information to the NPMS database, along with changes made after the original submission? Satisfactory

Reviewed 2021 submission. No changes.

INCIDENT/SRC/AOC REPORTS REVIEW

Question #4 Were there any federally reportable incidents during the previous year? Are there any discernable trends to these incidents? 4. Results Not

Applicable

No reportable incidents for the year 2021.

Q4: Federally reportable incidents

NotificationID	Operator	Company	NRC#	Assigned Engineer	Date & Time of Incident	Street Address of event/incident	Incident Address: City	Closure Date	Reporting Level
3199	McChord Pipeline Company	McChord Pipeline Company	1,186,063	Dennis Ritter	08-02-2017 12:12 PM	Intersection of 100th St and A St			Federal

Question #5.

5. Result Not Applicable

Review operator records of previous year's accidents and failures including reported third party damage and leak response. Is the operator ensuring appropriate evaluation and response as required in 192.617 (Gas) or 195.402 (HL) to determine cause of failure? Is the operator taking appropriate steps to minimize the possibility of reoccurrence?

5. Notes

No accidents, failures, or leaks for the year 2021.

Question #6.

Review incident reports for the previous year for accuracy and identify any trends. If any trends discovered please describe. (Please see list of incident data at end of this report)

O6: Incident Reports

	NotificationID	Inspector	Company	Street Address of event/incident	Date & Time of Incident	Is 30-Day Report Received?	Reporting Level	
No Incident Notification records found							Ī	

6. Result Not Applicable

8. Result

Satisfactory

14. Result

Satisfactory

6. Notes

No incident reports for the year 2021.

Question #7.

Were there reportable or unreportable safety related conditions during the previous year? If yes please describe.

	Q7. Report of SRCS								7. Result
	NotificationID	Company	Safety- Related Condition	SafetyRelatedConditionChoices	Reportable?	Date & Time of Incident	Company Notified Date	Report Date	Not Applicable
No Incident Notification records found									

7. Notes

No SRC occurred during 2021 calendar year.

For transmission systems, were there any abnormal operating conditions (as described in 192.605 (c) or 195.402(d)) since the last annual review? If yes please describe.

8. Notes

Operations Manual, Section IV - Abnormal Operations.

Approximately 4-6 times throughout year, during jet fuel transfer volume transferred is compared to the volume recieved at the base and it triggers an alarm. Procedure from Section IV is followed when this occurs and involves shutting down pipeline and notifying pipeline inspector who physically drives the pipeline route to look for any visible AOC's. Once it is confirmed that no immediate threat exists, the pipeline is blocked in and re-pressurized to check integrity of line before startup procedures are implemented.

O&M & EMERGENCY PROGRAMS

9. Result Operator Manuals on Sharepoint Is the O&M Manual up to date and were changes made in the previous year? Satisfactory

9. Notes

Operations Manual does not have change log documenting what changes were made during revision. This is being rectified

Maintenance Manual had no changes made during 2021.

 $Administrative\ Manual\ had\ two\ minor\ changes\ -\ Updated\ call\ out\ list\ and\ Updated\ Management\ support\ for\ PA\ program.$

Question #10. 10. Result If changes to the O&M were made, are changes acceptable? Satisfactory

10. Notes

Changes were acceptable and of minimal impact.

Question #11.

Were emergency plans changed during the previous year?

11. Result

Satisfactory

11. Notes

 $Updated\ procedure\ for\ Manual\ operation\ of\ McChord\ Pipeline.\ This\ was\ in\ response\ to\ TSA\ Cybersercurity\ guidelines\ that\ were\ provided\ to\ facility\ operators.$

Question #12.

Were any changes to emergency plans satisfactory?

12. Result

Satisfactory

12. Notes

Changes were satisfactory.

INTEGRITY MANAGEMENT PROGRAMS

13. Result Were there changes to the Integrity Management programs (TIMP, DIMP or both, as applicable)? Not Applicable

13. Notes

14. Notes

No changes made to LIMP program in 2021. LIMP program audit is due in 2023.

Question #14.

 $Is the DIMP/TIMP\ up\ to\ date?\ What\ are\ the\ results\ of\ the\ operator's\ program\ review\ (effectiveness\ evaluation)\ (DIMP\ every\ 5\ years)?$

Reviewed IM Performance Measure Review Checklist - Appendix D-1 for 2021.

15. Result Question #15 Are IMP program changes acceptable? Satisfactory

15. Notes

Changes are acceptable.

Question #16 Was appropriate assessment/repair work conducted during the past year? (monitor progress of IMP activities) 16. Results Applicable

No assessment / repair work was conducted during 2021

Does the operator's HCA location data correspond to the positional data located in UTC GIS?

17. Results Satisfactory

17. Notes

Pipeline is located in a heavily developed area with minimal change to HCA. The entire system is classified as "Could Affect" HCA.

Question #18

18. Results

What assessment work is planned for the upcoming year?

Not Applicable

18. Notes

No assessment work planned for year 2023. Next ILI is scheduled for 2024.

Question #19 Within the operator's DIMP, are low pressure systems evaluated for overpressure threats? 19. Results Not Applicable

19. Notes

Operator does not have any low pressure systems.

Question #20

20. Results

Did the operator develop and follow specific procedures for low pressure system construction or maintenance projects? (Note: this question is revisited in greater detail in the ADB review section)

Not Applicable

20. Notes

Question #21

Operator does not have any low pressure systems.

21. Results

Are plastic pipe and components that have shown a record of defects/leaks being mitigated through the DIMP plans?

Not Applicable

21. Notes

Operator has no plastic pipe in their system.

Question #22 Has appropriate DIMP remediation work occurred during the past year? (monitor progress of DIMP activities) 22. Results

Applicable

22. Notes

Operator is a HL Transmission. No requirement for DIMP program.

Question #23

23. Results

What DIMP remediation work is anticipated for upcoming year?

Applicable

23. Notes

Operator is a HL Transmission. No requirement for DIMP program.

OQ PROGRAM

Question #24 24. Results

Is the OQ program up to date? Were there changes to the Operator Qualification (OQ) program in the last year? If yes, please describe.

Satisfactory

No substantial changes to OQ program. Switching over to OQSG (Pinion) software to track OQ training records. OQ program audit was conducted in 2022 with no significant findings or

Question #25 25. Results

Are the OQ plan updates satisfactory?

Satisfactory

25. Notes

Changes are acceptable

Question #26 Are personnel performing covered tasks (including contractors) properly qualified and requalified at intervals determined in the operator's plan? Satisfactory

26. Results

26. Notes

Reviewed OQ records for:

Inspectors

Contractors

Instrument Techinicans

CP Techinicans

PUBLIC AWARENESS PROGRAM

Question #27 27. Results Is the PA program up to date? And were there changes to the Public Awareness (PA) program within the last year? Satisfactory

27. Notes

Reviewed 2021 PA Program effectiveness measurements.

No significant changes were to PA program

Question #28

28 Results

Not Applicable

Are changes to the PA program satisfactory?

28. Notes

No significant changes made to program.

CONTROL ROOM PROGRAM

Question #29 29. Results Satisfactory

 $Is the CRM\ program\ up\ to\ date?\ And\ were\ there\ changes\ to\ the\ Control\ Room\ Management\ (CRM)\ program\ within\ the\ last\ year?$

Some changes to CRM manual are currently underway. The main change is removing the ability for a supervisor to suerpsede the actions of a controller. This was discovered during the CRM audit conducted in 2022 and is being handled through the Management of Change process.

Question #30 30. Results

Are the CRM program changes satisfactory?

Satisfactory

30. Notes

Changes are acceptable.

SAFETY MANAGEMENT SYSTEM API 1173

Is the operator developing and implementing an API 1173 Safety Management System?

31. Results

Satisfactory

31. Notes

Operator is not currently developing an SMS. Currently operating under Process Safety Management (PSM) which includes a substantial amount of API 1173 content.

INSPECTOR ASSESSMENT OF INSPECTION UNITS

Question #32 32. Results

Are inspection units broken down appropriately? Do you recommend any changes to inspection units?

Satisfactory

32. Notes

Operator only has on unit for their entire system.

Q32: List of current inspection units

Unit Name	Distribution/Transmission	Intrastate or Interstate?	GAS or LIQUID	UTC Unit ID	UTC Operator ID
No Unit records	found				

OPERATOR'S PUBLIC WEB PAGE

For informational purposes: Using the drop down selections available in the "Results" block, indicate whether the operator's web page contains the information listed by placing a check in the box adjacent to all items that are present.

33. Results

Q33.A Pipeline Purpose and Reliability; Q33.B Damage Prevention; Q33.C Pipe Location Information; Q33.D How to get additional information; Q33.E National Pipeline Mapping System; Q33.F On Call Requirements; Q33.G Potential Hazards; Q33.H Prevention Measures; Q33.I Leak/Damage Recognition; Q33.J ROW Encroachment; Q33.K Pipeline Location Information; Q33.M Emergency Preparedness

33. Notes

ADVISORY BULLETIN REVIEW

Is there potential for damage to the operator's pipeline facilities caused by flooding, river scour, or channel migration?

34. Results

ADB 2019-01 Flood Mitigation

YES

Pipeline only crosses one navigatable waterway (Puyallup River). Operator conducts a river scour study evdry 5 years.

Question #35

If "YES" to Q34, did the operator take appropriate action in accordance with the guidance contained ADB 2019-01? Discuss ADB's guidance with operator's representative, and annotate any

ADB 2019-01 35. Results ADB 2019-01: Flood Mitigation Satisfactory

35. Notes

Reviewed 5 year underwater inspection of Puyallup River (8/24/2021). No signficant findings or exposed pipe from river scour.

Question #36

Is there potential for the operator's system to be damaged by earth movement or other seismic/geological activities?

ADB 2019-02 36. Results ADB 2019-02: Earth Movement/Geological Hazards YES

36. Notes

Question #37

If "YES" to Q36, did the operator take appropriate action according to ADB 2019-02? Discuss suggested actions from ADB with operator's representative and annotate any concerns.

ADB 2019-02 37. Results ADB 2019-02: Earth Movement/Geological Hazards

Satisfactory

LandIslides are not a major area of concern for pipeline. Earthquake effects would be dealt with as a SRC and procedure is to use CPM (Computational Pipeline Monitoring) leak detection system to determine if there is any significant damage that would require an emergency shutdown of the pipeline.

Question #38

Does the operator have any indoor meter sets or regulators in their system?

ADB 2020-01 ADB 2020-01 Inside Meter Sets

38. Results Not Applicable

Operator is HL Transmission only. No indoor meter sets.

Question #39

If operator's system has indoor meter sets/regulators, did the operator review ADB 2020-0115? Discuss ADB guidance with operator's representative and annotate any concerns. Particular attention must be given to the operator's plan to conduct leak surveys, AC inspections, and other maintenance activities in locations that are difficult to access, as well as the inclusion of inside meters/regulators within the operator's DIMP plan, as applicable.

ADB 2020-01 39. Results

ADB 2020-01 Inside Meter Sets Not Applicable

39. Notes

Operator is HL Transmission only. No indoor meter sets.

Is the operator's record of locations for all indoor meter sets/regulators within their system complete and sufficently detailed??

ADB 2020-01 40. Results Not Applicable

ADB 2020-01 Inside Meter Sets

40. Notes

Question #41

Does the operator have any low pressure systems?

Operator is HL Transmission only. No indoor meter sets.

ADB 2020-02

ADB 2020-02 Low Pressure Systems Not Applicable

Operator is HL Transmission only. No low pressure systems.

If "YES" to Q41, did the operator review ADB 2020-0025 for Overpressure Protection of Low-Pressure Natural Gas Distribution Systems? Review ADB guidance with operator and annotate

41. Results

ADB 2020-02 42. Results ADB 2020-02 Low Pressure Systems Not Applicable

42. Notes

Operator is HL Transmission only. No low pressure systems.

For low pressure construction/maintenance projects, does the operator have a process for review of engineering plans and constructibility reviews that are carried out through all applicable departments? Do all applicable departments review project plans for accuracy, completeness and correctness? How are control procedures developed that could identity system threats that could result in a common failure mode? How is the operator mitigating risk in their low presure system?

ADB 2020-02 43. Results ADB 2020-02 Low Pressure Systems Not Applicable

Operator is HL Transmission only. No low pressure systems.

Does the operator include all low-pressure system risks in their DIMP program appropriately?

44. Results ADB 2020-02 Low Pressure Systems Not Applicable

44. Notes

Operator is HL Transmission only. No low pressure systems or requirement for DIMP program.

SUMMARY OF REQUIRED COMMENTS

COMMENTS: Required for any ratings other than Satisfactory. Summarize/consolidate entries from the "Notes" blocks above. Ensure you annotate the question number for each comment.