S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

A completed **Standard Inspection Checklist, OQ Field Validation Protocol form and Cover Letter/Field Report** are to be submitted to the Chief Engineer within **30 days** from completion of the inspection.

Inspection Report							
Inspection ID/Docket Nu	mber	7229					
Inspector Name & Submit Date		Dave Cullom 7/24/2017					
Chief Eng Name & Review/Date		oe Subsits received and reviewed on 7/25/2017					
	•	Operator Information					
Name of Operator:	Puget	Sound Energy		OP ID #:	22189		
Name of Unit(s):	Pierce	;					
Records Location:	Georg	getown (Seattle), South 38 th St (Tacoma)					
Date(s) of Last (unit)				April 3-6, N	1ay 10, May 22-		
Inspection: 7/22/		2014	Inspection Date(s):	24, June 22,	, and July 17,		
				2017			

Inspection Summary:

There are two probable violations and one area of concern for the Pierce County inspection unit.

This standard audit consisted of a joint records review for multiple inspection units (Pierce, Thurston/Lewis, and Kittitas)

The records verification of PSE's facilities for the Pierce County unit included but was not limited to: Leak survey records, leak work orders, cathodic protection (CP) test and remediation records, valve inspections, bridge and slide patrols, odorant checks, equipment calibrations, pressure control records, operator qualification (OQ) records, new construction records, and additional compliance records for drug and alcohol, damage prevention, and public awareness were reviewed.

The UTC also performed spot field checks in the field for operator qualification verification and to verify records reviewed in PSE's offices through field data collection. The field portion included: pipe to soil readings, isolation testing, rectifier inspections, pressure regulator and over pressure operation, emergency block valve operation, and odorant concentration testing.

The field portion included: pipe to soil readings, isolation testing, rectifier inspections; pressure regulator and over pressure operation; block valve operation, and odorant concentration testing.

HQ Address: PO Box 97034 M/S: PSE Bellevue, WA 98009-973			System/Unit Name & Address: Pierce County Field Office 3130 South 38th Street Tacoma, WA 98409			
Co. Official: Phone No.: Fax No.: Emergency Phone No.:	425-462-3843 425-456-2724	ertson, Sr. VP Operations	Phone: 509-201-3037 Fax No.: Emergency Phone No.:	800-552-7171		
Persons Intervi	ewed	Title		Phone No.		
Tony Lupo		Gas Contract Manager		206-517-3431		
Angela Wing	ate	Quality Control Project Manager		206-716-2627		
Gary Swanso	on	Maintenance Program Coordinator		260-716-2632		

Pressure Control Supervisor

425-505-3442

Dave Wooten

Heidi Brewer	Pressure Control Resource Coordinator	253-476-6224
Brett Conrad	Interim Super Supervisor Contractor Management	425-398-6165
Signe Lippert	Supervisor of Maintenance Programs	206-716-2630
Stephanie Silva	Gas Compliance Program Manager	425-462-3923
Lee Maxwell	Sr. Regulatory Compliance Analyst	425-462-3575
Derek Koo	Consulting Engineer	425-462-3819
Monica Ferguson	Regulatory Compliance Analyst	425-462-3087
Dave Moffett	Supervisor of Corrosion South	253-476-6216
John Batinovich	Corrosion Control Technician	Contact supervisor for phone call
Arne Johansen	Corrosion Control Technician	Contact supervisor for phone call
Edd Osborn	CFS Technician	Contact supervisor for phone call
Paul Bench	Pressure Control Technician	Contact supervisor for phone call
Mark Paras	Pressure Control Technician	Contact supervisor for phone call
Martin "Marty" Medley	Pressure Control Technician	Contact supervisor for phone call
Roy McOmber	Pressure Control Technician	Contact supervisor for phone call
Tony Gargiulo	Pressure Control Technician	Contact supervisor for phone call

WU	WUTC staff conducted an abbreviated procedures inspection on 192 O&M and WAC items that changed since the last inspection. This checklist focuses on Records and Field items per a routine standard inspection.					
	(check one below and enter appropriate date)					
	Team inspection was performed (Within the past five years.) or,	Date:	N/A			
	Other WUTC Inspector reviewed the O & M Manual (Since the last yearly review of the manual by the operator.)	Date:	10/29/2015			
\boxtimes	OQ Program Review (PHMSA Form 14)	Date:	11/12/2014			

		GAS SYS	TEM OPERATIONS			
Gas Supp	lier	Williams				
Services:	Residenti	al 161,556 Commercial 4000 Industrial 1100 Other				
Number o	f reporta	ble safety related conditions last year 0	Number of deferred leaks in syst	em 256		
Number of non-reportable safety related conditions last year 0			Number of third party hits last ye	ear 144		
Miles of tr		ion pipeline within unit (total miles and miles in $0,0$	Miles of main within inspection unit(total miles and miles in class 3 & 4 areas)			
			Not separated by class 3 or 4 locations.			
			Pierce County Total Main Footage (mi) 2840.68 per LM (PSE)			
		Operating Pressure(s):	MAOP (Within last year) (psig)	Actual Operating Pressure (psig) (At time of Inspection)		
Town:		e see the field notes for actual operating ures and system MAOPs	Please see the field notes for actual operating pressures and system MAOPs	Please see the field notes for actual operating pressures and system MAOPs		
Other:						

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

	GAS SYSTEM OPERATIONS					
Does the operator have any transmission pipelines?	Yes, In other units.					
Compressor stations? Use Attachment 1.	N/A					
Have incident reports and the annual report been revi	ewed for accuracy and analyzed for trends and operator issues? Yes ⊠ No□					
Comments: I reviewed the annual report for this operator and will also be cross referencing the information in the annual report with DIMP and TIMP program audits later this year						

Pipe Specifications:			
Year Installed (Range)	1955 – 2017	Pipe Diameters (Range)	1/2" to 16"
Material Type	PE, STW, WI	Line Pipe Specification Used	API 5L ASTM D2513
Mileage (Main)	2840.68 miles per LM (PSE)	SMYS %	<20%

Operator Qualification Field Validation

Important: Per OPS, the OQ Field Inspection Protocol Form (Rev 4, May 2007) shall be used by the inspector as part of this standard inspection. When completed, the inspector will upload this information into the PHMSA OQ Database (OQDB) located at http://primis.phmsa.dot.gov/oqdb/home.oq Date Completed/Uploaded ***Notes – This will be uploaded once the inspection is finalized***

Integrity Management Field Validation

PART 199 Drug and Alcohol Testing Regulations and Procedures			U	NA	NC
Subparts A - C	Drug & Alcohol Testing & Misuse Prevention Program – Use PHMSA Form #13, Rev 3/19/2010. Do not ask the company to have a drug and alcohol expert available for this portion of your inspection.	X			

		REPORTING RECORDS	S	U	N/A	N/C
1.	49 U.S.C. 60132, Subsection (b)	For Gas Transmission Pipelines and LNG Plants. Submission of Data to the National Pipeline Mapping System Under the Pipeline Safety Improvement Act of 2002 Updates to NPMS: Operators are required to make update submissions every 12 months if any system modifications have occurred. If no modifications have occurred since the last complete submission (including operator contact information), send an email to opsgis@rspa.dot.gov stating that fact. Include operator contact information with all updates. ***Notes – An email was sent March 1, 2017 for this year's submission***	X			
2.	RCW 81.88.080	Pipeline Mapping System: Has the operator provided accurate maps (or updates) of pipelines, operating over two hundred fifty pounds per square inch gauge, to specifications developed by the commission sufficient to meet the needs of first responders?	X			
3.	191.5	Immediate Notice of certain incidents to NRC (800) 424-8802, or electronically at http://www.nrc.uscg.mil/nrchp.html , and additional report if significant new information becomes available. Operator must have a written procedure for calculating an initial estimate of the amount of product released in an accident. ***Notes – The operator has a written procedure for calculating lost gas during an incident that the RPE uses***	X			
4.	191.7	Reports (except SRCR and offshore pipeline condition reports) must be submitted electronically to PHMSA at http://portal.phmsa.dot.gov/pipeline at unless an alternative reporting method is authorized IAW with paragraph (d) of this section.	X			
5.	191.15(a)	30-day follow-up written reports to PHMSA (Form F7100.2) Submittal must be electronically to http://pipelineonlinereporting.phmsa.dot.gov	X			

		REPORTING RECORDS	S	U	N/A	N/C
6.	191.15(c)	Supplemental report (to 30-day follow-up)	X			
7.	191.17	Complete and submit DOT Form PHMSA F 7100-2.1 by March 15 of each calendar year for the preceding year. (NOTE: June 15, 2011 for the year 2010).	X			
8.	191.22	Each operator must obtain an OPID, validate its OPIDs, and notify PHMSA of certain events at http://portal.phmsa.dot.gov/pipeline	X			
9.	191.23	Filing the Safety Related Condition Report (SRCR)	X			
10.	191.25 49 U.S.C. 60139, Subsection (b)(2)	 Filing the SRCR within 5 days of determination, but not later than 10 days after discovery. Note: Operators of gas transmission pipelines that if the pipeline pressure exceeds maximum allowable operating pressure (MAOP) plus the build-up, owner/operator must report the exceedance to PHMSA on or before the fifth day following the date on which the exceedance occurs. The report should be titled "Gas Transmission MAOP Exceedance" and provide the following information: The name and principal address of the operator date of the report, name, job title, and business telephone number of the person submitting the report. The name, job title, and business telephone number of the person who determined the condition exists. The date the condition was discovered and the date the condition was first determined to exist. The location of the condition, with reference to the town/city/county and state or offshore site, and as appropriate, nearest street address, offshore platform, survey station number, milepost, landmark, and the name of the commodity transported or stored. The corrective action taken before the report was submitted and the planned follow-up or future corrective action, including the anticipated schedule for starting and concluding such action. ****Notes - This does not apply. This is 			X	
11.	.605(d)	not a transmission unit audit.**** Instructions to enable operation and maintenance personnel to recognize potential Safety Related Conditions	X			
12.	191.27	Offshore pipeline condition reports – filed within 60 days after the inspections ****Notes – This condition does not apply. ****			X	
13.	192.727(g)	Abandoned facilities offshore, onshore crossing commercially navigable waterways reports ****Notes – This condition does not apply for this inspection time period. ****			X	
14.	480-93-200(1)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 2 hours) for events which results in;				
15.	480-93-200(1)(a)	A fatality or personal injury requiring hospitalization; ****Notes – This condition does not apply for this inspection time period. ****			X	
16.	480-93-200(1)(b)	Damage to property of the operator and others of a combined total exceeding fifty thousand dollars; ****Notes – This condition does not apply for this inspection time period. ****			X	
17.	480-93-200(1)(c)	The evacuation of a building, or high occupancy structures or areas; ****Notes – This condition does not apply for this inspection time period. ****			Х	
18.	480-93-200(1)(d)	The unintentional ignition of gas; ****Notes – This condition does not apply for this inspection time period. ****			Х	
19. 20.	480-93-200(1)(e)	The unscheduled interruption of service furnished by any operator to twenty five or more distribution customers; ****Notes – There has been only 1 reportable incident since 2008 per the Pipeline Safety Database**** A pipeline pressure exceeding the MAOP plus ten percent or the maximum pressure	X			
	480-93-200(1)(f)	allowed by proximity considerations outlined in WAC 480-93-020; ****Notes – This condition does not apply for this inspection time period. ****			X	
21.	480-93-200(1)(g)	Is significant, in the judgment of the operator, even though it does not meet the criteria of (a) through (f) of this subsection; ****Notes – This condition does not apply for this inspection time period. ****			X	

Records Review and Field Inspection

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked

If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		REPORTING RECORDS	S	U	N/A	N/C
22.	480-93-200(2)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9146 (Within 24 hours) for;				
23.	480-93-200(2)(a)	The uncontrolled release of gas for more than two hours; ****Notes – This condition does not apply for this inspection time period. ****			X	
24.	480-93-200(2)(b)	The taking of a high pressure supply or transmission pipeline or a major distribution supply gas pipeline out of service; ***Notes – This condition does not apply for this inspection time period.****			X	
25.	480-93-200(2)(c)	A gas pipeline operating at low pressure dropping below the safe operating conditions of attached appliances and gas equipment; or ****Notes – This condition does not apply for this inspection time period. ****			X	
26.	480-93-200(2)(d)	A gas pipeline pressure exceeding the MAOP ****Notes – This condition does not apply for this inspection time period. ****			X	
27.	480-93-200(4)	Did written incident reports (within 30 days of telephonic notice) include the following				
28.	480-93-200(4)(a)	Name(s) and address(es) of any person or persons injured or killed, or whose property was damaged; ****Notes – This condition does not apply for this inspection time period. ****			X	
29.	480-93-200(4)(b)	The extent of injuries and damage; ****Notes – This condition does not apply for this inspection time period. ****			X	
30.	480-93-200(4)(c)	A description of the incident or hazardous condition including the date, time, and place, and reason why the incident occurred. If more than one reportable condition arises from a single incident, each must be included in the report;	X			
31.	480-93-200(4)(d)	A description of the gas pipeline involved in the incident or hazardous condition, the system operating pressure at that time, and the MAOP of the facilities involved;	X			
32.	480-93-200(4)(e)	The date and time the gas pipeline company was first notified of the incident;	X			
33.	480-93-200(4)(f)	The date and time the ((operators')) gas pipeline company's first responders arrived on-site;	X			
34.	480-93-200(4)(g)	The date and time the gas ((facility)) pipeline was made safe;	X			
35.	480-93-200(4)(h)	The date, time, and type of any temporary or permanent repair that was made;	X			
36.	480-93-200(4)(i)	The cost of the incident to the ((operator)) gas pipeline company;	X			
37.	480-93-200(4)(j)	Line type;	X			
38.	480-93-200(4)(k)	City and county of incident; and	X			
39.	480-93-200(4)(1)	Any other information deemed necessary by the commission.	X			
40.	480-93-200(5)	Supplemental report if required information becomes available after 30 day report submitted	X			
41.	480-93-200(6)	Written report within 5 days of receiving the failure analysis of any incident or hazardous condition due to construction defects or material failure	X			
42.	480-93-200(7)	Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form) ***Notes - Some PSE provided damage metrics for the last three years are: 2014 is 5.1 (damages) per 1000 2015 is 2.8 (damages) per 1000 2016 is 5.26 (damages) per 1000***				

		REPORTING RECORDS	S	U	N/A	N/C
43.	480-93-200(7)(a)	Does the operator report to the commission the requirements set forth in RCW 19.122.053(3) (a) through (n) ****Notes – This probable violation is addressed in the Pierce County probable violation report and the supporting files are contained in the Pierce County inspection, but this is a headquarters function that affects all inspection units across PSE.*** 1. WAC 480-93-200 Reporting requirements. (7) In the event of damage to a gas pipeline, each gas pipeline company must provide to the commission the following information using either the commission's web-based damage reporting tool or its successor, or the damage reporting form located on the commission's web site: (a) The reporting requirements set forth in RCW 19.122.053 (3)(a) through (n); RCW 19.122.053 Report of damage to underground facility. (3) Reports must be made to the commission's office of pipeline safety within forty-five days of the damage event, or sooner if required by law, using the commission's virtual private damage information reporting tool (DIRT) report form. Finding(s): Records obtained from DIRT via Commission Damage Prevention Program staff indicate that for the time period of 1/1/2016 to 3/23/2017 there were 1108 exceedances of the 45 day submission requirement out of a total of 1174 records submitted by PSE. PSE representatives indicated they were unaware of being able to change a record after the fact. Additionally, issues around excavators not maintaining paint locates took longer to research and that was the explanation for the reports taking so long to complete. PSE stated they opened a Probable Violation Incident Report (PVIR) in the		X		
44.	480-93-200(7)(b)	Compliance Department for this. Does the operator report the name, address, and phone number of the person or entity that the company has reason to believe may have caused damage due to excavations conducted without facility locates first being completed?	X			
45.	480-93-200(7)(c)	Does the operator retain all damage and damage claim records it creates related to damage events reported under 93-200(7)(b), including photographs and documentation supporting the conclusion that a facilities locate was not completed? Note: Records maintained for two years and made available to the commission upon request. ***Notes - They keep them for 3 years.****	X			
46.	480-93-200(8)	Does the operator provide the following information to excavators who damage gas pipeline facilities? ***Notes - They hand out dig books and send letters when needed***				
47.	480-93-200(8)(a)	Notification requirements for excavators under RCW 19.122.050(1)	X			
48.	480-93-200(8)(b)	A description of the excavator's responsibilities for reporting damages under RCW 19.122.053; and	X			
49.	480-93-200(8)(c)	 Information concerning the safety committee referenced under RCW 19.122.130, including committee contact information, and the process for filing a complaint with the safety committee. 	X			
50.	480-93-200(9)	Reports to the commission only when the operator or its contractor observes or becomes aware of the following activities • An excavator digs within thirty-five feet of a transmission pipeline, as defined by RCW 19.122.020(26) without first obtaining a facilities locate; (200(9)(a) • A person intentionally damages or removes marks indicating the location or presence of gas pipeline facilities. 200(9)(b) ***Notes – No instances during the last three years***			X	
51.	480-93-200(10)	Annual Reports filed with the commission no later than March 15 for the proceeding calendar year				

Records Review and Field Inspection

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked

If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		REPORTING RECORDS	S	U	N/A	N/C
52.	480-93-200(10)(a)	A copy of PHMSA F-7100.1-1 and F-7100.2-1 annual report required by U.S. Department of Transportation, PHMSA/Office of Pipeline Safety	X			
53.	480-93-200(10)(b)	Reports detailing all construction defects and material failures resulting in leakage. Categorizing the different types of construction defects and material failures. The report must include the following: (i) Types and numbers of construction defects; and (ii) Types and numbers of material failures.	X			
54.	480-93-200(11)	Providing updated emergency contact information to the commission and appropriate officials of all municipalities where gas pipeline companies have facilities	X			
55.	480-93-200(12)	Providing by email, reports of daily construction and repair activities no later than 10:00 a.m.	X			
56.	480-93-200(13)	Submitting copy of DOT Drug and Alcohol Testing MIS Data Collection Form when required	X			

Comments:		

	CUSTOMER a	and EXCESS FLOW VALVE INSTALLATION NOTIFICATION	S	U	N/A	N/C
57.	192.16	Customer notification - Customers notified, within 90 days , of their responsibility for those service lines not maintained by the operator	X			
58.	192.381	Does the excess flow valve meet the performance standards prescribed under §192.381?	X			
59.	192.383	Does the operator have an installation and reporting program for excess flow valves and does the program meet the requirements outlined in §192.383? Are records adequate?	X			

Comments:			

		CONSTRUCTION RECORDS	S	U	N/A	N/C
60.	480-93-013	OQ records for personnel performing New Construction covered tasks	X			
61.	192.225	Test Results to Qualify Welding Procedures	X			
62.	192.227	Welder Qualification	X			
63.	480-93-080(1)(b)	Appendix C Welders re-qualified 2/Yr (7.5Months)	X			
64.	480-93-080(2)	Plastic pipe joiners re-qualified 1/Yr (15 Months) ***Notes – PSE requalifies annually***	X			
65.	480-93-080(2)(b)	Plastic pipe joiners re-qualified if no production joints made during any 12 month period ***Notes – PSE requalifies annually***			X	
66.	480-93-080(2)(c)	Tracking Production Joints or Re-qualify joiners 1/Yr (12Months) ***Notes – PSE requalifies annually***			X	

		CONSTRUCTION RECORDS	S	U	N/A	N/C
67.	480-93-115(2)	Test leads on casings (without vents) installed after 9/05/1992 ***Notes – No casings installed without test leads****			X	
68.	480-93-115(3)	Sealing ends of casings or conduits on transmission lines and mains	X			
69.	480-93-115(4)	Sealing ends (nearest building wall) of casings or conduits on services ***Notes – this is observed during our design, construction, and testing, (DTC) audits throughout the year.****	X			
70.	192.241(a)	Visual Weld Inspector Training/Experience	X			
71.	192.243(b)(2)	Nondestructive Technician Qualification	X			
72.	192.243(c)	NDT procedures	X			
73.	192.243(f)	Total Number of Girth Welds	X			
74.	192.243(f)	Number of Welds Inspected by NDT	X			
75.	192.243(f)	Number of Welds Rejected	X			
76.	192.243(f)	Disposition of each Weld Rejected	X			
77.	.273/.283	Qualified Joining Procedures Including Test Results	X			
78.	192.303	Construction Specifications	X			
79.	192.325 WAC 480-93- 178(4)(5)	Underground Clearances	X			
80.	192.327	Amount, location, cover of each size of pipe installed	X			
81.	480-93-160(1)	Report filed 45 days prior to construction or replacement of transmission pipelines ≥ 100 feet in length ***Notes - No transmission construction in this unit.***			X	
82.	480-93-160(2)	Did report describe the proposed route and the specifications for the pipeline and must include, but is not limited to the following items: ***Notes - No transmission construction in this unit.***			X	
83.	480-93-160(2)(a)	Description and purpose of the proposed pipeline; ***Notes - No transmission construction in this unit.***			X	
84.	480-93-160(2)(b)	Route map showing the type of construction to be used throughout the length of the line, and delineation of class location as defined in 49 CFR Part 192.5, and incorporated boundaries along the route. ***Notes - No transmission construction in this unit.***			X	
85.	480-93-160(2)(c)	Location and specification of principal valves, regulators, and other auxiliary equipment to be installed as a part of the pipeline system to be constructed***Notes - No transmission construction in this unit.***			Х	
86.	480-93-160(2)(d)	MAOP for the gas pipeline being constructed; ***Notes - No transmission construction in this unit.***			X	
87.	480-93-160(2)(e)	Location and construction details of all river crossings or other unusual construction requirements encountered en route. ***Notes - No transmission construction in this unit.***			X	
88.	480-93-160(2)(f)	Proposed corrosion control program to be followed inc specs for coating and wrapping, and method to ensure the integrity of the coating using holiday detection equipment; ***Notes - No transmission construction in this unit.***			Х	
89.	480-93-160(2)(g)	Welding specifications; and***Notes - No transmission construction in this unit.***			X	
90.	480-93-160(2)(h)	Bending procedures to be followed if needed. ***Notes - No transmission construction in this unit.***			X	
91.	480-93-170(1)	Commission notified 2 days prior to pressure testing pipelines with an MAOP producing a hoop stress ≥ 20% SMYS? ***Notes - No transmission construction in this unit.***			X	
92.	480-93-170(7)	Pressure tests records at a minimum include required information listed under 480-93-170(a-h)	X			
93.	480-93-170(9)	Individual pressure test records maintained for single installations where multiple pressure tests were performed?	X			

Records Review and Field Inspection

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked

If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		CONSTRUCTION RECORDS	S	U	N/A	N/C
94.	480-93-170(10)	Pressure Testing Equipment checked for accuracy/intervals (Manufacturers Rec or Operators schedule) ***Notes - Checked gauges and MAOP info for Thorne Ln job for Pierce County as part of the records portion of the joint unit audit. Checked gauges for jobs 107049447 and 107047690. Gauges are routinely checked during DTC audits and during the field portions of our inspections***	X			
95.	480-93-175(2)	Study prepared and approved prior to moving and lowering of metallic pipelines > 60 psig ***Notes – This condition did not occur during this inspection time period***			X	
96.	480-93-175(4)	Leak survey within 30 days of moving or lowering pipelines ≤ 60 psig ***Notes – This condition did not occur during this inspection time period***			X	

Comments:		

		OPERATIONS and MAINTENANCE RECORDS	S	U	N/A	N/C
97.	192.517(a)	Pressure Testing (operates at or above 100 psig) – useful life of pipeline	X			
98.	192.517(b)	Pressure Testing (operates below 100 psig, service lines, plastic lines) – 5 years	X			
99.	192.605(a)	Procedural Manual Review – Operations and Maintenance (1 per yr/15 months) Note: Including review of OQ procedures as <u>suggested</u> by PHMSA - ADB-09-03 dated 2/7/09	X			
100.	192.605(b)(3)	Availability of construction records, maps, operating history to operating personnel	X			
101.	480-93-018(3)	Records, including maps and drawings updated within 6 months of completion of construction activity? ****Notes – The 21 construction job samples were reviewed for mapping updates and all met the time frame****	X			
102.	192.605(b)(8)	Periodic review of personnel work – effectiveness of normal O&M procedures	X			
103.	192.605(c)(4)	Periodic review of personnel work – effectiveness of abnormal operation procedures	X			
104.	192.609	Class Location Study (If applicable) ***Notes – This is a distribution inspection. This condition does not apply***			X	
105.	192.611	Confirmation or revision of MAOP	X			
106.		Damage Prevention (Operator Internal Performance Measures)				
107.	192.614	Does the operator have a quality assurance program in place for monitoring the locating and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices, Best Practice 4-18. Recommended only, not required) ****Notes – ELM is the vendor used for locates in this unit. ELM uses the 1 in 1000 criteria. They are going to start using metrics at 1:2000. Last year's metric was .52 or 80861 and 31 at fault damages. PSE performs locate damage investigations. Each month they get a report from ELM that discusses at fault or not at fault. The operator does not conduct field audits in Contract Management, but Quality Management may monitor the locating contract in the future. There are currently no PSE staff field monitoring locates as they are being performed in the field.******	x			

	OPERATIONS and MAINTENANCE RECORDS	S	U	N/A	N/C
108.	Does operator including performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties? Notes – The operator did not provide incentives in the past, but now they are setting action thresholds to allow tracking so contract management can implement incentives and penalties. In the past the incentive was simply contractor retention.	X			
109.	Do locate contractors address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing	X			
110.	levels? Does the operator periodically review the Operator Qualification plan criteria and				
110.	methods used to qualify personnel to perform locates? ***Notes - OQ records recently were reviewed***	X			
111.	Review operator locating and excavation <u>procedures</u> for compliance with state law and regulations.	X			
112.	Are locates are being made within the timeframes required by state law and regulations? Examine record sample. ***Notes - 6/5/2014, 2015 and 2016 days - aka "Extended Tickets")*** (Staff reviewed tickets still open beyond two days - aka "Extended Tickets")***	X			
113.	Are locating and excavating personnel properly <u>qualified</u> in accordance with the operator's Operator Qualification plan and with federal and state requirements? ****Notes - Quality Management reviewed this in 1/13/17 is when they received the report. The audit was completed 12/19/16.****	X			
114.	Follow-up inspection performed on the pipeline where there is reason to believe the pipeline could be damaged .614(c) (6) 1. Is the inspection the done as frequently as necessary during and after the activities to verify the integrity of the pipeline? 2. In the case of blasting, does the inspection include leakage surveys?	X			

Comments:		

115.		Emergency Response Plans	S	U	N/A	N/C
116.	192.603(b)	Prompt and effective response to each type of emergency .615(a)(3) Note: Review operator records of previous accidents and failures including third-party damage and leak response	X			
117.	192.615(b)(1)	Location Specific Emergency Plan	X			
118.	192.615(b)(2)	Emergency Procedure training, verify effectiveness of training. ***Notes – This is done on a two year cycle***	X			
119.	192.615(b)(3)	Employee Emergency activity review, determine if procedures were followed.	X			
120.	192.615(c)	Liaison Program with Public Officials	X			
121.	192.616	Public Awareness Program				

,		_		1	ı	1	,
122.	192.616(e&f)	and content, delivery method and frequency evaluations, etc. (i.e. contact or mailing ros audience contact documentation, etc. for er superintendents, program evaluations, etc.)	older Audience identification, message type y, supplemental enhancements, program sters, postage receipts, return receipts, mergency responder, public officials, school See table below:	X			
123.		Operators in existence on June 20, 2005, m later than June 20, 2006. See 192.616(a) an	aust have completed their written programs no ad (j) for exceptions.				
124.		API RP 1162 Baseline* Rec	ommended Message Deliveries				
125.		Stakeholder Audience (LDC's)	Baseline Message Frequency (starting from effective date of Plan)				
		Residence Along Local Distribution System	Annual				
		LDC Customers	Twice annually				
		One-Call Centers	As required of One-Call Center				
		Emergency Officials	Annual				
		Public Officials	3 years				
		Excavator and Contractors	Annual				
		Stakeholder Audience (Transmission	Baseline Message Frequency				
		line operators)	(starting from effective date of Plan)				
		Residence Along Local Distribution System	2 years				
		One-Call Centers	As required of One-Call Center				
		Emergency Officials	Annual				
		Public Officials	3 years				
		Excavator and Contractors	Annual				
126.		* Refer to API RP 1162 for additional requ recommendations, supplemental requireme	irements, including general program nts, recordkeeping, program evaluation, etc.				
127.	192.616(g)	significant number of the population in the	other languages commonly understood by a operator's area. ***Notes - The operator to check the predominant languages used a scratch and sniff cards in 11	X			
128.	.616(h)	IAW API RP 1162, the operator's program four years of the date the operator's program existence on June 20, 2005, who must have than June 20, 2006, the first evaluation is d	e completed their written programs no later	X			
129.	192.616(j)	Operators of a Master Meter or petroleum stimes annually: (1) A description of the purpose and (2) An overview of the hazards of th (3) Information about damage preveit (4) How to recognize and respond to (5) How to get additional information system***	reliability of the pipeline; e pipeline and prevention measures used; ntion; a leak; and			X	
130.	192.617	·		X			

Comments:		

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

#122-#127 The operator has mailers that are customized to the system. I reviewed public notice content for LDC transmission residents and fire/police response employees near transmission pipelines in other units as examples. The operator sends bill stuffers. For paperless billing, the operator is using hyperlinks to direct the customer to the correct web site.

131.	192.619/621/623	Maximum Allowable Operating Pressure (MAOP) Note: New PA-11 design criteria is incorporated into 192.121 & .123 (Final Rule Pub. 12/24/08)	X		
132.	480-93-015(1)	Odorization of Gas – Concentrations adequate ***Notes – The operator uses .8% Gas/Air as the high level for detecting properly odorized gas given the current gas chemistry/supply to meet the 1/5 th of the LEL detection criteria.***	Х		
133.	480-93-015(2)	Monthly Odorant Sniff Testing	X		
134.	480-93-015(3)	Prompt action taken to investigate and remediate odorant concentrations not meeting the minimum requirements ****Notes – This condition did not exist in this unit for this inspection time period (2014-1st qtr 2017)****		Х	
135.	480-93-015(4)	Odorant Testing Equipment Calibration/Intervals (Annually or Manufacturers Recommendation)	X		
136.	480-93-124(3)	Pipeline markers attached to bridges or other spans inspected? 1/yr(15 months) ***Notes - 10 actual sites slightly exceeding the deadline out of 2567 total sites for all three units inspected this year. PSE had comments detailing justification for the delayed inspections that were deemed adequate at the time of this inspection***	Х		
137.	480-93-124(4)	Markers reported missing or damaged replaced within 45 days?	X		
138.	480-93-140(2)	Service regulators and associated safety devices tested during initial turn-on. ***Notes- This is done with a manometer when a meter is set during turn-on. ***	Х		
139.	480-93-155(1)	Up-rating of system MAOP to >60 psig? Procedures and specifications submitted 45 days prior?	X		
140.	480-93-185(1)	Reported gas leaks promptly investigated? Graded in accordance with 480-93-186? Records retained?	X		
141.	480-93-185(3)(a)	Leaks originating from a foreign source. Take appropriate action to protect life and property regarding the pipeline company's own facilities, and;	X		
142.	480-93-185(3)(b)	Leaks originating from a foreign source reported promptly/notification by mail. Records retained?	X		
143.	480-93-186(3)	Leak evaluations: Are follow-up inspections performed within 30 days of a leak repair? ***Notes – I reviewed randomly selection leak evaluations that included all three units inspected this year and the sites requiring a 30 day follow-up met the time allowance for follow-up.***0	х		
144.	480-93-186(4)	Leak evaluations: Grade 1 and 2 leaks (if any), downgraded once to a grade 3 without physical repair?	X		
145.	480-93-187	Gas leak records: at a minimum include required information listed under 480-93-187(1-13)	X		
146.	480-93-188(1)	Gas leak surveys	X		
147.	480-93-188(2)	Gas detection instruments tested for accuracy/intervals (Mfct recommended or monthly not to exceed 45 days) ***Notes - GFR GMI Units were reviewed during the combined 3 unit records portion during this inspection containing records from Thurston/Lewis, Kittitas, and Pierce Counties*** 6/18/2014 GDI 611212 Calibrated 5/30/2014 - OK 4/8/2016 GDI 611135 Calibrated 4/7/2016 - OK 5/17/2016 GDI 611188 Calibrated 5/12/2016 - OK***	х		

148.			Leak survey frequency (Refer to Table	Below)				
			that were missed. The locations review this inspection. The leak survey maps appear to have exceeded the required the district. A number of plat maps were randomly and Thurston/Lewis service areas to reinspection. Of 69 maps selected, 29 instiminimum required inspection frequence.	y selected from the Pierce County, Kittitas, eview leak survey records for during this tances of leak surveys exceeding the cies for business districts were identified.				
			Q214057 Q26	0060				
	480-93	3-188(3)		3063		X		
		(- /		3068				
				66233				
				7074				
			Q238047 Q26	9016				
			Q248055 Q26	9023				
			Q249063 Q27	5014				
			Q251055 Q31	1008				
				4011				
				8011				
				.0009				
				5013				
				2021				
			Q260050					<u> </u>
		Busin	ness Districts (implement by 6/02/07)	1/yr (15 months)				
			High Occupancy Structures	1/yr (15 months)				
			Pipelines Operating ≥ 250 psig	1/yr (15 months)				
		Other N	Mains: CI, WI, copper, unprotected steel	2/yr (7.5 months)				
			1		I I			
149.	480-93-	188(4)(a)	repairs ***Those responsible for coor being notified from the Master Contro Liaison Managers (MLMs). There wer demonstrated that PSE had any record	resurfacing, following street alterations or edinating and scheduling leak surveys are not al Planners (MCPs) and the Municipal re no records available or provided that als of special leak surveys being performed for reet expansions, alterations, or repairs.***	X			
150.	480-93-	188(4)(b)		ould have occurred ***Notes – There were no damage has occurred during the combined 3 etion containing records from			X	
151.	480-93-	188(4)(c)	Special leak surveys - Unstable soil areas	s where active gas lines could be affected			X	
150	700-23-	100(7)(0)	***Notes – This condition did not occu				Λ	
152.	480-93-	188(4)(d)		of unusual activity, such as earthquake, floods, dition did not occur for this inspection time			X	

153.		Special leak surveys - A	fter third-party excavation damage to services,	onerators must			
100.	490 02 199(4)(-)		ey to eliminate the possibility of multiple leaks		v		
	480-93-188(4)(e)	migration into nearby bu	nildings. ***Notes – I reviewed some specia		X		
			lamaged by third-party excavation.***				
154.	480-93-188(5)	Gas Survey Records (M under 480-93-188 (5) (a	in 5 yrs) and at a minimum include required i -f)	nformation listed	X		
155.	480-93-188(6)	Leak program - Self Au	dits		X		
156.	192.709	Patrolling (Transmission transmission inspection	n Lines) (Refer to Table Below) .705 *** Not n***	tes – Not a		X	
			-		1		
		Class Location	At Highway and Railroad Crossings	At All Other I	Places		
		1 and 2	2/yr (7½ months)	1/yr (15 mon	ths)		
		3	4/yr (4½ months)	2/yr (7½ moi			
		4	4/yr (4½ months)	4/yr (4½ moi	nths)		
157.	192.709	Leak Surveys (Transn	nission Lines) (Refer to Table Below) .706** transmission inspection***	**Notes – Not a		X	
		Class Location	Required	Not Excee	ed		
		1 and 2	1/yr	15 month	ıs		
		3	2/yr	7½ month	ıs		
		4	4/yr	4½ month	ıs		
158.	192.603(b)	Patrolling Business Dist	rict (4 per yr/4 ½ months) .721(b)(1)		X		Ī
159.	192.603(b)		ness District (2 per yr/7½ months) 192.721(b))(2)	X		
160.	192.603(b)	_	de Business District (5 years) 192 .723(b)(1)		X		
161.		Leakage Survey 192.723	3(b)(2)				
	192.603(b)		ess District (5 years)		X		
			inprotected distribution lines (3 years)				
162.	192.603(b)	Tests for Reinstating Se	rvice Lines 192.725		X		
163.	192.603(b)/.727(g)	Abandoned Pipelines; U inspection unit***	Inderwater Facility Reports 192.727***Notes	– None in this		X	
164.	192.709		egulating Stations (1 per yr/15 months) .739 s were looked at and all stations met the req		X		
165.	192.709		egulator Stations – Capacity (1 per yr/15 mon				
			Kittitas capacity review for RS-2560. The		X		
			RS-2549, RS-2726 I reviewed the records of S-2560 for 2014, 2015, 2016.****	tne annuai			
166.	192.709	Valve Maintenance – Tr	ransmission (1 per yr/15 months) .745 ***	Notes – This is		X	
167.	192.709	Valve Maintenance – D		Notes- We looked			
1071	1,2.,,0,		e valves, emergency section valves for the las		X		
168.	480-93-100(3)	Service valve maintenar	ace (1 per yr/15 months) ***Notes - We look	ed at HOS valves			
		*	last three years and 8147 and 4 short exceed	ances were	X		
169.	192.709	Nault maintenance (>20	esolved)**** 0 cubic feet)(1 per yr/15 months) .749 ***	Notes - No			+
107.	192.709	vaults that meet this vo		Notes – No		X	
170.	192. 603(b)		l Ignition (hot work permits) .751 ***Notes	– No hot work		X	
171.	192. 603(b)	Welding – Procedure 19			X		+
172.	192. 603(b)	Welding – Welder Qual			X		+
173.	192. 603(b)	,	Qualification .243(b)(2)**		_		+
1/3.	192. 003(D)	NDI – NDI Personnel	Quaimeation .245(0)(2)***		X		

174.	192.709	NDT Records (pipeline life) .243(f) ***Notes – This is covered in the transmission inspection. PSE elects to NDT some jobs as required by their operating procedures that exceed the requirements of NDT testing of a pipeline not at the %SMYS required for NDT testing under the CFR.***		X	
175.	192.709	Repair: pipe (pipeline life); Other than pipe (5 years)	X		
176.	192.905(c)	Periodically examining their transmission line routes for the appearance of newly identified area's (HCA's) ***Notes - This is covered in the transmission inspection.***		X	

Com	nments:			

		CORROSION CONTROL RECORDS	S	U	N/A	N/C
177.	192.455(a)(1)	Pipeline coatings meet requirements of 192.461 (for buried pipelines installed after 7/31/71)	X			
178.	192.455(a)(2)	CP system installed on and operating within 1 yr of completion of pipeline construction (after 7/31/71)	X			
179.	192.465(a)	Annual Pipe-to-soil Monitoring (1 per yr/15 months) for short sections (10% per year; all in 10 years)	X			
180.	192.491	Test Lead Maintenance .471	X			
181.	192.491	Maps or Records .491(a)	X			
182.	192.491	Examination of Buried Pipe when exposed .459	X			
183.	480-93-110(8)	CP test reading on all exposed facilities where coating has been removed	X			
184.	192.491	Annual Pipe-to-soil monitoring (1 per yr/15 months) .465(a)	X			
185.	192.491	Rectifier Monitoring (6 per yr/2½ months) .465(b)	X			
186.	192.491	Interference Bond Monitoring – Critical (6 per yr/2½ months) .465(c) ***Notes – None identified for Pierce, Thurston/Lewis, or Kittitas this inspection cycle.***			X	
187.	192.491	Interference Bond Monitoring – Non-critical (1 per yr/15 months) .465(c) ***Notes – None identified for Pierce, Thurston/Lewis, or Kittitas this inspection cycle.***			X	
188.	480-93-110(2)	Remedial action taken within 90 days (Up to 30 additional days if other circumstances. Must document) .465(d)	X			
189.	480-93-110(3)	CP equipment/ instrumentation maintained, tested for accuracy, calibrated, and operated in accordance with manufactures recommendations, or at appropriate schedule determined by gas company if no recommendation.	X			
190.	192.491	Unprotected Pipeline Surveys, CP active corrosion areas (1 per 3 cal yr/39 months) .465(e) ***Notes – No active corrosion areas***			X	
191.	192.491	Electrical Isolation (Including Casings) .467	X			
192.	480-93-110(5)	Casings inspected/tested annually not to exceed fifteen months	X			
193.	480-93-110(5)(a)	Casings w/no test leads installed prior to 9/05/1992. Demonstrate other acceptable test methods ***Notes – None found in this unit***			X	
194.	480-93-110(5)(b)	Possible shorted conditions – Perform confirmatory follow-up inspection within 90 days ***Notes – No noted shorted casings from records review or field observation***			Х	
195.	480-93-110(5)(c)	Casing shorts cleared when practical ***Notes – No noted shorted casings from records review or field observation***			X	
196.	480-93-110(5)(d)	Shorted conditions leak surveyed within 90 days of discovery. Twice annually/7.5 months ***Notes - No noted shorted casings from records review or field observation***			X	

Records Review and Field Inspection

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked

If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		CORROSION CONTROL RECORDS	S	U	N/A	N/C
197.	192.491	Interference Currents .473 ***Notes – The operator was asked about interference currents and the operator said they have not experienced any stray AC (or DC) that has impacted their CP system in the Pierce County unit. ***			X	
198.	192.491	Internal Corrosion; Corrosive Gas Investigation .475(a) ***Notes – No corrosive gas found in this unit. No digesters or other biogas sources are active or planned in this unit that would be a gas source.***			X	
199.	192.491	Internal Corrosion; Internal Surface Inspection; Pipe Replacement .475(b) ***Notes - This is done as part of the EPCRs during service or main replacement.***	X			
200.	192.491	Internal Corrosion Control Coupon Monitoring (2 per yr/7½ months) .477 ***Notes – No internal coupons***			X	
201.	192.491	Atmospheric Corrosion Control Monitoring (1 per 3 cal yr/39 months onshore; 1 per yr/15 months offshore) .481	X			
202.	192.491	Remedial: Replaced or Repaired Pipe; coated and protected; corrosion evaluation and actions .483/.485	X			

Comments:			

		PIPELINE INSPECTION (Field)	S	U	N/A	N/C
203.	192.161	Supports and anchors	X			
204.	480-93-080(1)(d)	Welding procedures located on site where welding is performed? ***Notes – Did not observe construction being performed during the field portion of this inspection***				X
205.	480-93-080(1)(b)	Use of testing equipment to record and document essential variables ***Notes – Did not observe construction being performed during the field portion of this inspection***				X
206.	480-93-080(2)(a)	Plastic procedures located on site where welding is performed? ***Notes – Did not observe construction being performed during the field portion of this inspection***				X
207.	480-93-080(3)	Identification and qualification cards/certificates w/name of welder/joiner, their qualifications, date of qualification and operator whose qualification procedures were followed.	X			
208.	480-93-013	Personnel performing "New Construction" covered tasks OQ qualified?	X			
209.	480-93-015(1)	Odorization	X			
210.	480-93-018(3)	Updated records, inc maps and drawings made available to appropriate operations personnel?	X			
211.	192.179	Valve Protection from Tampering or Damage	X			
212.	192.455	Pipeline coatings meet requirements of 192.461 (for buried pipelines installed after 7/31/71)	X			
213.	192.463	Levels of cathodic protection	X			
214.	192.465	Rectifiers	X			
215.	192.467	CP - Electrical Isolation	X			
216.	192.476	Systems designed to reduce internal corrosion	X			
217.	192.479	Pipeline Components exposed to the atmosphere	X			
218.	192.481	Atmospheric Corrosion: monitoring	X			
219.	192.491	Test Stations – Sufficient Number .469	X			
220.	480-93-115(2)	Casings – Test Leads (casings w/o vents installed after 9/05/1992)	X			
221.	480-93-115(2)	Mains or transmission lines installed in casings/conduit. Are casing ends sealed?	X			
222.	480-93-115(4)	Service lines installed in casings/conduit. Are casing ends nearest to building walls sealed?	X			

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		PIPELINE INSPECTION (Field)	S	U	N/A	N/C
223.	192.605(a)	Appropriate parts of manuals kept at locations where O&M activities are conducted	X			
224.	192.605	Knowledge of Operating Personnel	X			
225.	480-93-124	Pipeline markers	X			
226.	480-93-124(4)	Markers reported missing or damaged replaced within 45 days?	X			
227.	192.719	Pre-pressure Tested Pipe (Markings and Inventory)	X			
228.	192.195	Overpressure protection designed and installed where required?	X			
229.	192.739/743	Pressure Limiting and Regulating Devices (Mechanical/Capacities)	X			
230.	192.741	Telemetering, Recording Gauges	X			
231.	192.751	Warning Signs	X			
232.	192.355	Customer meters and regulators. Protection from damage	X			
233.	192.355(c)	Pits and vaults: Able to support vehicular traffic where anticipated.	X			
234.	480-93-140	Service regulators installed, operated and maintained per state/fed regs and manufacturers recommended practices?	X			
235.	480-93-178(2)	Plastic Pipe Storage facilities – Maximum Exposure to Ultraviolet Light (2yrs)	X			
236.	480-93-178(4)	Minimum Clearances from other utilities. For parallel lines a minimum of twelve inches. Where a minimum twelve inches of separation is not possible, must take adequate precautions, such as inserting the plastic pipeline in conduit, to minimize any potential hazards.	X			
237.	480-93-178(5)	Minimum Clearances from other utilities. For perpendicular lines a minimum of six inches of separation from the other utilities. Where a minimum six inches of separation is not possible, must take adequate precautions, such as inserting the plastic pipeline in conduit, to minimize any potential hazards	X			
238.	480-93-178(6)	Are there Temporary above ground PE pipe installations currently? Yes No X				
239.	480-93-178(6)(a)	If yes, is facility monitored and protected from potential damage? ***Notes – No facilities installed***			X	
240.	480-93-178(6)(b)	If installation exceeded 30 days, was commission staff notified prior to exceeding the deadline? ***Notes – No facilities installed***			X	
241.	192.745	Valve Maintenance (Transmission) ***Notes – This is a separate unit – transmission is looked at during the transmission audit***			X	
242.	192.747	Valve Maintenance (Distribution)	X			

Facility Sites Visited:

Facility Type	Facility ID Number	Location		
Please see field notes for site documentation	Please see field notes for site documentation	Please see field notes for site documentation		

Comments:

After the field portion of the inspection was completed PSE went out and performed additional testing to ensure they had adequate protection.

PSE's Cathodic Protection SMEs confirmed that all of the test sites found with low reads during the field audit had a differential greater than 100mV when tested using the 100mV shift criteria. There was a casing that was shorted and it was added to the semi-annual leak survey.

Per PSE, Soundview Dr NW & Hollycroft St NW achieved >100mV depol on 06/07/2017 (-642mV depol read of -514mV). The Johnston Test shows pipe is shorted to casing. Leak survey CS-00049 created and scheduled for July 2017.

138 St E & 38 Ave E site appears shorted but recently proved short is at wires. Job scheduled to repair prior to HP uprate. Casing found to be "shorted" on 6/20/2012 per G1 1465826. Casing was put on special leak survey 07/27/2012 (defined as CS-00027 since

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Comments	,
----------	---

2015). Notification 11046333/order 874017213 scheduled for 08/07/2017 for repairs per the PM.

Recent Gas Pipeline Safety Advisory Bulletins: (Last 2 years)

<u>Number</u>	<u>Date</u>	<u>Subject</u>
ADB-2013-07	July 12, 13	Potential for Damage to Pipeline Facilities Caused by Flooding
ADB-2012-10	Dec 5, 12	Using Meaningful Metrics in Conducting Integrity Management Program Evaluations
ADB-2012-09	Oct 11, 12	Communication During Emergency Situations
ADB-2012-08	Jul 31, 12	Inspection and Protection of Pipeline Facilities After Railway Accidents
ADB-12-07	Jun 11, 12	Mechanical Fitting Failure Reports
ADB-12-06	May 7, 12	Verification of Records establishing MAOP and MOP
ADB-12-05	Mar 23, 12	Cast Iron Pipe (Supplementary Advisory Bulletin)
ADB -12-04	Mar 21, 12	Implementation of the National Registry of Pipeline and Liquefied Natural Gas Operators
ADB-12-03	Mar 6, 12	Notice to Operators of Driscopipe 8000 High Density Polyethylene Pipe of the Potential for Material Degradation
ADB-11-05	Sep 1, 11	Potential for Damage to Pipeline Facilities Caused by the Passage of Hurricanes

For more PHMSA Advisory Bulletins, go to http://phmsa.dot.gov/pipeline/regs/advisory-bulletin

Attachment 1

 $\begin{array}{c} \textbf{Distribution Operator Compressor Station Inspection} \\ \textbf{Unless otherwise noted, all code references are to 49CFR Part 192.} & S-Satisfactory & U-Unsatisfactory & N/A-Not Applicable \\ \textbf{If an item is marked U, N/A, or N/C, an explanation must be included in this report.} \end{array}$

N/C - Not Checked

243.	.605(b)	COMPRESSOR STATION PROCEDURES	S	U	N/A	N/C
244.		.605(b)(6) Maintenance procedures, including provisions for isolating units or sections of pipe and for purging before returning to service			X	
245.]	.605(b)(7) Starting, operating, and shutdown procedures for gas compressor units			X	
246.		.731 Inspection and testing procedures for remote control shutdowns and pressure relieving devices (1 per yr/15 months), prompt repair or replacement			X	
247.		.735 (a) Storage of excess flammable or combustible materials at a safe distance from the compressor buildings			X	
248.		(b) Tank must be protected according to NFPA #30			X	
249.		.736 Compressor buildings in a compressor station must have fixed gas detection and alarm systems (must be performance tested), unless:			X	
250.		• 50% of the upright side areas are permanently open, or			X	
251.		It is an unattended field compressor station of 1000 hp or less			X	

Comments:

#243-251 No Compressors in this unit.

COMPRESSOR STATION O&M PERFORMANCE AND RECORDS			S	U	N/A	N/C	
252.	.709	.731(a)	Compressor Station Relief Devices (1 per yr/15 months)			X	
253.		.731(c)	Compressor Station Emergency Shutdown (1 per yr/15 months)			X	
254.		.736(c)	Compressor Stations – Detection and Alarms (Performance Test)			X	

Comments:		
#252-254 No	Compressors in	thic unit

			COMPRESSOR STATIONS INSPECTION (Field) (Note: Facilities may be "Grandfathered")	S	U	N/A	N/C
255.	.163	(c)	Main operating floor must have (at least) two (2) separate and unobstructed exits			X	
256.			Door latch must open from inside without a key			X	
257.			Doors must swing outward			X	
258.		(d)	Each fence around a compressor station must have (at least) 2 gates or other facilities for emergency exit			X	
259.			Each gate located within 200 ft of any compressor plant building must open outward			X	
260.			When occupied, the door must be opened from the inside without a key			X	
261.		(e)	Does the equipment and wiring within compressor stations conform to the National Electric Code , ANSI/NFPA 70?			X	
262.	.165	(a)	If applicable, are there liquid separator(s) on the intake to the compressors?			X	
263.		(b)	Do the liquid separators have a manual means of removing liquids?			X	

Attachment 1

 $\begin{array}{c} \textbf{Distribution Operator Compressor Station Inspection} \\ \textbf{Unless otherwise noted, all code references are to 49CFR Part 192.} & S-Satisfactory & U-Unsatisfactory & N/A-Not Applicable \\ \textbf{If an item is marked U, N/A, or N/C, an explanation must be included in this report.} \end{array}$

N/C - Not Checked

			COMPRESSOR STATIONS INSPECTION (Field)	S	U	N/A	N/C
			(Note: Facilities may be "Grandfathered")	3		IN/A	N/C
264.			If slugs of liquid could be carried into the compressors, are there automatic dumps on the separators, Automatic compressor shutdown devices, or high liquid level alarms?			X	
265.	.167	(a)	ESD system must:				
266.			- Discharge blowdown gas to a safe location			X	
267.			- Block and blow down the gas in the station			X	
268.			- Shut down gas compressing equipment, gas fires, electrical facilities in compressor building and near gas headers			X	
269.			- Maintain necessary electrical circuits for emergency lighting and circuits needed to protect equipment from damage			X	
270.			ESD system must be operable from at least two locations, each of which is:				
271.	.167		- Outside the gas area of the station			X	
272.			- Not more than 500 feet from the limits of the station			X	
273.			- ESD switches near emergency exits?			X	
274.		(b)	For stations supplying gas directly to distribution systems, is the ESD system configured so that the LDC will not be shut down if the ESD is activated?			X	
275.		(c)	Are ESDs on platforms designed to actuate automatically by				
276.			- For unattended compressor stations, when:				
277.			 The gas pressure equals MAOP plus 15%? 			X	
278.			 An uncontrolled fire occurs on the platform? 			X	
279.			- For compressor station in a building, when				
280.			An uncontrolled fire occurs in the building?			X	
281.			 Gas in air reaches 50% or more of LEL in a building with a source of ignition (facility conforming to NEC Class 1, Group D is not a source of ignition)? 			X	
282.	.171	(a)	Does the compressor station have adequate fire protection facilities? If fire pumps are used, they must not be affected by the ESD system.			X	
283.		(b)	Do the compressor station prime movers (other than electrical movers) have over-speed shutdown?			X	
284.		(c)	Do the compressor units alarm or shutdown in the event of inadequate cooling or lubrication of the unit(s)?			X	
285.		(d)	Are the gas compressor units equipped to automatically stop fuel flow and vent the engine if the engine is stopped for any reason?			X	
286.		(e)	Are the mufflers equipped with vents to vent any trapped gas?			X	
287.	.173		Is each compressor station building adequately ventilated?			X	
288.	.457		Is all buried piping cathodically protected?			X	
289.	.481		Atmospheric corrosion of aboveground facilities			X	
290.	.603		Does the operator have procedures for the start-up and shut-down of the station and/or compressor units?			X	
291.			Are facility maps current/up-to-date?			X	
292.	.615		Emergency Plan for the station on site?			X	
293.	.619		Review pressure recording charts and/or SCADA			X	
294.	.707		Markers			X	
295.	.731		Overpressure protection – relief's or shutdowns			X	
296.	.735		Are combustible materials in quantities exceeding normal daily usage, stored a safe distance from the compressor building?			X	
297.			Is aboveground oil or gasoline storage tanks protected in accordance with NFPA standard No. 30?			X	

Attachment 1

 $\begin{array}{c} \textbf{Distribution Operator Compressor Station Inspection} \\ \textbf{Unless otherwise noted, all code references are to 49CFR Part 192.} & S-Satisfactory & U-Unsatisfactory & N/A-Not Applicable \\ \textbf{If an item is marked U, N/A, or N/C, an explanation must be included in this report.} \end{array}$

N/C - Not Checked

	COMPRESSOR STATIONS INSPECTION (Field) (Note: Facilities may be "Grandfathered")			U	N/A	N/C
298.	.736	Gas detection – location			X	

Comments: #255-298 No Compressors in this unit.		