

Inspection Output (IOR)

Generated on 2021.August.09 15:24

Inspection Information

Inspection Name	8290 PSE Snohomish Standard Comprehensive	Operator(s)	PUGET SOUND ENERGY (22189) Lead Darren Tinnerstet	Plan Submitted	05/05/2021
Status	PLANNED	Observer(s)	Scott Rukke, David Cullom, Dennis Ritter, Lex Vinsel, Anthony Dorough, Derek Norwood, Scott Anderson	Plan Approval	05/06/2021 by Joe Subsits
Start Year	2021	Supervisor	Joe Subsits	All Activity Start	07/12/2021
System Type	GD	Director	Sean Mayo	All Activity End	--
Protocol Set ID	WA.GD.2020.02			Inspection Submitted	--
				Inspection Approval	--

Inspection Summary

Inspection Scope and Summary

This is a PSE Unit inspection for the Snohomish County District (WUTC Inspection #8290)

Records are physically located in the Georgetown office but were reviewed virtually.

There were no issues noted with this inspection.

Facilities visited and Total AFOD

Pre-audit field : 5/18/21 to 5/20/2021 = 3 AFOD days

Virtual records and field : 7/12/21 to 7/15/21 (records); 8/3/21 to 8/5/21 (field) = 7 AFOD days (exit interview was conducted on 8/5/21)

Summary of Significant Findings

(DO NOT Discuss Enforcement options)

No issues noted

Primary Operator contacts and/or participant

Danielle Troupe

Senior Regulatory Compliance Analyst - Gas Pipeline Safety

Puget Sound Energy

Office: 425-456-2526

Cell: 425-941-1460

Operator executive contact and mailing address for any official correspondence

Booga K. Gilbertson
Senior VP of Operations

355 110th Ave. NE, M/S EST 11W

Bellevue, WA 98004

Scope (Assets)

#	Short Label	Long Label	Asset Type	Asset IDs	Excluded Topics	Planned	Required	Inspected	Total	Required % Complete
1.	90870 (1642)	Puget Sound Energy-SNOHOMISH	unit	90870	--	146	146	146	146	100.0%

1. Percent completion excludes unanswered questions planned as "always observe".

Plans

#	Plan Assets	Focus Directives	Involved Groups/Subgroups	Qst Type(s)	Extent Notes
1.	90870 (1642)	Baseline Records (Form 2), Field Inspection (Form 2)	PRO, PRR, FR, GDIM, MMLPGIM, MISCTOPICS, GENERIC	P, R, O, S	Detail

Plan Implementations

Activity #	Name	SMAR T Act#	Start Date	End Date	Focus Directives	Involved Groups/Subgroups	Asset s	Qst Type(s)	Planned	Required	Inspected	Total	Required % Complete
1	PSE Snohomish	--	07/12/2021	07/12/2021	n/a	all planned questions	all assets	all types	146	146	146	146	100.0%

1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table.
2. Percent completion excludes unanswered questions planned as "always observe".

Forms

No.	Entity	Form Name	Status	Date Completed	Activity Name	Asset
1.	Attendance List	PSE Snohomish	STARTED	--	PSE Snohomish	90870 (1642)

Results (all values, 146 results)

151 (instead of 146) results are listed due to re-presentation of questions in more than one sub-group.

PRR.REPORT: Reporting

1. Question Result, ID, References **Sat, RPT.RR.IMMEDREPORT.R, 191.5(a) (191.7(a), 191.7(d))**
 Question Text *Do records indicate immediate notifications of incidents were made in accordance with 191.5?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed incident notification records for 2018-2020. 18 total state reportable incidents and zero federal.**

2. Question Result, ID, References **NA, RPT.RR.INCIDENTREPORT.R, 191.9(a)**
 Question Text *Do records indicate reportable incidents were identified and reports were submitted to DOT on Form 7100.1 within the required time frame?*
 Assets Covered **90870 (1642)**
 Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

3. Question Result, ID, References **NA, RPT.RR.INCIDENTREPORTSUPP.R, 191.9(b)**
 Question Text *Do records indicate accurate supplemental incident reports were filed and within the required timeframe?*
 Assets Covered **90870 (1642)**
 Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

4. Question Result, ID, References **Sat, RPT.RR.ANNUALREPORT.R, 191.11(a)**
 Question Text *Have complete and accurate Annual Reports been submitted?*
 Assets Covered **90870 (1642)**
 Result Notes **2020 submitted 3/12/2021**

2019 submitted 3/12/2020

2018 submitted 3/14/2019

5. Question Result, ID, References **Sat, RPT.RR.UTCANNUALREPORTS.R,**
 Question Text *Have complete and accurate annual reports been submitted to the commission?*
 Assets Covered **90870 (1642)**
 Result Notes **2020 submitted 3/15/2021**

2019 submitted 3/13/2020

2018 submitted 3/14/02019

6. Question Result, ID, References **Sat, RPT.RR.MISDATAREPORTS.R,**
 Question Text *Has the operator submitted a copy of DOT Drug and Alcohol Testing MIS Data Collection Form to the commission when required?*
 Assets Covered **90870 (1642)**
 Result Notes **2018 submitted 3/6/2019**

2019 submitted 3/6/2020

2020 submitted 3/9/2021

7. Question Result, ID, References **Sat, GDIM.RR.MECHANICALFITTINGDATAIMPL.R, 192.1009 (191.12)** (also presented in: GDIM.IMPL)
 Question Text *Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed mechanical failure reports for 2018-2020. There were 10 failures submitted for audit period from Snohomish County. No trends or outstanding areas of concern.**

8. Question Result, ID, References **Sat, RPT.RR.SRCR.R, 191.23(a) (191.23(b), 191.25(a), 191.25(c))**
 Question Text *Do records indicate safety-related condition reports were filed as required?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed 4/30/2018 Lynnwood MAOP exceedance. Only one SRC for audit period.**
9. Question Result, ID, References **NA, RPT.RR.MAOPINCREASENOTIFY.R,**
 Question Text *Do records indicate submittal of a written plan of procedures to the commission at least forty-five days before uprating to a MAOP greater than 60 psig?*
 Assets Covered **90870 (1642)**
 Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**
10. Question Result, ID, References **Sat, RPT.RR.THIRTYDAYRPT.R,**
 Question Text *Has the operator submitted a written report within 30 days following each reportable incident?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed 18 state reportable incidents. All 30 day reports were submitted within timeframe.**
11. Question Result, ID, References **Sat, MO.GO.CUSTNOTIFY.R, 192.16(d) (192.16(a), 192.16(b), 192.16(c))**
 Question Text *Do records indicate the customer notification process satisfies the requirements of 192.16?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed 2018-2020 customer newsletters which are sent via mail and e-mail every February to customers.**
12. Question Result, ID, References **Sat, RPT.RR.DAILYCONSTRUCTIONRPT.R,**
 Question Text *Do records indicate daily construction and repair activities were emailed to the commission no later than 10 AM each day work is scheduled?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed construction activity email log. No issues..**
13. Question Result, ID, References **Sat, RPT.RR.PIPELINEMAPPING.R,**
 Question Text *Has the operator provided accurate maps (or updates) of all pipelines operating over 250 psig to specifications developed by the commission sufficient to meet the needs of first responders?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed 3/15/2021 map submittal for Golden Givens Project (above 250 psig)**

PRR.CORROSION: Corrosion Control

14. Question Result, ID, References **Sat, TQ.QU.CORROSION.R, 192.453 (192.807(a), 192.807(b))**
 Question Text *Do records indicate qualification of personnel implementing pipeline corrosion control methods?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed OQ records for Michelle Gallardov - PSE Corrosion Engineer. All corrosion OQ are up to date and valid.**
15. Question Result, ID, References **Sat, TD.CP.RECORDS.R, 192.491(a)**
 Question Text *Do records indicate the location of all items listed in 192.491(a)?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed SAP system records for CP. Also viewed Corrosion control layer in GIS system ESRI for Snohomish County.**
16. Question Result, ID, References **Sat, TD.CP.MONITOR.CURRENTTEST.R, 192.491(c) (192.465(b))**
 Question Text *Do records document details of electrical checks of sources of rectifiers or other impressed current sources?*

Assets Covered 90870 (1642)

Result Notes Reviewed power source and test site inspection records for 2018-2020. Spot checked records for equipment calibration. Spot checked remediation for deficiencies found during power source checks (G3 work orders in SAP). No issues identified.

17. Question Result, ID, References Sat, TD.CPEXPOSED.EXPOSEINSPECT.R, 192.491(c) (192.459)

Question Text *Do records adequately document that exposed buried piping was examined for corrosion?*

Assets Covered 90870 (1642)

Result Notes Reviewed Exposed Pipe Condition Reports (EPCR) 1,282 recorded EPCR's in audit period, 32 had low PSP reads. Spot checked remediation work orders for audit period. No issues.

18. Question Result, ID, References Sat, TD.CPMONITOR.TEST.R, 192.491(c) (192.465(a))

Question Text *Do records adequately document cathodic protection monitoring tests have occurred as required?*

Assets Covered 90870 (1642)

Result Notes Reviewed test site inspection records for 2018-2020 audit period. See #4 response for EPCR records of PSP on exposed pipe. Spot checked remediation checks of discrepancies. No issues identified. Also reviewed calibration records for CP tech Thane Sunde's CP equipment (half cell, MM).

19. Question Result, ID, References NA, TD.CPMONITOR.REVCURRENTTEST.R, 192.491(c) (192.465(c))

Question Text *Do records document details of electrical checks interference bonds, diodes, and reverse current switches?*

Assets Covered 90870 (1642)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

20. Question Result, ID, References Sat, TD.CPMONITOR.DEFICIENCY.R, 192.491(c) (192.465(d))

Question Text *Do records adequately document actions taken to correct any identified deficiencies in corrosion control?*

Assets Covered 90870 (1642)

Result Notes Reviewed CP records for 2018-2020 audit period. Spot checked that remediations were conducted within 90 days. There were 3 that exceeded the 120 day requirement which were due to permitting and COVID issues in 2020.

21. Question Result, ID, References NA, TD.CP.UNPROTECT.R, 192.491(c) (192.465(e))

Question Text *Do records adequately document that exposed buried piping was examined for corrosion and deteriorated coating?*

Assets Covered 90870 (1642)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

22. Question Result, ID, References Sat, FS.FG.CASINGTESTLEAD.R,

Question Text *Do records indicate that all casings without vents installed after September 5, 1992 had separate test lead wires installed?*

Assets Covered 90870 (1642)

Result Notes Reviewed 195 casing test site inspections during audit period. 12 low reads, all remediated within 120 days.

23. Question Result, ID, References Sat, FS.FG.CASINGSEALS.R,

Question Text *Do records indicate that mains and service lines installed in casing or conduit are sealed at the ends as required?*

Assets Covered 90870 (1642)

Result Notes Reviewed GOS 2525.1900 Casing procedure.

Reviewed as-built for casing installation which contained the required information regarding sealing of casing endsends.

24. Question Result, ID, References Sat, TD.CP.ELECISOLATE.R, 192.491(c) (192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e))

- Question Text *Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed CP records for audit period. Spot checked remediation of discrepancies. No issues.
25. Question Result, ID, References Sat, TD.CP.CASINGINSPECT.R,
- Question Text *Do records indicate that annual casing inspections have been performed to ensure electrical isolation from the pipeline?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed CP casing inspection records for audit period. No issues.
26. Question Result, ID, References Sat, TD.CP.MONITOR.TESTSTATION.R, 192.469
- Question Text *Do records identify the location of test stations and show a sufficient number of test stations?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed GIS CP map layer in ESRI which show locations of test stations and casings.
27. Question Result, ID, References Sat, TD.CP.MONITOR.TESTLEAD.R, 192.491(c) (192.471(a), 192.471(b), 192.471(c))
- Question Text *Do records document that pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed GOS 2600.1200 for test lead installation procedures. Also view as-builts and GIS CP maps to confirm.
28. Question Result, ID, References Sat, TD.CP.MONITOR.INTFRCURRENT.R, 192.491(c) (192.473(a))
- Question Text *Do records document an effective program is in place to minimize detrimental effects of interference currents and that detrimental effects of interference currents from CP systems on other underground metallic structures are minimized?*
- Assets Covered 90870 (1642)
- Result Notes Operator has regular contact with other utility operators to compare and remediate any interference issues. There were no interference issues documented for 2018-2020 audit period in Snohomish County.
29. Question Result, ID, References NA, TD.ICP.CORRGAS.R, 192.491(c) (192.475(a))
- Question Text *Do the records demonstrate that the corrosive effect of the gas in the pipeline has been investigated and if determined to be corrosive, steps be taken to minimize internal corrosion?*
- Assets Covered 90870 (1642)
- Result Notes No such event occurred, or condition existed, in the scope of inspection review.
30. Question Result, ID, References Sat, TD.ICP.EXAMINE.R, 192.491(c) (192.475(a), 192.475(b))
- Question Text *Do records document examination of removed pipe for evidence of internal corrosion?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed two EPCR's for internal corrosion during 2018-2020. Also reviewed remediation records. No issues detected.
31. Question Result, ID, References NA, TD.ICP.CORRGASACTION.R, 192.491(c) (192.477)
- Question Text *Do records document the actions taken when corrosive gas is being transported by pipeline?*
- Assets Covered 90870 (1642)
- Result Notes No such event occurred, or condition existed, in the scope of inspection review.
32. Question Result, ID, References Sat, TD.ATM.ATMCORRODEINSP.R, 192.491(c) (192.481(a), 192.481(b), 192.481(c))
- Question Text *Do records document inspection of aboveground pipe for atmospheric corrosion?*
- Assets Covered 90870 (1642)

Result Notes reviewed leak survey maps, and patrolling records. (Bridges, slides, exposed pipe is all included). No issues or outstanding concerns.

33. Question Result, ID, References Sat, TD.COAT.NEWPIPE.R, 192.491(c) (192.455(a), 192.461(a), 192.461(b), 192.483(a))

Question Text *Do records document that each buried or submerged pipeline installed after July 31, 1971 has been externally coated with a suitable coating material?*

Assets Covered 90870 (1642)

Result Notes Reviewed as-built for 6" main extension in Everett (2019). Reviewed material work order for project to verify pipe used is properly coated. No issues.

34. Question Result, ID, References NA, TD.ICP.REPAIR.R, 192.485(a) (192.485(b))

Question Text *Do records document the repair or replacement of pipe that has been internally corroded to an extent that there is not sufficient remaining strength in the pipe wall?*

Assets Covered 90870 (1642)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

35. Question Result, ID, References NA, TD.ICP.EVALUATE.R, 192.491(c) (192.485(c))

Question Text *Do records document adequate evaluation of internally corroded pipe?*

Assets Covered 90870 (1642)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

PRR.PT: Pressure Test

36. Question Result, ID, References Sat, DC.PTLOWPRESS.PRESSTESTLOWSTRESS.R, 192.517(a) (192.507(a), 192.507(b), 192.507(c))

Question Text *Do records indicate that pressure testing is conducted in accordance with 192.507?*

Assets Covered 90870 (1642)

Result Notes All records and pressure charts included calibration dates and serial model.

Reviewed the following projects:

Lyons Gate (11/14/2018)

Patrick Crosby (4/11/2019) - 2" main extension

Castlewood (9/24/2019) - 2" main extension

Whiskey Ridge Views (5/15/2020) - 2" main extension

RS-2821 Mill Creek (7/23/2018) - Reg station

Mountlake Terrace Reconstruction (9/23/2018) - 6" IP main relocate

Everett Reinforcement project (5/16/2018) - 2" IP main

Dupont Pipe Replacement Bothell (2/26/2020) - 2" main extension

RS-2819 Sultan (8/23/2018) - Reg Station

Dupont pipe Replacement Everett (4/9/2019) - 2" IP main

Dupont Pipe Replacement Edmonds (1/20/2020) - 2" IP main

Everett main relocate (5/23/2019) - 6" HP main relocate

Dupont pipe replacement Mountlake Terrace (3/18/2020) - 2" IP main

Lake Forrest Park Main Extension (5/8/2019) - 1.25" main

Everett main replacement (7/26/2019) - Shallow main replacement 2"

37. Question Result, ID, References **Sat, DC.PT.LOWPRESS.PRESSTEST100PSIG.R, 192.517(b) (192.509(a), 192.509(b))**
Question Text *Do records indicate that pressure testing is conducted in accordance with 192.509(a)?*
Assets Covered **90870 (1642)**
Result Notes **Included in question #1**
38. Question Result, ID, References **Sat, DC.PT.SERVICELINE.R, 192.517(b) (192.511(a), 192.511(b), 192.511(c))**
Question Text *Do records indicate that pressure testing is conducted in accordance with 192.511?*
Assets Covered **90870 (1642)**
Result Notes **included in question #1**
39. Question Result, ID, References **Sat, DC.PT.PRESSTESTPLASTIC.R, 192.517(b) (192.513(a), 192.513(b), 192.513(c), 192.513(d))**
Question Text *Do records indicate that pressure testing is conducted in accordance with 192.513?*
Assets Covered **90870 (1642)**
Result Notes **included in question #1**

PRR.UPRATE: Uprating

40. Question Result, ID, References **NA, MO.GOUPRATE.MAOPINCREASE.R, 192.553(a) (192.553(b), 192.553(c))**
Question Text *Do records indicate that increases in MAOP of pipeline were determined in accordance with 192.553?*
Assets Covered **90870 (1642)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**
41. Question Result, ID, References **NA, MO.GOUPRATE.MAOPINCREASELIMIT.R, 192.553(b) (192.553(c), 192.553(d), 192.557(a))**
Question Text *Do records indicate that increases in MAOP are limited in accordance with 192.619 and 192.621?*
Assets Covered **90870 (1642)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**
42. Question Result, ID, References **NA, MO.GOUPRATE.MAOPINCREASEPREP.R, 192.553(b) (192.553(c), 192.553(a), 192.557(b), 192.557(c))**
Question Text *Do records indicate that increases in MAOP were preceded by the actions specified in 192.557?*
Assets Covered **90870 (1642)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**
43. Question Result, ID, References **NA, MO.GOUPRATE.MAOPINCREASECASTDUCTILE.R, 192.553(b) (192.553(c), 192.557(d))**
Question Text *Do records indicate that requirements were followed for increasing the MAOP for cast iron or ductile iron pipe where records are inadequate for evaluating the level of safety of the pipeline when operating at the proposed increased pressure?*
Assets Covered **90870 (1642)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

PRR.OM: Operations And Maintenance

44. Question Result, ID, References **Sat, MO.GO.OMANNUALREVIEW.R, 192.605(a)**
Question Text *Have annual reviews of the written procedures or processes in the manual been conducted as required?*
Assets Covered **90870 (1642)**

Result Notes Reviewed submittals to Commission. No issues.

Reviewed 2018- 2021 Gas Operating Standards (GOS) new and rescinded standards.

2018-2021 Gas Field Procedures (GFP) new and rescinded standards.

2021 Welding Manual

45. Question Result, ID, References Sat, MO.GO.OMHISTORY.R, 192.605(a) (192.605(b)(3))

Question Text *Are construction records, maps and operating history available to appropriate operating personnel?*

Assets Covered 90870 (1642)

Result Notes Gas standards manuals available via web portal on PSE intranet

Image Search (internal PSE database) - digital records of all construction records.

ESRI (PSE internal map database) -

Reviewed MRT compliance dashboard for 2018-2020. 2018 and 2019 were in compliance, 2020 saw significant increases in delayed updating of construction activity (due to COVID restrictions)

46. Question Result, ID, References Sat, MO.GO.OMEFFECTREVIEW.R, 192.605(a) (192.605(b)(8))

Question Text *Do records indicate periodic review of the work done by operator personnel to determine the effectiveness, and adequacy of the processes used in normal operations and maintenance and modifying the processes when deficiencies are found?*

Assets Covered 90870 (1642)

Result Notes External reviews (IFS contractor) - reviewed Gas High Pressure Inspection QAI reports. Also reviewed QAI data spreadsheet which compiled data for audit period.

Internal reviews (PSE) - reviewed Quality Control Investigation Reports for audit period.

47. Question Result, ID, References Sat, MO.GO.ABNORMAL.ABNORMALREVIEW.R, 192.605(a) (192.605(c)(4))

Question Text *Do records indicate periodic review of work done by operator personnel to determine the effectiveness of the abnormal operation processes and corrective action taken where deficiencies are found?*

Assets Covered 90870 (1642)

Result Notes Reviewed Corrective Action Report (CAR) for North Bend low pressure incident in 2019. Corrective actions were implemented involving notifications to Capacity Planning prior to approval. Operator used root cause analysis to determine appropriate corrective action. Reviewed updated procedure which included the new implemented notifications.

48. Question Result, ID, References Sat, PD.OC.PDPROGRAM.R, 192.614(c)

Question Text *Does the damage prevention program meet minimum requirements specified in 192.614(c)?*

Assets Covered 90870 (1642)

Result Notes Reviewed 2021 PSE Damage Prevention Plan. GOS 2425.1600, section 3.2 is standard for subscribing to 811 locating service. Reviewed QC report for locating contractor (ELM) which notes a 97% locating completion within two business days. Reviewed PSE High Profile (4" one way feed or larger) report which is a daily report from ELM to operator. Reviewed contractor letter that is sent out to excavator's who damage PSE gas facilities. Reviewed DIRT submission spreadsheet (GREMLIN). 301,988 gas locates performed in 2020.

49. Question Result, ID, References Sat, MO.GO.CLASS.CLASSLOCATESTUDY.R, 192.605(b)(1) (192.609(a), 192.609(b), 192.609(c), 192.609(d), 192.609(e), 192.609(f))

Question Text *Do records indicate performance of the required study whenever the population along a pipeline increased or there was an indication that the pipe hoop stress was not commensurate with the present class location?*

Assets Covered 90870 (1642)

- Result Notes All distribution systems are built to class 4 specifications. No studies have been conducted or required due to this construction process being in place.
50. Question Result, ID, References Sat, EP.ERG.POSTEVTREVIEW.R, 192.605(a) (192.615(b)(1), 192.615(b)(3))
- Question Text *Do records indicate review of employee activities to determine whether the procedures were effectively followed in each emergency?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed Emergency Information and Leak Reporting records for incidents that occurred in 2018-2020. No noted follow ups for 2018-2020. Did review follow up recommendations for incident in 2021 where supervisor requested more detailed information be added to reports from field techs to make records more comprehensible.
51. Question Result, ID, References Sat, EP.ERG.TRAINING.R, 192.605(a) (192.615(b)(2))
- Question Text *Has the operator trained the appropriate operating personnel on emergency procedures and verified that the training was effective in accordance with its procedures?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed Emergency response training documents. Training records are incorporated with OQ records. Spot checked GFR OQ records for appropriate emergency procedures training. Refresher training is conducted every 3 years.
52. Question Result, ID, References Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), 192.616(c), ADB-05-03) (also presented in: MISCTOPICS.PUBAWARE)
- Question Text *Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?*
- Assets Covered 90870 (1642)
- Result Notes Question #9 in OM r
53. Question Result, ID, References Sat, PD.PA.LANGUAGE.R, 192.616(g) (API RP 1162 Section 2.3.1) (also presented in: MISCTOPICS.PUBAWARE)
- Question Text *Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?*
- Assets Covered 90870 (1642)
- Result Notes PA plan section 6.3.3 identifies percentages which need to be met to produce messages in alternate languages. There are currently no counties in PSE's service territory which meet or exceed 15%. Basic safety materials are prepared in 11 different languages. DP brochure "know whats below" is provided in English and Spanish.
54. Question Result, ID, References Sat, PD.PA.EVALEFFECTIVENESS.R, 192.616(c) (API RP 1162 Section 8.4) (also presented in: MISCTOPICS.PUBAWARE)
- Question Text *Have effectiveness evaluation(s) of the program been performed for all stakeholder groups in all notification areas along all systems covered by the program?*
- Assets Covered 90870 (1642)
- Result Notes Four effectiveness study was completed in June 2021. Data is still being evaluated and analyzed. Reviewed Emergency Responder results. Will review this evaluation in more depth during PA inspection the week of July 20th 2021. Add inspection number.
55. Question Result, ID, References NA, PD.PA.MSTRMETER.R, 192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 Section 8.5) (also presented in: MISCTOPICS.PUBAWARE)
- Question Text *Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?*
- Assets Covered 90870 (1642)
- Result Notes No such relevant facilities/equipment existed in the scope of inspection review.
56. Question Result, ID, References Sat, EP.ERG.INCIDENTANALYSIS.R, 192.605(a) (192.617)
- Question Text *Do records indicate actions initiated to analyze accidents and failures, including the collection of appropriate samples for laboratory examination to determine the causes of the failure and minimize the possibility of recurrence, in accordance with its procedures?*
- Assets Covered 90870 (1642)
- Result Notes Reviewed mechanical fitting failure reports

2018-2020 PSE Snohomish County Failure report. 46 failures were documented for audit period. Randomly selected several failures for further analysis. In house testing and examinations are routinely conducted. No external laboratory examinations were conducted during audit period.

57. Question Result, ID, References Sat, MO.GOMAOP.MAOPDETERMINE.R, 192.619(a) (192.619(b), 192.621(a), 192.621(b), 192.623(a), 192.623(b))
Question Text *Do records indicate determination of the MAOP of pipeline segments in accordance with 192.619 and limiting of the operating pressure as required?*
Assets Covered 90870 (1642)
Result Notes Reviewed as-builts for:

6" HP main relocate in Everett (5/23/2019). As built contains system MAOP of 250 psig.

Dupont Pipe Replacement Bothell (2/26/2020). As built contains system MAOP of 60 psig. Test pressure was 100 psig.
58. Question Result, ID, References Sat, MO.GOODOR.ODORIZE.R, 192.709(c) (192.625(a), 192.625(b), 192.625(c), 192.625(d), 192.625(e), 192.625(f))
Question Text *Do records indicate appropriate odorization of its combustible gases in accordance with its processes and conduct of the required testing to verify odorant levels met requirements?*
Assets Covered 90870 (1642)
Result Notes Reviewed records for 2018-2020. No levels above .800 requiring follow up.
59. Question Result, ID, References NA, MO.RW.TRANSPATROL.R, 192.709(c) (192.705(a), 192.705(b), 192.705(c))
Question Text *Do records indicate that transmission line ROW surface conditions have been patrolled as required?*
Assets Covered 90870 (1642)
Result Notes No such requirement existed in the scope of inspection review.
60. Question Result, ID, References NA, MO.RW.TRANSLEAKAGE.R, 192.709(c) (192.706, 192.706(a), 192.706(b))
Question Text *Do records indicate transmission leakage surveys conducted as required?*
Assets Covered 90870 (1642)
Result Notes No such requirement existed in the scope of inspection review.
61. Question Result, ID, References Sat, MO.RW.DISTPATROL.R, 192.603(b) (192.721(a), 192.721(b))
Question Text *Do records indicate distribution patrolling was conducted as required?*
Assets Covered 90870 (1642)
Result Notes reviewed records for 2018-2020. AC inspections done every 3 years in conjunction with patrolling. No significant follow ups. Corrosion levels were level 2 only.
62. Question Result, ID, References Sat, MO.RW.LEAKFOLLOW.R,
Question Text *Do records indicate that a follow-up inspection was performed not more than thirty days following a repair where residual gas remained in the ground?*
Assets Covered 90870 (1642)
Result Notes Reviewed follow up records for selected leak repairs. No issues.
63. Question Result, ID, References Sat, MO.RW.DOWNGRADELEAKREPAIR.R,
Question Text *Do records indicate that leaks that have been downgraded are repaired within twenty-one months?*
Assets Covered 90870 (1642)
Result Notes Reviewed follow up records for selected leak repairs. No issues.
64. Question Result, ID, References Sat, MO.RW.LEAKREPAIRTIME.R,
Question Text *Do records indicate that leaks were repaired and re-evaluated in the timeframes specified in WAC 480-93-18601?*
Assets Covered 90870 (1642)
Result Notes All leaks repair records were within the required timeframes.

65. Question Result, ID, References Sat, MO.RW.LEAKRECORDS.R,

Question Text *Have gas leak records been prepared and maintained as required?*

Assets Covered 90870 (1642)

Result Notes review leak repair records for the following leaks:

N00393347 (2018)

N0113080 (2018)

N0120725 (2018)

N0122083 (2018)

N0124924 (2018)

N0126167 (2019)

N0126580 (2019)

N0126644 (2019)

N0126679 (2019)

N0126698 (2019)

N0127589 (2019)

N0127632 (2019)

N0127793 (2019)

N0127804 (2020)

N0129433 (2020)

66. Question Result, ID, References Sat, MO.RW.DISTPATROLLEAKAGE.R, 192.603(b) (192.723(a), 192.723(b))

Question Text *Do records indicate distribution leakage surveys were conducted as required?*

Assets Covered 90870 (1642)

Result Notes

Reviewed maps for 2018-2020 for the following locations

115.071 Collins Salifu (OQ 4/6/2016) instrument #9101551022 6/26/2019 (2019) (PR - every 3 years)

116.085 (2018-2020)

116.086 (2018-2020) Randell Starr (OQ 12/5/2019) #9101551029 3/31/2020

119.075 (2020) (PR Only)

119.076 (2020) (PR Only)

119.077 (2020) (PR)

125.100 (2018-2020)
125.101 (2018-2020)
130.088 (2020)
130.089 (2020) Chad Zamzow (OQ 10/23/2018) #9101733015 1/10/20
130.090 (2020)
135.084 (2018-2020)
135.085 (2018-2020)
135.086 (2018-2020)
140.094 (2019)
140.095 (2019 PR; 2020 Annual)
140.096 (2019 PR)
150.071 (2018 PR)
150.072 (2018-2020)
150.073 (2018-2020)
165.067 (2018-2020)
165.068 (2018-2020)
165.069 (2018-2020)

67. Question Result, ID, References Sat, MO.RW.CASINGLEAKSURVEY.R,

Question Text *Do records indicate shorted casings were leak surveyed as required?*

Assets Covered 90870 (1642)

Result Notes One shorted casing located at 84th St. and hwy 9 in Marysville. 8" HP STW in 20" casing. Reviewed leak survey records for 2018-2020 for this shorted casing. No issues.

68. Question Result, ID, References Sat, MO.RW.MARKERSURVEY.R,

Question Text *Do records indicate that pipeline marker surveys were completed in the timeframe specified by WAC 480-93-124?*

Assets Covered 90870 (1642)

Result Notes reviewed records for 2018-2020. Reviewed bridge crossing patrols timeframes (conducted quarterly)

69. Question Result, ID, References Sat, MO.RW.MARKERREPLACE.R,

Question Text *Do records indicate that damaged or missing markers were replaced within forty-five days of discovery?*

Assets Covered 90870 (1642)

Result Notes Reviewed pipeline marker replacement records. All markers were replaced within 45 days of discovery on records reviewed.

70. Question Result, ID, References **NA, AR.RMP.TESTREINSTATE.R, 192.603(b) (192.725(a), 192.725(b))**
 Question Text *From the review of records, did the operator properly test disconnected service lines?*
 Assets Covered **90870 (1642)**
 Result Notes **Operator does not do temporary disconnects of service lines. They replace the service.**
71. Question Result, ID, References **Sat, MO.GM.ABANDONPIPE.R, 192.709(c) (192.727(a), 192.727(b), 192.727(c), 192.727(d), 192.727(e), 192.727(f), 192.727(g))**
 Question Text *Do records indicate pipelines and facilities were abandoned or deactivated in accordance with requirements?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed Dupont Pipeline Replacement Bothell (2019). Replacement construction notes detail de-activation procedures and references applicable operating standards.**
72. Question Result, ID, References **Sat, MO.GMOPP.PRESSREGTEST.R, 192.709(c) (192.739(a), 192.739(b))**
 Question Text *Do records indicate inspection and testing of pressure limiting, relief devices, and pressure regulating stations?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed 2018-2020 Reg station and valve maintenance records. No remediations were discovered during audit period. Reviewed OQ's for pressure control tech Eric Cannon(covered task PSE 192-1803.01 Pressure regulating, limiting, relief devices,) expires 12/31/2023. Also Stephen Gray, expires 2023.**
73. Question Result, ID, References **Sat, MO.GMOPP.PRESSREGCAP.R, 192.709(c) (192.743(a), 192.743(b), 192.743(c))**
 Question Text *Do records indicate testing or review of the capacity of each pressure relief device at each pressure limiting station and pressure regulating station as required?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed the following relief device capacity records:**
- RS-2819 Sultan (11/19/2020)**
- RS-0084 Kenmore (7/1/2020)**
- RS-1602 Snohomish (7/1/2020)**
74. Question Result, ID, References **Sat, DC.METERREGSVC.REGTEST.R,**
 Question Text *Do records indicate that service regulators have been installed, operated, maintained, tested during initial turn-on and tested when customers experience pressure problems?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed GFR records for service regulators installed, operated, maintained and test in 2018-2020. No issues or failures noted.**
75. Question Result, ID, References **Sat, MO.GM.DISTVALVEINSPECT.R, 192.603(b) (192.747(a), 192.747(b))**
 Question Text *Do records indicate proper inspection of each distribution system valve that might be required in an emergency at intervals not exceeding 15 months, but at least once each calendar year, and prompt remedial action to correct any valve found inoperable?*
 Assets Covered **90870 (1642)**
 Result Notes **Valve maintenance is organized by evacuation concern and hard to reach locations. No valves needed repair or failed inspections during audit years 2018-2020. Reviewed emergency section valve records (performed annually) - no issues or failed inspections noted.**
76. Question Result, ID, References **NA, FS.FG.VAULTINSPECT.R, 192.709(c) (192.749(a), 192.749(b), 192.749(c), 192.749(d))**
 Question Text *Do records document the adequacy of inspections of all vaults having an internal volume \geq 200 cubic feet (5.66 cubic meters) that house pressure regulating/limiting equipment?*
 Assets Covered **90870 (1642)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**

77. Question Result, ID, References **Sat, MO.GM.IGNITION.R, 192.709 (192.751(a), 192.751(b), 192.751(c))**
 Question Text *Do records indicate personnel followed processes for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed GFP 0100.1040 procedure for Conducting an Emergency Assessment. GOS 2575.2000. Reviewed PSE Form 1284 for recent Seattle Incident (Monday 7/12/21) which documents steps taken during emergency operations and leak responses.**
78. Question Result, ID, References **NA, MO.GM.BELLSPIGOTJOINT.R, 192.603(b) (192.753(a), 192.753(b))**
 Question Text *Do records indicate that caulked bell and spigot joints were correctly sealed?*
 Assets Covered **90870 (1642)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
79. Question Result, ID, References **Sat, DC.DPC.FLANGE.R, 192.147(a) (192.147(b), 192.147(c))**
 Question Text *Do records indicate flanges and flange accessories meet the requirements of 192.147?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed 2021 PSE Gas Bolt Kit Catalog for specifications.**

Reviewed 6" Everett main relocate as-builts. 8" 30FFV(X) flange assembly was used for 8" bind flange.
80. Question Result, ID, References **Sat, DC.WELDPROCEDURE.WELD.R, 192.225(a) (192.225(b))**
 Question Text *Do records indicate weld procedures are being qualified in accordance with 192.225?*
 Assets Covered **90870 (1642)**
 Result Notes **Welding procedures were qualified in 1995 under WNG (see transmission audit for details)**

Previous procedure for wire feed is being brought back into manual and welders will be re-qualified under this procedure in 2021. This is not a new procedure but a previously qualified one that was not being used.
81. Question Result, ID, References **Sat, DC.WELDPROCEDURE.ESSENTIAL.R,**
 Question Text *Do records indicate that essential variables were measured and documented when welders and procedures were qualified?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed Weld Test Inspection Reports - form used for both procedure and welder qualifications.**

Reviewed Harely Mauck Procedure test conducted for Arc II on 6/9/2021. Stan Bouchard is technical trainer for welding procedures.
82. Question Result, ID, References **Sat, TQ.QUOMCONST.WELDER.R, 192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))**
 Question Text *Do records indicate adequate qualification of welders?*
 Assets Covered **90870 (1642)**
 Result Notes **Welder OQ's are performed by PSE (even for IFS)**

Reviewed records for:

Bill Root (IFS)

Cody Rutkowski (IFS)

Michael Whaley (IFS)

No Appendix C welders for audit period in Snohomish County

83. Question Result, ID, References **Sat, TQ.QUOMCONST.NDT.R, 192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b))**
 Question Text *Do records indicate the qualification of nondestructive testing personnel?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed NDT records for:**

RS-2819 Sultan - Nicole May (Radiographic) from OWL (Oregon Washington Laboratories) (2019). OQ recertified 4/14/2017 expires 4/30/2022

Everett 6" HP main relocate - Nicholas Rossiello (Mag Particle) from OWL (2019), OQ re-certified 1/6/2017 expires 12/31/2022.
84. Question Result, ID, References **Sat, DC.CO.PLASTICJOINTPROCEDURE.R, 192.273(b) (192.283(a), 192.283(b), 192.283(c), 192.283(d))**
 Question Text *Have plastic pipe joining procedures been qualified in accordance with 192.283?*
 Assets Covered **90870 (1642)**
 Result Notes **Same response as #37**
85. Question Result, ID, References **Sat, DC.CO.PLASTICJOINTQUAL.R, 192.285(d) (192.285(a), 192.285(b), 192.285(c), 192.807(a), 192.807(b))**
 Question Text *Do records indicate persons making joints in plastic pipelines are qualified in accordance with 192.285?*
 Assets Covered **90870 (1642)**
 Result Notes **Same response as #39. Also reviewed Robert Ly (IFS) fuser OQ for annual re-qualification.**
86. Question Result, ID, References **Sat, DC.CO.PLASTICJOINTINSR.R, 192.287 (192.807(a), 192.807(b))**
 Question Text *Do records indicate persons inspecting the making of plastic pipe joints have been qualified?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed IFS foreman Tyler Smith OQ**
87. Question Result, ID, References **Sat, DC.CO.PLASTICPIPESEP.R,**
 Question Text *Do records indicate minimum separation requirements are met for plastic pipelines?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed as-built for Lyons Gate I project (2" main extension). 12" separation is documented in trench detail schematic on as-built.**
88. Question Result, ID, References **Sat, MO.GM.EQUIPPLASTICJOINT.R, 192.603(b) (192.756)**
 Question Text *Do records indicate equipment used in joining plastic pipe was maintained in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed maintenance records for joining equipment provided by contractor (IFS). Reviewed calibration records for electrofusion machine.**
89. Question Result, ID, References **NA, MO.GM.RECORDS.R, 192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c))**
 Question Text *Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?*
 Assets Covered **90870 (1642)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
90. Question Result, ID, References **NA, MO.GM.MOVEANDLOWER.R,**
 Question Text *Do records indicate that a study was prepared before moving or lowering a steel gas pipeline as required?*
 Assets Covered **90870 (1642)**
 Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**
91. Question Result, ID, References **NA, MO.GM.MOVEANDLOWERSURVEY.R,**

Question Text *Do records indicate that a leak survey was conducted not more than thirty days after moving and/or lowering a metallic pipeline?*

Assets Covered 90870 (1642)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

92. Question Result, ID, References Sat, MO.RW.MARKERSMAPSDRAW.R,

Question Text *Are records sufficient to indicate class location and other areas where pipeline markers are required?*

Assets Covered 90870 (1642)

Result Notes Reviewed GOS 2525.2500, Table 4-1 for pipeline marker requirements for buried pipelines.

Reviewed Everett 6" HP relocate as-builts. References GOS 2525.2500 and provides.

Reviewed GIS map layer with PLM (pipeline maker) notations.

FR.FIELDPIPE: Pipeline Inspection (Field)

93. Question Result, ID, References Sat, DC.MA.MARKING.O, 192.63(a) (192.63(b), 192.63(c), 192.63(d))

Question Text *Are pipe, valves, and fittings properly marked for identification?*

Assets Covered 90870 (1642)

Result Notes Examined pipe and component materials at Everett station on 8/5/21.

94. Question Result, ID, References Sat, DC.DPC.FLANGE.O, 192.141 (192.147(a), 192.147(b), 192.147(c))

Question Text *Do flanges and flange accessories meet the requirements of 192.147?*

Assets Covered 90870 (1642)

Result Notes Examined pipe and component materials at Everett station on 8/5/21.

95. Question Result, ID, References Sat, DC.DPC.GDVALVEPLACEMENT.O, 192.141 (192.181(a), 192.181(b), 192.181(c))

Question Text *Are distribution line valves being installed as required of 192.181?*

Assets Covered 90870 (1642)

96. Question Result, ID, References Sat, DC.CO.PLASTICPIPEPROC.O,

Question Text *Is plastic pipe handled, stored and installed in accordance with manufacturer's recommendations, including maximum ultraviolet exposure?*

Assets Covered 90870 (1642)

Result Notes Examined pipe and component materials at Everett station on 8/5/21.

97. Question Result, ID, References NA, DC.CO.PLASTICWEAKLINK.O,

Question Text *Is a weak link installed when pulling plastic pipe by mechanical means?*

Assets Covered 90870 (1642)

Result Notes No such activity/condition was observed during the inspection.

98. Question Result, ID, References NA, DC.CO.PLASTICPIPESEP.O,

Question Text *Are plastic pipelines installed with the minimum separation from other utilities as required?*

Assets Covered 90870 (1642)

Result Notes No such activity/condition was observed during the inspection.

99. Question Result, ID, References NA, DC.CO.PLASTICBACKFILL.O,

Question Text *Is plastic pipe buried in essentially rock-free material or material recommended by the pipe manufacturer?*

Assets Covered 90870 (1642)

Result Notes No such activity/condition was observed during the inspection.

100. Question Result, ID, References **Sat, DC.CO.PLASTICSQUEEZING.O,**
 Question Text *Verify that the operator has limits in place for squeezing plastic pipe.*
 Assets Covered **90870 (1642)**
101. Question Result, ID, References **Sat, DC.METERREGSVC.CUSTOMETERREGLOC.O, 192.351 (192.353(a), 192.353(b), 192.353(c), 192.353(d))**
 Question Text *Are meters and service regulators being located consistent with the requirements of 192.353?*
 Assets Covered **90870 (1642)**
102. Question Result, ID, References **Sat, DC.METERREGSVC.CUSTOMETERREGPROT.O, 192.351 (192.355(a), 192.355(b), 192.355(c))**
 Question Text *Are meters and service regulators being protected from damage consistent with the requirements of 192.355?*
 Assets Covered **90870 (1642)**
103. Question Result, ID, References **Sat, DC.METERREGSVC.CUSTOMETERREGINSTALL.O, 192.351 (192.357(a), 192.357(b), 192.357(c), 192.357(d))**
 Question Text *Are meters and service regulators being installed consistent with the requirements of 192.357?*
 Assets Covered **90870 (1642)**
104. Question Result, ID, References **NA, DC.METERREGSVC.CUSTOMETEROPPRESS.O, 192.351 (192.359(a), 192.359(b), 192.359(c))**
 Question Text *Are customer meter operating pressures consistent with the requirements of 192.359?*
 Assets Covered **90870 (1642)**
 Result Notes **No such activity/condition was observed during the inspection.**
105. Question Result, ID, References **NA, DC.METERREGSVC.SVCLINEINSTALL.O, 192.351 (192.361(a), 192.361(b), 192.361(c), 192.361(d), 192.361(e), 192.361(f), 192.361(g))**
 Question Text *Are customer service lines being installed consistent with the requirements of 192.361?*
 Assets Covered **90870 (1642)**
 Result Notes **No such activity/condition was observed during the inspection.**
106. Question Result, ID, References **Sat, DC.METERREGSVC.SVCLINEVLVLOCATEREQT.O, 192.351 (192.363(a), 192.363(b), 192.363(c), 192.365(a), 192.365(b), 192.365(c))**
 Question Text *Are customer service line valves being installed meeting the valve and locations requirements of 192.363 and 192.365?*
 Assets Covered **90870 (1642)**
107. Question Result, ID, References **NA, DC.METERREGSVC.SVCLINECONNECT.O, 192.351 (192.367(a), 192.367(b), 192.369(a), 192.369(b))**
 Question Text *Are customer service lines being installed with connections meeting the requirements of 192.367 and 192.369?*
 Assets Covered **90870 (1642)**
 Result Notes **No such activity/condition was observed during the inspection.**
108. Question Result, ID, References **Sat, DC.METERREGSVC.SVCLINEMATERIAL.O, 192.351 (192.371, 192.373(a), 192.373(b), 192.373(c), 192.375(a), 192.375(b), 192.377)**
 Question Text *Are customer service lines being installed constructed appropriately for the types of materials used?*
 Assets Covered **90870 (1642)**
109. Question Result, ID, References **NA, DC.METERREGSVC.NEWSVCLINENOTUSED.O, 192.351 (192.379, 192.379(a), 192.379(b), 192.379(c))**
 Question Text *Are new customer service lines not in use configured in accordance with the requirements of 192.379?*
 Assets Covered **90870 (1642)**
 Result Notes **No such activity/condition was observed during the inspection.**
110. Question Result, ID, References **Sat, DC.METERREGSVC.EXCSFLOWVLVLOCATE.O, 192.351 (192.381(c), 192.381(d), 192.381(e))**
 Question Text *Are service line excess flow valves located and identified in accordance with the requirements of 192.381?*

Assets Covered 90870 (1642)

111. Question Result, ID, References NA, DC.METERREGSVC.REGTEST.O,
Question Text *Are service regulators operated, maintained, installed and tested during the initial turn-on in accordance with manufacturer's recommendations and WAC requirements?*
Assets Covered 90870 (1642)
Result Notes No such activity/condition was observed during the inspection.
112. Question Result, ID, References NA, DC.WELDPROCEDURE.ONSITE.O,
Question Text *Are qualified written welding procedures located onsite where welding is being performed?*
Assets Covered 90870 (1642)
Result Notes No such activity/condition was observed during the inspection.
113. Question Result, ID, References NA, DC.WELDPROCEDURE.ESSENTIAL.O,
Question Text *Does the operator document essential variables when qualifying welders and weld procedures?*
Assets Covered 90870 (1642)
Result Notes No such activity/condition was observed during the inspection.
114. Question Result, ID, References NA, TD.COAT.NEWPIPEINSTALL.O, 192.461(d)
Question Text *Is external protective coating being protected from damage that could result from adverse ditch conditions or supporting blocks?*
Assets Covered 90870 (1642)
Result Notes No such activity/condition was observed during the inspection.
115. Question Result, ID, References Sat, TD.CPMONITOR.MONITORCRITERIA.O, 192.465(a) (192.463(b), 192.463(c), 192.463(a))
Question Text *Are methods used for taking CP monitoring readings that allow for the application of appropriate CP monitoring criteria?*
Assets Covered 90870 (1642)
Result Notes See Form R for field observation records of CP equipment calibrations and testing results.
116. Question Result, ID, References Sat, TD.CPMONITOR.CURRENTTEST.O, 192.465(b)
Question Text *Are impressed current sources properly maintained and are they functioning properly?*
Assets Covered 90870 (1642)
Result Notes See Form R for field observation records of rectifier and galvanic system testing results.
117. Question Result, ID, References Sat, TD.CP.ELECISOLATE.O, 192.467(a) (192.467(b), 192.467(c), 192.467(d), 192.467(e))
Question Text *Are measures performed to ensure electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?*
Assets Covered 90870 (1642)
118. Question Result, ID, References Sat, TD.CP.CASINGINSPECT.O,
Question Text *Are casings electrically isolated from the pipeline?*
Assets Covered 90870 (1642)
Result Notes See Form R for field observation records of casing test results.
119. Question Result, ID, References Sat, TD.CPMONITOR.TESTSTATION.O, 192.469
Question Text *Do cathodically protected pipelines have a sufficient number of test stations?*
Assets Covered 90870 (1642)
120. Question Result, ID, References Sat, TD.CPMONITOR.TESTLEAD.O, 192.471(a)

Question Text *Do pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?*

Assets Covered 90870 (1642)

121. Question Result, ID, References Sat, TD.CP.MONITOR.INTFRCURRENT.O, 192.473(a)

Question Text *Are areas of potential stray current identified, and if found, the detrimental effects of stray currents minimized?*

Assets Covered 90870 (1642)

122. Question Result, ID, References Sat, TD.CP.ADJACENTMETAL.O, 192.473(b)

Question Text *Are impressed current type cathodic protection systems and galvanic anode systems installed so as to minimize any adverse effect on existing adjacent underground metallic structures?*

Assets Covered 90870 (1642)

123. Question Result, ID, References NA, TD.ICP.CORRGASPRVNT.O, 192.475(a)

Question Text *If the transportation of corrosive gas is not allowed, is the transportation of corrosive gas prevented?*

Assets Covered 90870 (1642)

Result Notes No such activity/condition was observed during the inspection.

124. Question Result, ID, References NA, TD.ICP.CORRGASACTION.O, 192.477

Question Text *Are adequate actions taken when corrosive gas is being transported by pipeline?*

Assets Covered 90870 (1642)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

125. Question Result, ID, References NA, TD.ICP.PIPEBOTTLE.O, 192.475(c)

Question Text *Is gas containing more than 0.25 grain of hydrogen sulfide per 100 standard cubic feet (5.8 milligrams/m³) at standard conditions (4 parts per million) being stored in pipe-type or bottle-type holders?*

Assets Covered 90870 (1642)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

126. Question Result, ID, References Sat, TD.ATM.ATMCORRODEINSP.O, 192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c))

Question Text *Is pipe that is exposed to atmospheric corrosion protected?*

Assets Covered 90870 (1642)

Result Notes See Form R for field observation records of above ground bridge crossing inspections.

127. Question Result, ID, References Sat, AR.COM.REMEDIATIONOM.O, 192.487(a) (192.487(b))

Question Text *Is anomaly remediation and documentation of remediation adequate for all segments?*

Assets Covered 90870 (1642)

128. Question Result, ID, References NA, TD.CP.GRAPHITIZE.O, 192.489(a) (192.489(b))

Question Text *Has there been adequate remediation for the graphitization of cast iron or ductile iron pipe?*

Assets Covered 90870 (1642)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

129. Question Result, ID, References Sat, MO.GOODOR.ODORIZE.O, 192.625(a) (192.625(c), 192.625(d), 192.625(e), 192.625(f))

Question Text *Is sampling of combustible gases adequate using an instrument capable of determining the percentage of gas in air at which it becomes readily detectable?*

Assets Covered 90870 (1642)

Result Notes See Form R for field observation records of Odorization tests conducted during audit.

130. Question Result, ID, References NA, MO.GO.PURGE.O, 192.629(a) (192.629(b))

Question Text *Are lines being purged in accordance with 192.629?*

Assets Covered 90870 (1642)

Result Notes No such activity/condition was observed during the inspection.

131. Question Result, ID, Sat, MO.RW.ROWMARKER.O, 192.707(a) (192.707(b), 192.707(d), CGA Best Practices, v4.0, Practice 2-References 5, CGA Best Practices, v4.0, Practice 4-20)

Question Text *Are line markers placed and maintained as required?*

Assets Covered 90870 (1642)

132. Question Result, ID, Sat, MO.RW.ROWMARKERABOVE.O, 192.707(c) (CGA Best Practices, v4.0, Practice 2-5, CGA Best Practices, v4.0, Practice 4-20)

Question Text *Are line markers placed and maintained as required for above ground pipelines?*

Assets Covered 90870 (1642)

133. Question Result, ID, Sat, MO.GMOPP.PRESSREGTEST.O, 192.739(a) (192.739(b))
References

Question Text *Are field or bench tests or inspections of regulating stations, pressure limiting stations or relief devices adequate?*

Assets Covered 90870 (1642)

Result Notes See Form R for field observation records of regulator stations tested during field audit. Observed lock up and relief testing for six regulator stations.

134. Question Result, ID, Sat, MO.GMOPP.PRESSREGMETER.O, 192.741(a) (192.741(b), 192.741(c))
References

Question Text *Are telemetering or recording gauges properly utilized as required for distribution systems?*

Assets Covered 90870 (1642)

135. Question Result, ID, Sat, MO.GMOPP.MULTIPRESSREG.O,
References

Question Text *Are regulator stations installed in a manner to provide protection between regulator stages?*

Assets Covered 90870 (1642)

136. Question Result, ID, Sat, MO.GM.DISTVALVEINSPECT.O, 192.747(a) (192.747(b))
References

Question Text *Is proper inspection being performed for each distribution system valve that might be required in an emergency, and prompt remedial action to correct any valves found inoperable?*

Assets Covered 90870 (1642)

Result Notes See Form R for field observation records of valves checked and partially operated during field audit.

137. Question Result, ID, Sat, FS.FG.CASING.O,
References

Question Text *Are all casings bare steel and do they have test leads installed on new casings without vents?*

Assets Covered 90870 (1642)

138. Question Result, ID, Sat, FS.FG.CASESEAL.O,
References

Question Text *Does the operator seal both ends of casings/conduits for mains and transmission lines and seal the end nearest the building for service lines?*

Assets Covered 90870 (1642)

139. Question Result, ID, NA, FS.FG.VAULTINSPECT.O, 192.749(a) (192.749(b), 192.749(c), 192.749(d))
References

Question Text *Are inspections of selected vaults with internal volume ≥ 200 cubic feet (5.66 cubic meters) housing pressure regulating/limiting equipment adequate?*

Assets Covered 90870 (1642)

Result Notes No such activity/condition was observed during the inspection.

140. Question Result, ID, Sat, AR.RMP.IGNITION.O, 192.751(a) (192.751(b), 192.751(c))
References

Question Text *Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.*

Assets Covered 90870 (1642)

141. Question Result, ID, References **NA, MO.GM.BELLSPIGOTJOINT.O, 192.753(a) (192.753(b))**
 Question Text *Do records indicate that caulked bell and spigot joints were correctly sealed?*
 Assets Covered **90870 (1642)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
142. Question Result, ID, References **NA, MO.GM.CASTIRONPROTECT.O, 192.755(a) (192.755(b))**
 Question Text *Is adequate protection in place for segments of a buried cast-iron pipeline for which support has been disturbed?*
 Assets Covered **90870 (1642)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
143. Question Result, ID, References **Sat, MO.GM.EQUIPPLASTICJOINT.O, 192.756**
 Question Text *Is proper maintenance being performed on equipment used in joining plastic pipe in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?*
 Assets Covered **90870 (1642)**
144. Question Result, ID, References **Sat, MO.GM.ONSITEPROCS.O,**
 Question Text *Are procedures applicable to the work being done located onsite where the work is being done?*
 Assets Covered **90870 (1642)**
 Result Notes **PSE Pressure control personnell had hard copies onsite of regulator data sheets, schematics, and procedures for each regulator station inspected.**
145. Question Result, ID, References **Sat, AR.PTI.EQUIPCALIB.O,**
 Question Text *Is pressure testing equipment calibrated according to calibration schedules and procedures?*
 Assets Covered **90870 (1642)**
 Result Notes **See Form R for field observation records of pressure testing equipment calibrations.**
146. Question Result, ID, References **NA, AR.PTI.PLASTICPRESSURETEST.O,**
 Question Text *Is plastic pipe installed and backfilled prior to pressure testing?*
 Assets Covered **90870 (1642)**
 Result Notes **No such activity/condition was observed during the inspection.**

GDIM.IMPL: GDIM Implementation

147. Question Result, ID, References **Sat, GDIM.RR.MECHANICALFITTINGDATAIMPL.R, 192.1009 (191.12)** (also presented in: PRR.REPORT)
 Question Text *Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?*
 Assets Covered **90870 (1642)**
 Result Notes **Reviewed mechanical failure reports for 2018-2020. There were 10 failures submitted for audit period from Snohomish County. No trends or outstanding areas of concern.**

MISCTOPICS.PUBAWARE: Public Awareness Program Effectiveness

148. Question Result, ID, References **Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), 192.616(c), ADB-05-03)** (also presented in: PRR.OM)
 Question Text *Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?*
 Assets Covered **90870 (1642)**
 Result Notes **Question #9 in OM r**

149. Question Result, ID, References [Sat, PD.PA.LANGUAGE.R, 192.616\(g\) \(API RP 1162 Section 2.3.1\)](#) (also presented in: PRR.OM)
Question Text *Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?*
Assets Covered [90870 \(1642\)](#)
Result Notes [PA plan section 6.3.3 identifies percentages which need to be met to produce messages in alternate languages. There are currently no counties in PSE;s service territory which meet or exceed 15%. Basic safety materials are prepared in 11 different languages. DP brochure "know whats below" is provided in English and Spanish.](#)
150. Question Result, ID, References [Sat, PD.PA.EVALEFFECTIVENESS.R, 192.616\(c\) \(API RP 1162 Section 8.4\)](#) (also presented in: PRR.OM)
Question Text *Have effectiveness evaluation(s) of the program been performed for all stakeholder groups in all notification areas along all systems covered by the program?*
Assets Covered [90870 \(1642\)](#)
Result Notes [Four effectiveness study was completed in June 2021. Data is still being evaluated and analyzed. Reviewed Emergency Responder results. Will review this evaluation in more depth during PA inspection the week of July 20th 2021. Add inspection number.](#)
151. Question Result, ID, References [NA, PD.PA.MSTRMETER.R, 192.616\(j\) \(192.616\(h\), API RP 1162 Section 2.7 \(Step 12\), API RP 1162 Section 8.5\)](#) (also presented in: PRR.OM)
Question Text *Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?*
Assets Covered [90870 \(1642\)](#)
Result Notes [No such relevant facilities/equipment existed in the scope of inspection review.](#)

Report Parameters: Results: all

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

Inspection Results (IRR)

Generated on 2021.August.09 18:02

• 90870 (1642) (151)

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
1.	(and 1 other asset)	Sat	PRR.REPORT	1.	RPT.RR.IMMEDREPORT.R	191.5(a) (191.7(a), 191.7(d))	Do records indicate immediate notifications of incidents were made in accordance with 191.5?
2.	(and 1 other asset)	NA	PRR.REPORT	2.	RPT.RR.INCIDENTREPORT.R	191.9(a)	Do records indicate reportable incidents were identified and reports were submitted to DOT on Form 7100.1 within the required time frame?
3.	(and 1 other asset)	NA	PRR.REPORT	3.	RPT.RR.INCIDENTREPORTSUPP.R	191.9(b)	Do records indicate accurate supplemental incident reports were filed and within the required timeframe?
4.	(and 1 other asset)	Sat	PRR.REPORT	4.	RPT.RR.ANNUALREPORT.R	191.11(a)	Have complete and accurate Annual Reports been submitted?
5.	(and 1 other asset)	Sat	PRR.REPORT	5.	RPT.RR.UTCANNUALREPORTS.R		Have complete and accurate annual reports been submitted to the commission?
6.	(and 1 other asset)	Sat	PRR.REPORT	6.	RPT.RR.MISDATAREPORTS.R		Has the operator submitted a copy of DOT Drug and Alcohol Testing MIS Data Collection Form to the commission when required?
7.	(and 1 other asset)	Sat	(2) PRR.REPORT	7.	GDIM.RR.MECHANICALFITTINGDATAIMPL.R	192.1009 (191.12)	Have accurate records been maintained documenting mechanical fitting failures that resulted in

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							hazardous leaks?
8.	(and 1 other asset)	Sat	PRR.REPORT	8.	RPT.RR.SRCR.R	191.23(a) (191.23(b), 191.25(a), 191.25(c))	Do records indicate safety-related condition reports were filed as required?
9.	(and 1 other asset)	NA	PRR.REPORT	9.	RPT.RR.MAOPINCREASENOTIFY.R		Do records indicate submittal of a written plan of procedures to the commission at least forty-five days before upgrading to a MAOP greater than 60 psig?
10.	(and 1 other asset)	Sat	PRR.REPORT	10.	RPT.RR.THIRTYDAYRPT.R		Has the operator submitted a written report within 30 days following each reportable incident?
11.	(and 1 other asset)	Sat	PRR.REPORT	11.	MO.GO.CUSTNOTIFY.R	192.16(d) (192.16(a), 192.16(b), 192.16(c))	Do records indicate the customer notification process satisfies the requirements of 192.16?
12.	(and 1 other asset)	Sat	PRR.REPORT	12.	RPT.RR.DAILYCONSTRUCTIONRPT.R		Do records indicate daily construction and repair activities were emailed to the commission no later than 10 AM each day work is scheduled?
13.	(and 1 other asset)	Sat	PRR.REPORT	13.	RPT.RR.PIPELINEMAPPING.R		Has the operator provided accurate maps (or updates) of all pipelines operating over 250 psig to specifications developed by the commission sufficient to meet the needs of first responders?
14.	(and 1 other asset)	Sat	PRR.CORROSION	1.	TQ.QU.CORROSION.R	192.453 (192.807(a), 192.807(b))	Do records indicate qualification of personnel implementing pipeline

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							corrosion control methods?
15.	(and 1 other asset)	Sat	PRR.CORROSION	2.	TD.CP.RECORDS.R	192.491(a)	Do records indicate the location of all items listed in 192.491(a)?
16.	(and 1 other asset)	Sat	PRR.CORROSION	3.	TD.CP.MONITOR.CURRENTTEST.R	192.491(c) (192.465(b))	Do records document details of electrical checks of sources of rectifiers or other impressed current sources?
17.	(and 1 other asset)	Sat	PRR.CORROSION	4.	TD.CP.EXPOSED.EXPOSEINSPECT.R	192.491(c) (192.459)	Do records adequately document that exposed buried piping was examined for corrosion?
18.	(and 1 other asset)	Sat	PRR.CORROSION	5.	TD.CP.MONITOR.TEST.R	192.491(c) (192.465(a))	Do records adequately document cathodic protection monitoring tests have occurred as required?
19.	(and 1 other asset)	NA	PRR.CORROSION	6.	TD.CP.MONITOR.REVCURRENTTEST.R	192.491(c) (192.465(c))	Do records document details of electrical checks interference bonds, diodes, and reverse current switches?
20.	(and 1 other asset)	Sat	PRR.CORROSION	7.	TD.CP.MONITOR.DEFICIENCY.R	192.491(c) (192.465(d))	Do records adequately document actions taken to correct any identified deficiencies in corrosion control?
21.	(and 1 other asset)	NA	PRR.CORROSION	8.	TD.CP.UNPROTECT.R	192.491(c) (192.465(e))	Do records adequately document that exposed buried piping was examined for corrosion and deteriorated coating?
22.	(and 1 other asset)	Sat	PRR.CORROSION	9.	FS.FG.CASINGTESTLEAD.R		Do records indicate that all casings without vents installed after September 5, 1992 had

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							separate test lead wires installed?
23.	(and 1 other asset)	Sat	PRR.CORROSION	10.	FS.FG.CASINGSEALS.R		Do records indicate that mains and service lines installed in casing or conduit are sealed at the ends as required?
24.	(and 1 other asset)	Sat	PRR.CORROSION	11.	TD.CP.ELECISOLATE.R	192.491(c) (192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e))	Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?
25.	(and 1 other asset)	Sat	PRR.CORROSION	12.	TD.CP.CASINGINSPECT.R		Do records indicate that annual casing inspections have been performed to ensure electrical isolation from the pipeline?
26.	(and 1 other asset)	Sat	PRR.CORROSION	13.	TD.CP.MONITOR.TESTSTATION.R	192.469	Do records identify the location of test stations and show a sufficient number of test stations?
27.	(and 1 other asset)	Sat	PRR.CORROSION	14.	TD.CP.MONITOR.TESTLEAD.R	192.491(c) (192.471(a), 192.471(b), 192.471(c))	Do records document that pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?
28.	(and 1 other asset)	Sat	PRR.CORROSION	15.	TD.CP.MONITOR.INTFRCURRENT.R	192.491(c) (192.473(a))	Do records document an effective program is in place to minimize detrimental effects of interference

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							currents and that detrimental effects of interference currents from CP systems on other underground metallic structures are minimized?
29.	(and 1 other asset)	NA	PRR.CORROSION	16.	TD.ICP.CORRGAS.R	192.491(c) (192.475(a))	Do the records demonstrate that the corrosive effect of the gas in the pipeline has been investigated and if determined to be corrosive, steps be taken to minimize internal corrosion?
30.	(and 1 other asset)	Sat	PRR.CORROSION	17.	TD.ICP.EXAMINE.R	192.491(c) (192.475(a), 192.475(b))	Do records document examination of removed pipe for evidence of internal corrosion?
31.	(and 1 other asset)	NA	PRR.CORROSION	18.	TD.ICP.CORRGASACTION.R	192.491(c) (192.477)	Do records document the actions taken when corrosive gas is being transported by pipeline?
32.	(and 1 other asset)	Sat	PRR.CORROSION	19.	TD.ATM.ATMCORRODEINSP.R	192.491(c) (192.481(a), 192.481(b), 192.481(c))	Do records document inspection of aboveground pipe for atmospheric corrosion?
33.	(and 1 other asset)	Sat	PRR.CORROSION	20.	TD.COAT.NEWPIPE.R	192.491(c) (192.455(a), 192.461(a), 192.461(b), 192.483(a))	Do records document that each buried or submerged pipeline installed after July 31, 1971 has been externally coated with a suitable coating material?
34.	(and 1 other asset)	NA	PRR.CORROSION	21.	TD.ICP.REPAIR.R	192.485(a) (192.485(b))	Do records document the repair or replacement of pipe that has been internally corroded to an

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							extent that there is not sufficient remaining strength in the pipe wall?
35.	(and 1 other asset)	NA	PRR.CORROSION	22.	TD.ICP.EVALUATE.R	192.491(c) (192.485(c))	Do records document adequate evaluation of internally corroded pipe?
36.	(and 1 other asset)	Sat	PRR.PT	1.	DC.PTLOWPRESS.PRESSTESTLOWSTRESS.R	192.517(a) (192.507(a), 192.507(b), 192.507(c))	Do records indicate that pressure testing is conducted in accordance with 192.507?
37.	(and 1 other asset)	Sat	PRR.PT	2.	DC.PTLOWPRESS.PRESSTEST100PSIG.R	192.517(b) (192.509(a), 192.509(b))	Do records indicate that pressure testing is conducted in accordance with 192.509(a)?
38.	(and 1 other asset)	Sat	PRR.PT	3.	DC.PT.SERVICELINE.R	192.517(b) (192.511(a), 192.511(b), 192.511(c))	Do records indicate that pressure testing is conducted in accordance with 192.511?
39.	(and 1 other asset)	Sat	PRR.PT	4.	DC.PT.PRESSTESTPLASTIC.R	192.517(b) (192.513(a), 192.513(b), 192.513(c), 192.513(d))	Do records indicate that pressure testing is conducted in accordance with 192.513?
40.	(and 1 other asset)	NA	PRR.UPRATE	1.	MO.GOUPRATE.MAOPINCREASE.R	192.553(a) (192.553(b), 192.553(c))	Do records indicate that increases in MAOP of pipeline were determined in accordance with 192.553?
41.	(and 1 other asset)	NA	PRR.UPRATE	2.	MO.GOUPRATE.MAOPINCREASELIMIT.R	192.553(b) (192.553(c), 192.553(d), 192.557(a))	Do records indicate that increases in MAOP are limited in accordance with 192.619 and 192.621?
42.	(and 1 other asset)	NA	PRR.UPRATE	3.	MO.GOUPRATE.MAOPINCREASEPREP.R	192.553(b) (192.553(c), 192.553(a), 192.557(b), 192.557(c))	Do records indicate that increases in MAOP were preceded by the actions specified in 192.557?
43.	(and 1 other asset)	NA	PRR.UPRATE	4.	MO.GOUPRATE.MAOPINCREASECASTDUCTILE.R	192.553(b) (192.553(c), 192.557(d))	Do records indicate that requirements were followed for increasing the MAOP for

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Qst #	Question ID	References	Question Text
							cast iron or ductile iron pipe where records are inadequate for evaluating the level of safety of the pipeline when operating at the proposed increased pressure?
44.	(and 1 other asset)	Sat	PRR.OM	1.	MO.GO.OMANNUALREVIEW.R	192.605(a)	Have annual reviews of the written procedures or processes in the manual been conducted as required?
45.	(and 1 other asset)	Sat	PRR.OM	2.	MO.GO.OMHISTORY.R	192.605(a) (192.605(b)(3))	Are construction records, maps and operating history available to appropriate operating personnel?
46.	(and 1 other asset)	Sat	PRR.OM	3.	MO.GO.OMEFFECTREVIEW.R	192.605(a) (192.605(b)(8))	Do records indicate periodic review of the work done by operator personnel to determine the effectiveness, and adequacy of the processes used in normal operations and maintenance and modifying the processes when deficiencies are found?
47.	(and 1 other asset)	Sat	PRR.OM	4.	MO.GO.ABNORMAL.ABNORMALREVIEW.R	192.605(a) (192.605(c)(4))	Do records indicate periodic review of work done by operator personnel to determine the effectiveness of the abnormal operation processes and corrective action taken where deficiencies are found?
48.	(and 1 other asset)	Sat	PRR.OM	5.	PD.OC.PDPROGRAM.R	192.614(c)	Does the damage prevention program meet minimum

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Asset	Result (Note 1)	Sub-Group	Qs	Question ID	References	Question Text
Number	Number	Text		Text			
							requirements specified in 192.614(c)?
49.	(and 1 other asset)	Sat		PRR.OM	6. MO.GOCLASS.CLASSLOCATESTUDY.R	192.605(b)(1) (192.609(a), 192.609(b), 192.609(c), 192.609(d), 192.609(e), 192.609(f))	Do records indicate performance of the required study whenever the population along a pipeline increased or there was an indication that the pipe hoop stress was not commensurate with the present class location?
50.	(and 1 other asset)	Sat		PRR.OM	7. EP.ERG.POSTEVTNTREVIEW.R	192.605(a) (192.615(b)(1), 192.615(b)(3))	Do records indicate review of employee activities to determine whether the procedures were effectively followed in each emergency?
51.	(and 1 other asset)	Sat		PRR.OM	8. EP.ERG.TRAINING.R	192.605(a) (192.615(b)(2))	Has the operator trained the appropriate operating personnel on emergency procedures and verified that the training was effective in accordance with its procedures?
52.	(and 1 other asset)	Sat	(2)	PRR.OM	9. EP.ERG.LIAISON.R	192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), 192.616(c), ADB-05-03)	Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?
53.	(and 1 other asset)	Sat	(2)	PRR.OM	10. PD.PA.LANGUAGE.R	192.616(g) (API RP 1162 Section 2.3.1)	Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Sat	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
54.	(and 1 other asset)	Sat	(2)	PRR.OM	11.	PD.PA.EVALEFFECTIVENESS.R	192.616(c) (API RP 1162 Section 8.4)	the operator's areas? Have effectiveness evaluation(s) of the program been performed for all stakeholder groups in all notification areas along all systems covered by the program?
55.	(and 1 other asset)	NA	(2)	PRR.OM	12.	PD.PA.MSTRMETER.R	192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 Section 8.5)	Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?
56.	(and 1 other asset)	Sat		PRR.OM	13.	EP.ERG.INCIDENTANALYSIS.R	192.605(a) (192.617)	Do records indicate actions initiated to analyze accidents and failures, including the collection of appropriate samples for laboratory examination to determine the causes of the failure and minimize the possibility of recurrence, in accordance with its procedures?
57.	(and 1 other asset)	Sat		PRR.OM	14.	MO.GOMAOP.MAOPDETERMINE.R	192.619(a) (192.619(b), 192.621(a), 192.621(b), 192.623(a), 192.623(b))	Do records indicate determination of the MAOP of pipeline segments in accordance with 192.619 and limiting of the operating pressure as required?
58.	(and 1 other asset)	Sat		PRR.OM	15.	MO.GOODOR.ODORIZE.R	192.709(c) (192.625(a), 192.625(b), 192.625(c), 192.625(d), 192.625(e), 192.625(f))	Do records indicate appropriate odorization of its combustible gases in accordance with its processes and conduct of

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Qs t #	Question ID	References	Question Text
							the required testing to verify odorant levels met requirements?
59.	(and 1 other asset)	NA	PRR.OM	16.	MO.RW.TRANSPATROL.R	192.709(c) (192.705(a), 192.705(b), 192.705(c))	Do records indicate that transmission line ROW surface conditions have been patrolled as required?
60.	(and 1 other asset)	NA	PRR.OM	17.	MO.RW.TRANSLEAKAGE.R	192.709(c) (192.706, 192.706(a), 192.706(b))	Do records indicate transmission leakage surveys conducted as required?
61.	(and 1 other asset)	Sat	PRR.OM	18.	MO.RW.DISTPATROL.R	192.603(b) (192.721(a), 192.721(b))	Do records indicate distribution patrolling was conducted as required?
62.	(and 1 other asset)	Sat	PRR.OM	19.	MO.RW.LEAKFOLLOW.R		Do records indicate that a follow-up inspection was performed not more than thirty days following a repair where residual gas remained in the ground?
63.	(and 1 other asset)	Sat	PRR.OM	20.	MO.RW.DOWNGRADELEAKREPAIR.R		Do records indicate that leaks that have been downgraded are repaired within twenty-one months?
64.	(and 1 other asset)	Sat	PRR.OM	21.	MO.RW.LEAKREPAIRTIME.R		Do records indicate that leaks were repaired and re-evaluated in the timeframes specified in WAC 480-93-18601?
65.	(and 1 other asset)	Sat	PRR.OM	22.	MO.RW.LEAKRECORDS.R		Have gas leak records been prepared and maintained as required?
66.	(and 1 other asset)	Sat	PRR.OM	23.	MO.RW.DISTPATROLLEAKAGE.R	192.603(b) (192.723(a), 192.723(b))	Do records indicate distribution leakage surveys were conducted as required?

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
67.	(and 1 other asset)	Sat	PRR.OM	24.	MO.RW.CASINGLEAKSURVEY.R		Do records indicate shorted casings were leak surveyed as required?
68.	(and 1 other asset)	Sat	PRR.OM	25.	MO.RW.MARKERSURVEY.R		Do records indicate that pipeline marker surveys were completed in the timeframe specified by WAC 480-93-124?
69.	(and 1 other asset)	Sat	PRR.OM	26.	MO.RW.MARKERREPLACE.R		Do records indicate that damaged or missing markers were replaced within forty-five days of discovery?
70.	(and 1 other asset)	NA	PRR.OM	27.	AR.RMP.TESTREINSTATE.R	192.603(b) (192.725(a), 192.725(b))	From the review of records, did the operator properly test disconnected service lines?
71.	(and 1 other asset)	Sat	PRR.OM	28.	MO.GM.ABANDONPIPE.R	192.709(c) (192.727(a), 192.727(b), 192.727(c), 192.727(d), 192.727(e), 192.727(f), 192.727(g))	Do records indicate pipelines and facilities were abandoned or deactivated in accordance with requirements?
72.	(and 1 other asset)	Sat	PRR.OM	29.	MO.GMOPP.PRESSREGTEST.R	192.709(c) (192.739(a), 192.739(b))	Do records indicate inspection and testing of pressure limiting, relief devices, and pressure regulating stations?
73.	(and 1 other asset)	Sat	PRR.OM	30.	MO.GMOPP.PRESSREGCAP.R	192.709(c) (192.743(a), 192.743(b), 192.743(c))	Do records indicate testing or review of the capacity of each pressure relief device at each pressure limiting station and pressure regulating station as required?
74.	(and 1 other asset)	Sat	PRR.OM	31.	DC.METERREGSVC.REGTEST.R		Do records indicate that service regulators have been installed, operated,

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							maintained, tested during initial turn-on and tested when customers experience pressure problems?
75.	(and 1 other asset)	Sat	PRR.OM	32.	MO.GM.DISTVALVEINSPECT.R	192.603(b) (192.747(a), 192.747(b))	Do records indicate proper inspection of each distribution system valve that might be required in an emergency at intervals not exceeding 15 months, but at least once each calendar year, and prompt remedial action to correct any valve found inoperable?
76.	(and 1 other asset)	NA	PRR.OM	33.	FS.FG.VAULTINSPECT.R	192.709(c) (192.749(a), 192.749(b), 192.749(c), 192.749(d))	Do records document the adequacy of inspections of all vaults having an internal volume ≥ 200 cubic feet (5.66 cubic meters) that house pressure regulating/limiting equipment?
77.	(and 1 other asset)	Sat	PRR.OM	34.	MO.GM.IGNITION.R	192.709 (192.751(a), 192.751(b), 192.751(c))	Do records indicate personnel followed processes for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion?
78.	(and 1 other asset)	NA	PRR.OM	35.	MO.GM.BELLSPIGOTJOINT.R	192.603(b) (192.753(a), 192.753(b))	Do records indicate that caulked bell and spigot joints were correctly sealed?
79.	(and 1 other asset)	Sat	PRR.OM	36.	DC.DPC.FLANGE.R	192.147(a) (192.147(b), 192.147(c))	Do records indicate flanges and flange accessories meet the requirements of 192.147?

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Qs	Question ID	References	Question Text
Number				Number			
80.	(and 1 other asset)	Sat	PRR.OM	37.	DC.WELDPROCEDURE.WELD.R	192.225(a) (192.225(b))	Do records indicate weld procedures are being qualified in accordance with 192.225?
81.	(and 1 other asset)	Sat	PRR.OM	38.	DC.WELDPROCEDURE.ESSENTIAL.R		Do records indicate that essential variables were measured and documented when welders and procedures were qualified?
82.	(and 1 other asset)	Sat	PRR.OM	39.	TQ.QUOMCONST.WELDER.R	192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))	Do records indicate adequate qualification of welders?
83.	(and 1 other asset)	Sat	PRR.OM	40.	TQ.QUOMCONST.NDT.R	192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b))	Do records indicate the qualification of nondestructive testing personnel?
84.	(and 1 other asset)	Sat	PRR.OM	41.	DC.CO.PLASTICJOINTPROCEDURE.R	192.273(b) (192.283(a), 192.283(b), 192.283(c), 192.283(d))	Have plastic pipe joining procedures been qualified in accordance with 192.283?
85.	(and 1 other asset)	Sat	PRR.OM	42.	DC.CO.PLASTICJOINTQUAL.R	192.285(d) (192.285(a), 192.285(b), 192.285(c), 192.807(a), 192.807(b))	Do records indicate persons making joints in plastic pipelines are qualified in accordance with 192.285?
86.	(and 1 other asset)	Sat	PRR.OM	43.	DC.CO.PLASTICJOINTINSP.R	192.287 (192.807(a), 192.807(b))	Do records indicate persons inspecting the making of plastic pipe joints have been qualified?
87.	(and 1 other asset)	Sat	PRR.OM	44.	DC.CO.PLASTICPIPESEP.R		Do records indicate minimum separation requirements are met for plastic pipelines?
88.	(and 1 other asset)	Sat	PRR.OM	45.	MO.GM.EQUIPPLASTICJOINT.R	192.603(b) (192.756)	Do records indicate equipment used in joining plastic pipe was maintained in

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Asset	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?
89.	(and 1 other asset)	NA	PRR.OM	46.	MO.GM.RECORDS.R	192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c))	Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?
90.	(and 1 other asset)	NA	PRR.OM	47.	MO.GM.MOVEANDLOWER.R		Do records indicate that a study was prepared before moving or lowering a steel gas pipeline as required?
91.	(and 1 other asset)	NA	PRR.OM	48.	MO.GM.MOVEANDLOWERSURVEY.R		Do records indicate that a leak survey was conducted not more than thirty days after moving and/or lowering a metallic pipeline?
92.	(and 1 other asset)	Sat	PRR.OM	49.	MO.RW.MARKERSMAPSDRAW.R		Are records sufficient to indicate class location and other areas where pipeline markers are required?
93.	(and 1 other asset)	Sat	FR.FIELDPIPE	1.	DC.MA.MARKING.O	192.63(a) (192.63(b), 192.63(c), 192.63(d))	Are pipe, valves, and fittings properly marked for identification?
94.	(and 1 other asset)	Sat	FR.FIELDPIPE	2.	DC.DPC.FLANGE.O	192.141 (192.147(a), 192.147(b), 192.147(c))	Do flanges and flange accessories meet the requirements of 192.147?

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
95.	(and 1 other asset)	Sat	FR.FIELDPIPE	3.	DC.DPC.GDVALVEPLACEMENT.O	192.141 (192.181(a), 192.181(b), 192.181(c))	Are distribution line valves being installed as required of 192.181?
96.	(and 1 other asset)	Sat	FR.FIELDPIPE	4.	DC.CO.PLASTICPIPEPROC.O		Is plastic pipe handled, stored and installed in accordance with manufacturer's recommendations, including maximum ultraviolet exposure?
97.	(and 1 other asset)	NA	FR.FIELDPIPE	5.	DC.CO.PLASTICWEAKLINK.O		Is a weak link installed when pulling plastic pipe by mechanical means?
98.	(and 1 other asset)	NA	FR.FIELDPIPE	6.	DC.CO.PLASTICPIPESEP.O		Are plastic pipelines installed with the minimum separation from other utilities as required?
99.	(and 1 other asset)	NA	FR.FIELDPIPE	7.	DC.CO.PLASTICBACKFILL.O		Is plastic pipe buried in essentially rock-free material or material recommended by the pipe manufacturer?
100.	(and 1 other asset)	Sat	FR.FIELDPIPE	8.	DC.CO.PLASTICSQUEEZING.O		Verify that the operator has limits in place for squeezing plastic pipe.
101.	(and 1 other asset)	Sat	FR.FIELDPIPE	9.	DC.METERREGSVC.CUSTOMETERREGLOC.O	192.351 (192.353(a), 192.353(b), 192.353(c), 192.353(d))	Are meters and service regulators being located consistent with the requirements of 192.353?
102.	(and 1 other asset)	Sat	FR.FIELDPIPE	10.	DC.METERREGSVC.CUSTOMETERREGPROT.O	192.351 (192.355(a), 192.355(b), 192.355(c))	Are meters and service regulators being protected from damage consistent with the requirements of 192.355?
103.	(and 1 other asset)	Sat	FR.FIELDPIPE	11.	DC.METERREGSVC.CUSTOMETERREGINSTAL L.O	192.351 (192.357(a), 192.357(b),	Are meters and service regulators being installed

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
						192.357(c), 192.357(d))	consistent with the requirements of 192.357?
104	(and 1 other asset)	NA	FR.FIELDPIPE	12.	DC.METERREGSVC.CUSTOMETEROPPRESS.O	192.351 (192.359(a), 192.359(b), 192.359(c))	Are customer meter operating pressures consistent with the requirements of 192.359?
105	(and 1 other asset)	NA	FR.FIELDPIPE	13.	DC.METERREGSVC.SVCLINEINSTALL.O	192.351 (192.361(a), 192.361(b), 192.361(c), 192.361(d), 192.361(e), 192.361(f), 192.361(g))	Are customer service lines being installed consistent with the requirements of 192.361?
106	(and 1 other asset)	Sat	FR.FIELDPIPE	14.	DC.METERREGSVC.SVCLINEVLVLOCATEREQT.O	192.351 (192.363(a), 192.363(b), 192.363(c), 192.365(a), 192.365(b), 192.365(c))	Are customer service line valves being installed meeting the valve and locations requirements of 192.363 and 192.365?
107	(and 1 other asset)	NA	FR.FIELDPIPE	15.	DC.METERREGSVC.SVCLINECONNECT.O	192.351 (192.367(a), 192.367(b), 192.369(a), 192.369(b))	Are customer service lines being installed with connections meeting the requirements of 192.367 and 192.369?
108	(and 1 other asset)	Sat	FR.FIELDPIPE	16.	DC.METERREGSVC.SVCLINEMATERIAL.O	192.351 (192.371, 192.373(a), 192.373(b), 192.373(c), 192.375(a), 192.375(b), 192.377)	Are customer service lines being installed constructed appropriately for the types of materials used?
109	(and 1 other asset)	NA	FR.FIELDPIPE	17.	DC.METERREGSVC.NEWSVCLINENOTUSED.O	192.351 (192.379, 192.379(a), 192.379(b), 192.379(c))	Are new customer service lines not in use configured in accordance with the requirements of 192.379?
110	(and 1 other asset)	Sat	FR.FIELDPIPE	18.	DC.METERREGSVC.EXCSFLOWVLVLOCATE.O	192.351 (192.381(c), 192.381(d), 192.381(e))	Are service line excess flow valves located and identified in accordance with the requirements of 192.381?
111	(and 1 other asset)	NA	FR.FIELDPIPE	19.	DC.METERREGSVC.REGTEST.O		Are service regulators operated,

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Qs	Question ID	References	Question Text
							maintained, installed and tested during the initial turn-on in accordance with manufacturer's recommendations and WAC requirements?
112	(and 1 other asset)	NA	FR.FIELDPIPE	20.	DC.WELDPROCEDURE.ONSITE.O		Are qualified written welding procedures located onsite where welding is being performed?
113	(and 1 other asset)	NA	FR.FIELDPIPE	21.	DC.WELDPROCEDURE.ESSENTIAL.O		Does the operator document essential variables when qualifying welders and weld procedures?
114	(and 1 other asset)	NA	FR.FIELDPIPE	22.	TD.COAT.NEWPIPEINSTALL.O	192.461(d)	Is external protective coating being protected from damage that could result from adverse ditch conditions or supporting blocks?
115	(and 1 other asset)	Sat	FR.FIELDPIPE	23.	TD.CPMONITOR.MONITORCRITERIA.O	192.465(a), 192.463(b), 192.463(c), 192.463(a)	Are methods used for taking CP monitoring readings that allow for the application of appropriate CP monitoring criteria?
116	(and 1 other asset)	Sat	FR.FIELDPIPE	24.	TD.CPMONITOR.CURRENTTEST.O	192.465(b)	Are impressed current sources properly maintained and are they functioning properly?
117	(and 1 other asset)	Sat	FR.FIELDPIPE	25.	TD.CP.ELECISOLATE.O	192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e)	Are measures performed to ensure electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							cathodically protect the pipeline and the other structures as a single unit?
118	(and 1 other asset)	Sat	FR.FIELDPIPE	26.	TD.CP.CASINGINSPECT.O		Are casings electrically isolated from the pipeline?
119	(and 1 other asset)	Sat	FR.FIELDPIPE	27.	TD.CPMONITOR.TESTSTATION.O	192.469	Do cathodically protected pipelines have a sufficient number of test stations?
120	(and 1 other asset)	Sat	FR.FIELDPIPE	28.	TD.CPMONITOR.TESTLEAD.O	192.471(a)	Do pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?
121	(and 1 other asset)	Sat	FR.FIELDPIPE	29.	TD.CPMONITOR.INTFRCURRENT.O	192.473(a)	Are areas of potential stray current identified, and if found, the detrimental effects of stray currents minimized?
122	(and 1 other asset)	Sat	FR.FIELDPIPE	30.	TD.CP.ADJACENTMETAL.O	192.473(b)	Are impressed current type cathodic protection systems and galvanic anode systems installed so as to minimize any adverse effect on existing adjacent underground metallic structures?
123	(and 1 other asset)	NA	FR.FIELDPIPE	31.	TD.ICP.CORRGASPRVNT.O	192.475(a)	If the transportation of corrosive gas is not allowed, is the transportation of corrosive gas prevented?
124	(and 1 other asset)	NA	FR.FIELDPIPE	32.	TD.ICP.CORRGASACTION.O	192.477	Are adequate actions taken when corrosive gas is being transported by pipeline?

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Qs	Question ID	References	Question Text
Number		Text		Number			
125	(and 1 other asset)	NA	FR.FIELDPIPE	33.	TD.ICP.PIPEBOTTLE.O	192.475(c)	Is gas containing more than 0.25 grain of hydrogen sulfide per 100 standard cubic feet (5.8 milligrams/m3) at standard conditions (4 parts per million) being stored in pipe-type or bottle-type holders?
126	(and 1 other asset)	Sat	FR.FIELDPIPE	34.	TD.ATM.ATMCORRODEINSP.O	192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c))	Is pipe that is exposed to atmospheric corrosion protected?
127	(and 1 other asset)	Sat	FR.FIELDPIPE	35.	AR.RCOM.REMEDIATIONOM.O	192.487(a) (192.487(b))	Is anomaly remediation and documentation of remediation adequate for all segments?
128	(and 1 other asset)	NA	FR.FIELDPIPE	36.	TD.CP.GRAPHITIZE.O	192.489(a) (192.489(b))	Has there been adequate remediation for the graphitization of cast iron or ductile iron pipe?
129	(and 1 other asset)	Sat	FR.FIELDPIPE	37.	MO.GOODOR.ODORIZE.O	192.625(a) (192.625(c), 192.625(d), 192.625(e), 192.625(f))	Is sampling of combustible gases adequate using an instrument capable of determining the percentage of gas in air at which it becomes readily detectable?
130	(and 1 other asset)	NA	FR.FIELDPIPE	38.	MO.GO.PURGE.O	192.629(a) (192.629(b))	Are lines being purged in accordance with 192.629?
131	(and 1 other asset)	Sat	FR.FIELDPIPE	39.	MO.RW.ROWMARKER.O	192.707(a) (192.707(b), 192.707(d), CGA Best Practices, v4.0, Practice 2-5, CGA Best Practices, v4.0, Practice 4-20)	Are line markers placed and maintained as required?
132	(and 1 other asset)	Sat	FR.FIELDPIPE	40.	MO.RW.ROWMARKERABOVE.O	192.707(c) (CGA Best Practices, v4.0, Practice 2-5, CGA Best	Are line markers placed and maintained as required for

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Asset	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
						Practices, v4.0, Practice 4-20)	above ground pipelines?
133	(and 1 other asset)	Sat	FR.FIELDPIPE	41.	MO.GMOPP.PRESSREGTEST.O	192.739(a) (192.739(b))	Are field or bench tests or inspections of regulating stations, pressure limiting stations or relief devices adequate?
134	(and 1 other asset)	Sat	FR.FIELDPIPE	42.	MO.GMOPP.PRESSREGMETER.O	192.741(a) (192.741(b), 192.741(c))	Are telemetering or recording gauges properly utilized as required for distribution systems?
135	(and 1 other asset)	Sat	FR.FIELDPIPE	43.	MO.GMOPP.MULTIPRESSREG.O		Are regulator stations installed in a manner to provide protection between regulator stages?
136	(and 1 other asset)	Sat	FR.FIELDPIPE	44.	MO.GM.DISTVALVEINSPECT.O	192.747(a) (192.747(b))	Is proper inspection being performed for each distribution system valve that might be required in an emergency, and prompt remedial action to correct any valves found inoperable?
137	(and 1 other asset)	Sat	FR.FIELDPIPE	45.	FS.FG.CASING.O		Are all casings bare steel and do they have test leads installed on new casings without vents?
138	(and 1 other asset)	Sat	FR.FIELDPIPE	46.	FS.FG.CASESEAL.O		Does the operator seal both ends of casings/conduits for mains and transmission lines and seal the end nearest the building for service lines?
139	(and 1 other asset)	NA	FR.FIELDPIPE	47.	FS.FG.VAULTINSPECT.O	192.749(a) (192.749(b), 192.749(c), 192.749(d))	Are inspections of selected vaults with internal volume ≥ 200 cubic feet (5.66 cubic meters) housing pressure

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text
							regulating/limiting equipment adequate?
140	(and 1 other asset)	Sat	FR.FIELDPIPE	48.	AR.RMP.IGNITION.O	192.751(a) (192.751(b), 192.751(c))	Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.
141	(and 1 other asset)	NA	FR.FIELDPIPE	49.	MO.GM.BELLSPIGOTJOINT.O	192.753(a) (192.753(b))	Do records indicate that caulked bell and spigot joints were correctly sealed?
142	(and 1 other asset)	NA	FR.FIELDPIPE	50.	MO.GM.CASTIRONPROTECT.O	192.755(a) (192.755(b))	Is adequate protection in place for segments of a buried cast-iron pipeline for which support has been disturbed?
143	(and 1 other asset)	Sat	FR.FIELDPIPE	51.	MO.GM.EQUIPPLASTICJOINT.O	192.756	Is proper maintenance being performed on equipment used in joining plastic pipe in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?
144	(and 1 other asset)	Sat	FR.FIELDPIPE	52.	MO.GM.ONSITEPROCS.O		Are procedures applicable to the work being done located onsite where the work is being done?
145	(and 1 other asset)	Sat	FR.FIELDPIPE	53.	AR.PTI.EQUIPCALIB.O		Is pressure testing equipment calibrated according to calibration schedules and procedures?

Inspection Results Report (ALL Non-Empty Results) - Scp_PK 90870 (1642)

Row	Assets	Result (Note 1)	Sub-Group	Question #	Question ID	References	Question Text	
146	(and 1 other asset)	NA	FR.FIELDPIPE	54.	AR.PTI.PLASTICPRESSURETEST.O		Is plastic pipe installed and backfilled prior to pressure testing?	
147	(and 1 other asset)	Sat	(2)	GDIM.IMPL	34.	GDIM.RR.MECHANICALFITTINGDATAIMPL.R	192.1009 (191.12)	Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?
148	(and 1 other asset)	Sat	(2)	MISCTOPICS.PUBAWARE	11.	EP.ERG.LIAISON.R	192.605(a) (192.615(c)(1)), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), 192.616(c), ADB-05-03)	Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?
149	(and 1 other asset)	Sat	(2)	MISCTOPICS.PUBAWARE	13.	PD.PA.LANGUAGE.R	192.616(g) (API RP 1162 Section 2.3.1)	Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?
150	(and 1 other asset)	Sat	(2)	MISCTOPICS.PUBAWARE	18.	PD.PA.EVALEFFECTIVENESS.R	192.616(c) (API RP 1162 Section 8.4)	Have effectiveness evaluation(s) of the program been performed for all stakeholder groups in all notification areas along all systems covered by the program?
151	(and 1 other asset)	NA	(2)	MISCTOPICS.PUBAWARE	25.	PD.PA.MSTRMETER.R	192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 Section 8.5)	Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?

1. Result is repeated (N) times in this report due to re-presentation of the question in multiple sub-groups.

Report Parameters: All non-empty Results

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

UTC Standard Inspection Report
 Intrastate Gas Distribution
 RC - State Statutes and Rules
 Records Review and Field Inspections

Inspector and Operator Information

Inspection Link 8290	Inspector - Lead Tinnerstet, Darren	Inspector - Assist
Operator Puget Sound Energy	Unit Snohomish	Records Location - City & State Georgetown, WA
Inspection Start Date 07-12-2021	Inspection Exit Interview Date 08-05-2021	Engineer Submit Date 08-09-2021

Inspection Summary

Inspection Scope and Summary

This is a PSE Unit inspection for the Snohomish County District #8290
 Records are physically located in the Georgetown office but were reviewed virtually.
 There were no issues noted with this inspection.

Facilities visited and Total AFOD

Pre-audit field : 5/18/21 to 5/20/2021 = 3 AFOD days
 Virtual records and field : 7/12/21 to 7/15/21 (records); 8/3/21 to 8/5/21 (field) = 7 AFOD days (exit interview was conducted on 8/5/21)

Summary of Significant Findings

No issues noted.

Primary Operator contacts and/or participants

Danielle Troupe
 Senior Regulatory Compliance Analyst - Gas Pipeline Safety
 Puget Sound Energy
 Office: 425-456-2526
 Cell: 425-941-1460

Instructions and Ratings Definitions

INSTRUCTIONS

S - Satisfactory

U - Unsatisfactory

Area Of Concern

N/A - Not Applicable (does not apply in this inspection)

N/C - Not Checked/Evaluated (was not inspected during this inspection)

Unanswered Questions

0

INSPECTION RESULTS

Satisfactory Responses

15

Unsatisfactory Responses

0

Area of Concern Responses

0

Not Applicable Responses

1

Not Checked / Evaluated Responses

1

Unanswered Questions List

Satisfactory List

1,2,3,4,6,7,8,9,10,11,12,13,14,15,16,

Unsatisfactory List

Area of Concern List

Not Applicable List

5,

Not Checked / Evaluated List

17

**If an item is marked Form a- annual review. U, N/Form a- annual review or N/C, an explanation must be included in this report.

Records, Procedures and Reports

Question #1.

Has the operator provided accurate maps (or updates) of pipelines operating over 250PSIG to specifications developed by the commission and sufficient to meet the needs of first responders?

Statutory Reference

RCW 81.88.080

1. Result

Satisfactory

1. Notes

Reviewed Golden Givens submittal (#13 in IA Records Reporting)

Question #2.

Do records indicate that the operator appropriately addresses discovered mapping errors, including all mapping errors that have resulted in excavation damage?

Statutory Reference

WAC 480-93-018

2. Result

Satisfactory

2. Notes

reviewed Map revision forms which are submitted when mapping errors are discovered by field personnel.

reviewed Corrective Action Reports (CAR) - none for snohomish county but reviewed reports for King County (Midvale Ave. incident)

Question #3.

Do records indicate that the operator's mapping corrections are made in a timely manner and in accordance with the operator's written procedures?

Statutory Reference

WAC 480-93-018

3. Result

Satisfactory

3. Notes

reviewed Maps Records and Technologies (MRT) system data.

Question #4

Do records indicate that the operator has and follows a quality assurance program for monitoring the locating and marking of facilities? Do records show that the operator conducts regular field audits of the performance of locators/contractors and takes action when necessary?

Reference:

Operator Internal Performance Measures; PHMSA State Program Guidelines

4. Results

Satisfactory

4. Notes

PSE does not conduct regular field audits of ELM. PSE is notified of all high profile tickets. ELM does their own quarterly audit of locating metrics which is provided to PSE for review and action. PSE also conducts annual QC plan audit of all contractors including ELM. Reviewed 2018-2020 PSE Quality Management Department Audit Reports, noted findings and corrective ations.

Question #5.

Does operator include performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties?

Statutory Reference

WAC 480-93-007

Statutory Reference

WAC 480-93-013

Reference:

PHMSA State Program Guidelines

5. Result

Not Applicable

Q5. Within Scope of this Inspection:

No such event occurred, or condition existed.

5. Notes

PSE does not currently have incentives and penalties included within contracts. In current negotiations there are discussions about adding performance based monetary incentives for exceeding metrics.

Question #6.

Do operator contracted (or organic) locators address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing levels?

Statutory Reference

WAC 480-93-007

Statutory Reference

WAC 480-93-013

6. Result

Satisfactory

6. Notes

PSE is changing current procedures with contractor ELM to make OQ training annual as opposed to every three years starting in July 2022. Also will be increasing passing score from 80% to 87%. This change is the direct result of Corrective Action Report (CAR) related to Puyallup Meridian incident in June 2020.

Question #7.

Does the operator periodically review the Operator Qualification plan criteria and methods used to qualify personnel to perform locates?

Statutory Reference

WAC 480-93-007

Statutory Reference

WAC 480-93-013

7. Result

Satisfactory

7. Notes

The ELM OQ plan is reviewed and approved annually by PSE standards department. Reiveiwed emails confirming review of OQ plan for 2018-2020.

Question #8.

Do records indicate that operator locating and excavation practices are in compliance with the requirements for facility owners prescribed by RCW 19.122?

Statutory Reference

RCW 19.122

Statutory Reference

WAC 480-93-250

8. Result

Satisfactory

8. Notes

Reviewed ELM monthly reporting metrics for 2018-2020. Reviewed 2020 emergency locate ticket called in by PSE for Everett gas leak. Reviewed positive response log to determine that locate was completed within required timeframe.

Question #9.

Are locates made within the required timelines specified within RCW 19.122 (2 full business days)? Examine record sample.

Statutory Reference	Statutory Reference	9. Result	9. Notes
RCW 19.122	WAC 480-93-250	Satisfactory	Reviewed ELM monthly reporting metrics for 2020. ELM completed 97% of locates within required two business day timeframe.

Question #10.

Are locating and excavating personnel properly qualified in accordance with the operator's Operator Qualification plan and with federal and state requirements?

Statutory Reference	Statutory Reference	10. Result	10. Notes
WAC 480-93-007	WAC 480-93-013	Satisfactory	Reviewed ELM OQ plan (specific for PSE) revised 6/1/2021, Version 4. This OQ plan is reviewed and approved annually by PSE standards department. PSE is changing current procedures with contractor ELM to make OQ training annual as opposed to every three years starting in July 2022. Also will be increasing passing score from 80% to 87%

Question #11.

Do records indicate that the operator has and follows a procedure for leaks caused by excavation damage near buildings such that the procedure adequately addresses the possibility of multiple leaks and underground migration of gas into nearby buildings/structures?

Reference:	11. Result	11. Notes
PHMSA State Program Guidelines Operator Internal Performance Measures	Satisfactory	Reviewed GOP 0100.1040. Operator does not have procedure specific to leaks caused by excavation damage near buildings. This GOP covers leaks near buildings in general. Step 10 covers consideration for multiple leaks and migration of gas.

Question #12.

Do the operator's leak records indicate that the operator is conducting detailed leak investigations, evaluations, classification, and remedial action/repair prioritization steps in sufficient detail to ensure compliance with WACs 480-93-185, -186, and -18601?

Reference:	12. Result	12. Notes
PHMSA State Program Guidelines Operator Internal Performance Measures	Satisfactory	Reviewed leak records for 2018-2020

Question #13

Do records indicate that shorted conditions are leak surveyed within ninety (90) days of discovery and twice annually, not to exceed 7.5 months thereafter?

Statutory Reference	13. Result	13. Notes
WAC 480-93-200	Satisfactory	duplicate of PHMSA Operations and Maintenance #24

Question #14.

Did the operator submit a copy of DOT Drug and Alcohol Testing MIS Data Collection Form to the commission when required?

Statutory Reference	14. Result	14. Notes
WAC 480-93-200(13)	Satisfactory	Duplicate question from IA #6 records reporting.

Question #15

Does the operator file complete Material/Failure Analysis reports as required by WAC 480-93-200 (10)(b) no later than March 15 for the preceding year?

Statutory Reference	15. Result	15. Notes
WAC 480-93-200(10)(b)	Satisfactory	Reviewed Material/Failure Analysis report for 2020. Submitted to UTC on 3/15/2021.

Comments - Records, Procedures & Reports

RECORDS REVIEW SUMMARY: Comments are required for any rating other than "Satisfactory". Summarize the "Notes" blocks above, and ensure you annotate the question number for each comment.

FIELD INSPECTION OBSERVATIONS

Question #16

Are welding procedures located on site where welding is performed?

Statutory Reference	16. Results	16. Notes
WAC 480-93-080(1)(e)	Satisfactory	Performed multiple crew inspections during the 2018-2020 audit period and did not observe procedures not being available onsite when welding was being performed.

Question #17

Is the operator using testing equipment necessary to record and document essential variables during welder and procedure testing/qualifications?

Statutory Reference
WAC 480-93-080(1)(c)

17. Results
Not Checked/Evaluated

17. Notes

Comments - Field Observations

FIELD OBSERVATION SUMMARY: Comments are required for any rating other than "Satisfactory". Summarize the "Notes" blocks above, and ensure you annotate the question number for each comment.