

A completed **Standard Inspection Checklist, Cover Letter and Field Report** are to be submitted to the Senior Engineer within **30 days** from completion of the inspection.

Inspection Report			
Inspection ID/Docket #	6764		
Inspector Name & Submit Date	Lead: Joe Subsits Team: Derek Norwood/October 20, 2016		
Chief Engineer Name & Review Date	Joe Subsits, October 24, 2016		
Operator Information			
Name of Operator:	Tidewater Terminal Company	OPID #:	31051
Name of Unit(s):	Headquarters		
Records Location:	Pasco, WA		
Date(s) of Last (unit) Inspection:	May 4-7, 2015	Inspection Date(s):	August 5 – October 20, 2016

<p>Inspection Summary:</p> <p>This review is to assess compliance with all applicable provisions of 49 CFR 195 and WAC 480-75 that pertain to Tidewater Terminal Company’s (Tidewater) Snake River Terminal (SRT) Inbound/Outbound Pipelines and SRT Pasco Rail Diesel Line.</p> <p>This inspection consists of a review of Tidewater’s Pipeline Operations and Maintenance Manual. In addition, the Manual references several other Tidewater documents including the Integrated Contingency Plan, System Operation Manuals for Inbound/Outbound Pipeline and the Pasco Rail Diesel Line. As these manuals have specific operating procedures affecting hazardous liquid pipeline facilities, they were included in this review.</p> <p>Per commission staff’s request, Tidewater made additions/revisions to the Pipeline Operations and Maintenance Manual in order to meet the requirements of Items 23, 100, 110, 163, 184, 185, 244, 261 and 266 of Form G1 along with Question 7 under “Facilities and Storage – Tanks and Storage” on PHMSA Form 10.</p>

HQ Address: P.O. Box 1210 6305 NW Old Lower River Rd Vancouver, WA 98660		System/Unit Name & Address: 671 Tank Farm Rd Pasco, WA 99301	
Co. Official:	Bruce Reed	Phone No.:	:
Phone No.:		Fax No.:	
Fax No.:		Emergency Phone No.:	509-547-7701 Office
Emergency Phone No.:	509-547-7701		509-727-1144 Cell
Persons Interviewed	Title		Phone No.
Josh Jarman	Quality & Compliance Manager		360-693-1491

CONVERSION TO SERVICE			S	U	N/A	N/C
1.	195.5(a-c)	Has a written procedure been developed addressing all applicable requirements and followed?			X	

REGULATED RURAL GATHERING LINES			S	U	N/A	N/C
2.	195.11	Operator has identified pipelines that are Regulated Rural Gathering Lines that meet all of the following criteria: (1) nominal diameter from 6 5/8 inches to 8 5/8 inches; (2) located in or within one-quarter mile of a USA (3) operates at an MOP established under §195.406 that is: (i) greater than 20% SMYS; or (ii) if the stress level is unknown, or not steel; > 125 psig.			X	
3.	195.11(b)	Operator has prepared written procedures to carry out the requirements of 195.11 . <ul style="list-style-type: none"> • Subpart B Reporting • Corrosion Control • Damage Prevention • Public Awareness • Establish MAOP • Line Markers • Operator Qualification 			X	
4.	195.11(c)	If a new USA is identified after July 3, 2008, the operator must implement the requirements in paragraphs (b)(2 - 8), and (b)(11) for affected pipelines within 6 months of identification. For steel pipelines, comply with the deadlines in paragraphs (b)(9 & 10).			X	
5.	195.11(d)	Operator must maintain : (1) Segment identification records required in paragraph (b)(1) of this section and the records required to comply with (b)(10) of this section, for the life of the pipe. (2) records necessary to demonstrate compliance (b)(2 – 9 & 11) of this section according to the record retention requirements of the referenced section or subpart.			X	

Comments:

Item 1 – Tidewater has not converted any lines to service
 Items 2-5 – Tidewater has no gathering lines

LOW-STRESS PIPELINES IN RURAL AREAS			S	U	N/A	N/C
6.	195.12(a)	Operator has identified pipelines that are Regulated Low-stress Pipelines in Rural Areas that meet all of the following criteria: (except for those already covered by 49 CFR 195) (1) nominal diameter of 8 5/8 inches or more; (2) located in or within one-half mile of a USA (3) operates at an MOP established under §195.406 that is: (i) greater than 20% SMYS; or (ii) if the stress level is unknown, or not steel; > 125 psig.			X	
7.	195.12(b)	Operator has prepared written procedures to carry out the requirements of 195.12 . <ul style="list-style-type: none"> • Subpart B Reporting • Establish Integrity Management Plan • All Part 195 Safety Requirements 			X	

8.	195.12(c)(1)	Operator may notify PHMSA of economic burden.			X	
9.	195.12(d)	If, after July 3, 2008, a new USA is identified, the operator must implement the requirements in paragraphs (b)(2)(i) for affected pipelines within 12 months of identification.			X	
10.	195.12(d)	Operator must maintain: (1) Segment identification records required in paragraph (b)(1) for the life of the pipeline. (2) Records necessary to demonstrate compliance (b)(2 - 4) according to the record retention requirements of the referenced section or subpart.			X	

Comments:

Items 6-10 – Tidewater is already regulated by 49 CFR Part 195

SUBPART B - REPORTING PROCEDURES			S	U	N/A	N/C
11.	195.402(a) 195.402(c)(2)	Complete and submit DOT Form PHMSA F 7000-1.1 for each type of hazardous liquid pipeline facility operated at the end of the previous year for each commodity, and each state a pipeline traverses by June 15 of each calendar year. (<i>NOTE: August 15, 2011 for the year 2010</i>). (Amdt. 195-95, 75 FR 72877, November 26, 2010, eff. 1/1/2011). .49 Section 800.1	X			
12.		Accident report criteria, as detailed under 195.50. A release that results in, 5 gallons or more, death or personal injury necessitating hospitalization, an explosion or fire not intentionally set by the operator , or total estimated property damage including clean-up and product lost equaling \$50,000 or more. (Note: A release of less than 5 gals may still require reporting. See 195.50(b) and 195.52(a)(4) for additional requirements and exemptions for maintenance work under 5 BBLs). .50 Section 805.1	X			
13.		Immediate notice to NRC (800) 424-8802 , or electronically at http://www.nrc.uscg.mil , of certain events, and additional report if significant new information becomes available. Operator must have a written procedure for calculating an initial estimate of the amount of product released in an accident. (Amdt. 195-95, 75 FR 72878, November 26, 2010, eff. 1/1/2011). .52 Section 805.2	X			
14.		Accident Report - file as soon as practicable, but no later than 30 days after discovery. Submittal must be electronically to http://pipelineonlinereporting.phmsa.dot.gov (Amdt. 195-95, 75 FR 72878, November 26, 2010). .54(a) Section 810.1	X			
15.		Supplemental report - required within 30 days of information change/addition .54(b) Section 810.2	X			
16.		Safety-related conditions (SRC) - criteria .55 Appendix 600A	X			
17.		SRC Report is required to be filed within five (5) working days of the determination and within ten (10) working days after discovery .56(a) Appendix 600A-4	X			
18.		SCR Report requirements, including corrective actions (taken and planned) .56(b) Appendix 600A-5	X			
19.	195.402(a) 195.402(c)(2)	Reports (except SRCR and offshore pipeline condition reports) must be submitted electronically to PHMSA at http://portal.phmsa.dot.gov/pipeline unless an alternative reporting method is authorized IAW with paragraph (d) of this section. (Amdt. 195-95, 75 FR 72878, Nov. 26, 2010, eff. 1/1/2011). Section 810.1	X			
20.		Each operator must obtain an OPID, validate its OPIDs, and notify PHMSA of certain events at http://portal.phmsa.dot.gov/pipeline (Amdt. 195-95, 75 FR 72878, Nov.26, 2010, eff. 1/1/2011). .64(a-d) Section 800.2	X			
WAC 480-75 REPORTING PROCEDURES			S	U	N/A	N/C
21.	480-75-610	Reporting of proposed pipeline construction 45 days prior to construction Section 602(d)	X			
22.	480-75-620	Providing notice of hydrotest to change MOP Section 219	X			
23.	480-75-630	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 2 hours of discovery) for events which results in; a) A fatality; (b) Personal injury requiring hospitalization; (c) Fire or explosion not intentionally set by the pipeline company; (d) Spills of five gallons or more of product from the pipeline; (e) Damage to the property of the pipeline company and others of a	X			

SUBPART B - REPORTING PROCEDURES			S	U	N/A	N/C
		combined total cost exceeding twenty-five thousand dollars (automobile collisions and other equipment accidents not involving hazardous liquid or hazardous-liquid-handling equipment need not be reported under this rule); (f) A significant occurrence in the judgment of the pipeline company, even though it does not meet the criteria of (a) through (e) of this subsection; (g) The news media reports the occurrence, even though it does not meet the criteria of (a) through (f) of this subsection. Section 805.2(e)				
24.	480-75-630(2)	Written reports to the commission within 30 calendar days of the incident. The report must include the following: a) Name(s) and address(es) of any person or persons injured or killed or whose property was damaged; (b) The extent of injuries and damage; (c) A description of the incident including date, time, and place; (d) A description and maximum operating pressure of the pipeline implicated in the incident and the system operating pressure at the time of the incident; (e) The date and time the pipeline returns to safe operations; and (f) The date, time, and type of any temporary or permanent repair. Section 810.3	X			
25.	480-75-630(3)	Notification within 24 hours of emergency situations including emergency shutdowns, material defects or physical damage that impairs serviceability? Section 810.3	X			
26.	480-75-630(4)	Filing Reports of Damage to Hazardous Liquid Pipeline Facilities to the commission. (eff. 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form)				
27.	480-75-630(4)(a)	Does the operator report to the commission the requirements set forth in RCW 19.122.053(3) (a) through (n) Section 208.3(c)	X			
28.	480-75-630(4)(b)	Does the operator report the name, address, and phone number of the person or entity that the company has reason to believe may have caused damage due to excavations conducted <u>without facility locates</u> first being completed? Section 208.3(d)	X			
29.	480-75-630(4)(c)	Does the operator retain all damage and damage claim records it creates related to damage events reported under 93-200(7)(b), including photographs and documentation supporting the conclusion that a facilities locate was not completed? Note: Records maintained for two years and made available to the commission upon request. Section 208.3(e)	X			
30.	480-75-630(5)	Does the operator provide the following information to excavators who damage hazardous liquid pipeline facilities? Section 208.3(f)				
31.	480-75-630(5)(a)	<ul style="list-style-type: none"> Notification requirements for excavators under RCW 19.122.050(1) 	X			
32.	480-75-630(5)(b)	<ul style="list-style-type: none"> A description of the excavator's responsibilities for reporting damages under RCW 19.122.053; and 	X			
33.	480-75-630(5)(c)	<ul style="list-style-type: none"> Information concerning the safety committee referenced under RCW 19.122.130, including committee contact information, and the process for filing a complaint with the safety committee. 	X			
34.	480-75-630(6)	Reports to the commission only when the operator or its contractor observes or becomes aware of the following activities... <ul style="list-style-type: none"> An excavator digs within thirty-five feet of a transmission pipeline, as defined by RCW 19.122.020(26) without first obtaining a facilities locate; (630(6)(a) A person intentionally damages or removes marks indicating the location or presence of hazardous liquid pipeline facilities. 630(6)(b) Section 208.3(g) 	X			

Comments:

Item 15 – Procedure does not include timeframe to submit

SUBPART C – INTERNAL DESIGN PRESSURE PROCEDURES			S	U	N/A	N/C
35.	195.402(c) 195.422	Internal design pressure for pipe in a pipeline is determined in accordance with the requirements of this section and the formula: $P = (2 St/D) \times E \times F$.106 Section 602(g)	X			

SUBPART C - PASSAGE OF INTERNAL INSPECTION DEVICE PROCEDURES			S	U	N/A	N/C
36.	195.402(c) 195.422	Each new pipeline or each section of a pipeline which pipe or components has been replaced must be designed and constructed to accommodate the passage of instrumented internal inspection devices that are applicable to this section .120(a) Section 602.11	X			

Comments:

SUBPART D – WELDING, NDT, and REPAIR /REMOVAL PROCEDURES			S	U	N/A	N/C
Compliance with welding requirements for pipe replaced or repaired in the course of pipeline maintenance is required by §195.422 and §195.200.						
37.	195.402(c) 195.422	Welding must be performed by qualified welders using qualified welding procedures. .214(a) Section 521	X			
38.		Are welding procedures qualified in accordance with Sec. 5 of API 1104 or Section IX of ASME Boiler & Pressure Code? Welding Specification & Testing Procedures	X			
39.		Welding procedures must be qualified by destructive testing. Welding Specification & Testing Procedures	X			
40.		Each welding procedure must be recorded in detail including results of qualifying tests. .214(b) Welding Specification & Testing Procedures	X			
41.		Welders must be qualified in accordance with Section 6 of API Standard 1104 (20th edition 2007, including errata 2008) or Section IX of the ASME Boiler and Pressure Vessel Code (2007 edition, July 1, 2007) , except that a welder qualified under an earlier edition than currently listed in 195.3 may weld, but may not re-qualify under that earlier edition. (Amdt 195-94 Pub. 8/11/10 eff. 10/01/10). .222(a) Section 521	X			
42.		Welders may not weld with a particular welding process unless, within the preceding 6 calendar months, the welder has--(1) Engaged in welding with that process; and (2) Had one weld tested and found acceptable under Section 9 of API 1104. .222(b) Section 521	X			
43.	195.402(c) 195.422	Arc burns must be repaired. .226(a) Section 527	X			
44.		Do arc burn repair procedures require verification of the removal of the metallurgical notch by nondestructive testing? (Ammonium Persulfate). Pipe must be removed for non-repairable notches. .226(b) Section 527	X			
45.		The ground wire may not be welded to the pipe/fitting being welded. .226(c) Section 527	X			
Nondestructive Testing Procedures						
46.	195.402(c) 195.422	Do procedures require welds to be nondestructively tested to ensure their acceptability according to API 1104 and as per 195.228(b) and per the requirements of 195.234 in regard to the number of welds to be tested? Section 521.1	X			
47.		Nondestructive testing of welds must be performed: .234(b)				
48.		1. In accordance with written procedures for NDT Section 521.1.1	X			
49.		2. By qualified personnel Section 521.1.1	X			
50.		3. By a process that will indicate any defects that may affect the integrity of the weld Section 521.1.1	X			
51.	Records of the total number of girth welds and the number nondestructively tested, including the number rejected and the disposition of each rejected weld, must be maintained. .266 Section 703	X				
Repair or Removal of Weld Defect Procedures						
52.	195.402(c) 195.422	Welds that are unacceptable must be removed and/or repaired. See .228 and .230 for exceptions. .230 Section 521.2	X			

Comments:

Item 38 – Manual does not specify API 1104 Section 5, 12, Appendix A or ASME Section IX

SUBPART E - PRESSURE TESTING PROCEDURES		S	U	N/A	N/C
53.	Pipelines, and each pipeline segment that has been relocated, replaced, or otherwise changed, must be pressure tested without leakage (see .302(b), (c), and .305(b) for exceptions). .302(a) Section 585.1	X			
54.	Except for lines converted under §195.5 , the following pipelines may be operated without having been pressure tested per Subpart E and without having established MOP under 195.406(a)(5) [80% of the 4 hour documented test pressure, or 80% of the 4 hour documented operating pressure] .302(c) - Intrastate liquid lines constructed before 10/21/85 (excluding HVL onshore or low stress lines). .302(b)(iii) - Carbon dioxide pipeline constructed before 07/12/91 that is located in a rural area as part of production field distribution system. .302(b)(2)(ii) - Any low-stress pipeline constructed before 8/11/1994, that does not transport HVL. .302(b)(3) - Those portions of older hazardous liquid and carbon dioxide pipelines for which an operator has elected the risk-based alternative under §195.303 and which are not required to be tested based on the risk-based criteria. .302(b)(4)/.303 <i>Note: (An operator that elected to follow a risk-based alternative must have developed plans that included the method of testing and a schedule for the testing by December 7, 1998. The compliance deadlines for completion of testing are as shown in the table in §195.303, and in no case was testing to be completed later than 12/07/2004).</i>				
55.					
56.					
57.					
58.	Have pipelines <u>other than those described above</u> been pressure tested per Subpart E? TM-SRT-005 (585.1)	X			
59.	If pipelines <u>other than those described above</u> have not been pressure tested per Subpart E, has MOP been established under 195.406(a)(5) , in accordance with .302(c)? <i>Note: Establishing MOP under 195.406(a)(5) only applies to specified "older" pipelines constructed prior to the dates in .302(b).</i>			X	
60.	Test pressure must be maintained for at least 4 continuous hours at a pressure equal to 125 percent, or more, of the MOP. If not visually inspected during the test, at least an additional 4 hours at 110 percent of MOP is required. .304 TM-SRT-005 (585.1)	X			
61.	All pipe, all attached fittings, including components, must be pressure tested in accordance with §195.302 . .305(a) Section 585.2	X			
62.	A component, other than pipe, that is the only item being replaced or added to the pipeline system need not be hydrostatically tested under paragraph (a) of this section if the manufacturer certifies that either: (1) The component was hydrostatically tested at the factory; or (2) The component was manufactured under a quality control system that ensures each component is at least equal in strength to a prototype that was hydrostatically tested at the factory. .305(b) Section 585.2	X			
63.	Appropriate test medium .306 Section 585.5	X			
64.	Pipe associated with tie-ins must be pressure tested. .308 Section 585.6	X			
65.	Test records must be retained for useful life of the facility. .310(a) Section 704	X			
	Does the record required by paragraph (a) of this section include: .310(b)				
66.	Pressure recording charts. .310(b)(1) Section 585.7	X			
67.	Test instrument calibration data. .310(b)(2) Section 585.7	X			
68.	Name of the operator, person responsible, test company used, if any. .310(b)(3) Section 585.7	X			
69.	Date and time of the test. .310(b)(4) Section 585.7	X			
70.	Minimum test pressure. .310(b)(5) Section 585.7	X			
71.	Test medium. .310(b)(6) Section 585.7	X			
72.	Description of the facility tested and the test apparatus. .310(b)(7) Section 585.7	X			
73.	Explanation of any pressure discontinuities, including test failures that appear on the pressure recording charts. .310(b)(8) Section 585.7	X			

195.402(c)
195.422
480-93-420

SUBPART E - PRESSURE TESTING PROCEDURES			S	U	N/A	N/C
74.		Where elevation differences in the test section exceed 100 feet , a profile of the elevation over entire length of the test section must be included. .310(b)(9) Section 585.7	X			
75.		Temperature of the test medium or pipe during the test period. Amdt 195-78 pub. 9/11/03, eff. 10/14/03. .310(b)(10) Section 585.7	X			
76.		Signature of certifying agent. WAC 480-75-420 (4)(b) Section 585.7	X			
77.		Beginning and ending times of the test. WAC 480-75-420 (4)(c) Section 585.7	X			
78.		Highest and lowest pressure achieved. WAC 480-75-420 (4)(e) Section 585.7	X			
79.		Is report submitted to the commission 45 days prior to a hydro test, if test was used to raise the MOP (after 9/26/02)? WAC 480-75-620 Section 219	X			

Comments:

Item 59 – Lines were pressure tested

SUBPART F - OPERATIONS & MAINTENANCE PROCEDURES			S	U	N/A	N/C
80.	195.402(a)	a. Has the operator prepared a manual for normal operations & maintenance activities & handling abnormal operations & emergencies? .402 Section 201	X			
81.		b. Procedures for reviewing the manual at intervals not exceeding 15 months, but at least each calendar year? Section 201.1	X			
82.		c. Appropriate parts must be kept at locations where O&M activities are conducted. Section 606.1	X			

Comments:

SUBPART F - MAINTENANCE & NORMAL OPERATION PROCEDURES			S	U	N/A	N/C
		Written procedures must be followed to provide safety during maintenance and normal operations. Does the operator have procedures for: .402(c)				
83.	195.402(a)	Determining which pipeline facilities are located in areas that would require an immediate response by the operator to prevent hazards to the public if the facilities failed or malfunctioned? .402(c)(4) Section 202	X			
84.		Analyzing pipeline accidents to determine their causes? .402 (c)(5) Section 811.1	X			
85.		Minimizing the potential for hazards identified under paragraph (c)(4) and minimizing the possibility of recurrence of accidents analyzed under paragraph (c)(5)? .402(c)(6) Section 811.2	X			
86.		Starting up and shutting down any part of the pipeline system in a manner designed to assure operation within limits prescribed by §195.406 , considering the hazardous liquid or carbon dioxide in transportation, variations in the altitude along the pipeline, and pressure monitoring and control devices? .402(c)(7) TO-SRT-024, TO-SRT-014	X			
87.		A pipeline that is not equipped to fail safe monitoring from an attended location pipeline pressure during startup until steady state pressure and flow conditions are reached and during shut-in to assure operation within limits prescribed by §195.406 ? .402(c)(8) Section 200.2.2	X			
88.		Facilities not equipped to fail safe that are identified under §195.402(c)(4) or that control receipt and delivery of hazardous liquid, detecting abnormal operating conditions by monitoring pressure, temperature, flow or other appropriate operational data and transmitting this data to an attended location? .402(c)(9) Section 200.2.2	X			
89.		Abandoning pipeline facilities, including safe disconnection from an operating pipeline system, purging of combustibles, and sealing abandoned environmental hazards .402(c)(10) Section 203	X			
90.		Reporting abandoned pipeline facilities offshore, or onshore crossing commercially navigable waterways per 195.59.			X	
91.		Minimizing the likelihood of accidental ignition of vapors in areas near facilities identified under paragraph (c)(4) of this section where the potential exists for the presence of flammable liquids or gases? .402(c)(11) Section 502	X			

SUBPART F - MAINTENANCE & NORMAL OPERATION PROCEDURES			S	U	N/A	N/C
92.		Establishing and maintaining liaison with fire, police, and other appropriate public officials to learn the responsibility and resources of each hazardous liquid pipeline emergency. .402(c)(12) Section 204	X			
93.		Periodically reviewing the work done by operator's personnel to determine the effectiveness of the procedures used in normal operation and maintenance and taking corrective action where deficiencies are found? .402(c)(13) Section 216	X			
94.		Taking adequate precautions in excavated trenches to protect personnel from hazards of unsafe accumulations of vapor or gas, making available when needed at the excavation site, emergency rescue equipment, including a breathing apparatus and, a rescue harness and line. .402(c)(14) Section 503.2, 504	X			
Comments: Item 90 – No pipelines that cross navigable waterways						

MAINTENANCE & NORMAL OPERATION PROCEDURES CONT:			S	U	N/A	N/C
95.	.402(c)(15)	Implementing the applicable control room management procedures required by 195.446 . (Amdt. 195-93, 74 FR 63310, December 3, 2009, eff. 2/1/2010). .402(c)(15)			X	
96.	480-75-300	Providing leak detection under flow and no flow conditions and including a procedure for responding to alarm SRT Pasco Rail Diesel Line Section 4.12, SRT Inbound/Outbound section 4.2.2	X			
97.	480-75-330	Responding to breakout tank overflow alarms SRT Inbound/Outbound section 4.2.4	X			
98.	480-75-400	Backfilling pipe Section 504.2	X			
99.	480-75-410	Using a holiday detector to check coating condition prior to backfilling Appendix 500C (5.2)	X			
100.	480-75-460	100% Inspection of welds. Section 521.1.1	X			
101.	480-75-550	Reviewing change in class location for pipelines installed after 9/26/2003.			X	

ABNORMAL OPERATION PROCEDURES (CONTROL CENTER FUNCTION)			S	U	N/A	N/C
		The O&M manual must contain written procedures to provide safety when operating design limits have been exceeded. Does the operator have procedures for: .402(d)				
		Responding to, investigating, and correcting the cause of: .402(d)(1)				
102.	195.402(a)	i. Unintended closure of valves or shutdowns? SRT In/Outbound Pipeline 5.2.1, SRT Pasco Rail Diesel 5.0	X			
103.		ii. An increase or decrease in pressure or flow rate outside normal operating limits? SRT In/Outbound Pipeline 5.2.2, SRT Pasco Rail Diesel 5.0	X			
104.		iii. Loss of communications? SRT In/Outbound Pipeline 5.2.4, SRT Pasco Rail Diesel 5.0	X			
105.		iv. The operation of any safety device? SRT In/Outbound Pipeline 5.2.6, SRT Pasco Rail Diesel 5.0	X			
106.		v. Any other malfunction of a component, deviation from normal operation, or personnel error which could cause a hazard to persons or property? SRT In/Outbound Pipeline 5.2.7, SRT Pasco Rail Diesel 5.0	X			
107.		Checking variations from normal operation after abnormal operations have ended at sufficient critical locations in the system to determine continued integrity and safe operations? .402(d)(2) SRT In/Outbound Pipeline 5.2.9, SRT Pasco Rail Diesel 5.0	X			
108.		Correcting variations from normal operation of pressure and flow equipment controls? .402(d)(3) SRT In/Outbound Pipeline 5.2.2, SRT Pasco Rail Diesel 5.0	X			
109.		Does operating personnel notify responsible operator personnel where notice of an abnormal operation is received? .402(d)(4) SRT In/Outbound Pipeline 5.2, SRT Pasco Rail Diesel 5.0	X			
110.		Periodically reviewing the response of operating personnel to determine the effectiveness of the procedures and taking corrective action where deficiencies are found? .402(d)(5) Section 216(a)	X			
Comments:						

Comments:

Item 95 – No control room

Item 101 – No pipeline constructed after 9/26/2003

EMERGENCY PROCEDURES			S	U	N/A	N/C
		The O&M manual must include written procedures to provide safety when an emergency condition occurs. Does the operator have procedures for: .402(e)				
111.	195.402(a)	Receiving, identifying, and classifying notices of events which need immediate response by the operator or fire, police, or other, and notifying appropriate operator's personnel for corrective action? .402(e)(1) Note: Including third-party damage Integrated Contingency Plan (Section 2, 5)	X			
112.		Making a prompt and effective response to a notice of each type of emergency, fire, explosion, accidental release of hazardous liquid, operational failure, natural disaster affecting the pipeline? .402(e)(2) Note: Including third party damage Section 208.3, 105, Integrated Contingency Plan	X			
113.		Making personnel, equipment, instruments, tools, and materials available at the scene of an emergency? .402(e)(3) Integrated Contingency Plan	X			
114.		Taking action; such as emergency shutdown or pressure reduction, to minimize release of liquid at a failure site? .402(e)(4) Integrated Contingency Plan (Section 2.2, 2.4)	X			
115.		Controlling the release of liquid at the failure site? .402(e)(5) Integrated Contingency Plan (Section 2)	X			
116.	195.402(a)	Minimizing the public .402(e)(6) exposure and accidental ignition, evacuation, and halting traffic on roads, railroads, etc.? Integrated Contingency Plan (Section 2)	X			
117.		Notifying fire, police, and others of hazardous liquid emergencies and preplanned responses including HVLs ? .402(e)(7) Integrated Contingency Plan (Section 2.2)	X			
118.		Determining extent and coverage of vapor cloud and hazardous areas of HVLs by using appropriate instruments? .402(e)(8)			X	
119.		Post-incident review of employee's activities to determine if procedures were effective and corrective action was taken? .402(e)(9) Integrated Contingency Plan (Section 8.3)	X			
120.		Actions to be taken by a controller during an emergency in accordance with 195.446 . (Amdt. 195-93, 74 FR 63310, December 3, 2009, eff. 2/1/2010). .402(e)(10)			X	

Comments:

Item 118 – Tidewater does not transport HVLs

Item 120 – Tidewater has no control room

EMERGENCY RESPONSE TRAINING PROCEDURES (CONTROL CENTER & FIELD)			S	U	N/A	N/C
		Each operator shall establish and conduct a written continuing training program to instruct operating and maintenance personnel to: .403(a)				
121.	195.402(a)	Carry out the emergency response procedures established under §195.402. .403(a)(1)	X			
122.		Know the characteristics and hazards of liquids or carbon dioxide transported, including in the case of HVL , flammability, of mixtures with air, odorless vapors, and water reactions. .403(a)(2)	X			
123.		Recognize conditions that are likely to cause emergencies; predict the consequences of malfunction or failures and take appropriate actions. .403(a)(3)	X			
124.		Take steps necessary to control any accidental release of hazardous liquid or carbon dioxide and to minimize the potential for fire, explosion, toxicity, or environmental damage. .403(a)(4)	X			
125.		Learn the potential causes, types, sizes, and consequences of fire and the appropriate use of portable fire extinguishers and other on-site fire control equipment, involving, where feasible, a simulated pipeline emergency condition. .403(a)(5) Section 209(a)	X			
126.		Instructions to enable O&M personnel to recognize and report potential safety related conditions. .402(f) Appendix 600A-3, 4	X			
			At intervals not exceeding 15 months, but at least once each calendar year: .403(b)			
127.		Review with personnel their performance in meeting the objectives of the emergency response training program .403(b)(1) Section 209(c)	X			
128.		Make appropriate changes to the emergency response training program .403(b)(2) Section 209(c)	X			

EMERGENCY RESPONSE TRAINING PROCEDURES (CONTROL CENTER & FIELD)			S	U	N/A	N/C
129.		Require and verify that supervisors maintain a thorough knowledge of the emergency response procedures for which they are responsible. .403(c) Section 209(d)	X			

Comments:

MAPS and RECORDS PROCEDURES			S	U	N/A	N/C
130.	195.402(a) & WAC 480-75-600	Making construction records, maps, and operating history available as necessary for safe operation and maintenance. .402(c)(1) Section 702	X			
		Each operator shall maintain current maps and records of its pipeline system that include at least the following information: .404(a) Updated within 6 months 480-75-600				
		Location and identification of the following facilities: .404(a)(1) Section 705(a)				
131.		i. Breakout tanks Section 705(a)	X			
132.		ii. Pump stations Section 705(a)	X			
133.		iii. Scraper and sphere facilities Section 705(a)	X			
134.		iv. Pipeline valves Section 705(a)	X			
135.		v. Facilities to which §195.402(c)(9) applies Section 705(a)	X			
136.		vi. Rights-of-way Section 705(a)	X			
137.		vii. Safety devices to which §195.428 applies Section 705(a)	X			
138.		All crossings of public roads, railroads, rivers, buried utilities and foreign pipelines. .404(a)(2) Section 705(a)	X			
139.		The maximum operating pressure of each pipeline. .404(a)(3) Section 705(a)	X			
140.		The diameter, grade, type, and nominal wall thickness of all pipe. .404(a)(4) Section 705(a)	X			
		Each operator shall maintain for at least 3 years daily operating records for the following: .404(b)				
141.		The discharge pressure at each pump station. .404(b)(1) Section 705(a)	X			
142.	Any emergency or abnormal operation to which the procedures under §195.402 apply. .404(b)(2) Section 705(a)	X				
	Each operator shall maintain the following records for the periods specified: .404(c)					
143.	The date, location, and description of each repair made on the pipe and maintain it for the life of the pipe . .404(c)(1) Section 705(b)	X				
144.	The date, location, and description of each repair made to parts of the pipeline system other than the pipe and maintain it for at least 1 year . .404(c)(2) Section 705(b)	X				
145.	Each inspection and test required by Subpart F shall be maintained for at least 2 years, or until the next inspection or test is performed, whichever is longer . .404(c)(3) Section 705(b)	X				

Comments:

MAXIMUM OPERATING PRESSURE PROCEDURES (MOP) - ALL SYSTEMS			S	U	N/A	N/C
	195.402(a)	Except for surge pressures and other variations from normal operations, the MOP may not exceed any of the following: .406(a)				
146.		The internal design pressure of the pipe determined by §195.106 . Amt. 195-86 Pub. 06/09/06 eff. 07/10/06 .406(a)(1) Section 218.1(a)	X			
147.		The design pressure of any other component on the pipeline. .406(a)(2) Section 218.1(a)	X			
148.		80% of the test pressure (Subpart E). .406(a)(3) Section 218.1(a)	X			
149.		80% of the factory test pressure or of the prototype test pressure for any individual component. .406(a)(4) Section 218.1 (a)	X			

MAXIMUM OPERATING PRESSURE PROCEDURES (MOP) - ALL SYSTEMS			S	U	N/A	N/C
150.		80% of the test pressure or the highest operating pressure for a minimum of 4 hours for a pipeline that has not been tested under Subpart E. .406(a)(5) Section 218.1(a)	X			
151.		The pipeline may not be operated at a pressure that exceeds 110% of the MOP during surges or other variations from normal operations: .406(b) Section 218.1(b)	X			
152.		Adequate controls and protective equipment must be installed to prevent the pressure from exceeding 110% of the MOP. Section 218.1	X			

Comments:

COMMUNICATION PROCEDURES (CONTROL CENTER)			S	U	N/A	N/C
153.		Operator must have a communication system to provide for the transmission of information needed for the safe operation of its pipeline system. .408(a) Section 106	X			
		Does the communication system required by paragraph (a) include means for: .408(b)				
154.	.402(a)	Monitoring operational data as required by §195.402(c)(9). .408(b)(1) Section 106(a)	X			
155.		Receiving notices from operator personnel, the public, and others about abnormal or emergency conditions and initiating corrective actions. .408(b)(2) Section 106(b)	X			
156.		Conducting two-way vocal communication between a control center and the scene of abnormal operations and emergencies. .408(b)(3) Section 106(c)	X			
157.		Providing communication with fire, police, and other appropriate public officials during emergency conditions, including a natural disaster. .408(b)(4) Section 106(c)	X			

Comments:

LINE MARKER PROCEDURES			S	U	N/A	N/C
158.	480-75-540	Markers checked annually and replaced within 30 days Section 211.1(d)	X			
159.	195.402(a)	Line markers must be placed over each buried pipeline in accordance with the following: .410(a) Section 211.1(a), (b)	X			
160.		Located at each public road crossing, railroad crossing, and sufficient number along the remainder of each buried line so that its location is accurately known .410(a)(1) Section 211.1(a)	X			
161.		Must have the correct characteristics and information .410(a)(2) Section 211.1(b)	X			
162.		Must be placed where pipelines are aboveground in areas that are accessible to the public .410(c) Section 211.1(d)	X			

Comments:

INSPECTION RIGHTS-of -WAY & CROSSINGS UNDER NAVIGABLE WATER PROCEDURES			S	U	N/A	N/C
163.	480-75-640	Depth of Cover - For pipelines constructed after 4/1/70, depth of cover surveys every five years or every three years for areas subject to erosion or subsoiling Section 602.3.1	X			
164.	195.402(a)	Operator must inspect the right-of-way weekly (unless weather impedes flyovers when applicable) WAC 480-75-530 Section 207.1	X			
165.		Operator must inspect each crossing under a navigable waterway to determine the crossing condition at intervals not exceeding 5 years. .412(b)			X	

Comments:

Item 165 – No navigable waterway crossings

UNDERWATER INSPECTION PROCEDURES of OFFSHORE PIPELINES			S	U	N/A	N/C
		When the operator discovers that a pipeline it operates is exposed on the seabed or constitutes a hazard to navigation, does the operator: .413(c)				
166.		Promptly, but no later than 24 hours after discovery, notify the NRC by phone. .413(c)(1)			X	

UNDERWATER INSPECTION PROCEDURES of OFFSHORE PIPELINES			S	U	N/A	N/C
167.	195.402(a)	Promptly, but not later than 7 days after discovery, mark the location of the pipeline in accordance with 33 CFR Part 64 at each end of the pipeline segment and at intervals of not over 500 yards long , except that a pipeline segment less than 200 yards long need only be marked at the center. .413(c)(2)			X	
168.		Within 6 months after discovery, or not later than November 1 of the following year if the 6 month period is after November 1 of that year the discovery is made, place the pipeline so that the top of the pipe is 36 inches below the seabed for normal excavation or 18 inches for rock excavation. .413(c)(3)			X	
169.		Offshore pipeline condition reports - must be filed within 60 days after the inspections .57			X	
Comments: Items 166-169 – Tidewater has no pipelines in Gulf of Mexico						

VALVE MAINTENANCE PROCEDURES			S	U	N/A	N/C
170.	195.402(a)	Operator must maintain each valve that is necessary for the safe operation of its pipeline system in good working order at all times. .420(a) Section 580	X			
171.		Operator must inspect each mainline valve to determine that it is functioning properly at intervals not exceeding 7 ½ months , but at least twice each calendar year. .420(b) Section 580(c)	X			
172.		Operator must provide protection for each valve from unauthorized operation and from vandalism. .420(c) Section 580(g)	X			

Comments:

PIPELINE REPAIR PROCEDURES			S	U	N/A	N/C
173.	WAC 480-75-440	Repairs made in accordance with ASME B31.4 Section 520	X			
174.	195.402(a)	Operator must, in repairing its pipeline systems, insure that the repairs are made in a safe manner and are made so as to prevent damage to persons and property. .422(a) Section 500.1	X			
175.		No operator may use any pipe, valve, or fitting, for replacement in repairing pipeline facilities, unless it is designed and constructed as required by this part. .422(b) Section 500.1	X			

Comments:

PIPE MOVEMENT PROCEDURES			S	U	N/A	N/C
176.	480-75-500	For evaluating pipe conditions during pipe movement including API 1117 stress calculations? Section 565(a)	X			
177.	195.402(a)	When moving any pipeline, the operator must reduce the pressure for the line segment involved to 50% of the MOP . .424(a) Section 565(a)	X			
		For HVL lines joined by welding, the operator must: .424(b)				
178.		Move the line when it does not contain HVL , unless impractical. .424(b)(1)			X	
179.		Have procedures under §195.402 containing precautions to protect the public. .424(b)(2)			X	
180.		Reduce the pressure for the line segment involved to the lower of 50% of the MOP or the lowest practical level that will maintain the HVL in a liquid state. (Minimum = V.P. + 50 psig) .424(b)(3)			X	
		For HVL lines not joined by welding, the operator must: .424(c)				
181.		Move the line when it does not contain HVL , unless impractical. .424(c)(1)			X	

Comments:					
182.		Have procedures under §195.402 containing precautions to protect the public. .424(c)(2)			X
183.		Isolate the line to prevent flow of the HVL. .424(c)(3)			X

Comments:
Items 178-183 – Tidewater does not transport HVLs

SCRAPER and SPHERE FACILITY PROCEDURES			S	U	N/A	N/C
184.	195.402(a)	Operator must have a relief device capable of safely relieving the pressure in the barrel before insertion or removal of scrapers or spheres. .426 Section 407	X			
185.		Operator must have a suitable device to indicate that pressure has been relieved, or a means to prevent insertion. Section 407	X			

Comments:

OVERPRESSURE SAFETY DEVICE PROCEDURES			S	U	N/A	N/C
186.	195.402(a)	Operator must inspect and test each pressure limiting device, relief valve, pressure regulator, or other items of pressure control equipment to determine that it is functioning properly, in good mechanical condition, has adequate capacity, and is reliable. .428(a) Section 590, TM-SRT-004	X			
		Operator must inspect and test overpressure safety devices at the following intervals:				
187.		1. Non-HVL pipelines at intervals not to exceed 15 months, but at least once each calendar year. Section 590(c)	X			
188.		2. HVL pipelines at intervals not to exceed 7-1/2 months, but at least twice each calendar year.			X	
189.		Operator must inspect and test relief valves on HVL breakout tanks at intervals not exceeding 5 years. .428(b)			X	
190.		Aboveground breakout tanks that are constructed or significantly altered according to API Standard 2510 after October 2, 2000, must have an overflow protection system installed according to section 5.1.2 of API Standard 2510.	X			
191.	Tanks over 600 gallons (2271 liters) constructed or significantly altered after October 2, 2000, must have overflow protection according to API Recommended Practice 2350 unless operator noted in procedures manual (§195.402) why compliance with API RP 2350 is not necessary for the safety of a particular breakout tank. .428(c) Section 205.8					
		After October 2, 2000, the requirements of paragraphs (a) and (b) of this section for inspection and testing of pressure control equipment apply to the inspection and testing of overflow protection systems. .428(d) Section 205.8	X			

Comments:
Item 188 – Tidewater does not transport HVLs
Item 189 – Tidewater has no HVL breakout tanks

FIREFIGHTING EQUIPMENT PROCEDURES			S	U	N/A	N/C
192.	195.402(a)	Operator must maintain adequate firefighting equipment at each pump station and breakout tank areas. .430 (a-c) Section 210	X			
		The equipment must be:				
193.		a. In proper operating condition at all times. Section 210	X			
194.		b. Plainly marked so that its identity as firefighting equipment is clear. Section 210	X			
195.		c. Located so that it is easily accessible during a fire. Section 210	X			

Comments:

BREAKOUT TANK PROCEDURES

196.	195.402(a)	Utilize PHMSA Form #10 for all Breakout Tank Procedures				
------	------------	---	--	--	--	--

SIGN PROCEDURES

			S	U	N/A	N/C
197.		Operator must maintain signs visible to the public around each pumping station and breakout tank area. Section 211.2	X			
198.	.402(a)	.434 Signs must contain the name of the operator and a telephone number (including area code) where the operator can be reached at all times. Amdt 195-78 pub. 9/11/03, eff. 10/14/03. Section 211.2	X			

Comments:

SECURITY of FACILITY PROCEDURES

			S	U	N/A	N/C
199.	195.402(a)	Operator must provide protection for each pumping station and breakout tank area and other exposed facilities from vandalism and unauthorized entry. .436 Section 212	X			

Comments:

SMOKING OR OPEN FLAME PROCEDURES

			S	U	N/A	N/C
200.	195.402(a)	Operator must prohibit smoking and open flames in each pump station and breakout tank area where there is the possibility of the presence of hazardous liquids or flammable vapors. .438 Section 213	X			

Comments:

PUBLIC AWARENESS PROGRAM PROCEDURES
(Also in accordance with API RP 1162)

			S	U	N/A	N/C
1.	192.402(a)	Public Awareness Program in accordance with API RP 1162, (1 st edition Dec-2003) .440				
2.		The operators program must specifically include provisions to educate the public, appropriate government organizations, and persons engaged in excavation related activities on: .440(d) Section 214				
3.		(1) Use of a one-call notification system prior to excavation and other PA Section 2.5	X			
4.		(2) Possible hazards associated with unintended releases from a hazardous liquids or carbon dioxide pipeline facility; PA Section 2.5	X			
5.		(3) Physical indications of a possible release; PA Section 2.5	X			
6.		(4) Steps to be taken for public safety in the event of a hazardous liquid or carbon dioxide pipeline release; PA Section 2.5	X			
7.		(5) Procedures to report such an event (to the operator). PA Section 2.5	X			
8.		Does program include activities to advise affected municipalities, school districts, businesses, and residents of pipeline facility locations? .440(e) PA Section 3.4	X			
9.		The operator's program and the media used must be comprehensive enough to reach all areas the operator transports gas. .440(f) PA Section 2.2, 2.3	X			
10.		Is the program conducted in English and any other languages commonly understood by a significant number of the population? .440(g) PA Section 2.5, 3.4	X			
11.		IAW API RP 1162, the operator's program should be reviewed for effectiveness within four years of the date the operator's program was first completed. <u>For operators in existence on June 20, 2005</u> , who must have completed their written programs no later than June 20, 2006, the first evaluation is due no later than June 20, 2010 . .440(i) PA Section 2.8	X			

Comments:

DAMAGE PREVENTION PROGRAM PROCEDURES (Also in accordance with API 1162)				S	U	N/A	N/C	
201.	.402(a)	.442(a)	Is there a written program in place to prevent damage by excavation activities applicable to the operator's pipelines? Section 208	X				
202.		.442(b)	Does the operator participate in a qualified One-Call program? Section 208.1	X				
203.		.442(c)(1)	Include the identity, on a current basis, of persons who normally engage in excavation activities in the area in which the pipeline is located. Section 208.1	X				
		.442(c)(2)	Provide for notification to the public in the vicinity of the pipeline and actual notification to the persons identified in paragraph (c)(1) of this section of the following, as often as needed to make them aware of the damage prevention program: Section 208, PA Program					
204.		i.	The program's existence and purpose.	X				
205.		ii.	How to learn the location of underground pipelines before excavation activities are begun.	X				
206.		.442(c)(3)	Provide a means of receiving and recording notification of planned excavation activities. Section 208.1, 208.2	X				
207.		.442(c)(4)	If the operator has buried pipelines in the area of excavation activity, provide for actual notification of persons who give notice of their intent to excavate of the type of temporary marking to be provided and how to identify the markings. Section 208.1	X				
208.		.442(c)(5)	Provide for marking of buried pipelines in the area of excavation activity within 2 business days. WAC 480-75-270 RCW 19.122.030 Section 208.2(a)	X				
		.442(c)(6)	Provide as follows for inspection of pipelines that an operator has reason to believe could be damaged by excavation activities:					
209.		i.	The inspection must be done as frequently as necessary during and after the activities to verify the integrity of the pipeline. Section 208.2(e)	X				
210.		ii.	In the case of blasting, any inspection must include leakage surveys. Section 208.2(f)	X				
211.			Does the operator have directional drilling/boring procedures which include taking actions necessary to protect their facilities from the dangers posed by drilling and other trenchless technologies? Section 208.2	X				
212.			Does the operator review records of accidents and failures due to excavation damage to ensure causes of failures are addressed to minimize the possibility of reoccurrence? Section 208.3	X				
213.		Damage Prevention (Operator Internal Performance Measures) PHMSA – State Program Evaluation Questions						
214.			Does the operator have a quality assurance program in place for monitoring the locating and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices v. 6.0, Best Practice 4-18. Recommended only, not required)				X	
215.			Does operator include performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties?				X	
216.			Do locate contractors address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing levels?				X	
217.			Does the operator periodically review the Operator Qualification plan criteria and methods used to qualify personnel to perform locates? OQ Program	X				
218.			Review operator locating and excavation <u>procedures</u> for compliance with state law and regulations. Section 208	X				
219.		Are locates are being made within the timeframes required by state law and regulations? Examine record sample. Sample Locates	X					
220.		Are locating and excavating personnel properly <u>qualified</u> in accordance with the operator's Operator Qualification plan and with federal and state requirements? OQ Records for Locators	X					

DAMAGE PREVENTION PROGRAM PROCEDURES (State Requirements)		S	U	N/A	N/C
221.	Terminating the flow of hazardous liquid in pipeline immediately upon receiving information of <u>third party damage</u> . RCW 19.122.035 (2) Section 208.3	X			
222.	Has the pipeline company visually inspected the damaged pipeline RCW 19.122.035 (2) Section 208.3	X			
223.	Has the pipeline company determined if the damaged pipeline should be repaired or replaced RCW 19.122.035 (2) Section 208.3	X			
224.	Notification to local first responders and Dept of Ecology of any reportable release? Integrated Contingency Plan	X			

Comments:

Items 214216 – Tidewater does all locating in-house. No contractors/contracts

CPM/LEAK DETECTION PROCEDURES			S	U	N/A	N/C
225.	.402(a)	Each new computational pipeline monitoring (CPM) leak detection system and each replaced component of an existing CPM system must comply with section 4.2 of API 1130, (3rd Edition, September 2007) in its design and with any other design criteria addressed in API 1130 for components of the CPM leak detection system. (Amdt 195-94 Pub. 75 FR 48593 8/11/10 eff. 10/01/10). .134			X	
226.		If a CPM system is installed, operator's procedures for the CPM leak detection system shall comply with API 1130, (3rd Edition, September 2007) in operating, maintaining, testing, record keeping, and dispatching training. (Amdt 195-94, 75 FR 48593 Pub. 8/11/10 eff. 10/01/10). .444; .446(b)(c)			X	

Comments:

Items 225-226 – Tidewater has no CPM leak detection

CONTROL ROOM MANAGEMENT PROCEDURES (Amdt. 195-93, 74 FR 63310, December 3, 2009, eff. 2/1/2010) <i>*Tidewater has no control room*</i>			S	U	N/A	N/C
.402(a)	.446	This section applies to each operator of a pipeline facility with a controller working in a control room who monitors and controls all or part of a pipeline facility through a SCADA system.				
	.446(a)	Operator must develop written procedures no later than August 1, 2011, and implement the procedures no later than February 1, 2013. Amdt. 195-93 Pub. 12/03/09 eff. 02/01/10,			X	
	.446(b)	Operator must define roles and responsibilities of a controller during normal, abnormal, and emergency operating conditions including: (1) When making decisions and taking actions during normal operations; (2) When an abnormal operating condition is detected; (3) During an emergency; (4) A method of recording controller shift-changes and any hand-over of responsibility between controllers.			X	
	.446(c)(1)	Operator must implement API RP 1165, (1st Edition, January 2007) (incorporated by reference, <i>see</i> § 195.3) whenever a SCADA system is added, expanded or replaced, unless the operator demonstrates that certain provisions of API RP 1165 are not practical for the SCADA system used.			X	
	.446(c)(2)	Operator must conduct a point-to-point verification between SCADA displays and related field equipment when field equipment is added or moved and when other changes that affect pipeline safety are made to field equipment or SCADA displays.			X	
	.446(c)(3)	Operator must test and verify an internal communication plan to provide adequate means for manual operation of the pipeline safely, once each calendar year, NTE 15 months.			X	
	.446(c)(4)	Operator must test any backup SCADA systems once each calendar year, NTE 15 months.			X	
	.446(c)(5)	Operator must implement section 5 of API RP 1168, (1st Edition, September 2008) (incorporated by reference, <i>see</i> § 195.3) to establish procedures for when a different controller assumes responsibility, including the content of information to be exchanged.			X	
.446(d)	Operator must implement the following methods to reduce the risk associated with controller fatigue that could inhibit a controller's ability to carry out the defined roles and responsibilities:					

CONTROL ROOM MANAGEMENT PROCEDURES (Amdt. 195-93, 74 FR 63310, December 3, 2009, eff. 2/1/2010) <i>*Tidewater has no control room*</i>			S	U	N/A	N/C
		<ul style="list-style-type: none"> (1) Establish shift lengths and schedule rotations that provide controllers off-duty time sufficient to achieve eight hours of continuous sleep; (2) Educate controllers and supervisors in fatigue mitigation strategies and how off-duty activities contribute to fatigue; (3) Train controllers and supervisors to recognize the effects of fatigue; and (4) Establish a maximum limit on controller hours-of-service, which may provide for an emergency deviation from the maximum limit if necessary for the safe operation of a pipeline facility. 			X	
	.446 (e)	<p>If a SCADA system is used, operator must have a written Alarm Management Plan including the following provisions to:</p> <ul style="list-style-type: none"> (1) Review SCADA safety-related alarm operations using a process that ensures alarms are accurate and support safe pipeline operations; (2) Identify at least once each calendar month points affecting safety that have been taken off scan in the SCADA host, have had alarms inhibited, generated false alarms, or that have had forced or manual values for periods of time exceeding that required for associated maintenance or operating activities; (3) Verify the correct safety-related alarm set-point values and alarm descriptions when associated field instruments are calibrated or changed and once each calendar year, NTE 15 months; (4) Review the alarm management plan required by this paragraph once each calendar year, NTE 15 months, to determine the effectiveness of the plan; (5) Monitor the content and volume of general activity being directed to and required of each controller once each calendar year, NTE 15 months, that will assure controllers have sufficient time to analyze and react to incoming alarms; and (6) Address deficiencies identified through the implementation of paragraphs (e)(1) through (e)(5) of this section. 			X	
	.446 (f)	<p>Assure changes that could affect control room operations are coordinated with the control room personnel by performing each of the following:</p> <ul style="list-style-type: none"> (1) Implement section 7 of API RP 1168 for control room management change and require coordination between control room representatives, operator's management, and associated field personnel when planning and implementing physical changes to pipeline equipment or configuration; and (2) Require field personnel to contact the control room when emergency conditions exist and when making field changes that affect control room operations. 			X	
	.446 (g)	<p>Assure lessons learned from operating experience are incorporated, as appropriate, into control room management procedures by performing each of the following:</p> <ul style="list-style-type: none"> (1) Review accidents that must be reported pursuant to § 195.50 and 195.52 to determine if control room actions contributed to the event and, if so, correct, where necessary, deficiencies related to: <ul style="list-style-type: none"> (i) Controller fatigue; (ii) Field equipment; (iii) The operation of any relief device; (iv) Procedures; (v) SCADA system configuration; and (vi) SCADA system performance. (2) Include lessons learned from the operator's experience in the training program required by this section. 			X	
	.446 (h)	Operator must establish a controller training program to provide for training each controller to carry out the roles and responsibilities defined by the operator and review the training program content to identify potential improvements once each calendar year, NTE 15 months.			X	
	.446(h)	<p>An operator's controller training program must include the following elements:</p> <ul style="list-style-type: none"> (1) Responding to abnormal operating conditions likely to occur simultaneously or in sequence; (2) Use of a computerized simulator or non-computerized (tabletop) method for training controllers to recognize abnormal operating conditions; (3) Training controllers on their responsibilities for communication under the operator's emergency response procedures; (4) Training that will provide a controller a working knowledge of the pipeline system, especially during the development of abnormal operating conditions; and (5) For pipeline operating setups that are periodically, but infrequently used, providing an opportunity for controllers to review relevant procedures in advance of their application. 			X	

Required Submission of Data to the National Pipeline Mapping System Under the Pipeline Safety Improvement Act of 2002			S	U	N/A	N/C
	49 U.S.C. 60132, Subsection (b) ADB-08-07	Updates to NPMS: Operators are required to make update submissions every 12 months if any system modifications have occurred. Go to https://www.npms.phmsa.dot.gov/DataReview/login.jsp to review existing data on record. Also report no modifications if none have occurred since the last complete submission. Include operator contact information with all updates. Section 800, 822	X			
	RCW 81.88.080	Pipeline Mapping System: Operator provides accurate maps (or updates) of pipelines, operating over two hundred fifty pounds per square inch gauge, to specifications developed by the commission sufficient to meet the needs of first responders?	X			

PIPELINE INTEGRITY MANAGEMENT IN HIGH CONSEQUENCE AREAS PROCEDURES			S	U	N/A	N/C
	.452	This form does not cover Liquid Pipeline Integrity Management Programs				
SUBPART G - OPERATOR QUALIFICATION PROCEDURES			S	U	N/A	N/C
	.501 -.509	Refer to Operator Qualification Inspection Forms and Protocols (OPS web page)				

SUBPART H - CORROSION CONTROL PROCEDURES 195.402(a)			S	U	N/A	N/C
227.	195.402(a)	Do procedures require that supervisors maintain a thorough knowledge of that portion of the corrosion control procedures for which they are responsible for insuring compliance? .555 Section 400.1(b)	X			
		Except bottoms of aboveground breakout tanks, each buried or submerged pipeline must have an external coating for external corrosion control if the pipeline is : .557				
228.		a) Constructed, relocated, replaced, or otherwise changed after the applicable dates : 3/31/70 - interstate pipelines excluding low stress 7/31/77 -interstate offshore gathering excluding low stress 10/20/85-intrastate pipeline excluding low stress 7/11/91- carbon dioxide pipelines 8/10/94 - low stress pipelines NOTE: This does not include the movement of pipe under 195.424. Section 402.2	X			
229.		b) Converted under 195.5 and 1) Has an external coating that substantially meets 195.559 before the pipeline is placed in service or;			X	
230.		2) Is a segment that is relocated, replaced, or substantially altered?			X	
231.		Coating Materials; Coating material for external corrosion control must: a. Be designed to mitigate corrosion of the buried or submerged pipeline; b. Have sufficient adhesion to the metal surface to prevent under film migration of moisture; c. Be sufficiently ductile to resists cracking; d. Have enough strength to resist damage due to handling and soil stress; e. Support any supplemental cathodic protection; and f. If the coating is an insulating type, have low moisture absorption and provide high electrical resistance. .559 Section 402.2(a)	X			
232.		All external pipe coatings required under 195.557 must be inspected just prior to lowering the pipe in the ditch or submerging the pipe. .561(a) Section 402.2(b), Appendix 500C	X			
233.		All coating damage discovered must be repaired. .561(b) Appendix 500C (5.4)	X			
234.		Is cathodic protection applied to pipelines that have been subjected to the conditions listed in 195.557(a) within one (1) year? .563(b) Section 400.1	X			
		Each buried or submerged pipeline converted under 195.5 must have cathodic protection if the pipeline-				
235.		1) Has cathodic protection that substantially meets 195.571 before the pipeline is placed in service, or			X	
236.		2) Is a segment that is relocated, replaced, or substantially altered?			X	
237.		c. All other buried or submerged pipelines that have an effective external coating must have cathodic protection. Section 400.1	X			
238.		d. Bare pipelines, breakout tank areas, and buried pumping station piping must have cathodic protection in places where previous editions of this part required cathodic protection as a result of electrical inspections. Section 400.1	X			

SUBPART H - CORROSION CONTROL PROCEDURES 195.402(a)			S	U	N/A	N/C
239.		e. Unprotected pipe must have cathodic protection if required by 195.573(b) .			X	
240.		Test leads installation and maintenance. .567(b)(c) Section 403.6	X			
241.		For placement of test stations at casing? WAC 480-75-340 Section 402.3	X			
242.		Examination of Exposed Portions of Buried Pipelines. .569 Section 404, Appendix 500A	X			
243.		Examination of pipe prior to backfilling. WAC 480-75-520 Section 404, Appendix 500C	X			
244.		Cathodic protection must comply with one or more of the applicable criteria and other considerations for cathodic protection contained in paragraphs 6.2 and 6.3 of NACE Standard RP0169-2007 (incorporated by reference). Amdt 195-94, 75 FR 48593, Pub. 8/11/10 eff. 10/01/10. .571 Section 401.2	X			
245.		Pipe to soil monitoring (annually / 15months). .573(a) Section 403.4(a)	X			
246.		(1) Separately protected short sections of bare ineffectively coated pipelines (every 3 years not to exceed 39 months).			X	
247.		(2) Identify not more than 2 years after cathodic protection is installed, the circumstances in which a close-interval survey or comparable technology is practicable and necessary to accomplish the objectives of paragraph 10.1.1.3 of NACE SP 0169-2007 . Amdt 195-94, 75 FR 48593 Pub. 8/11/10 eff. 10/01/10. Section 403.4(c)	X			
		b. Unprotected buried or submerged pipe must be evaluated and cathodically protected in areas in which active corrosion is found as follows;				
248.		1) Determine areas of active corrosion by electrical survey (closely spaced pipe-to-soil survey), or where electrical survey is impractical, by other means that include review of analysis of leak repair and inspection records, corrosion monitoring records, exposed pipe inspection records, and the pipe environment			X	
249.		2) Before 12/29/2003 - at least once every 5 years not to exceed 63 months . Beginning 12/29/2003 - at least once every 3 years not to exceed 39 months .			X	
250.		c. Rectifiers, Reverse Current Switches, Diodes, Interference Bonds whose failure would jeopardize structural protection - at least 6 times each year, intervals not to exceed 2-1/2mos. Section 403.2, 403.9	X			
251.		d. Inspect each cathodic protection system used to control corrosion on the bottom of an aboveground breakout tank to ensure that operation and maintenance of the system are in accordance with API Recommended Practice 651. (Not required if it is noted in the corrosion control procedures why compliance with all or certain operation and maintenance provisions of API Recommended Practice 651 is not necessary for the safety of the tank.) Section 403.10	X			
252.		e. Any deficiencies identified in corrosion control must be corrected as required by 195.401(b). Section 403.1(e)	X			
253.		Remediation of corrosion system deficiencies initiated within 90 days of discovery WAC 480-75-510 Section 403.1(e)	X			
254.		Are there adequate provisions for electrical isolations? .575 Section 402.4, 402.5	X			
255.		a. For pipelines exposed to stray currents, is there a program to minimize the detrimental effects. b. Design & install CP systems to minimize effects on adjacent metallic structures. .577 Section 402.5	X			
256.		a. For pipelines that transport any hazardous liquid or carbon dioxide that would corrode the pipe, are corrosive effects investigated and adequate steps taken. .579			X	
257.		b. Internal Corrosion - Inhibitors - do procedures show that they are to be used in conjunction with coupons or other monitoring equipment to determine the effectiveness of the inhibitors in mitigating internal corrosion. .579			X	
258.		Coupons or other monitoring equipment must be examined at least 2 times each year, not to exceed 7-1/2 months .			X	
259.		c. Whenever pipe is removed from a pipeline, the internal surface of the pipe must be inspected for evidence of corrosion as well as the adjacent pipe. Appendix 500A (5.4)	X			
260.		Are pipelines protected against Atmospheric Corrosion using required coating material? (See exception to this statement). .581(a) Section 403.7	X			

SUBPART H - CORROSION CONTROL PROCEDURES 195.402(a)			S	U	N/A	N/C
		Atmospheric corrosion monitoring - .583 ONSHORE - At least once every 3 years but at intervals not exceeding 39 months. OFFSHORE - At least once each year, but at intervals not exceeding 15 months.				
261.		(b) Inspect pipe at soil-to-air interfaces, under thermal insulation, under disbonded coatings, at pipe supports, in splash zones, at deck penetrations, and in spans over water. Section 403.7	X			
262.		(c) If atmospheric corrosion is found during an inspection, procedures for protection against the corrosion as per §195.581. Section 403.7	X			
263.		Are procedures in place and are they followed to either reduce the MOP , or repair/replace pipe if general corrosion has reduced the wall thickness? .585(a) Section 403.7, 404, 528	X			
264.		Are procedures in place and are they followed to either reduce the MOP , or repair/replace if localized corrosion has reduced the wall thickness? .585(b) Section 403.7, 404, 429	X			
265.		Are applicable methods used in determining the strength of corroded pipe (ASME B-31G, RSTRENG)? .587 Section 529(b)	X			
266.		Corrosion Control Records Retention (Some are required for 5 yrs) (Note - §§195.569, 195.573(a & b), and 195.579(b)(3) & (c) for the life of the pipeline). .589 Section 705(d)	X			

PART 199 – DRUG and ALCOHOL TESTING REGULATIONS and PROCEDURES		S	U	N/A	N/C
Subparts A - C	Drug & Alcohol Testing & Alcohol Misuse Prevention Program – Use PHMSA Form # 13, PHMSA Drug and Alcohol Program Check.				

<p>Comments: Items 229-230 – Tidewater has no pipelines converted under 195.5 Items 235-236 – Tidewater has no pipelines converted under 195.5 Item 239 – Tidewater has no unprotected pipe Item 246 – Tidewater has no bare ineffectively coated pipelines Items 248-249 – Tidewater has no unprotected pipelines Item 256 – Tidewater has determined that their products are non-corrosive Item 257 – Tidewater does not use inhibitors Item 258 – Tidewater does not use internal coupons</p>

Recent PHMSA Advisory Bulletins (Last 2 years)

Leave this list with the operator.

<u>Number</u>	<u>Date</u>	<u>Subject</u>
ADB-2013-07	July 12, 13	Potential for Damage to Pipeline Facilities Caused by Flooding
ADB-12-10	Dec 5, 12	Using Meaningful Metrics in Conducting Integrity Management Program Evaluations
ADB-12-09	Oct 11, 12	Communication During Emergency Situations
ADB-12-08	Jul 31, 12	Inspection and Protection of Pipeline Facilities After Railway Accidents
ADB -12-06	May 7, 12	Verification of Records Establishing MAOP and MOP.
ADB-12-04	Mar 21, 12	Implementation of the National Registry of Pipeline and Liquefied Natural Gas Operators
ADB -12-03	Mar 6, 12	Notice to Operators of Driscopipe 8000 High Density Polyethylene Pipe of the Potential for Material Degradation

For more PHMSA Advisory Bulletins, go to <http://phmsa.dot.gov/pipeline/regs/advisory-bulletin>