

8203 Incident Investigation

5/28/2020 -


Staff began investigation into an account where multiple pieces of equipment were found on a crew truck during a random field crew inspection audit that were out of calibration. Staff contacted the person responsible to maintain equipment calibration, according to crew personnel on site, by phone, and noted that person was unaware that the equipment was out of compliance.

6/2 & 6/4/2020-

Staff contacted CNGC via phone and email, to request vehicle location, personnel and equipment records related to the investigation. To date there has been no response.



Picture #1 - Staff captured screen shot on site of the Pyrometer and calibration due date of a borrowed piece of equipment from a nearby crew, which was allegedly used by fitter "William Doyle" to join the new service after discovering that the Pyrometer on his own crew truck was out of compliance.



Picture #2 - Calibration record for new gauge used for pressure test on the gas service.



Picture #3 - Verification of calibrated gauge used for new gas service.



Picture #4 - OQ verification