



Karl Jay
Roadmaster Bellingham WA
1200 "D" Street
Bellingham, WA 98225
Telephone: 360.922.1401
Fax:
Karl.jay@bnsf.com

December 23, 2021

IMPORTANT NOTICE

This is to inform you of BNSF's plan to repair a rail defect within crossing at South Texas Rd. in Anacortes, WA, at approximately MP 4.85 on the Bellingham Sub (Anacortes Branch) DOT# 092232S. This will be a hard closure from approximately 0800 04JAN2022 until 1400 04JAN2022. There is route around the closure. I have contacted Northwest Safety Signs and they will be providing signage, detour information and flagging protection.

If you have questions about the regulatory process, you may need to contact Washington Utilities and Transportation Commission at: WUTC, 1300 S. Evergreen Park Dr. S.W., P.O. Box 47250, Olympia, WA. 98504-7250; 1-800-562-6150 (toll-free). Also, you may contact the Federal Railroad Administration at 1-800-724-5998 (toll-free).

If you have any questions please contact Karl Jay, BNSF Roadmaster, at (360) 922-1401.