# Inspection Output (IOR)

Generated on 2022.October.09 14:28

### **Report Filters**

Assets Cascade Natural Gas- YAKIMA / 90875 (1916) Results All

### **Inspection Information**

Inspection Name [8427] CNGC(MDU) 19Sep22 Yakima Status PLANNED Start Year 2022 System Type GD Protocol Set ID WA.GD.2022.01 Operator(s) CASCADE NATURAL GAS CORP (2128) Lead Lex Vinsel Team Members Scott Anderson Observer(s) David Cullom, Dennis Ritter, Derek Norwood Supervisor Scott Rukke Director Sean Mayo Plan Submitted 09/17/2022 Plan Approval 09/19/2022 by Scott Rukke All Activity Start 09/20/2022 All Activity End 09/23/2022 Inspection Submitted --Inspection Approval --

### Inspection Summary

### **Inspection Scope and Summary**

CNGC (MDU) Yakima District

### Facilities visited and Total AFOD

CNGC Yakima Office

AFOD 14

### Summary of Significant Findings

(DO NOT Discuss Enforcement options)

No violations or issues were noted as a result of this inspection.

### Primary Operator contacts and/or participants

Colby Lundstrom

### Operator executive contact and mailing address for any official correspondence

Mr. Pat Darras

VP, Engineering & Ops Services

Cascade Natural Gas Corp. (MDU)

400 North 4th Street

Bismarck North Dakota 58501

Scope (Assets)

# Short Name Long Name	Asset Type	Asset IDs	Excluded Topics	Planned Re	equired Ins	Total spected	Required % Complete
1. 90875 (1916) Cascade Natural Gas- YAKIMA	unit	90875	Storage Fields Bottle/Pipe - Holders Offshore GOM OCS Aluminum/Amphoteric Copper Pipe Abandoned	150	150	150	100.0%

1. Percent completion excludes unanswered questions planned as "always observe".

### Plans

# Plan Assets Focus		Involved Groups/Subgroups	Qst Type(s)	Extent Notes
1. 90875 (1916) WUTC	Standard Inspection	PRO, PRR, FR, GDIM, LPGIM, MISCTOPICS, GENERIC	P, R, O, S	Detail

### **Plan Implementations**

										Require
										d
	SMAR	Start	Focus	Involved		Qst			Total	%
	Т	Date	Directiv	Groups/Subgro		Type(	Planne	Require	Inspect	Comple
# Activity Name	Act#	End Date	es	ups	Assets	s)	d	d	ed	te
1 WUTC Standard Inspec		09/20/20	WUTC	PRO, PRR, FR,	90875 (191	all	150	150	150	100.0%
. tion		22	Standard	GDIM, LPGIM,	6)	types				
		09/23/20	Inspectio	MISCTOPICS,						
		22	n	GENERIC						

- 1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table.
- 2. Percent completion excludes unanswered questions planned as "always observe".
- 3. Question counts and completion percents are filtered to include only questions planned for and results applied to the filtered Assets.

### Forms

No. Entity	Form Name	Status	Date Completed	Activity Name	Asset
1. Attendance List	WUTC Standard Inspection	COMPLETED	10/07/2022	WUTC Standard Inspection	90875 (1916)
2. Attendance List	WUTC Field Day	COMPLETED	10/09/2022	WUTC Standard Inspection	90875 (1916)

### Results (all values, 150 results)

155 (instead of 150) results are listed due to re-presentation of questions in more than one sub-group.

### **PRO.SUBLNORMOPS: Normal Operating And Maintenance**

1. Question Result, ID, Sat, MO.GO.ODDOR.P, 192.605(a) (192.605(b)(11)) References

Question Text Does the process require prompt response to the report of a gas odor inside or near a building?

Assets Covered 90875 (1916)

Result Notes OP 613 Gas Emergency Response Plan - Step 4.2 & Step 11

### **PRR.REPORT:** Reporting

2. Question Result, ID, Sat, RPT.RR.IMMEDREPORT.R, 191.5(a) (191.7(a), 191.7(d)) References

Question Text *Do records indicate immediate notifications of incidents were made in accordance with 191.5?* Assets Covered 90875 (1916)

Result Notes Reviewedd alll of the reportable incident for Yakima for 2019-2021 and partial for 2022.

No issues - 1 2021 - 3 2020 - 1 2019 - 1 3. Question Result, ID, NA, RPT.RR.INCIDENTREPORT.R, 191.9(a) References Question Text Do records indicate reportable incidents were identified and reports were submitted to DOT on Form 7100.1 within the required time frame? Assets Covered 90875 (1916) Result Notes No such event occurred, or condition existed, in the scope of inspection review. 4. Question Result, ID, NA, RPT.RR.INCIDENTREPORTSUPP.R, 191.9(b) References Question Text Do records indicate accurate supplemental incident reports were filed and within the required timeframe? Assets Covered 90875 (1916) Result Notes No such event occurred, or condition existed, in the scope of inspection review. 5. Question Result, ID, Sat, RPT.RR.ANNUALREPORT.R, 191.11(a) References Question Text Have complete and accurate Annual Reports been submitted? Assets Covered 90875 (1916) 6. Question Result, ID, Sat, RPT.RR.UTCANNUALREPORTS.R, References Question Text Have complete and accurate annual reports been submitted to the commission? Assets Covered 90875 (1916) Result Notes Annual Reports submitted March 15, 2022. 7. Question Result, ID, Sat, RPT.RR.MISDATAREPORTS.R, References Question Text Has the operator submitted a copy of DOT Drug and Alcohol Testing MIS Data Collection Form to the commission when required? Assets Covered 90875 (1916) Result Notes Reviewed MIS report 8. Question Result, ID, Sat, GDIM.RR.MECHANICALFITTINGDATAIMPL.R, 192.1009 (191.12) (also presented in: GDIM.IMPL) References Question Text Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?

Assets Covered 90875 (1916)

Result Notes Submitted on March 10, 2022 Receipt on the 11.

Report appears complete.

9. Question Result, ID, NA, RPT.RR.SRCR.R, 191.23(a) (191.23(b), 191.25(a), 191.25(c)) References

Question Text Do records indicate safety-related condition reports were filed as required?

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

10. Question Result, ID, NA, RPT.RR.MAOPINCREASENOTIFY.R, References

Question Text Do records indicate submittal of a written plan of procedures to the commission at least forty-five days before uprating to a MAOP greater than 60 psig?

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

11. Question Result, ID, Sat, RPT.RR.THIRTYDAYRPT.R, References

Question Text Has the operator submitted a written report within 30 days following each reportable incident? Assets Covered 90875 (1916)

Result Notes No issues found.

12. Question Result, ID, Sat, MO.GO.CUSTNOTIFY.R, 192.16(d) (192.16(a), 192.16(b), 192.16(c)) References

Question Text *Do records indicate the customer notification process satisfies the requirements of 192.16?* Assets Covered 90875 (1916)

Result Notes Reviewed sample of customer notifications and reviewed letters to customers.

Looking for evidence of packets delivered to new customers

- 13. Question Result, ID, Sat, RPT.RR.DAILYCONSTRUCTIONRPT.R, References
  - Question Text Do records indicate daily construction and repair activities were emailed to the commission no later than 10 AM each day work is scheduled?

Assets Covered 90875 (1916)

Result Notes Notice of daily construction and repair activities appear to be adequate.

- 14. Question Result, ID, Sat, RPT.RR.PIPELINEMAPPING.R, References
  - Question Text Has the operator provided accurate maps (or updates) of all pipelines operating over 250 psig to specifications developed by the commission sufficient to meet the needs of first responders?
  - Assets Covered 90875 (1916)

Result Notes Maps and updates will be provided upon request.

### **PRR.CORROSION:** Corrosion Control

15. Question Result, ID, Sat, TQ.QU.CORROSION.R, 192.453 (192.807(a), 192.807(b)) References

> Question Text *Do records indicate qualification of personnel implementing pipeline corrosion control methods?* Assets Covered 90875 (1916)

Result Notes Brandon Croy CP3 - Cathodic Protection Technologist Expires May 31, 2024

Theron Doughty CP3 - Cathodic Protection Technologist Expires Jun 20, 2025

16. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) References

Question Text *Do records indicate the location of all corrosion control items listed in §192.491(a)?* Assets Covered 90875 (1916) Result Notes Mapping is on each operators computer and appears to be adequate for CP items.

17. Question Result, ID, Sat, TD.CPMONITOR.CURRENTTEST.R, 192.491(c) (192.465(b)) References

Question Text Do records document details of electrical checks of sources of rectifiers or other impressed current sources?

Assets Covered 90875 (1916)

Result Notes CNG 651 for Sept 2019 to Jun 2021 were paper forms

Reviewed records from July 2021 - June 2022 was in Maximo

18. Question Result, ID, Sat, TD.CPEXPOSED.EXPOSEINSPECT.R, 192.491(c) (192.459) References Question Text Do records adequately document that exposed buried piping was examined for corrosion? Assets Covered 90875 (1916)

Result Notes Reviewed Sample of reports and found that exposed pipe was examined for corrosion.

315 315R are for service lines

336 for mains

19. Question Result, ID, Sat, TD.CPMONITOR.TEST.R, 192.491(c) (192.465(a)) References

> Question Text Do records adequately document cathodic protection monitoring tests have occurred as required? Assets Covered 90875 (1916)

Result Notes Further investigation found the low reads were compared to the Native Reads (every 5 years) through Maximo.

20. Question Result, ID, NA, TD.CPMONITOR.REVCURRENTTEST.R, 192.491(c) (192.465(c)) References

> Question Text Do records document details of electrical checks interference bonds, diodes, and reverse current switches?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

21. Question Result, ID, Sat, TD.CPMONITOR.DEFICIENCY.R, 192.491(c) (192.465(d)) References

Question Text Do records adequately document actions taken to correct any identified deficiencies in corrosion control? Assets Covered 90875 (1916) Result Notes Form 650

22. Question Result, ID, NA, TD.CP.UNPROTECT.R, 192.491(c) (192.465(e)) References

> Question Text Do records adequately document that exposed buried piping was examined for corrosion and deteriorated coating?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

## 23. Question Result, ID, NA, FS.FG.CASINGTESTLEAD.R,

References

Question Text Do records indicate that all casings without vents installed after September 5, 1992 had separate test lead wires installed?

### Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

24. Question Result, ID, NA, FS.FG.CASINGSEALS.R, References

Question Text Do records indicate that mains and service lines installed in casing or conduit are sealed at the ends as reauired?

### Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

- 25. Question Result, ID, NA, TD.CP.ELECISOLATE.R, 192.491(c) (192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e)) References
  - Question Text Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?

#### Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

### 26. Question Result, ID, Sat, TD.CP.CASINGINSPECT.R, References

- - Question Text Do records indicate that annual casing inspections have been performed to ensure electrical isolation from the pipeline?

### Assets Covered 90875 (1916)

Result Notes Survey reads appear adequate.

27. Question Result, ID, Sat, TD.CPMONITOR.TESTSTATION.R, 192.469 References

Question Text Do records identify the location of test stations and show a sufficient number of test stations?

### Assets Covered 90875 (1916)

Result Notes Review of GIS mapping show that there appear to be adequate coverage.

- 28. Question Result, ID, Sat, TD.CPMONITOR.TESTLEAD.R, 192.491(c) (192.471(a), 192.471(b), 192.471(c))
  - Question Text Do records document that pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?

#### Assets Covered 90875 (1916)

Result Notes Electrical Test Leads are attached using procedure OPS 407, Exothermic Welding Connections to Steel Pipelines.

## 29. Question Result, ID, Sat, TD.CPMONITOR.INTFRCURRENT.R, 192.491(c) (192.473(a))

Question Text Do records document an effective program is in place to minimize detrimental effects of interference currents and that detrimental effects of interference currents from CP systems on other underground metallic structures are minimized?

#### Assets Covered 90875 (1916)

Result Notes Reviewed sample of 35-36 forms for 2019-2022 low potential reads.

30. Question Result, ID, NA, TD.ICP.CORRGAS.R, 192.491(c) (192.475(a)) References

> Question Text Do the records demonstrate that the corrosive effect of the gas in the pipeline has been investigated and if determined to be corrosive, steps be taken to minimize internal corrosion?

### Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

### NO corrosive gas in the system.

31. Question Result, ID, Sat, TD.ICP.EXAMINE.R, 192.491(c) (192.475(a), 192.475(b)) References

Question Text Do records document examination of removed pipe for evidence of internal corrosion?

Assets Covered 90875 (1916)

Result Notes Currently needed multiple inspections for each exposed pipe. With exposed internal pipeline ; (coupons from stopples and bottom outs. Any time you exposed the internal surface you should keep a record of what was found.

32. Question Result, ID, NA, TD.ICP.CORRGASACTION.R, 192.491(c) (192.477) References

Question Text Do records document the actions taken when corrosive gas is being transported by pipeline? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

Cascade Natural does not transport corrosive gas.

33. Question Result, ID, Sat, TD.ATM.ATMCORRODEINSP.R, 192.491(c) (192.481(a), 192.481(b), 192.481(c)) References

Question Text Do records document inspection of aboveground pipe for atmospheric corrosion? Assets Covered 90875 (1916)

Result Notes Reviewed sample of addresses for review of aboveground pipe, Atmospheric Corrosion.

34. Question Result, ID, Sat, TD.COAT.NEWPIPE.R, 192.491(c) (192.455(a), 192.461(a), 192.461(b), 192.483(a)) References

Question Text Do records document that each buried or submerged pipeline installed after July 31, 1971 has been externally coated with a suitable coating material?

Assets Covered 90875 (1916)

Result Notes Reviewed work orders for steel pipeline that show FBE coating on steel install.

### 35. Question Result, ID, Sat, TD.ICP.EVALUATE.R, 192.491(c) (192.487)

References

Question Text Do records document adequate evaluation of internally corroded pipe?

Assets Covered 90875 (1916)

Result Notes Internal corrosion inspection records appear to be adequate.

- 36. Question Result, ID, NA, AR.RCOM.REPAIR.R, 192.487 (192.489)
  - References

Question Text Do records document the repair or replacement of pipe that has been internally corroded to an extent that there is not sufficient remaining strength in the pipe wall?

#### Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

### **PRR.PT: Pressure Test**

37. Question Result, ID, Sat, DC.PTLOWPRESS.PRESSTESTLOWSTRESS.R, 192.517(a) (192.507(a), 192.507(b), 192.507(c)) References

Question Text Do records indicate that pressure testing is conducted in accordance with 192.507?

Assets Covered 90875 (1916)

Result Notes Reviewed high pressure and immediate test records R-93 Construction WO#273228.

- 38. Question Result, ID, Sat, DC.PTLOWPRESS.PRESSTEST100PSIG.R, 192.517(b) (192.509(a), 192.509(b)) References
  - Question Text Do records indicate that pressure testing is conducted in accordance with 192.509(a) (except for service lines and plastic pipelines)?

### Assets Covered 90875 (1916)

Result Notes Reviewed pressure testing for pressure tests at 100 and below.

39. Question Result, ID, Sat, DC.PT.SERVICELINE.R, 192.517(b) (192.511(a), 192.511(b), 192.511(c))

Question Text Do records indicate that pressure testing is conducted in accordance with 192.511? Assets Covered 90875 (1916)

Result Notes Service line pressure tests appear adequate.

40. Question Result, ID, Sat, DC.PT.PRESSTESTPLASTIC.R, 192.517(b) (192.513(a), 192.513(b), 192.513(c), 192.513(d)) References

Question Text Do records indicate that pressure testing is conducted in accordance with 192.513? Assets Covered 90875 (1916)

Result Notes Testing for install appears adequate.

### **PRR.UPRATE: Uprating**

41. Question Result, ID, NA, MO.GOUPRATE.MAOPINCREASE.R, 192.553(a) (192.553(b), 192.553(c)) References

Question Text Do records indicate that increases in MAOP of pipeline were determined in accordance with 192.553? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

42. Question Result, ID, NA, MO.GOUPRATE.MAOPINCREASELIMIT.R, 192.553(b) (192.553(c), 192.553(d), 192.557(a)) References

Question Text Do records indicate that increases in MAOP are limited in accordance with 192.619 and 192.621? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

43. Question Result, ID, NA, MO.GOUPRATE.MAOPINCREASEPREP.R, 192.553(b) (192.553(c), 192.553(a), 192.557(b), References 192.557(c))

Question Text Do records indicate that increases in MAOP were preceded by the actions specified in 192.557? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

44. Question Result, ID, NA, MO.GOUPRATE.MAOPINCREASECASTDUCTILE.R, 192.553(b) (192.553(c), 192.557(d)) References

Question Text Do records indicate that requirements were followed for increasing the MAOP for cast iron or ductile iron pipe where records are inadequate for evaluating the level of safety of the pipeline when operating at the proposed increased pressure?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

### PRR.OM: Operations And Maintenance

45. Question Result, ID, Sat, MO.GO.OMANNUALREVIEW.R, 192.605(a) References

> Question Text Have annual reviews of the written procedures or processes in the manual been conducted as required? Assets Covered 90875 (1916)

Result Notes Reviewed annual reviews for pipeline procedures.

46. Question Result, ID, Sat, MO.GO.OMHISTORY.R, 192.605(a) (192.605(b)(3)) References

> Question Text Are construction records, maps and operating history available to appropriate operating personnel? Assets Covered 90875 (1916)

Result Notes GIS Web Viewer is available on the operators Toughbook. Review of sample of locations finds that the up to date information is available for use on the GIS Web Viewer.

## 47. Question Result, ID, Sat, MO.GO.OMEFFECTREVIEW.R, 192.605(a) (192.605(b)(8)) References

Question Text Do records indicate periodic review of the work done by operator personnel to determine the effectiveness, and adequacy of the processes used in normal operations and maintenance and modifying the processes when deficiencies are found?

#### Assets Covered 90875 (1916)

Result Notes Reviewed Form 640 - Construction Inspection Checklist

The checklist is completed each month that construction occurs.

48. Question Result, ID, NA, MO.GOCLASS.CLASSLOCATESTUDY.R, 192.605(b)(1) (192.609(a), 192.609(b), 192.609(c), References 192.609(d), 192.609(e), 192.609(f))

Question Text Do records indicate performance of the required study whenever the population along a pipeline increased or there was an indication that the pipe hoop stress was not commensurate with the present class location?

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

### 49. Question Result, ID, Sat, EP.ERG.POSTEVNTREVIEW.R, 192.605(a) (192.615(b)(1), 192.615(b)(3)) References

Question Text Do records indicate review of employee activities to determine whether the procedures were effectively followed in each emergency?

Assets Covered 90875 (1916)

Result Notes

Reviewed 234 form or 23001 form for Incident and Hazardous Condition report. Procedure effectiveness is reviewed for each incident as part of the Incident and Hazardous Condition report.

50. Question Result, ID, Sat, EP.ERG.TRAINING.R, 192.605(a) (192.615(b)(2)) References

Question Text Has the operator trained the appropriate operating personnel on emergency procedures and verified that the training was effective in accordance with its procedures?

Assets Covered 90875 (1916)

Result Notes Training was performed for each mock drill done by CNG. Mock drills were two in 2019, one in 2020 and two in 2021.

- 51. Question Result, ID, Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), References 192.616(c), ADB-05-03) (also presented in: MISCTOPICS.PUBAWARE)
  - Question Text Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?

Assets Covered 90875 (1916)

Result Notes Newsletter mailing records for Liaison appear adequate.

52. Question Result, ID, Sat, PD.PA.LANGUAGE.R, 192.616(g) (API RP 1162 Section 2.3.1) (also presented in: References MISCTOPICS.PUBAWARE)

Question Text Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?

Assets Covered 90875 (1916)

Result Notes Reviewed English and Spanish language fliers, and 7 other languages are available on the web site.

53. Question Result, ID, NC, PD.PA.EVALEFFECTIVENESS.R, 192.616(c) (API RP 1162 Section 8.4) (also presented in: References MISCTOPICS.PUBAWARE)

Question Text Do records indicate program effectiveness evaluation(s) have been performed and cover all program requirements and all systems covered by the program?

Assets Covered 90875 (1916)

Result Notes Will be reviewed on the PA inspection next week

- 54. Question Result, ID, NA, PD.PA.MSTRMETER.R, 192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 References Section 8.5) (also presented in: MISCTOPICS.PUBAWARE)
  - Question Text Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?
  - Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

- 55. Question Result, ID, NA, EP.ERG.INCIDENTANALYSIS.R, 192.605(a) (192.617)
  - Question Text *Do records indicate actions initiated to analyze accidents and failures, including the collection of appropriate samples for laboratory examination to determine the causes of the failure and minimize the possibility of recurrence, in accordance with its procedures?*

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

56. Question Result, ID, NC, PD.DP.PDPROGRAM.R, 192.614(c) References

Question Text *Does the damage prevention program meet minimum requirements specified in 192.614(c)?* Assets Covered 90875 (1916)

Result Notes Question to be covered next week in PA inspection

- 57. Question Result, ID, Sat, MO.GOMAOP.MAOPDETERMINE.R, 192.619(a) (192.619(b), 192.621(a), 192.621(b), 192.623(a), References 192.623(b))
  - Question Text Do records indicate determination of the MAOP of pipeline segments in accordance with 192.619 and limiting of the operating pressure as required?
  - Assets Covered 90875 (1916)

Result Notes Review of sample of records show proper testing per requirements

- 58. Question Result, ID, Sat, MO.GOODOR.ODORIZE.R, 192.709(c) (192.625(a), 192.625(b), 192.625(c), 192.625(d), References 192.625(e), 192.625(f))
  - Question Text Do records indicate appropriate odorization of its combustible gases in accordance with its processes and conduct of the required testing to verify odorant levels met requirements?
  - Assets Covered 90875 (1916)

Result Notes Reviewed Odorant records and found no issues.

59. Question Result, ID, Sat, MO.RW.DISTPATROL.R, 192.603(b) (192.721(a), 192.721(b)) References

Question Text Do records indicate distribution patrolling was conducted as required?

Assets Covered 90875 (1916)

Result Notes Distribution records reviewed.

60. Question Result, ID, Sat, MO.RW.LEAKFOLLOW.R, References

Question Text Do records indicate that a follow-up inspection was performed not more than thirty days following a repair where residual gas remained in the ground?

Assets Covered 90875 (1916)

Result Notes Reviewed 100% or 2020, 2021 and 2020 leak repair records. SR

61. Question Result, ID, NA, MO.RW.DOWNGRADELEAKREPAIR.R, References

Question Text *Do records indicate that leaks that have been downgraded are repaired within twenty-one months?* Assets Covered 90875 (1916)

- Result Notes No such event occurred, or condition existed, in the scope of inspection review. No leaks were downgraded.
- 62. Question Result, ID, Sat, MO.RW.LEAKREPAIRTIME.R,

Question Text Do records indicate that leaks were repaired and re-evaluated in the timeframes specified in WAC 480-93-18601?

Assets Covered 90875 (1916)

Result Notes Reviewed 100% or 2020, 2021 and 2020 leak repair records. SR

63. Question Result, ID, Sat, MO.RW.LEAKRECORDS.R, References

Question Text Have gas leak records been prepared and maintained as required?

Assets Covered 90875 (1916)

Result Notes Reviewed 100% or 2020, 2021 and 2020 leak repair records. SR

## 64. Question Result, ID, Sat, MO.RW.DISTPATROLLEAKAGE.R, 192.603(b) (192.723(a), 192.723(b)) References

Question Text Do records indicate distribution leakage surveys were conducted as required?

Assets Covered 90875 (1916)

Result Notes Reviewed Leak survey maps for 2019 & 2020 for Moxee Sec 1, Seleh Sec 1 and Yakima Sec 1

Records appear complete.

Also checking on GIS for 2021 to current records for Yakima Unit. 65. Question Result, ID, Sat, MO.RW.CASINGLEAKSURVEY.R, References Question Text Do records indicate shorted casings were leak surveyed as required? Assets Covered 90875 (1916) Result Notes Reviewed leak survey records for all shorted casings. 66. Question Result, ID, Sat, MO.RW.MARKERSURVEY.R, References Question Text Do records indicate that pipeline marker surveys were completed in the timeframe specified by WAC 480-93-124? Assets Covered 90875 (1916) Result Notes Pipeline marker surveys are performed during the leak survey. Missing or damaged markers are noted on the CNG 297 Corrective Action Log for each survey. 67. Question Result, ID, Sat, MO.RW.MARKERREPLACE.R, References Question Text Do records indicate that damaged or missing markers were replaced within forty-five days of discovery? Assets Covered 90875 (1916) Result Notes Reviewed marker replacement records and all markers were replace within the 45 days. 68. Question Result, ID, Sat, AR.RMP.TESTREINSTATE.R, 192.603(b) (192.725(a), 192.725(b)) References Question Text From the review of records, did the operator properly test disconnected service lines? Assets Covered 90875 (1916) Result Notes All damaged services were pressure tested from the damage to the meter. 69. Question Result, ID, Sat, MO.GMOPP.PRESSREGTEST.R, 192.709(c) (192.739(a), 192.739(b)) References Question Text Do records indicate inspection and testing of pressure limiting, relief devices, and pressure regulating stations? Assets Covered 90875 (1916) Result Notes Reviewed 100% of regulator and relief station records for 2021 through 2022. No issues noted. No dithiazine noted in any reg stations. 70. Question Result, ID, Sat, MO.GMOPP.PRESSREGCAP.R, 192.709(c) (192.743(a), 192.743(b), 192.743(c)) References Question Text Do records indicate testing or review of the capacity of each pressure relief device at each pressure limiting station and pressure regulating station as required? Assets Covered 90875 (1916) Result Notes Reviewed CNG's capacity review log for 2020 and 2021. 71. Question Result, ID, Sat, DC.METERREGSVC.REGTEST.R, References Question Text Do records indicate that service regulators have been installed, operated, maintained, tested during initial turn-on and tested when customers experience pressure problems? Assets Covered 90875 (1916) Result Notes Reviewed sample of pressure turn ons and foun lockup pressure was 0.25 - .27 72. Question Result, ID, Sat, MO.GM.DISTVALVEINSPECT.R, 192.603(b) (192.747(a), 192.747(b)) References Question Text Do records indicate proper inspection of each distribution system valve that might be required in an emergency at intervals not exceeding 15 months, but at least once each calendar year, and prompt remedial action to correct any valve found inoperable? Assets Covered 90875 (1916) Result Notes Reviewed sample of annual valve inspections for 2019-2021. No issues 73. Question Result, ID, NA, FS.FG.VAULTINSPECT.R, 192.709(c) (192.749(a), 192.749(b), 192.749(c), 192.749(d)) References

Question Text Do records document the adequacy of inspections of all vaults having an internal volume =200 cubic feet (5.66 cubic meters) that house pressure regulating/limiting equipment?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

74. Question Result, ID, Sat, MO.GM.IGNITION.R, 192.709 (192.751(a), 192.751(b), 192.751(c)) References

Question Text Do records indicate personnel followed processes for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion?

Assets Covered 90875 (1916)

Result Notes Operator Qualifications & Safety Task Code are reviewed every month during the construction season.

Prevention of Accidental Ignition Practices (192-0101)

75. Question Result, ID, NA, MO.GM.BELLSPIGOTJOINT.R, 192.603(b) (192.753(a), 192.753(b)) References

Question Text Do records indicate that caulked bell and spigot joints were correctly sealed?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

### 76. Question Result, ID, Sat, DC.DPC.FLANGE.R, 192.147(a) (192.147(b), 192.147(c)) References

Question Text *Do records indicate flanges and flange accessories meet the requirements of 192.147?* Assets Covered 90875 (1916)

Result Notes Reviewed regulator station R-93 construction documents and flanges and accessories appear adequate.

77. Question Result, ID, Sat, DC.WELDPROCEDURE.WELD.R, 192.225(a) (192.225(b)) References

> Question Text *Do records indicate weld procedures are being qualified in accordance with 192.225?* Assets Covered 90875 (1916)

78. Question Result, ID, Sat, DC.WELDPROCEDURE.ESSENTIAL.R, References

Question Text Do records indicate that essential variables were measured and documented when welders and procedures were qualified?

### Assets Covered 90875 (1916)

Result Notes Welder procedures do not record essential variables for Welder Qualification.

Operator went to a new form this year that does not record essential variables Amp and Voltage and travel speed for welder qualification.

Operator change order OPS MOC-1601

**79.** Question Result, ID, Sat, TO.QUOMCONST.WELDER.R, 192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), References 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))

Question Text Do records indicate adequate qualification of welders?

Assets Covered 90875 (1916)

Result Notes Trent Johnson 2020 to current qualification records.

Justin Palmer Qualified from 5/10/2022 to current.

Ben Baumgarten 2019 to current.

 80. Question Result, ID, Sat, TQ.QUOMCONST.NDT.R, 192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b)) References
Question Text *Do records indicate the qualification of nondestructive testing personnel?*

Assets Covered 90875 (1916)

[8427] CNGC(MDU) 19Sep22 Yakima

Brian Martin qualification current at time of inspection 02/01/2020

Josh Remmme Qualification current at time of inspection 02/17/2020

81. Question Result, ID, Sat, DC.CO.PLASTICJOINTPROCEDURE.R, 192.273(b) (192.283(a), 192.283(b), 192.283(c)) References

Question Text Have plastic pipe joining procedures been qualified in accordance with 192.283?

Assets Covered 90875 (1916)

Result Notes CNGC follows TR-33, Generic Butt Fusion Joining Procedure for Field Joining of Polyethylene Pipe

82. Question Result, ID, Sat, DC.CO.PLASTICJOINTQUAL.R, 192.285(d) (192.285(a), 192.285(b), 192.285(c), 192.807(a), References 192.807(b))

Question Text Do records indicate persons making joints in plastic pipelines are qualified in accordance with 192.285? Assets Covered 90875 (1916)

Result Notes Reviewed annual fusion joiner certifications.

Trent Johnson - 2020-2022

Dave Haubrick 2022

Ben Baugarten 2019-2022

83. Question Result, ID, Sat, DC.CO.PLASTICJOINTINSP.R, 192.287 (192.807(a), 192.807(b)) References

Question Text Do records indicate persons inspecting the making of plastic pipe joints have been qualified?

Assets Covered 90875 (1916)

Result Notes Part of qualification for Fusion is to be able to inspect the own Fusions.

- 84. Question Result, ID, Sat, DC.CO.PLASTICPIPESEP.R,
  - References

Question Text Do records indicate minimum separation requirements are met for plastic pipelines?

Assets Covered 90875 (1916)

Result Notes Minimum separation is recorded when required.

- 85. Question Result, ID, Sat, MO.GM.EQUIPPLASTICJOINT.R, 192.603(b) (192.756)
  - References
    - Question Text Do records indicate equipment used in joining plastic pipe by heat fusion was maintained in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?
    - Assets Covered 90875 (1916)

Result Notes Reviewed Electro Fusion #9630193 and 9630204 certs.

86. Question Result, ID, NA, MO.GM.RECORDS.R, 192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c)) References

Question Text Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

87. Question Result, ID, NA, MO.GM.MOVEANDLOWER.R, References

> Question Text Do records indicate that a study was prepared before moving or lowering a steel gas pipeline as required? Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

88. Question Result, ID, NA, MO.GM.MOVEANDLOWERSURVEY.R, References

> Question Text Do records indicate that a leak survey was conducted not more than thirty days after moving and/or lowering a metallic pipeline?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

89. Question Result, ID, Sat, MO.RW.MARKERSMAPSDRAW.R, References

> Question Text Are records sufficient to indicate class location and other areas where pipeline markers are required? Assets Covered 90875 (1916)

Result Notes GIS Web Viewer has shows class location for the area.

### FR.FIELDPIPE: Pipeline Inspection (Field)

90. Question Result, ID, Sat, DC.MA.MARKING.O, 192.63(a) (192.63(b), 192.63(c), 192.63(d)) References

Question Text Are pipe, valves, and fittings properly marked for identification in accordance with the requirements of 192.63?

Assets Covered 90875 (1916)

Result Notes Pipe in stock yard are properly marked.

91. Question Result, ID, Sat, DC.DPC.FLANGE.O, 192.141 (192.147(a), 192.147(b), 192.147(c)) References

Question Text Do flanges and flange accessories meet the requirements of 192.147? Assets Covered 90875 (1916)

## 92. Question Result, ID, NA, DC.DPC.GDVALVEPLACEMENT.O, 192.141 (192.181(a), 192.181(b), 192.181(c))

Question Text Are distribution line valves being installed as required of 192.181?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

93. Question Result, ID, Sat, DC.CO.PLASTICPIPEPROC.O, References

> Question Text Is plastic pipe handled, stored and installed in accordance with manufacturer's recommendations, including maximum ultraviolet exposure?

Assets Covered 90875 (1916)

94. Question Result, ID, NA, DC.CO.PLASTICPIPESEP.O,

References

Question Text Are plastic pipelines installed with the minimum separation from other utilities as required? Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

95. Question Result, ID, NA, DC.CO.PLASTICBACKFILL.O, References

> Question Text Is plastic pipe buried in essentially rock-free material or material recommended by the pipe manufacturer?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

### 96. Question Result, ID, NA, DC.CO.PLASTICSQUEEZING.O, References

Question Text Verify that the operator has limits in place for squeezing plastic pipe.

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

97. Question Result, ID, NA, DC.METERREGSVC.CUSTMETERREGLOC.O, 192.351 (192.353(a), 192.353(b), 192.353(c), References 192.353(d))

Question Text Are meters and service regulators being located consistent with the requirements of 192.353? Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

98.	Question Result, ID, References	NA, DC.METERREGSVC.CUSTMETERREGPROT.O, 192.351 (192.355(a), 192.355(b), 192.355	(c))
		Are meters and service regulators being protected from damage consistent with the requiren 192.355?	nents of
	Assets Covered	90875 (1916)	
		No such activity/condition was observed during the inspection.	
99.		NA, DC.METERREGSVC.CUSTMETERREGINSTALL.O, 192.351 (192.357(a), 192.357(b), 192.3 192.357(d))	57(c),
		Based on the meters and service regulators observed being installed, are the installations con the requirements of §192.357?	nsistent with
	Assets Covered	90875 (1916)	
	Result Notes	No such activity/condition was observed during the inspection.	
100.	Question Result, ID, References	NA, DC.METERREGSVC.CUSTMETEROPPRESS.O, 192.351 (192.359(a), 192.359(b), 192.359(	(c))
	Question Text	Are customer meter operating pressures consistent with the requirements of 192.359?	
	Assets Covered	90875 (1916)	
	Result Notes	No such activity/condition was observed during the inspection.	
101.		NA, DC.METERREGSVC.SVCLINEINSTALL.O, 192.351 (192.361(a), 192.361(b), 192.361(c), 192.361(e), 192.361(f), 192.361(g))	192.361(d),
	Question Text	Are customer service lines being installed consistent with the requirements of 192.361?	
	Assets Covered	90875 (1916)	
	Result Notes	No such activity/condition was observed during the inspection.	
102.		NA, DC.METERREGSVC.SVCLINEVLVLOCATEREQT.O, 192.351 (192.363(a), 192.363(b), 192. 192.365(a), 192.365(b), 192.365(c))	363(c),
	Question Text	Are customer service line valves being installed meeting the valve and locations requirement and 192.365?	s of 192.363
	Assets Covered	90875 (1916)	
	Result Notes	No such activity/condition was observed during the inspection.	
103.	Question Result, ID, References	NA, DC.METERREGSVC.SVCLINECONNECT.O, 192.351 (192.367(a), 192.367(b), 192.369(a),	192.369(b))
	Question Text	Are customer service lines being installed with connections meeting the requirements of 192. 192.369?	.367 and
	Assets Covered	90875 (1916)	
	Result Notes	No such activity/condition was observed during the inspection.	
104.		NA, DC.METERREGSVC.SVCLINEMATERIAL.O, 192.351 (192.371, 192.373(a), 192.373(b), 192.375(a), 192.375(b), 192.377)	92.373(c),
	Question Text	Are customer service lines being installed constructed appropriately for the types of materials	s used?
	Assets Covered	90875 (1916)	
	Result Notes	No such activity/condition was observed during the inspection.	
105.		NA, DC.METERREGSVC.NEWSVCLINENOTUSED.O, 192.351 (192.379, 192.379(a), 192.379(b) 192.379(c))	),
	Question Text	Are new customer service lines not in use configured in accordance with the requirements of	192.379?
	Assets Covered		
		No such activity/condition was observed during the inspection.	
106.	Question Result, ID, References	NA, DC.METERREGSVC.EXCSFLOWVLVLOCATE.O, 192.351 (192.381(c), 192.381(d), 192.381	l (e))
	Question Text	Are service line excess flow valves located and identified in accordance with the requirements 192.381?	s of
	Assets Covered		
		No such activity/condition was observed during the inspection.	
107.	Question Result, ID, References	NA, DC.METERREGSVC.REGTEST.O,	
Donor	t Filtors: Dosults: all	[8427] CNGC(MDU) 19Sep22 Yakima	Page 15 of 21

Question Text Are service regulators operated, maintained, installed and tested during the initial turn-on in accordance with manufacturer's recommendations and WAC requirements?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

108. Question Result, ID, NA, DC.WELDPROCEDURE.ONSITE.O, References

Question Text Are qualified written welding procedures located onsite where welding is being performed?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

109. Question Result, ID, NA, DC.WELDPROCEDURE.ESSENTIAL.O, References

> Question Text *Does the operator document essential variables when qualifying welders and weld procedures?* Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

- 110. Question Result, ID, NA, TD.COAT.NEWPIPEINSTALL.O, 192.461(d) References
  - Question Text Is external protective coating being protected from damage that could result from adverse ditch conditions or supporting blocks?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

- 111. Question Result, ID, Sat, TD.CPMONITOR.MONITORCRITERIA.O, 192.465(a) (192.463(b), 192.463(c), 192.463(a))
  - Question Text Are methods used for taking CP monitoring readings that allow for the application of appropriate CP monitoring criteria?

Assets Covered 90875 (1916)

112. Question Result, ID, Sat, TD.CPMONITOR.CURRENTTEST.O, 192.465(b) References

Question Text Do field observations confirm impressed current sources are properly maintained and are functioning properly?

Assets Covered 90875 (1916)

113. Question Result, ID, Sat, TD.CP.ELECISOLATE.O, 192.467(a) (192.467(b), 192.467(c), 192.467(d), 192.467(e)) References

Question Text Are measures performed to ensure electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?

Assets Covered 90875 (1916)

114. Question Result, ID, Sat, TD.CP.CASINGINSPECT.O, References

Question Text *Are casings electrically isolated from the pipeline?* Assets Covered 90875 (1916)

115. Question Result, ID, Sat, TD.CPMONITOR.TESTSTATION.O, 192.469 References

> Question Text *Do cathodically protected pipelines have a sufficient number of test stations?* Assets Covered 90875 (1916)

116. Question Result, ID, References NA, TD.CPMONITOR.TESTLEAD.O, 192.471(a)

Question Text Do pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

117. Question Result, ID, NA, TD.CPMONITOR.INTFRCURRENT.O, 192.473(a) References Question Text Are areas of potential stray current identified, and if found, the detrimental effects of stray currents minimized?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

118. Question Result, ID, NA, TD.CP.ADJACENTMETAL.O, 192.473(b) References

> Question Text Do field observations confirm impressed current type cathodic protection systems and galvanic anode systems are installed so as to minimize any adverse effect on existing adjacent underground metallic structures?

#### Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

#### 119. Question Result, ID, NA, TD.ICP.CORRGASPRVNT.O, 192.475(a) References

Question Text If the transportation of corrosive gas is not allowed, is the transportation of corrosive gas prevented? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

- 120. Question Result, ID, NA, TD.ICP.CORRGASACTION.O, 192.477
  - References

Question Text Are adequate actions taken when corrosive gas is being transported by pipeline? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

## 121. Question Result, ID, Sat, TD.ATM.ATMCORRODEINSP.O, 192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c))

Question Text Do field observations indicate that pipe exposed to atmospheric corrosion is properly coated? Assets Covered 90875 (1916)

Result Notes Observed during Field Day

122. Question Result, ID, NA, TD.CP.GRAPHITIZE.O, 192.489(a) (192.489(b)) References

> Question Text Has there been adequate remediation for the graphitization of cast iron or ductile iron pipe? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

123. Question Result, ID, NA, PD.DP.ONECALL.O, 192.614(c)(3) References

Question Text Observe operator process a "One Call" ticket.

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

124. Question Result, ID, Sat, MO.GOODOR.ODORIZE.O, 192.625(a) (192.625(c), 192.625(d), 192.625(e), 192.625(f)) References

Question Text Is sampling of combustible gases adequate using an instrument capable of determining the percentage of gas in air at which it becomes readily detectable?

### Assets Covered 90875 (1916)

125. Question Result, ID, NA, MO.GO.PURGE.O, 192.629(a) (192.629(b)) References

> Question Text Are lines being purged in accordance with 192.629? Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

126. Question Result, ID, Sat, MO.RW.ROWMARKER.O, 192.707(a) (192.707(b), 192.707(d), CGA Best Practices, v4.0, Practice 2-References 5, CGA Best Practices, v4.0, Practice 4-20)

Question Text Are line markers placed and maintained as required?

Assets Covered 90875 (1916)

127. Question Result, ID, Sat, MO.RW.ROWMARKERABOVE.O, 192.707(c) (CGA Best Practices, v4.0, Practice 2-5, CGA Best References Practices, v4.0, Practice 4-20)

Question Text Are line markers placed and maintained as required for above ground pipelines? Assets Covered 90875 (1916)

128. Question Result, ID, Sat, MO.GMOPP.PRESSREGTEST.O, 192.739(a) (192.739(b)) References

Question Text Are field or bench tests or inspections of regulating stations, pressure limiting stations or relief devices adequate?

Assets Covered 90875 (1916)

129. Question Result, ID, NC, MO.GMOPP.PRESSREGMETER.O, 192.741(a) (192.741(b), 192.741(c)) References

Question Text Are telemetering or recording gauges properly utilized as required for distribution systems?

### Assets Covered 90875 (1916)

Result Notes Not checked during this inspection

130. Question Result, ID, NA, MO.GMOPP.MULTIPRESSREG.O, References

> Question Text Are regulator stations installed in a manner to provide protection between regulator stages? Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

### 131. Question Result, ID, Sat, MO.GM.DISTVALVEINSPECT.O, 192.747(a) (192.747(b)) References

Question Text Is proper inspection being performed for each distribution system valve that might be required in an emergency, and prompt remedial action to correct any valves found inoperable?

### Assets Covered 90875 (1916)

Result Notes Valve operation in the field

132. Question Result, ID, NA, FS.FG.CASING.O, References

Question Text Are all casings bare steel and do they have test leads installed on new casings without vents?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

## 133. Question Result, ID, NA, FS.FG.CASESEAL.O, References

Question Text Does the operator seal both ends of casings/conduits for mains and transmission lines and seal the end nearest the building for service lines?

### Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

#### 134. Question Result, ID, NA, FS.FG.VAULTINSPECT.O, 192.749(a) (192.749(b), 192.749(c), 192.749(d)) References

Question Text Are inspections of selected vaults with internal volume =200 cubic feet (5.66 cubic meters) housing pressure regulating/limiting equipment adequate?

### Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

## 135. Question Result, ID, NA, AR.RMP.IGNITION.O, 192.751(a) (192.751(b), 192.751(c))

Question Text Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.

#### Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

### 136. Question Result, ID, NA, MO.GM.BELLSPIGOTJOINT.O, 192.753(a) (192.753(b)) References

Question Text Do records indicate that caulked bell and spigot joints were correctly sealed?

#### Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

#### 137. Question Result, ID, NA, MO.GM.CASTIRONPROTECT.O, 192.755(a) (192.755(b)) References

Question Text Is adequate protection in place for segments of a buried cast-iron pipeline for which support has been disturbed?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

## 138. Question Result, ID, NA, DC.CO.PLASTICWEAKLINK.O, 192.329(b) (192.376(b), 192.303)

Question Text Do field observations confirm plastic lines and plastic service lines are being installed using a "weak link" (as defined by §192.3) to ensure the pipeline will not be damaged by any excessive forces during the pulling process?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

139. Question Result, ID, NA, MO.GM.EQUIPPLASTICJOINT.O, 192.756 References

Question Text Is proper maintenance being performed on equipment used in joining plastic pipe by heat fusion in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

140. Question Result, ID, NA, MO.GM.ONSITEPROCS.O, References

Question Text Are procedures applicable to the work being done located onsite where the work is being done? Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

141. Question Result, ID, NA, AR.PTI.PLASTICPRESSURETEST.O, References

Question Text Is plastic pipe installed and backfilled prior to pressure testing?

Assets Covered 90875 (1916)

Result Notes No such activity/condition was observed during the inspection.

## 142. Question Result, ID, Sat, AR.PTI.EQUIPCALIB.O, References

Question Text *Is pressure testing equipment calibrated according to calibration schedules and procedures?* Assets Covered 90875 (1916)

Result Notes Reviewed gauges prior to field day

### GDIM.IMPL: GDIM Implementation

143. Question Result, ID, Sat, GDIM.RR.MECHANICALFITTINGDATAIMPL.R, 192.1009 (191.12) (also presented in: PRR.REPORT) References

Question Text Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?

Assets Covered 90875 (1916)

Result Notes Submitted on March 10, 2022 Receipt on the 11.

### Report appears complete.

144. Question Result, ID, NA, GDIM.RR.MECHANICALFITTINGRPTIMPL.R, 192.1009 (191.12) References

> Question Text Did the operator report all mechanical fitting failures that resulted in a hazardous leak for the previous calendar year to PHMSA and State authorities, as appropriate, by March 15th of the next calendar year, and did the reports contain the information required by Department of Transportation Form PHMSA F-7100.1-2?

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

### **MISCTOPICS.PROT9: OQ Field Inspection**

145. Question Result, ID, NA, TO.PROT9.CORRECTION.O, 192.801(a) (192.809(a)) References

Question Text Have potential issues identified by the OQ plan inspection process been corrected at the operational level?

Assets Covered 90875 (1916)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

146. Question Result, ID, Sat, TQ.PROT9.QUALIFICATIONSTATUS.O, 192.801(a) (192.809(a)) References

leiei ences

Question Text Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

Assets Covered 90875 (1916)

147. Question Result, ID, Sat, TQ.PROT9.TASKPERFORMANCE.O, 192.801(a) (192.809(a)) References

Question Text Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

Assets Covered 90875 (1916)

148. Question Result, ID, Sat, TQ.PROT9.AOCRECOG.O, 192.801(a) (192.809(a)) References

Question Text Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

Assets Covered 90875 (1916)

149. Question Result, ID, Sat, TO.PROT9.VERIFYQUAL.O, 192.801(a) (192.809(a)) References

Question Text Observe in the field (job site, local office, etc.) that the foreman/supervisor/manager has verified the qualification of the individual performing the task, that the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

Assets Covered 90875 (1916)

### MISCTOPICS.OPTRQUAL: Operator Qualification

150. Question Result, ID, Sat, TQ.OQ.OQPLAN.O, 192.805(h) References

References

Question Text *Do individuals performing covered tasks demonstrate adequate skills, knowledge, and ability?* Assets Covered 90875 (1916)

151. Question Result, ID, Sat, TQ.OQ.ABNORMAL.O, 192.803 References

Question Text Do individuals performing covered tasks have adequate knowledge to recognize and react to abnormal operating conditions?

Assets Covered 90875 (1916)

### **MISCTOPICS.PUBAWARE:** Public Awareness Program Effectiveness

152. Question Result, ID, Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), References 192.616(c), ADB-05-03) (also presented in: PRR.OM)

Question Text Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?

Assets Covered 90875 (1916)

Result Notes Newsletter mailing records for Liaison appear adequate.

153. Question Result, ID, Sat, PD.PA.LANGUAGE.R, 192.616(g) (API RP 1162 Section 2.3.1) (also presented in: PRR.OM) References

Question Text Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?

Assets Covered 90875 (1916)

Result Notes Reviewed English and Spanish language fliers, and 7 other languages are available on the web site.

- 154. Question Result, ID, NC, PD.PA.EVALEFFECTIVENESS.R, 192.616(c) (API RP 1162 Section 8.4) (also presented in: PRR.OM) References
  - Question Text *Do records indicate program effectiveness evaluation(s) have been performed and cover all program requirements and all systems covered by the program?*
  - Assets Covered 90875 (1916)

Result Notes Will be reviewed on the PA inspection next week

155. Question Result, ID, NA, PD.PA.MSTRMETER.R, 192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 References Section 8.5) (also presented in: PRR.OM)

Question Text Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?

Assets Covered 90875 (1916)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

# **Inspection Results (IRR)**

Generated on 2022.October.09 13:48

### • 90875 (1916) (155)

Ro w	Assets	Resu It	(Note 1)	Sub-Group	Qs t #	Question ID	References	Question Text
1.	90875 (19 16)	Sat		PRO.SUBLNORMOP S	7.	MO.GO.ODDOR.P	192.605(a) (192.605(b)( 11))	Does the process require prompt response to the report of a gas odor inside or near a building?
2.	90875 (19 16)	Sat		PRR.REPORT	1.	RPT.RR.IMMEDREPORT.R	191.5(a) (191.7(a), 191.7(d))	Do records indicate immediate notifications of incidents were made in accordance with 191.5?
3.	90875 (19 16)	NA		PRR.REPORT	2.	RPT.RR.INCIDENTREPORT.R	191.9(a)	Do records indicate reportable incidents were identified and reports were submitted to DOT on Form 7100.1 within the required time frame?
4.	90875 (19 16)	NA		PRR.REPORT	3.	RPT.RR.INCIDENTREPORTSUPP.R	191.9(b)	Do records indicate accurate supplemental incident reports were filed and within the required timeframe?
5.	90875 (19 16)	Sat		PRR.REPORT	4.	RPT.RR.ANNUALREPORT.R	191.11(a)	Have complete and accurate Annual Reports been submitted?
6.	90875 (19 16)	Sat		PRR.REPORT	5.	RPT.RR.UTCANNUALREPORTS.R		Have complete and accurate annual reports been submitted to the commission?
7.	90875 (19 16)	Sat		PRR.REPORT	6.	RPT.RR.MISDATAREPORTS.R		Has the operator submitted a copy of DOT Drug and Alcohol Testing MIS Data Collection Form to the commission when required?
8.	90875 (19 16)	Sat	2	PRR.REPORT	7.	GDIM.RR.MECHANICALFITTINGDATAI MPL.R	192.1009 (191.12)	Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?
9.	90875 (19 16)	NA		PRR.REPORT	8.	RPT.RR.SRCR.R	191.23(a) (191.23(b), 191.25(a), 191.25(c))	Do records indicate safety-related condition reports were filed as required?
10.	90875 (19 16)	NA		PRR.REPORT	9.	RPT.RR.MAOPINCREASENOTIFY.R		Do records indicate submittal of a written plan of procedures to the commission at least forty-five days before uprating to a

Ro		Resu	(Note		Qs t			
w	Assets	lt	<sup>1</sup> )	Sub-Group	#	Question ID	References	<b>Question Text</b>
								MAOP greater than 60 psig?
11.	90875 (19 16)	Sat		PRR.REPORT	10	RPT.RR.THIRTYDAYRPT.R		Has the operator submitted a written report within 30 days following each reportable incident?
12.	90875 (19 16)	Sat		PRR.REPORT	11	MO.GO.CUSTNOTIFY.R	192.16(d) (192.16(a), 192.16(b), 192.16(c))	Do records indicate the customer notification process satisfies the requirements of 192.16?
13.	90875 (19 16)	Sat		PRR.REPORT	12	RPT.RR.DAILYCONSTRUCTIONRPT.R		Do records indicate daily construction and repair activities were emailed to the commission no later than 10 AM each day work is scheduled?
14.	90875 (19 16)	Sat		PRR.REPORT	13	RPT.RR.PIPELINEMAPPING.R		Has the operator provided accurate maps (or updates) of all pipelines operating over 250 psig to specifications developed by the commission sufficient to meet the needs of first responders?
15.	90875 (19 16)	Sat		PRR.CORROSION	1.	TQ.QU.CORROSION.R	192.453 (192.807(a), 192.807(b))	Do records indicate qualification of personnel implementing pipeline corrosion control methods?
16.	90875 (19 16)	Sat		PRR.CORROSION	2.	TD.CP.RECORDS.R	192.491(a) (192.491(b), 192.491(c))	Do records indicate the location of all corrosion control items listed in §192.491(a)?
17.	90875 (19 16)	Sat		PRR.CORROSION	3.	TD.CPMONITOR.CURRENTTEST.R	192.491(c) (192.465(b))	Do records document details of electrical checks of sources of rectifiers or other impressed current sources?
18.	90875 (19 16)	Sat		PRR.CORROSION	4.	TD.CPEXPOSED.EXPOSEINSPECT.R	192.491(c) (192.459)	Do records adequately document that exposed buried piping was examined for corrosion?
19.	90875 (19 16)	Sat		PRR.CORROSION	5.	TD.CPMONITOR.TEST.R	192.491(c) (192.465(a))	Do records adequately document cathodic protection monitoring tests have occurred as required?
20.	90875 (19 16)	NA		PRR.CORROSION	6.	TD.CPMONITOR.REVCURRENTTEST.R	192.491(c) (192.465(c))	Do records document details of electrical checks interference bonds, diodes, and reverse current switches?

_		_	<i>.</i>		Qs			
Ro w	Assets	Resu It	(Note <sup>1</sup> )	Sub-Group	t #	Question ID	References	Question Text
21.	90875 (19 16)	Sat		PRR.CORROSION	7.	TD.CPMONITOR.DEFICIENCY.R	192.491(c) (192.465(d))	Do records adequately document actions taken to correct any identified deficiencies in corrosion control?
22.	90875 (19 16)	NA		PRR.CORROSION	8.	TD.CP.UNPROTECT.R	192.491(c) (192.465(e))	Do records adequately document that exposed buried piping was examined for corrosion and deteriorated coating?
23.	90875 (19 16)	NA		PRR.CORROSION	9.	FS.FG.CASINGTESTLEAD.R		Do records indicate that all casings without vents installed after September 5, 1992 had separate test lead wires installed?
24.	90875 (19 16)	NA		PRR.CORROSION	10	FS.FG.CASINGSEALS.R		Do records indicate that mains and service lines installed in casing or conduit are sealed at the ends as required?
25.	90875 (19 16)	NA		PRR.CORROSION	11	TD.CP.ELECISOLATE.R	192.491(c) (192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e))	Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?
26.	90875 (19 16)	Sat		PRR.CORROSION	13	TD.CP.CASINGINSPECT.R		Do records indicate that annual casing inspections have been performed to ensure electrical isolation from the pipeline?
27.	90875 (19 16)	Sat		PRR.CORROSION	14	TD.CPMONITOR.TESTSTATION.R	192.469	Do records identify the location of test stations and show a sufficient number of test stations?
28.	90875 (19 16)	Sat		PRR.CORROSION	15	TD.CPMONITOR.TESTLEAD.R	192.491(c) (192.471(a), 192.471(b), 192.471(c))	Do records document that pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?
29.	90875 (19 16)	Sat		PRR.CORROSION	16	TD.CPMONITOR.INTFRCURRENT.R	192.491(c) (192.473(a))	Do records document an effective program is in place to minimize detrimental effects of interference currents and that detrimental effects of interference currents from CP systems on other

Do		Docu	(Noto		Qs t			
Ro w	Assets	lt	(Note <sup>1</sup> )	Sub-Group	ι #	Question ID	References	Question Text
								underground metallic structures are minimized?
30.	90875 (19 16)	NA		PRR.CORROSION	17	TD.ICP.CORRGAS.R	192.491(c) (192.475(a))	Do the records demonstrate that the corrosive effect of the gas in the pipeline has been investigated and if determined to be corrosive, steps be taken to minimize internal corrosion?
31.	90875 (19 16)	Sat		PRR.CORROSION	18	TD.ICP.EXAMINE.R	192.491(c) (192.475(a), 192.475(b))	Do records document examination of removed pipe for evidence of internal corrosion?
32.	90875 (19 16)	NA		PRR.CORROSION	19	TD.ICP.CORRGASACTION.R	192.491(c) (192.477)	Do records document the actions taken when corrosive gas is being transported by pipeline?
33.	90875 (19 16)	Sat		PRR.CORROSION	20	TD.ATM.ATMCORRODEINSP.R	192.491(c) (192.481(a), 192.481(b), 192.481(c))	Do records document inspection of aboveground pipe for atmospheric corrosion?
34.	90875 (19 16)	Sat		PRR.CORROSION	21	TD.COAT.NEWPIPE.R	192.491(c) (192.455(a), 192.461(a), 192.461(b), 192.483(a))	Do records document that each buried or submerged pipeline installed after July 31, 1971 has been externally coated with a suitable coating material?
35.	90875 (19 16)	Sat		PRR.CORROSION	23	TD.ICP.EVALUATE.R	192.491(c) (192.487)	Do records document adequate evaluation of internally corroded pipe?
36.	90875 (19 16)	NA		PRR.CORROSION	24	AR.RCOM.REPAIR.R	192.487 (192.489)	Do records document the repair or replacement of pipe that has been internally corroded to an extent that there is not sufficient remaining strength in the pipe wall?
37.	90875 (19 16)	Sat		PRR.PT	1.	DC.PTLOWPRESS.PRESSTESTLOWSTR ESS.R	192.517(a) (192.507(a), 192.507(b), 192.507(c))	Do records indicate that pressure testing is conducted in accordance with 192.507?
	90875 (19 16)			PRR.PT	2.	DC.PTLOWPRESS.PRESSTEST100PSIG .R	192.517(b) (192.509(a), 192.509(b))	Do records indicate that pressure testing is conducted in accordance with 192.509(a) (except for service lines and plastic pipelines)?
39.	90875 (19 16)	Sat		PRR.PT	3.	DC.PT.SERVICELINE.R	192.517(b) (192.511(a), 192.511(b), 192.511(c))	Do records indicate that pressure testing is conducted in

			1		Qs	IT (ALL RESULS) - SCP_FR		
Ro w	Assets	Resu It	(Note 1)	Sub-Group	t #	Question ID	References	Question Text
								accordance with 192.511?
40.	90875 (19 16)	Sat		PRR.PT	4.	DC.PT.PRESSTESTPLASTIC.R	192.517(b) (192.513(a), 192.513(b), 192.513(c), 192.513(d))	Do records indicate that pressure testing is conducted in accordance with 192.513?
41.	90875 (19 16)	NA		PRR.UPRATE	1.	MO.GOUPRATE.MAOPINCREASE.R	192.553(a) (192.553(b), 192.553(c))	Do records indicate that increases in MAOP of pipeline were determined in accordance with 192.553?
42.	90875 (19 16)	NA		PRR.UPRATE	2.	MO.GOUPRATE.MAOPINCREASELIMIT. R	192.553(b) (192.553(c), 192.553(d), 192.557(a))	Do records indicate that increases in MAOP are limited in accordance with 192.619 and 192.621?
43.	90875 (19 16)	NA		PRR.UPRATE	3.	MO.GOUPRATE.MAOPINCREASEPREP. R	192.553(b) (192.553(c), 192.553(a), 192.557(b), 192.557(c))	Do records indicate that increases in MAOP were preceded by the actions specified in 192.557?
44.	90875 (19 16)	NA		PRR.UPRATE	4.	MO.GOUPRATE.MAOPINCREASECASTD UCTILE.R	192.553(b) (192.553(c), 192.557(d))	Do records indicate that requirements were followed for increasing the MAOP for cast iron or ductile iron pipe where records are inadequate for evaluating the level of safety of the pipeline when operating at the proposed increased pressure?
45.	90875 (19 16)	Sat		PRR.OM	1.	MO.GO.OMANNUALREVIEW.R	192.605(a)	Have annual reviews of the written procedures or processes in the manual been conducted as required?
46.	90875 (19 16)	Sat		PRR.OM	2.	MO.GO.OMHISTORY.R	192.605(a) (192.605(b)( 3))	Are construction records, maps and operating history available to appropriate operating personnel?
47.	90875 (19 16)	Sat		PRR.OM	3.	MO.GO.OMEFFECTREVIEW.R	192.605(a) (192.605(b)( 8))	Do records indicate periodic review of the work done by operator personnel to determine the effectiveness, and adequacy of the processes used in normal operations and maintenance and modifying the processes when deficiencies are found?
48.	90875 (19 16)	NA		PRR.OM	5.	MO.GOCLASS.CLASSLOCATESTUDY.R	192.605(b)(1 ) (192.609(a), 192.609(b), 192.609(c), 192.609(d),	Do records indicate performance of the required study whenever the population along a pipeline increased or

Ro w	Assets	Resu It	(Note 1)	Sub-Group	Qs t #	Question ID	References	Question Text
							192.609(e), 192.609(f))	there was an indication that the pipe hoop stress was not commensurate with the present class location?
49.	90875 (19 16)	Sat		PRR.OM	6.	EP.ERG.POSTEVNTREVIEW.R	1),	Do records indicate review of employee activities to determine whether the procedures were effectively followed in each emergency?
50.	90875 (19 16)	Sat		PRR.OM	7.	EP.ERG.TRAINING.R	192.605(a) (192.615(b)( 2))	Has the operator trained the appropriate operating personnel on emergency procedures and verified that the training was effective in accordance with its procedures?
51.	90875 (19 16)	Sat	2	PRR.OM	8.	EP.ERG.LIAISON.R	),	Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?
52.	90875 (19 16)	Sat	2	PRR.OM	10	PD.PA.LANGUAGE.R	192.616(g) (API RP 1162 Section 2.3.1)	Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non- English speaking populations in the operator's areas?
53.	90875 (19 16)	NC	2	PRR.OM	11	PD.PA.EVALEFFECTIVENESS.R	192.616(c) (API RP 1162 Section 8.4)	Do records indicate program effectiveness evaluation(s) have been performed and cover all program requirements and all systems covered by the program?
54.	90875 (19 16)	NA	2	PRR.OM	12	PD.PA.MSTRMETER.R	192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 Section 8.5)	Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?
55.	90875 (19 16)	NA		PRR.OM	13	EP.ERG.INCIDENTANALYSIS.R	192.605(a) (192.617)	Do records indicate actions initiated to analyze accidents and failures, including the collection of appropriate samples for laboratory

Ro w	Assets	Resu It	(Note 1)	Sub-Group	Qs t #	Question ID	References	Question Text
								examination to determine the causes of the failure and minimize the possibility of recurrence, in accordance with its procedures?
56.	90875 (19 16)	NC		PRR.OM	14	PD.DP.PDPROGRAM.R	192.614(c)	Does the damage prevention program meet minimum requirements specified in 192.614(c)?
57.	90875 (19 16)	Sat		PRR.OM	15	MO.GOMAOP.MAOPDETERMINE.R	192.619(a) (192.619(b), 192.621(a), 192.621(b), 192.623(a), 192.623(b))	Do records indicate determination of the MAOP of pipeline segments in accordance with 192.619 and limiting of the operating pressure as required?
58.	90875 (19 16)	Sat		PRR.OM	16	MO.GOODOR.ODORIZE.R	192.709(c) (192.625(a), 192.625(b), 192.625(c), 192.625(d), 192.625(e), 192.625(f))	Do records indicate appropriate odorization of its combustible gases in accordance with its processes and conduct of the required testing to verify odorant levels met requirements?
59.	90875 (19 16)	Sat		PRR.OM	19	MO.RW.DISTPATROL.R	192.603(b) (192.721(a), 192.721(b))	Do records indicate distribution patrolling was conducted as required?
60.	90875 (19 16)	Sat		PRR.OM	20	MO.RW.LEAKFOLLOW.R		Do records indicate that a follow-up inspection was performed not more than thirty days following a repair where residual gas remained in the ground?
61.	90875 (19 16)	NA		PRR.OM	21	MO.RW.DOWNGRADELEAKREPAIR.R		Do records indicate that leaks that have been downgraded are repaired within twenty- one months?
62.	90875 (19 16)	Sat		PRR.OM	22	MO.RW.LEAKREPAIRTIME.R		Do records indicate that leaks were repaired and re- evaluated in the timeframes specified in WAC 480-93-18601?
63.	90875 (19 16)	Sat		PRR.OM	23	MO.RW.LEAKRECORDS.R		Have gas leak records been prepared and maintained as required?
64.	90875 (19 16)	Sat		PRR.OM	24	MO.RW.DISTPATROLLEAKAGE.R	192.603(b) (192.723(a), 192.723(b))	Do records indicate distribution leakage surveys were conducted as required?
65.	90875 (19 16)	Sat		PRR.OM	25	MO.RW.CASINGLEAKSURVEY.R		Do records indicate shorted casings were

_		_	<i>.</i>		Qs			
Ro w	Assets	Resu It	(Note <sup>1</sup> )	Sub-Group	t #	Question ID	References	Question Text
								leak surveyed as required?
66.	90875 (19 16)	Sat		PRR.OM	26	MO.RW.MARKERSURVEY.R		Do records indicate that pipeline marker surveys were completed in the timeframe specified by WAC 480-93-124?
67.	90875 (19 16)	Sat		PRR.OM	27	MO.RW.MARKERREPLACE.R		Do records indicate that damaged or missing markers were replaced within forty- five days of discovery?
68.	90875 (19 16)	Sat		PRR.OM	28	AR.RMP.TESTREINSTATE.R	192.603(b) (192.725(a), 192.725(b))	From the review of records, did the operator properly test disconnected service lines?
69.	90875 (19 16)	Sat		PRR.OM	30	MO.GMOPP.PRESSREGTEST.R	192.709(c) (192.739(a), 192.739(b))	Do records indicate inspection and testing of pressure limiting, relief devices, and pressure regulating stations?
70.	90875 (19 16)	Sat		PRR.OM	31	MO.GMOPP.PRESSREGCAP.R	192.709(c) (192.743(a), 192.743(b), 192.743(c))	Do records indicate testing or review of the capacity of each pressure relief device at each pressure limiting station and pressure regulating station as required?
71.	90875 (19 16)	Sat		PRR.OM	32	DC.METERREGSVC.REGTEST.R		Do records indicate that service regulators have been installed, operated, maintained, tested during initial turn-on and tested when customers experience pressure problems?
72.	90875 (19 16)	Sat		PRR.OM	33	MO.GM.DISTVALVEINSPECT.R	192.603(b) (192.747(a), 192.747(b))	Do records indicate proper inspection of each distribution system valve that might be required in an emergency at intervals not exceeding 15 months, but at least once each calendar year, and prompt remedial action to correct any valve found inoperable?
73.	90875 (19 16)	NA		PRR.OM	34	FS.FG.VAULTINSPECT.R	192.709(c) (192.749(a), 192.749(b), 192.749(c), 192.749(d))	Do records document the adequacy of inspections of all vaults having an internal volume =200 cubic feet (5.66 cubic meters) that house pressure

_		_	<i>.</i>		Qs			
Ro w	Assets	Resu It	(Note <sup>1</sup> )	Sub-Group	t #	Question ID	References	Question Text
								regulating/limiting equipment?
74.	90875 (19 16)	Sat		PRR.OM	35	MO.GM.IGNITION.R	192.709 (192.751(a), 192.751(b), 192.751(c))	Do records indicate personnel followed processes for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion?
75.	90875 (19 16)	NA		PRR.OM	36	MO.GM.BELLSPIGOTJOINT.R	192.603(b) (192.753(a), 192.753(b))	Do records indicate that caulked bell and spigot joints were correctly sealed?
76.	90875 (19 16)	Sat		PRR.OM	37	DC.DPC.FLANGE.R	192.147(a) (192.147(b), 192.147(c))	Do records indicate flanges and flange accessories meet the requirements of 192.147?
77.	90875 (19 16)	Sat		PRR.OM	38	DC.WELDPROCEDURE.WELD.R	192.225(a) (192.225(b))	Do records indicate weld procedures are being qualified in accordance with 192.225?
78.	90875 (19 16)	Sat		PRR.OM	39	DC.WELDPROCEDURE.ESSENTIAL.R		Do records indicate that essential variables were measured and documented when welders and procedures were qualified?
79.	90875 (19 16)	Sat		PRR.OM	40	TQ.QUOMCONST.WELDER.R	192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))	Do records indicate adequate qualification of welders?
80.	90875 (19 16)	Sat		PRR.OM	41	TQ.QUOMCONST.NDT.R	192.243(b)(2 ) (192.807(a), 192.807(b), 192.328(a), 192.328(b))	Do records indicate the qualification of nondestructive testing personnel?
81.	90875 (19 16)	Sat		PRR.OM	42	DC.CO.PLASTICJOINTPROCEDURE.R	192.273(b) (192.283(a), 192.283(b), 192.283(c))	Have plastic pipe joining procedures been qualified in accordance with 192.283?
82.	90875 (19 16)	Sat		PRR.OM	43	DC.CO.PLASTICJOINTQUAL.R	192.285(d) (192.285(a), 192.285(b), 192.285(c), 192.807(a), 192.807(b))	Do records indicate persons making joints in plastic pipelines are qualified in accordance with 192.285?
83.	90875 (19 16)	Sat		PRR.OM	44	DC.CO.PLASTICJOINTINSP.R	192.287 (192.807(a), 192.807(b))	Do records indicate persons inspecting the making of plastic pipe

Ro		Resu	(Note	Qs t			
w	Assets	lt	<sup>1</sup> ) Sub-Group	#	Question ID	References	Question Text
							joints have been qualified?
84.	90875 (19 16)	Sat	PRR.OM	45	DC.CO.PLASTICPIPESEP.R		Do records indicate minimum separation requirements are met for plastic pipelines?
85.	90875 (19	Sat	PRR.OM	46	MO.GM.EQUIPPLASTICJOINT.R	192.603(b) (192.756)	Do records indicate equipment used in joining plastic pipe by heat fusion was maintained in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?
86.	90875 (19 16)	NA	PRR.OM	47	MO.GM.RECORDS.R	192.605(b)(1 ) (192.243(f), 192.709(a), 192.709(b), 192.709(c))	Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?
87.	90875 (19 16)	NA	PRR.OM	49	MO.GM.MOVEANDLOWER.R		Do records indicate that a study was prepared before moving or lowering a steel gas pipeline as required?
88.	90875 (19 16)	NA	PRR.OM	50	MO.GM.MOVEANDLOWERSURVEY.R		Do records indicate that a leak survey was conducted not more than thirty days after moving and/or lowering a metallic pipeline?
89.	90875 (19 16)	Sat	PRR.OM	51	MO.RW.MARKERSMAPSDRAW.R		Are records sufficient to indicate class location and other areas where pipeline markers are required?
90.	90875 (19 16)	Sat	FR.FIELDPIPE	1.	DC.MA.MARKING.O	192.63(a) (192.63(b), 192.63(c), 192.63(d))	Are pipe, valves, and fittings properly marked for identification in accordance with the requirements of 192.63?
91.	90875 (19 16)	Sat	FR.FIELDPIPE	2.	DC.DPC.FLANGE.O	192.141 (192.147(a), 192.147(b), 192.147(c))	Do flanges and flange accessories meet the requirements of 192.147?
92.	90875 (19 16)	NA	FR.FIELDPIPE	3.	DC.DPC.GDVALVEPLACEMENT.O	192.141 (192.181(a), 192.181(b), 192.181(c))	Are distribution line valves being installed as required of 192.181?

Ro w	Assets	Resu It	(Note 1)	Sub-Group	Qs t #	Question ID	References	Question Text
93.	90875 (19 16)	Sat		FR.FIELDPIPE	4.	DC.CO.PLASTICPIPEPROC.O		Is plastic pipe handled, stored and installed in accordance with manufacturer's recommendations, including maximum ultraviolet exposure?
94.	90875 (19 16)	NA		FR.FIELDPIPE	5.	DC.CO.PLASTICPIPESEP.O		Are plastic pipelines installed with the minimum separation from other utilities as required?
95.	90875 (19 16)	NA		FR.FIELDPIPE	6.	DC.CO.PLASTICBACKFILL.O		Is plastic pipe buried in essentially rock-free material or material recommended by the pipe manufacturer?
96.	90875 (19 16)	NA		FR.FIELDPIPE	7.	DC.CO.PLASTICSQUEEZING.O		Verify that the operator has limits in place for squeezing plastic pipe.
97.	90875 (19 16)	NA		FR.FIELDPIPE	8.	DC.METERREGSVC.CUSTMETERREGLO C.O	192.351 (192.353(a), 192.353(b), 192.353(c), 192.353(d))	Are meters and service regulators being located consistent with the requirements of 192.353?
98.	90875 (19 16)	NA		FR.FIELDPIPE	9.	DC.METERREGSVC.CUSTMETERREGPR OT.O	192.351 (192.355(a), 192.355(b), 192.355(c))	Are meters and service regulators being protected from damage consistent with the requirements of 192.355?
99.	90875 (19 16)	NA		FR.FIELDPIPE	10	DC.METERREGSVC.CUSTMETERREGIN STALL.O	192.351 (192.357(a), 192.357(b), 192.357(c), 192.357(d))	Based on the meters and service regulators observed being installed, are the installations consistent with the requirements of §192.357?
100	90875 (19 16)	NA		FR.FIELDPIPE	11	DC.METERREGSVC.CUSTMETEROPPRE SS.O	192.351 (192.359(a), 192.359(b), 192.359(c))	Are customer meter operating pressures consistent with the requirements of 192.359?
101	90875 (19 16)	NA		FR.FIELDPIPE	12	DC.METERREGSVC.SVCLINEINSTALL. O	192.351 (192.361(a), 192.361(b), 192.361(c), 192.361(d), 192.361(e), 192.361(f), 192.361(g))	Are customer service lines being installed consistent with the requirements of 192.361?
102	90875 (19 16)	NA		FR.FIELDPIPE	13	DC.METERREGSVC.SVCLINEVLVLOCAT EREQT.O	192.351 (192.363(a), 192.363(b), 192.363(c), 192.365(a), 192.365(b), 192.365(c))	Are customer service line valves being installed meeting the valve and locations requirements of 192.363 and 192.365?
103	90875 (19 16)	NA		FR.FIELDPIPE	14	DC.METERREGSVC.SVCLINECONNECT. O	192.351 (192.367(a), 192.367(b), 192.369(a), 192.369(b))	Are customer service lines being installed with connections meeting the

De		Deeu	(Nete		Qs			
Ro w	Assets	lt	(Note <sup>1</sup> )	Sub-Group	t #	Question ID	References	Question Text
								requirements of 192.367 and 192.369?
	90875 (19 16)	NA		FR.FIELDPIPE	15	DC.METERREGSVC.SVCLINEMATERIAL .O	192.351 (192.371, 192.373(a), 192.373(b), 192.373(c), 192.375(a), 192.375(b), 192.377)	Are customer service lines being installed constructed appropriately for the types of materials used?
105	90875 (19 16)	NA		FR.FIELDPIPE	16	DC.METERREGSVC.NEWSVCLINENOTU SED.O	192.351 (192.379, 192.379(a), 192.379(b), 192.379(c))	Are new customer service lines not in use configured in accordance with the requirements of 192.379?
106	90875 (19 16)	NA		FR.FIELDPIPE	17	DC.METERREGSVC.EXCSFLOWVLVLOC ATE.O	192.351 (192.381(c), 192.381(d), 192.381(e))	Are service line excess flow valves located and identified in accordance with the requirements of 192.381?
	90875 (19 16)	NA		FR.FIELDPIPE	18	DC.METERREGSVC.REGTEST.O		Are service regulators operated, maintained, installed and tested during the initial turn- on in accordance with manufacturer's recommendations and WAC requirements?
108	90875 (19 16)	NA		FR.FIELDPIPE	19	DC.WELDPROCEDURE.ONSITE.O		Are qualified written welding procedures located onsite where welding is being performed?
109	90875 (19 16)	NA		FR.FIELDPIPE	20	DC.WELDPROCEDURE.ESSENTIAL.O		Does the operator document essential variables when qualifying welders and weld procedures?
	90875 (19 16)	NA		FR.FIELDPIPE	21	TD.COAT.NEWPIPEINSTALL.O	192.461(d)	Is external protective coating being protected from damage that could result from adverse ditch conditions or supporting blocks?
	90875 (19 16)	Sat		FR.FIELDPIPE	23	TD.CPMONITOR.MONITORCRITERIA.O	192.465(a) (192.463(b), 192.463(c), 192.463(a))	Are methods used for taking CP monitoring readings that allow for the application of appropriate CP monitoring criteria?
	90875 (19 16)	Sat		FR.FIELDPIPE	24	TD.CPMONITOR.CURRENTTEST.O	192.465(b)	Do field observations confirm impressed current sources are properly maintained and are functioning properly?
113	90875 (19 16)	Sat		FR.FIELDPIPE	25	TD.CP.ELECISOLATE.O	192.467(a) (192.467(b), 192.467(c), 192.467(d), 192.467(e))	Are measures performed to ensure electrical isolation of each buried or submerged pipeline

Ro		Resu	(Note		Qs t			
w	Assets	lt	<sup>1</sup> )	Sub-Group	#	Question ID	References	Question Text
								from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?
114	90875 (19 16)	Sat		FR.FIELDPIPE	27	TD.CP.CASINGINSPECT.O		Are casings electrically isolated from the pipeline?
115	90875 (19 16)	Sat		FR.FIELDPIPE	28	TD.CPMONITOR.TESTSTATION.O	192.469	Do cathodically protected pipelines have a sufficient number of test stations?
116	90875 (19 16)	NA		FR.FIELDPIPE	29	TD.CPMONITOR.TESTLEAD.O	192.471(a)	Do pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?
117	90875 (19 16)	NA		FR.FIELDPIPE	30	TD.CPMONITOR.INTFRCURRENT.O	192.473(a)	Are areas of potential stray current identified, and if found, the detrimental effects of stray currents minimized?
	90875 (19 16)	NA		FR.FIELDPIPE	31	TD.CP.ADJACENTMETAL.O	192.473(b)	Do field observations confirm impressed current type cathodic protection systems and galvanic anode systems are installed so as to minimize any adverse effect on existing adjacent underground metallic structures?
119	90875 (19 16)	NA		FR.FIELDPIPE	32	TD.ICP.CORRGASPRVNT.O	192.475(a)	If the transportation of corrosive gas is not allowed, is the transportation of corrosive gas prevented?
120	90875 (19 16)	NA		FR.FIELDPIPE	33	TD.ICP.CORRGASACTION.O	192.477	Are adequate actions taken when corrosive gas is being transported by pipeline?
121	90875 (19 16)	Sat		FR.FIELDPIPE	35	TD.ATM.ATMCORRODEINSP.O	192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c))	Do field observations indicate that pipe exposed to atmospheric corrosion is properly coated?
122	90875 (19 16)	NA		FR.FIELDPIPE	37	TD.CP.GRAPHITIZE.O	192.489(a) (192.489(b))	Has there been adequate remediation for the graphitization of cast iron or ductile iron pipe?

Ro		Resu	(Note	Qs t			
w	Assets	lt	<sup>1</sup> ) Sub-Gro		Question ID	References	Question Text
123	90875 (19 16)	NA	FR.FIELDPIPE	E 38	PD.DP.ONECALL.O	192.614(c)(3 )	Observe operator process a "One Call" ticket.
124	90875 (19 16)	Sat	FR.FIELDPIPE	E 39	MO.GOODOR.ODORIZE.O	192.625(a) (192.625(c), 192.625(d), 192.625(e), 192.625(f))	Is sampling of combustible gases adequate using an instrument capable of determining the percentage of gas in air at which it becomes readily detectable?
125	90875 (19 16)	NA	FR.FIELDPIPE	E 40	MO.GO.PURGE.O	192.629(a) (192.629(b))	Are lines being purged in accordance with 192.629?
126	90875 (19 16)	Sat	FR.FIELDPIPE	E 41	MO.RW.ROWMARKER.O	192.707(a) (192.707(b), 192.707(d), CGA Best Practices, v4.0, Practice 2-5, CGA Best Practices, v4.0, Practice 4-20)	Are line markers placed and maintained as required?
127	90875 (19 16)	Sat	FR.FIELDPIPE	E 42	MO.RW.ROWMARKERABOVE.O	192.707(c) (CGA Best Practices, v4.0, Practice 2-5, CGA Best Practices, v4.0, Practice 4-20)	Are line markers placed and maintained as required for above ground pipelines?
128	90875 (19 16)	Sat	FR.FIELDPIPE	E 43	MO.GMOPP.PRESSREGTEST.O	192.739(a) (192.739(b))	Are field or bench tests or inspections of regulating stations, pressure limiting stations or relief devices adequate?
129	90875 (19 16)	NC	FR.FIELDPIPE	E 44	MO.GMOPP.PRESSREGMETER.O	192.741(a) (192.741(b), 192.741(c))	Are telemetering or recording gauges properly utilized as required for distribution systems?
130	90875 (19 16)	NA	FR.FIELDPIPE	E 45	MO.GMOPP.MULTIPRESSREG.O		Are regulator stations installed in a manner to provide protection between regulator stages?
131	90875 (19 16)	Sat	FR.FIELDPIPE	E 46	MO.GM.DISTVALVEINSPECT.O	192.747(a) (192.747(b))	Is proper inspection being performed for each distribution system valve that might be required in an emergency, and prompt remedial action to correct any valves found inoperable?
132	90875 (19 16)	NA	FR.FIELDPIPE	E   47	FS.FG.CASING.O		Are all casings bare steel and do they have test leads installed on

		<b>D</b>	<b>(1</b> ) - 1 - 1		Qs			
Ro w	Assets	Resu It	(Note <sup>1</sup> )	Sub-Group	t #	Question ID	References	Question Text
								new casings without vents?
133	90875 (19 16)	NA		FR.FIELDPIPE	48	FS.FG.CASESEAL.O		Does the operator seal both ends of casings/conduits for mains and transmission lines and seal the end nearest the building for service lines?
134	90875 (19 16)	NA		FR.FIELDPIPE	49	FS.FG.VAULTINSPECT.O	192.749(a) (192.749(b), 192.749(c), 192.749(d))	Are inspections of selected vaults with internal volume =200 cubic feet (5.66 cubic meters) housing pressure regulating/limiting equipment adequate?
135	90875 (19 16)	NA		FR.FIELDPIPE	50	AR.RMP.IGNITION.O	192.751(a) (192.751(b), 192.751(c))	Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.
136	90875 (19 16)	NA		FR.FIELDPIPE	51	MO.GM.BELLSPIGOTJOINT.O	192.753(a) (192.753(b))	Do records indicate that caulked bell and spigot joints were correctly sealed?
137	90875 (19 16)	NA		FR.FIELDPIPE	52	MO.GM.CASTIRONPROTECT.O	192.755(a) (192.755(b))	Is adequate protection in place for segments of a buried cast-iron pipeline for which support has been disturbed?
138	90875 (19 16)	NA		FR.FIELDPIPE	55	DC.CO.PLASTICWEAKLINK.O	192.329(b) (192.376(b), 192.303)	Do field observations confirm plastic lines and plastic service lines are being installed using a "weak link" (as defined by §192.3) to ensure the pipeline will not be damaged by any excessive forces during the pulling process?
139	90875 (19 16)	NA		FR.FIELDPIPE	56	MO.GM.EQUIPPLASTICJOINT.O	192.756	Is proper maintenance being performed on equipment used in joining plastic pipe by heat fusion in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?
140	90875 (19 16)	NA		FR.FIELDPIPE	57	MO.GM.ONSITEPROCS.O		Are procedures applicable to the work being done located

Ro w	Assets	Resu It	(Note 1)	Sub-Group	Qs t #	Question ID	References	Question Text
								onsite where the work is being done?
141	90875 (19 16)	NA		FR.FIELDPIPE	59	AR.PTI.PLASTICPRESSURETEST.O		Is plastic pipe installed and backfilled prior to pressure testing?
142	90875 (19 16)	Sat		FR.FIELDPIPE	60	AR.PTI.EQUIPCALIB.O		Is pressure testing equipment calibrated according to calibration schedules and procedures?
143	90875 (19 16)	Sat	2	GDIM.IMPL	34	GDIM.RR.MECHANICALFITTINGDATAI MPL.R	192.1009 (191.12)	Have accurate records been maintained documenting mechanical fitting failures that resulted in hazardous leaks?
	90875 (19	NA		GDIM.IMPL	35	GDIM.RR.MECHANICALFITTINGRPTIM PL.R	192.1009 (191.12)	Did the operator report all mechanical fitting failures that resulted in a hazardous leak for the previous calendar year to PHMSA and State authorities, as appropriate, by March 15th of the next calendar year, and did the reports contain the information required by Department of Transportation Form PHMSA F-7100.1-2?
145	90875 (19 16)	NA		MISCTOPICS.PROT 9	1.	TQ.PROT9.CORRECTION.O	192.801(a) (192.809(a))	Have potential issues identified by the OQ plan inspection process been corrected at the operational level?
146	90875 (19 16)	Sat		MISCTOPICS.PROT 9	2.	TQ.PROT9.QUALIFICATIONSTATUS.O	192.801(a) (192.809(a))	Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.
	90875 (19 16)	Sat		MISCTOPICS.PROT 9	3.	TQ.PROT9.TASKPERFORMANCE.O	192.801(a) (192.809(a))	Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.
148	90875 (19 16)	Sat		MISCTOPICS.PROT 9	4.	TQ.PROT9.AOCRECOG.O	192.801(a) (192.809(a))	Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.
	90875 (19 16)	Sat		MISCTOPICS.PROT 9	5.	TQ.PROT9.VERIFYQUAL.O	192.801(a) (192.809(a))	Observe in the field (job site, local office, etc.) that the foreman/supervisor/ma nager has verified the qualification of the individual performing

_		_	<i>.</i>		Qs			
Ro W	Assets	Resu It	(Note 1)	Sub-Group	t #	Question ID	References	Question Text
								the task, that the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.
150	90875 (19 16)	Sat		MISCTOPICS.OPTR QUAL	9.	TQ.OQ.OQPLAN.O	192.805(h)	Do individuals performing covered tasks demonstrate adequate skills, knowledge, and ability?
151	90875 (19 16)	Sat		MISCTOPICS.OPTR QUAL	20	TQ.OQ.ABNORMAL.O	192.803	Do individuals performing covered tasks have adequate knowledge to recognize and react to abnormal operating conditions?
152	90875 (19 16)	Sat	2	MISCTOPICS.PUBA WARE	11	EP.ERG.LIAISON.R	192.605(a) (192.615(c)( 1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), 192.616(c), ADB-05-03)	Do records indicate liaisons established and maintained with appropriate fire, police and other public officials and utility owners in accordance with procedures?
153	90875 (19 16)	Sat	2	MISCTOPICS.PUBA WARE	13	PD.PA.LANGUAGE.R	192.616(g) (API RP 1162 Section 2.3.1)	Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non- English speaking populations in the operator's areas?
154	90875 (19 16)	NC	2	MISCTOPICS.PUBA WARE	18	PD.PA.EVALEFFECTIVENESS.R	192.616(c) (API RP 1162 Section 8.4)	Do records indicate program effectiveness evaluation(s) have been performed and cover all program requirements and all systems covered by the program?
155	90875 (19 16)	NA	2	MISCTOPICS.PUBA WARE	25	PD.PA.MSTRMETER.R	192.616(j) (192.616(h), API RP 1162 Section 2.7 (Step 12), API RP 1162 Section 8.5)	Do records indicate the public awareness program for a master meter or petroleum gas system operator has met the requirements of Part 192?

1. Result is repeated (N) times in this report due to re-presentation of the question in multiple sub-groups.

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

# UTC Standard Comprehensive Inspection Report Intrastate Gas Distribution FORM C: State-Specific Requirements

•	-		
** THIS FORM IS REQUIRED FOR MODULE IN THE MOST CURRI	USE FOR ALL INTRASTATE GAS I ENT WA-SPECIFIC GD QUESTIO	DISTRIBUTION OPERATORS. USE IN CONJ N SET IN INSPECTION ASSISTANT (IA)	UNCTION WITH THE "BASELINE RECORDS" and "BASELINE FIELD OBSERVATIONS"
PRINT Form (select "save and k	eep working" first)		PHMSA Advisory Bulletins
Inspector and Opera	ator Information		
Inspection ID 8427	Inspection Link 8427	Inspector - Lead Inspector - Assist Vinsel, Lex	
<b>Operator</b> Cascade Natural Gas Corporation	<b>Unit</b> Yakima	Records Location - City & State Yakima WA	
Inspection Start Date 09-19-2022	Inspection Exit Interview Date 10-05-2022	Engineer Submit Date	
You must include the following in y *Inspection Scope and Summary *Facilities visited and Total AFOD * Summary of Significant Finding * Primary Operator contacts and,	) )  S		
Scope and Summary			
Inspection of the Records and Field	l for CNGC(MDU) Yakima Distric	t	
Facilities Visited & AFOD			
Yakima Office for CNGC(MDU)			
AFOD 14			
Summary of Significant Findings			
No issues or violations were found.			
Priman Operator contacts and /ar	participante		
Primary Operator contacts and /or Colby Lundstrom	participants.		
Colby Lundstrom			

### Instructions and Ratings Definitions

INSTRUCTIONS	INSPECTION RESULTS	
S - Satisfactory	Satisfactory Responses 7	Satisfactory List Unanswered Questions Unanswered Questions List 1,2,3,4,6,7,8, 0
U - Unsatisfactory	Unsatisfactory Responses O	Unsatisfactory List
Area Of Concern	Area of Concern Responses O	Area of Concern List
N/A - Not Applicable (does not apply in this inspection)	Not Applicable Responses	Not Applicable List 5,
N/C - Not Checked/Evaluated (was not inspected during this inspection)	Not Checked / Evaluated Responses O	Not Checked / Evaluated List

\*\* If an item is marked Unsat, AOC, N/A, or N/C, an explanation must be included in the "Notes" block for that question, and summarized in the appropriate "Records/Field Observation: Summary of Required Comments" section at the end of this form

### Mapping Records

Question #1.						
Do records indicate that the operator appropriately addresses discovered mapping errors, including all mapping errors that have resulted in excavation damage?						
Q1 Reference	1. Result	Q1. Within Scope of this Inspection:				
WAC 480-93-018	Satisfactory					
1. Notes						
Reviewed map corrections (JIRA) tickets showing corrections.						
Completed within 6 month time frame.						
Question #2.						
Do records indicate that the operator's mapping corrections are made in a timely manner and in accordance with the operator's written procedures?						
Q2 Reference	2. Result	Q2. Within Scope of this Inspection:				
WAC 480-93-018	Satisfactory					
2. Notes						
OPS 626 - Gas Mapping Standard						

Reviewed map corrections (JIRA) tickets showing corrections completed with 6 month time frame.

### Damage Prevention Records

#### Question #3

Do records indicate that the operator has and follows a quality assurance program for monitoring the locating and marking of facilities? Do records show that the operator conducts regular field audits of the performance of locators/contractors and takes action when necessary?

Q3 Reference:	3. Results	Q3. Within Scope of this Inspection:				
Operator Internal Ferformance Measures; PHMSA State Program Guidelines	Satisfactory					
<b>3. Notes</b> OPS 611 Step 8						
Question #4. Does operator include performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties?						
<b>Q4 Reference 1</b> WAC 480-93-007	<b>Q4 Reference 2</b> WAC 480-93-013	Q4 Reference 3: PHMSA State Program Guidelines	<b>4. Result</b> Not Applicable	<b>Q4. Within Scope of this Inspection:</b> No such event occurred, or condition existed.		
4. Notes No outside contractors						
Question #5. Do operator contracted (or organic) locators address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing levels?						
<b>Q5 Reference 1</b> WAC 480-93-007	<b>Q5 Reference 2</b> WAC 480-93-013	<b>5. Result</b> Satisfactory	Q5. Within Scope of this Inspection:			
5. Notes OPS 611 Step 8						
Question #6. Does the operator periodically review the Operator Qualification plan criteria and methods used to qualify personnel to perform locates?						
Q6 Reference 1 WAC 480-93-007	<b>Q6 Reference 2</b> WAC 480-93-013	<b>6. Result</b> Satisfactory	Q6. Within Scope	of this Inspection:		
<b>6. Notes</b> OPS 800 - OQ is reviewed annually						
Question #7. Are locating and excavating personnel properly qualified in accordance with the operator's Operator Qualification plan and with federal and state requirements?						
Q7 Reference 1 WAC 480-93-007	<b>Q7 Reference 2</b> WAC 480-93-013	7. Result Satisfactory	Q7. Within Scope	of this Inspection:		
<b>7. Notes</b> Reviewed OQ qualifications for operation	s personnel.					
Question #8. Do records indicate that the operator has and follows a procedure for leaks caused by excavation damage near buildings such that the procedure adequately addresses the possibility of multiple leaks and underground migration of gas into nearby buildings/structures?						
Q8 Reference: PHMSA State Program Guidelines Operator Internal Ferformance Measures	<b>8. Result</b> Satisfactory	Q8. Within Scope of this Inspection:				
8. Notes OPS 617 - Reviewed Leak Investigation Re		mente				

### Records: Summary of Required Comments

RECORDS REVIEW SUMMARY: Comments are required for any rating other than "Satisfactory". Summarize the "Notes" blocks above, and ensure you annotate the question number for each comment. Question 4 NA - CNGC(MDU) does not use outside contractors for locating.

### Field: Summary of Required Comments

FIELD OBSERVATION SUMMARY: Comments are required for any rating other than "Satisfactory". Summarize the "Notes" blocks above, and ensure you annotate the question number for each comment.