Inspection Output (IOR)

Generated on 2023. March. 17 12:50

Report Filters

Assets Solvay Hydrogen System / 90612 Results All

Inspection Information

Inspection Name 8633 - Solvay Records and Field

> Status PLANNED Start Year 2023 System Type GT

Protocol Set ID WA.GT.2022.02

Operator(s) SOLVAY CHEMICALS, INC. (32399)

Lead Scott Anderson

Team Members David Cullom, Lex Vinsel, Anthony Dorrough, Derek Norwood

Observer(s) John Trier Supervisor Dennis Ritter **Director Scott Rukke**

Plan Submitted 01/30/2023 Plan Approval 01/30/2023

by Dennis Ritter

All Activity Start 03/15/2023 All Activity End 03/15/2023

Inspection Submitted ---

Inspection Approval --

Inspection Summary

Inspection Scope and Summary

This inspection consisted of a records and field review of Solvay Chemicals, Inc. Solvay operates a 6" hydrogen pipeline for approximately 481 feet across State Highway 432 in Longview, WA. The pipe was installed in 2006. Solvay does not have an IM plan as they do not have any HCAs. There are no jurisdictional valves, relief devices, or compressor stations.

Pipe Specs:

Diameter: 6.625"

Yield Strength (S): X42/X52

Wall Thickness (t): 0.280"

Class Location: 1

MAOP: 150 psig

Facilities visited and Total AFOD

1 AFOD

Summary of Significant Findings

No findings

Primary Operator contacts and/or participants

Pascal Mansy, Engineering and Maintenance Manager, Solvay Chemicals, Inc.

Tim Blume, PNW Field Service, Everline Consulting

Operator executive contact and mailing address for any official correspondence

Robert May

3333 Richmond Avenue

Houston, Texas 77098

Scope (Assets)

#	Short Name	Long Name	Asset Type	Asset IDs	Excluded Topics	Planned Red	Total quired Inspected	Required % Complete
1	. 90612	Solvay Hydrogen System	unit	90612	Compressor Stations Bottle/Pipe - Holders Vault Service Line Gas Storage Field (Aboveground) Offshore GOM OCS Cast or Ductile Iron Copper Pipe Aluminum/Amphoteric Plastic Pipe AMAOP CDA Abandoned	152	152 152	100.0%

1. Percent completion excludes unanswered questions planned as "always observe".

Plans

Plan # Assets Focus Directives		Involved Groups/Subgroups	Qst Type(s)	4 · ·	
1. 90612	WUTC Standard Inspection	AR, CR, DC, EP, FS, IM, MO, PD, RPT, SRN, TD, TQ, UNGS, 114 GENERIC	, P, R, O, S	Detail	

Plan Implementations

# Activity Name			Involved Groups/Subgroup s	Asset s		Planne d	Require d	Total	Required % Complet e
1 Records and Fiel . d	 3	Standard	AR, CR, DC, EP, FS, IM, MO, PD, RPT, SRN, TD, TQ, UNGS, 114, GENERIC	assets	all types	152	152	152	100.0%

- 1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table.
- 2. Percent completion excludes unanswered questions planned as "always observe".
- 3. Question counts and completion percents are filtered to include only questions planned for and results applied to the filtered Assets.

Forms

No.	Entity	Form Name	Status	Date Completed	Activity Name	Asset
1.	Attendance List	Records and Field	COMPLETED	03/16/2023	Records and Field	90612

Results (all values, 152 results)

174 (instead of 152) results are listed due to re-presentation of questions in more than one sub-group.

AR.PTI: Integrity Assessment Via Pressure Test

1. Question Result, ID, NA, AR.PTI.PRESSTESTREVQUAL.R, 192.947(g) (192.915(a), 192.915(b))

Question Text Do records demonstrate that operator/vendor personnel, including supervisors, who conduct or review pressure test assessment results are qualified for the tasks they perform?

Assets Covered 90612

Result Notes No such requirement existed in the scope of inspection review.

2. Question Result, ID, NA, AR.PTI.PRESSTESTRESULT.R, 192.517(a) (192.505(a), 192.505(b), 192.505(c), 192.505(d), References 192.507(a), 192.507(b), 192.507(c), 192.513(a), 192.513(b), 192.513(c), 192.513(d), 192.517(b), 192.617, 192.619(a), 192.919(e), 192.921(a)(2))

Question Text Do the test records validate the pressure test?

Assets Covered 90612

Result Notes No such requirement existed in the scope of inspection review.

3. Question Result, ID, NA, AR.PTI.PRESSTESTCOMPLETE.O, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.505(a), References 192.505(b), 192.505(c), 192.505(d), 192.507(a), 192.507(b), 192.507(c), 192.513(a), 192.513(b), 192.513(c), 192.513(d))

Question Text From field operations was the pressure test performed in accordance with Subpart J requirements and the process requirements?

Assets Covered 90612

Result Notes No such activity/condition was observed during the inspection. No IM

AR.RMP: Repair Methods and Practices

4. Question Result, ID, NA, AR.RMP.IGNITION.O, 192.751(a) (192.751(b), 192.751(c))

Question Text Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.

Assets Covered 90612

Result Notes No such activity/condition was observed during the inspection.

5. Question Result, ID, NA, AR.RMP.WELDTEST.O, 192.719(a) (192.719(b))
References

Question Text Does the operator properly test replacement pipe and repairs made by welding on transmission lines? Assets Covered 90612

Result Notes No such activity/condition was observed during the inspection.

DC.CO: Construction

6. Question Result, ID, References NA, DC.CO.CASING.O, 192.323 (192.467(a), 192.467(b))

Question Text Do field observations confirm railroad or highway casings are being installed as designed and specified, and in accordance with 192.323?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

7. Question Result, ID, NA, DC.CO.REPAIR.R, 192.303 (192.309)

Question Text Do records demonstrate that repairs to steel pipe are being made in accordance with §192.309? Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install

- 8. Question Result, ID, References NA, DC.DPC.CCPROTCOATLOWER.R, 192.143(b) (192.461(c)) (also presented in: DC.DPC)
 - Question Text Do records indicate that each pipe segment with external protective coating was inspected just prior to lowering into the ditch and backfilling, and any damage detrimental to effective corrosion control was repaired?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

DC.WELDINSP: Construction Weld Inspection

9. Question Result, ID, NA, DC.WELDINSP.WELDVISUALQUAL.R, 192.241 (192.225, 192.227, 192.229, 192.231, 192.233, References 192.243, 192.245)

Question Text Does the operator have records showing that the welding was visually and/or non-destructively tested according to the requirements of 192.241 and the operator's specifications or procedures?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

10. Question Result, ID, NA, DC.WELDINSP.WELDNDT.R, 192.243

Question Text Do records indicate that NDT and interpretation are in accordance with 192.243?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

11. Question Result, ID, NA, DC.WELDINSP.WELDREPAIR.R, 192.245 (192.303)

Question Text Do records indicate that unacceptable welds are removed and/or repaired in accordance with 192.245?
Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

DC.WELDPROCEDURE: Construction Welding Procedures

12. Question Result, ID, NA, DC.WELDPROCEDURE.WELD.R, 192.225

Question Text Does the operator have detailed records showing proper qualification of the welding procedures in accordance with 192.225?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

13. Question Result, ID, NA, DC.WELDPROCEDURE.WELDERQUAL.R, 192.227 (192.225, 192.229)

Question Text Do the records demonstrate that the welders are qualified in accordance with applicable sections of API Standard 1104 or ASME BPVC, Section IX, and cover the limitations in 192.229?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

14. Question Result, ID, NA, DC.WELDPROCEDURE.WELDERQUAL.O, 192.227 (192.225, 192.229)

Question Text Do field observations confirm that the welders are qualified in accordance with applicable sections of API Standard 1104 or ASME BPVC, Section IX, and cover the limitations in 192.229?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.DPCOPP: Design of Pipe - Overpressure Protection

8633 - Solvay Records and Field

```
15. Question Result, ID, NA, DC.DPCOPP.OVERPRESSURE.R, 192.195(a) (192.199(a), 192.199(b), 192.199(c), 192.199(d), References 192.199(e), 192.199(f), 192.199(g), 192.199(h), 192.201(a), 192.201(b), 192.201(c))
```

Question Text Do records indicate that the pipeline has pressure relieving or pressure limiting devices that are required by 192.195(a), and that they meet the requirements of 192.199 and 192.201?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

16. Question Result, ID, NA, DC.DPCOPP.OVERPRESSURE.O, 192.195(a) (192.199(a), 192.199(b), 192.199(c), 192.199(d), References 192.199(e), 192.199(f), 192.199(g), 192.199(h), 192.201(a), 192.201(b), 192.201(c))

Question Text Are required pressure relieving or pressure limiting devices being installed, and do they meet the requirements of 192.199 and 192.201?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

17. Question Result, ID, NA, DC.DPCOPP.PRESSLIMIT.R, 192.199(a) (192.199(b), 192.199(c), 192.199(d), 192.199(e), References 192.199(f), 192.199(g), 192.199(h))

Question Text Do records indicate that pressure relieving or pressure limiting devices meet the requirements of 192.199?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

18. Question Result, ID, NA, DC.DPCOPP.PRESSLIMIT.O, 192.199(a) (192.199(b), 192.199(c), 192.199(d), 192.199(e), References 192.199(f), 192.199(g), 192.199(h))

Question Text Do field observations confirm pressure relieving or pressure limiting devices meet the requirements of 192.199?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

19. Question Result, ID, NA, DC.DPCOPP.PRESSLIMITCAP.R, 192.201(a) (192.201(b), 192.201(c))

Question Text Do records indicate that pressure relief or pressure limiting stations being installed comply with 192.201? Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

20. Question Result, ID, NA, DC.DPCOPP.PRESSLIMITCAP.O, 192.201(a) (192.201(b), 192.201(c))

Question Text Do field observations verify pressure relief or pressure limiting stations comply with the requirements of 192,201?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

21. Question Result, ID, NA, DC.DPCOPP.MULTISTAGE.R, References

Question Text Do records indicate that the operator is installing multistage regulator equipment consistent with the requirements in WAC 480-93-130?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

DC.DPC: Design of Pipe Components

22. Question Result, ID, NA, DC.DPC.ILIPASS.R, 192.150 (192.150(a), 192.150(c))

Question Text Do records indicate that certain transmission pipeline components are designed and constructed to accommodate the passage of instrumented internal inspection devices?

Assets Covered 90612

Result Notes No such requirement existed in the scope of inspection review.

23. Question Result, ID, NA, DC.DPC.VALVESPACE.R, 192.179(a) (192.179(a)(1), 192.179(a)(2), 192.179(a)(3), 192.179(a)(4), References 192.179(b), 192.179(c), 192.179(d))

Question Text Do records indicate that transmission line valve spacing is in accordance with 192.179(a)?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

24. Question Result, ID, NA, DC.DPC.VALVESPACE.O, 192.141 (192.179(a), 192.179(b), 192.179(c), 192.179(d))

Question Text Are transmission line valves being installed as required by 192.179?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

25. Question Result, ID, NA, DC.DPC.INTCORRODE.R, 192.476(d) (192.476(b), 192.476(c), 192.476(a))

Question Text Do records demonstrate the transmission line project has features incorporated into its design and construction to reduce the risk of internal corrosion, as required of 192.476?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

26. Question Result, ID, NA, DC.DPC.INTCORRODE.O, 192.476(a) (192.476(b), 192.476(c))

Question Text Does the transmission project's design and construction comply with 192.476?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

27. Question Result, ID, NA, DC.DPC.CCPROTCOATLOWER.R, 192.143(b) (192.461(c)) (also presented in: DC.CO) References

Question Text Do records indicate that each pipe segment with external protective coating was inspected just prior to lowering into the ditch and backfilling, and any damage detrimental to effective corrosion control was repaired?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No new const. since install in 2006.

28. Question Result, ID, Sat, DC.DPC.CCELECTRICALISOL.R, 192.467(c) (192.143(b))

Question Text Do operator's records indicate that each pipeline was electrically isolated from metallic casings that are a part of the underground system?

Assets Covered 90612

Result Notes Solvay has 2 casings. Reviewed the cathodic protection survey records for the past three years, the casing is electrically isolated.

29. Question Result, ID, NA, DC.DPC.CCELECTRICALISOL.O, 192.467(c) (192.143(b))

Question Text Do field observations confirm that each pipeline was electrically isolated from metallic casings that are a part of the underground system?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

DC.MO: Maintenance and Operations

30. Question Result, ID, NA, DC.MO.ICEXAMINE.R, 192.491(c) (192.475(a), 192.475(b), 192.475(c))

Question Text Do records indicate examination of removed pipe for evidence of internal corrosion?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

31. Question Result, ID, NA, DC.MO.ICEXAMINE.O, 192.475(a) (192.475(b), 192.475(c))

Question Text Is examination of removed pipe conducted to determine any evidence of internal corrosion?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

32. Question Result, ID, NA, DC.MO.MAOPLIMIT.O, 192.605(b)(5)

Question Text During startup or shut-in, is it assured that the pressure limitations on the pipeline were not exceeded?

8633 - Solvay Records and Field

Page 6 of 25

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

33. Question Result, ID, NA, DC.MO.RECORDUPDATE.R, References

Question Text Do records indicate that records, maps, and drawings of gas facilities are updated not later than six months from completion of construction activity and made available to appropriate personnel?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. Solvay also reports yearly to NPMS

DC.PT: Pressure Testing

34. Question Result, ID, NA, DC.PT.PRESSTEST.R, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PTLOWPRESS)

Question Text Do records indicate that pressure testing is conducted in accordance with 192.503?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

35. Question Result, ID, NA, DC.PT.PRESSTEST.O, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PTLOWPRESS)

Question Text Is pressure testing conducted in accordance with 192.503?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

36. Question Result, ID, NA, DC.PT.PRESSTESTHIGHSTRESS.R, 192.505(a) (192.143(a), 192.517(a), 192.505(b), 192.505(c), References 192.505(d), 192.143(b), 192.143(c))

Question Text Do records indicate that the sections of a pipeline operating at a hoop stress equal to or greater than 30% of SMYS were strength tested in accordance with the requirements of 192.505?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

37. Question Result, ID, NA, DC.PT.PRESSTESTHIGHSTRESS.O, 192.505(a) (192.143(a), 192.505(b), 192.505(c), 192.505(d), References 192.143(b), 192.143(c))

Question Text Do field observations confirm that sections of a pipeline operating at a hoop stress equal to or greater than 30% of SMYS are strength tested in accordance with the requirements of 192.505?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

38. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.R, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, the test medium disposal was conducted in a manner that minimized damage to the environment?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

39. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.O, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, the test medium was disposed of in an environmentally sound manner?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

40. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.R, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, every reasonable precaution was taken to protect its employees and the general public throughout the testing?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

41. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.O, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

8633 - Solvay Records and Field

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, every reasonable precaution is taken to protect its employees and the general public throughout the testing?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

42. Question Result, ID, NA, DC.PT.PRESSTESTRECORD.R, 192.517(a) (192.517(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do records indicate creation and retention of a record for each Subpart J test performed for the required duration?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

43. Question Result, ID, NA, DC.PT.EQUIPMENTCALIBRATION.R,

Question Text Do records indicate that pressure testing equipment is maintained and calibrated at appropriate intervals in accordance with the manufacturer's recommendations?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.SPT: Spike Hydrotest

44. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.R, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, the test medium disposal was conducted in a manner that minimized damage to the environment?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

45. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.O, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, the test medium was disposed of in an environmentally sound manner?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

46. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.R, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, every reasonable precaution was taken to protect its employees and the general public throughout the testing?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

47. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.O, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, every reasonable precaution is taken to protect its employees and the general public throughout the testing?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

48. Question Result, ID, NA, DC.PT.PRESSTESTRECORD.R, 192.517(a) (192.517(b)) (also presented in: DC.PT, DC.PTLOWPRESS)

Question Text Do records indicate creation and retention of a record for each Subpart J test performed for the required duration?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.PTLOWPRESS: Pressure Testing - Low Pressure

49. Question Result, ID, NA, DC.PT.PRESSTEST.R, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PT)

Question Text Do records indicate that pressure testing is conducted in accordance with 192.503?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

50. Question Result, ID, NA, DC.PT.PRESSTEST.O, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PT)

Question Text Is pressure testing conducted in accordance with 192.503?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

51. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTESTLOWSTRESS.R, 192.507 (192.505, 192.515, 192.517, ANSI/GPTC References Z380.1-2018 Appendix G-192-9)

Question Text Do records indicate that, as applicable to the project, sections of a pipeline operating at a hoop stress less than 30% of SMYS and at or above 100 psig were tested in accordance with the requirements of 192 507?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

52. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTESTLOWSTRESS.O, 192.507 (192.505, 192.515, ANSI/GPTC Z380.1-2018 References Appendix G-192-9)

Question Text Do field observations confirm that sections of a pipeline operating at a hoop stress less than 30% of SMYS and at or above 100 psig are tested in accordance with the requirements of 192.507?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

53. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTEST100PSIG.R, 192.509 (192.143, 192.517)

Question Text Do records indicate that the sections of a pipeline operated below 100 psig were leak tested in accordance with the section requirements of 192.509 (except for service lines and plastic pipelines)?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

54. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTEST100PSIG.O, 192.509 (192.143)

Question Text Do field observations confirm that sections of a pipeline operated below 100 psig are leak tested in accordance with the requirements of 192.509 (except for service lines and plastic pipelines)?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

55. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.R, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, the test medium disposal was conducted in a manner that minimized damage to the environment?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

56. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.O, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, the test medium was disposed of in an environmentally sound manner?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

57. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.R, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, every reasonable precaution was taken to protect its employees and the general public throughout the testing?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

58. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.O, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, every reasonable precaution is taken to protect its employees and the general public throughout the testing?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

59. Question Result, ID, NA, DC.PT.PRESSTESTRECORD.R, 192.517(a) (192.517(b)) (also presented in: DC.PT, DC.SPT)

Question Text Do records indicate creation and retention of a record for each Subpart J test performed for the required duration?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.TQ: Training and Qualification

60. Question Result, ID, Sat, DC.TQ.ABNORMAL.R, 192.807(a) (192.803)

Question Text Do records show evaluation of qualified individuals for recognition and reaction to AOCs?

Assets Covered 90612

Result Notes Reviewed Tim Blume's recognition to AOCs in his Energy World Net profile. Reviewed tests, no issues.

61. Question Result, ID, Sat, DC.TQ.RECORDS.R, 192.807(a) (Operators OQ program manual)

Question Text Are qualification records maintained for operator personnel?

Assets Covered 90612

Result Notes Solvay uses Everline Consulting for all maintenance activities on the pipeline. Tim Blume performs any covered tasks, reviewed his OQs, they were accurate and up to date. No issues.

EP.ERG: Emergency Response

62. Question Result, ID, Sat, EP.ERG.REVIEW.R, 192.605(a)

Question Text Have annual reviews been conducted of the emergency plans and procedures as required, and any updates completed as appropriate?

Assets Covered 90612

Result Notes Reviewed annually.

63. Question Result, ID, Sat, EP.ERG.LOCATION.O, 192.615(b)(1)

Question Text Are supervisors provided the applicable portions of the emergency plan and procedures?

Assets Covered 90612

Result Notes Supervisors are provided access to all EPs. They have to review the plan annually. Reviewed documentation.

64. Question Result, ID, NA, EP.ERG.POSTEVNTREVIEW.R, 192.605(a) (192.615(b)(1), 192.615(b)(3))

Question Text Do records indicate review of employee activities to determine whether the procedures were effectively followed in each emergency?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

65. Question Result, ID, Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), References 192.616(c), ADB-05-03) (also presented in: PD.PA)

Question Text Do records indicate that liaison has been established and maintained with appropriate fire, police, public officials, and utility owners?

Assets Covered 90612

Result Notes PA letter sent annually to the stakeholders listed in this question. O&M Section 7.10.10 gives the list of liaison's

MO.GC: Conversion to Service

8633 - Solvay Records and Field

66. Question Result, ID, NA, MO.GC.CONVERSION.R, 192.14(a) (192.14(b), 192.14(c))

Question Text Do records indicate the process was followed for converting any pipelines into Part 192 service?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

MO.GOABNORMAL: Gas Pipeline Abnormal Operations

67. Question Result, ID, References NA, MO.GOABNORMAL.ABNORMAL.R, 192.605(a) (192.605(c)(1))

Question Text Did personnel respond to indications of abnormal operations as required by the process?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

68. Question Result, ID, NA, MO.GOABNORMAL.ABNORMALREVIEW.R, 192.605(a) (192.605(c)(4))

Question Text Do records indicate periodic review of work done by operator personnel to determine the effectiveness of the abnormal operation processes and corrective action taken where deficiencies are found?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

MO.GOCLASS: Gas Pipeline Class Location

69. Question Result, ID, NA, MO.GOCLASS.CLASSLOCATESTUDY.R, 192.605(b)(1) (192.609(a), 192.609(b), 192.609(c), References 192.609(d), 192.609(e), 192.609(f))

Question Text Do records indicate performance of the required study whenever the population along a pipeline increased or there was an indication that the pipe hoop stress was not commensurate with the present class location?

Assets Covered 90612

Result Notes No such requirement existed in the scope of inspection review.

70. Question Result, ID, NA, MO.GO.CONTSURVEILLANCE.R, 192.709(c) (192.613(a), 192.613(b), 192.703(b), 192.703(c)) (also References presented in: MO.GO)

Question Text Do records indicate performance of continuing surveillance of facilities as required, and also the reconditioning, phasing out, or MAOP reduction in any pipeline segment that was determined to be in unsatisfactory condition but on which no immediate hazard existed?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

71. Question Result, ID, NA, MO.GO.CONTSURVEILLANCE.O, 192.613(a) (192.613(b), 192.703(a), 192.703(b), 192.703(c)) (also References presented in: MO.GO)

Question Text Are unsatisfactory conditions being captured and addressed by continuing surveillance of facilities and the pipeline as required by 192.613?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

MO.GOMAOP: Gas Pipeline MAOP

72. Question Result, ID, Sat, MO.GOMAOP.MAOPDETERMINE.R, 192.709(c) (192.619(a), 192.619(b), 192.619(f), 192.517)

Question Text Do records indicate determination of the MAOP of pipeline segments in accordance with 192.619 and limiting of the operating pressure as required?

Assets Covered 90612

Result Notes Solvay MAOP is 150 psig. Pressure test minimum was 225psig and maximum was 250psig. Diameter: 6.625", Yield Strength (S): X42/X52, Wall Thickness (t): 0.280", Class Location: 1. Schedule 40 ASTM A53-B Seamless, Pipe Normal Operating Pressure: 60 psig @ 60°F, Hoop Stress: 1775 psig, % Specified Minimum Yield Strength (SMYS): 5.1%. The pipe was installed in 2006, reviewed original pressure test records.

MO.GM: Gas Pipeline Maintenance

73. Question Result, ID, NA, MO.GM.RECORDS.R, 192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c)) (also References presented in: MO.GMOPP)

Question Text Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No jurisdictional overpressure protection

According to a previous inspection in 2019 regarding overpressure protection. Solvay has a safety interlock in their system that closes the valve from the pipeline at their battery limit if the pressure reaches 145 psig. The interlock is tested annually. The compressor at Westlake Chemical was not capable to operate above 65 psig. The compressor max discharge pressure is limited to 100 psig at plant. Also Westlake has a pressure control valve that will close if the system gets to 70 psig and there is also a pressure safety valve on the compressor outlet that is set at 100 psig.

74. Question Result, ID, NA, MO.GM.IGNITION.R, 192.709 (192.751(a), 192.751(b), 192.751(c))

Question Text Do records indicate personnel followed processes for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

75. Question Result, ID, NA, MO.GM.VALVEINSPECT.R, 192.709(c) (192.745(a), 192.745(b))

Question Text Do records indicate proper inspection and partial operation of transmission line valves that may be required during an emergency as required and prompt remedial actions taken if necessary?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

76. Question Result, ID, NA, MO.GM.VALVEINSPECT.O, 192.745(a) (192.745(b))

Question Text Are field inspection and partial operation of transmission line valves adequate?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

MO.GOODOR: Gas Pipeline Odorization

77. Question Result, ID, NA, MO.GOODOR.ODORIZE.R, 192.709(c) (192.625(a), 192.625(b), 192.625(c), 192.625(d), References 192.625(e), 192.625(f))

Question Text Do records indicate appropriate odorization of its combustible gases in accordance with its processes and conduct of the required testing to verify odorant levels met requirements?

Assets Covered 90612

Result Notes No such requirement existed in the scope of inspection review. Hydrogen is non-odorized.

78. Question Result, ID, NA, MO.GOODOR.ODORIZE.O, 192.625(f)

Question Text Is sampling of combustible gases adequate using an instrument capable of determining the percentage of gas in air at which it becomes readily detectable?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

MO.GO: Gas Pipeline Operations

79. Question Result, ID, NA, MO.GO.CONTSURVEILLANCE.R, 192.709(c) (192.613(a), 192.613(b), 192.703(b), 192.703(c)) (also References presented in: MO.GOCLASS)

Question Text Do records indicate performance of continuing surveillance of facilities as required, and also the reconditioning, phasing out, or MAOP reduction in any pipeline segment that was determined to be in unsatisfactory condition but on which no immediate hazard existed?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

80. Question Result, ID, NA, MO.GO.CONTSURVEILLANCE.O, 192.613(a) (192.613(b), 192.703(a), 192.703(b), 192.703(c)) (also References presented in: MO.GOCLASS)

Question Text Are unsatisfactory conditions being captured and addressed by continuing surveillance of facilities and the pipeline as required by 192.613?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

81. Question Result, ID, Sat, MO.GO.OMANNUALREVIEW.R, 192.605(a) References

Question Text Has the operator conducted annual reviews of the written procedures or processes in the manual as required?

Assets Covered 90612

Result Notes Reviewed revisions log in Solvay O&M, reviewed passed 3 years. Most changes are clerical or rule changes.

82. Question Result, ID, Sat, MO.GO.OMEFFECTREVIEW.R, 192.605(a) (192.605(b)(8))

Question Text Do records indicate periodic review of the work done by operator personnel to determine the effectiveness, and adequacy of the processes used in normal operations and maintenance and modifying the processes when deficiencies are found?

Assets Covered 90612

Result Notes Contractors are audited annually. Reviewed Solvay Hydrogen Pipeline Field Audit Form. No deficiencies.

83. Question Result, ID, References Sat, MO.GO.OMHISTORY.R, 192.605(a) (192.605(b)(3))

Question Text Are construction records, maps, and operating history available to appropriate operating personnel?

Assets Covered 90612

Result Notes Yes, available to personnel when needed.

84. Question Result, ID, Sat, MO.GO.OMHISTORY.O, 192.605(b)(3) References

Question Text *Are construction records, maps and operating history available to appropriate operating personnel?*Assets Covered 90612

85. Question Result, ID, Sat, MO.GO.OMLOCATION.O, 192.605(a)

Question Text Are appropriate parts of the manual kept at locations where operations and maintenance activities are conducted?

Assets Covered 90612

86. Question Result, ID, NA, MO.GO.UPRATE.R, 192.553(b) (192.553(a), 192.553(c), 192.553(d))

Question Text Do records indicate the pressure uprating process was implemented per the requirements of 192.553? Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

MO.GMOPP: Gas Pipeline Overpressure Protection

87. Question Result, ID, NA, MO.GM.RECORDS.R, 192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c)) (also References presented in: MO.GM)

Question Text Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No jurisdictional overpressure protection

According to a previous inspection in 2019 regarding overpressure protection. Solvay has a safety interlock in their system that closes the valve from the pipeline at their battery limit if the pressure reaches 145 psig. The interlock is tested annually. The compressor at Westlake Chemical was not capable to operate above 65 psig. The compressor max discharge pressure is limited to 100 psig at plant. Also

Westlake has a pressure control valve that will close if the system gets to 70 psig and there is also a pressure safety valve on the compressor outlet that is set at 100 psig.

88. Question Result, ID, NA, MO.GMOPP.PRESSREGCAP.R, 192.709(c) (192.743(a), 192.743(b), 192.743(c))

Question Text Do records indicate testing or review of the capacity of each pressure relief device at each pressure limiting station and pressure regulating station as required?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review. No jurisdictional overpressure protection.

According to a previous inspection in 2019 regarding overpressure protection. Solvay has a safety interlock in their system that closes the valve from the pipeline at their battery limit if the pressure reaches 145 psig. The interlock is tested annually. The compressor at Westlake Chemical was not capable to operate above 65 psig. The compressor max discharge pressure is limited to 100 psig at plant. Also Westlake has a pressure control valve that will close if the system gets to 70 psig and there is also a pressure safety valve on the compressor outlet that is set at 100 psig.

89. Question Result, ID, NA, MO.GMOPP.PRESSREGTEST.R, 192.709(c) (192.739(a), 192.739(b))

Question Text Do records indicate inspection and testing of pressure limiting, relief devices, and pressure regulating stations?

Assets Covered 90612

Result Notes No jurisdictional overpressure protection

According to a previous inspection in 2019 regarding overpressure protection. Solvay has a safety interlock in their system that closes the valve from the pipeline at their battery limit if the pressure reaches 145 psig. The interlock is tested annually. The compressor at Westlake Chemical was not capable to operate above 65 psig. The compressor max discharge pressure is limited to 100 psig at plant. Also Westlake has a pressure control valve that will close if the system gets to 70 psig and there is also a pressure safety valve on the compressor outlet that is set at 100 psig.

90. Question Result, ID, NA, MO.GMOPP.PRESSREGTEST.O, 192.739(a) (192.739(b), 192.743)

Question Text Are field or bench tests or inspections of regulating stations, pressure limiting stations or relief devices adequate?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

MO.RW: ROW Markers, Patrols, Leakage Survey and Monitoring

91. Question Result, ID, References Sat, MO.RW.PATROL.R, 192.709(c) (192.705(a), 192.705(b), 192.705(c)) (also presented in: PD.RW)

Question Text Do records indicate that ROW surface conditions have been patrolled as required?

Assets Covered 90612

Result Notes Solvay patrols their ROW every other month. Reviewed Solvay Right-of-Way and Crossing Form for 2020-2022.

92. Question Result, ID, Sat, MO.RW.ROWMARKER.O, 192.707(a) (192.707(b), 192.707(c), 192.707(d)) (also presented in: References PD.RW)

Question Text Are line markers placed and maintained as required?

Assets Covered 90612

93. Question Result, ID, Sat, MO.RW.ROWCONDITION.O, 192.705(a) (192.705(c)) (also presented in: PD.RW)

Question Text Are the ROW conditions acceptable for the type of patrolling used?

Assets Covered 90612

94. Question Result, ID, Sat, MO.RW.MARKERSURVEY.R, References

Question Text Do records indicate that pipeline marker surveys were completed in the timeframe specified by WAC 480-93-124?

Assets Covered 90612

Result Notes Marker surveys are done every other month. Reviewed a sampling line marker inspections for 2020-2022.

95. Question Result, ID, Sat, MO.RW.LEAKAGE.R, 192.709(c) (192.706, 192.706(a), 192.706(b), 192.935(d))

Question Text Do records indicate leakage surveys conducted as required?

Assets Covered 90612

Result Notes Solvay leak surveys their line monthly with a Forensic Detector FD-600, S/N 211013022, calibration 2/24/22. Reviewed a sampling of the Leak Survey Record Form. No issues.

96. Question Result, ID, NA, MO.RW.CASINGLEAKSURVEY.R, References

Question Text Do records indicate shorted casings were leak surveyed as required?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

97. Question Result, ID, NA, MO.RW.SPECIALLEAKSURVEY.R, References

Question Text Do records indicate that special leak surveys have been conducted as required by WAC 480-93-188? Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

98. Question Result, ID, NA, MO.RW.LEAKGRADE.R, References

Question Text Do records indicate that the operator has graded leaks and determined the extent of each leak? Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

99. Question Result, ID, NA, MO.RW.LEAKFOLLOWUP.R, References

Question Text Do records indicate that a follow-up inspection was performed not more than thirty days following a repair where residual gas remained in the ground?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

100. Question Result, ID, NA, MO.RW.DOWNGRADELEAKREPAIR.R, References

Question Text Do records indicate that leaks that have been downgraded are repaired within twenty-one months? Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

101. Question Result, ID, NA, MO.RW.LEAKREPAIRTIME.R, References

Question Text Do records indicate that leaks were repaired and re-evaluated within the timeframes specified in WAC 480-93-18601?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

102. Question Result, ID, Sat, MO.RW.LEAKRECORDS.R, References

Question Text Have gas leak records been prepared and maintained as required?

Assets Covered 90612

Result Notes Yes.

103. Question Result, ID, References Sat, MO.RW.LEAKCALIBRATE.R,

Question Text Do records indicate that gas detection equipment has been maintained and calibrated in accordance with the manufacturer's recommendations?

Assets Covered 90612

PD.DP: Damage Prevention

104. Question Result, ID, NA, PD.DP.ONECALL.O, 192.614(c)(3)

References

Question Text Observe operator process a "One Call" ticket.

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

105. Question Result, ID, Sat, PD.DP.PDPROGRAM.R, 192.614(c) References

Question Text Does the damage prevention program meet minimum requirements specified in 192.614(c)?

Assets Covered 90612

Result Notes Meets requirements. Solvay has not had an excavator dig with out a One Call ticket. Due to the short distance of the line ~90% of one call tickets are able to be cleared because the line crosses one public

106. Question Result, ID, Sat, PD.DP.DPINFOGATHER.R, 192.947(b) (192.917(b), 192.935(b)(1)(ii))

Question Text Do records demonstrate that critical damage prevention information is being gathered and recorded during pipeline patrols, leakage surveys, and integrity assessments?

Assets Covered 90612

Result Notes Solvay has not had an excavator dig with out a One Call ticket. Due to the short distance of the line \sim 90% of one call tickets are able to be cleared because the line crosses one public road.

107. Question Result, ID, NA, PD.DP.NOTICETOEXCAVATOR.R, References

> Question Text Do records indicate that the operator provides the required information to excavators who damage pipeline facilities?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

108. Question Result, ID, NA, PD.DP.COMMISSIONREPORT.R, References

> Question Text Do records indicate the operator reports to the commission when the operator or its contractor observes or becomes aware of the activities described in WAC 480-93-200(9)?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

PD.PA: Public Awareness

109. Question Result, ID, Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), References 192.616(c), ADB-05-03) (also presented in: EP.ERG)

Question Text Do records indicate that liaison has been established and maintained with appropriate fire, police, public officials, and utility owners?

Assets Covered 90612

Result Notes PA letter sent annually to the stakeholders listed in this question. O&M Section 7.10.10 gives the list of liaison's

110. Question Result, ID, Sat, PD.PA.LANGUAGE.R, 192.616(g) (API RP 1162 Section 2.3.1) References

> Question Text Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?

Assets Covered 90612

Result Notes Solvay has evaluated that 90% of the surrounding area speaks English. The message is only sent in English. If demographics change the letter will go out in another language.

PD.RW: ROW Markers, Patrols, Monitoring

111. Question Result, ID, Sat, MO.RW.PATROL.R, 192.709(c) (192.705(a), 192.705(b), 192.705(c)) (also presented in: MO.RW)

Question Text Do records indicate that ROW surface conditions have been patrolled as required?

Assets Covered 90612

Result Notes Solvay patrols their ROW every other month. Reviewed Solvay Right-of-Way and Crossing Form for 2020-2022.

112. Question Result, ID, Sat, MO.RW.ROWMARKER.O, 192.707(a) (192.707(b), 192.707(c), 192.707(d)) (also presented in: References MO.RW)

Question Text Are line markers placed and maintained as required?

Assets Covered 90612

113. Question Result, ID, Sat, MO.RW.ROWCONDITION.O, 192.705(a) (192.705(c)) (also presented in: MO.RW)

Question Text Are the ROW conditions acceptable for the type of patrolling used?

Assets Covered 90612

PD.SP: Special Permits

114. Question Result, ID, NA, PD.SP.REPAIR.R, 190.341(d)(2)

Question Text If the operator operates a pipeline under a special permit, do records indicate that required repairs were performed?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

RPT.NR: Notices and Reporting

115. Question Result, ID, Sat, RPT.NR.CONTACTUPDATE.R, References

Question Text Do records indicate that the operator submits updated name, address, and phone numbers of emergency contacts/responsible officials to the commission and appropriate officials of ALL municipalities in which the company has pipeline facilities?

Assets Covered 90612

Result Notes Contacts are listed in the O&M and updated annually if necessary.

116. Question Result, ID, NA, RPT.NR.CONSTRUCTIONREPORT.R, References

Question Text Do records indicate the operator has filed a proposed construction report for construction or replacement of any segment of gas transmission pipeline of at least 100 feet in length?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

117. Question Result, ID, NA, RPT.NR.PRESSURETESTNOTIFY.R, References

Question Text Do records indicate that the operator notified the commission 3 days prior to commencement of any pressure test of a gas pipeline that will have a MAOP that produces a hoop stress of twenty percent or more of the specified minimum yield strength?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

118. Question Result, ID, NA, RPT.NR.PROXIMITYREQUEST.R, References

Question Text Do records demonstrate that the operator is in compliance with the proximity consideration requirements in WAC 480-93-020?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

RPT.RR: Regulatory Reporting (Traditional)

8633 - Solvay Records and Field

119. Question Result, ID, Sat, RPT.RR.ANNUALREPORT.R, 191.17(a)

Question Text Have complete and accurate Annual Reports utilizing the most recent form F 7 100.2-1 been submitted?

Assets Covered 90612

Result Notes Submitted 2/23/23 for CY 2022, 1/20/22 for CY 2021, 1/8/21 for CY 2020. No issues

120. Question Result, ID, Sat, RPT.RR.CONSTRUCTIONDEFECTS.R, References

Question Text Do records indicate that the operator has submitted timely and complete reports of construction defects and material failures that resulted in leaks?

Assets Covered 90612

Result Notes Reviewed construction defects and material failure reports for 20-22. Submitted on time and accurate.

121. Question Result, ID, NA, RPT.RR.IMMEDREPORT.R, 191.5(a) (191.7(a))

Ouestion Text Do records indicate immediate notifications of incidents were made in accordance with 191.5?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

122. Question Result, ID, NA, RPT.RR.INCIDENTREPORT.R, 191.15(a) (192.624(a)(1), 192.624(a)(2))

Question Text Do records indicate reportable incidents were identified and reports were submitted to DOT on the most recent Form within the required timeframe?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

123. Question Result, ID, NA, RPT.RR.INCIDENTREPORTSUPP.R, 191.15(d)

Question Text Do records indicate accurate supplemental incident reports were filed and within the required timeframe using the most recent Form?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

124. Question Result, ID, NA, RPT.RR.FAILUREANALYSIS.R,

Question Text Do records indicate that the operator submits failure analysis reports within 5 days of completion for incidents or hazardous conditions due to construction defects or material failures?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

125. Question Result, ID, NA, RPT.RR.SRCR.R, 191.23(a) (191.23(b), 191.25(a), 191.25(b), 191.25(c))

Question Text Do records indicate Safety-Related Condition Reports were filed as required?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

126. Question Result, ID, Sat, RPT.RR.NPMSANNUAL.R, 191.29(a) (191.29(b))

Question Text Do records indicate NPMS submissions were completed each year, on or before March 15, representing all in service, idle and retired assets as of December 31 of the previous year (excludes distribution lines and gathering lines) occurred, and that if no modifications occurred, an email was submitted stating that fact?

Assets Covered 90612

Result Notes Submitted 2/23/23 CY 2022, 1/20/22 CY 2021

127. Question Result, ID, NA, RPT.RR.PIPELINEMAPPING.R, References

Question Text Do records indicate that accurate maps (or updates) are provided for pipelines operating over 250 PSIG to specifications developed by the commission and sufficient to meet the needs of first responders?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

128. Question Result, ID, Sat, RPT.RR.OPID.R, 191.22(a) (191.22(c), 191.22(d)) References

Question Text Do records indicate appropriate obtaining, and control of, Operator Identification Numbers (OPIDs), including changes in entity, acquisition/divestiture, and construction/update/uprate?

Assets Covered 90612

Result Notes Solvay OPID 32399. The OPID has not changed since the install of the pipe in 2006.

129. Question Result, ID, NA, RPT.RR.DIRTREPORTS.R, References

Question Text Do records indicate that the operator has submitted reports of damage to the commission using the damage information reporting tool (DIRT) within 45 days?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TD.ATM: Atmospheric Corrosion

130. Question Result, ID, Sat, TD.ATM.ATMCORRODE.R, 192.491(c) (192.479(a), 192.479(b), 192.479(c))

Question Text Do records document the protection of above ground pipe from atmospheric corrosion?

Assets Covered 90612

Result Notes Reviewed atmospheric records from 5/2022, previous atmospheric records was 4/2019

131. Question Result, ID, Sat, TD.ATM.ATMCORRODEINSP.R, 192.491(c) (192.481(a), 192.481(b), 192.481(c), 192.481(d)) References

Question Text Do records document inspection of aboveground pipe for atmospheric corrosion?

Assets Covered 90612

Result Notes Reviewed Atmospheric Corrosion Control Inspection Form. Inspected 5/10/22 by Eric Larson NWMF.

132. Question Result, ID, Sat, TD.ATM.ATMCORRODEINSP.O, 192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c), References 192.481(d))

Question Text Is pipe that is exposed to atmospheric corrosion protected?

Assets Covered 90612

Result Notes Atmospheric adequate at exposed areas

TD.CPMONITOR: External Corrosion - CP Monitoring

133. Question Result, ID, Sat, TD.CPMONITOR.MONITORCRITERIA.R, 192.491(c) (192.463(a)) References

Question Text Do records document that the CP monitoring criteria used was acceptable?

Assets Covered 90612

Result Notes Solvay uses the "instant-off" -850mV criteria. When periodic CP checks are done, most read are "on". It was recommended they do record and "off reading" at least annually.

134. Question Result, ID, Sat, TD.CPMONITOR.MONITORCRITERIA.O, 192.465(a) (192.463(a), 192.463(b), 192.463(c), Part 192, References Appendix D)

Question Text Are methods used for taking CP monitoring readings that allow for the application of appropriate CP monitoring criteria?

Assets Covered 90612

Result Notes -850mV criteria is used, CP readings were taken "on"

135. Question Result, ID, References Sat, TD.CPMONITOR.TEST.R, 192.491(c) (192.465(a))

Question Text Do records adequately document cathodic protection monitoring tests have occurred as required?

Assets Covered 90612

Result Notes CP is checked every other month. Reviewed reads for last three years. All within acceptable criteria

Test sites are

TS 1 6" Solvay Riser Solvav Plan TS 2 Solvay plant, N end RR casing N of Slough TS 3 casing vent Solvay Isolation Westlake Chemical Isolation 136. Question Result, ID, Sat, TD.CPMONITOR.CURRENTTEST.R, 192.491(c) (192.465(b)) References Question Text Do records document details of electrical checks of sources of rectifiers or other impressed current sources? Assets Covered 90612 Result Notes Solvays 1 rectifier is checked monthly. Reviewed documentation, no issues. 137. Question Result, ID, Sat, TD.CPMONITOR.CURRENTTEST.O, 192.465(b) References Question Text Are impressed current sources properly maintained and are they functioning properly? Assets Covered 90612 Result Notes See attachment 138. Question Result, ID, NA, TD.CPMONITOR.REVCURRENTTEST.R, 192.491(c) (192.465(c)) Question Text Do records document details of electrical checks interference bonds, diodes, and reverse current switches? Assets Covered 90612 Result Notes No such relevant facilities/equipment existed in the scope of inspection review. 139. Question Result, ID, NA, TD.CPMONITOR.REVCURRENTTEST.O, 192.465(c) References Question Text Are interference bonds, diodes, and reverse current switches properly maintained and are they functioning properly? Assets Covered 90612 Result Notes No such relevant facilities/equipment existed in the scope of inspection review. 140. Question Result, ID, NA, TD.CPMONITOR.DEFICIENCY.R, 192.491(c) (192.465(d)) Question Text Do records adequately document actions taken to correct any identified deficiencies in corrosion control? Assets Covered 90612 Result Notes No such event occurred, or condition existed, in the scope of inspection review. 141. Question Result, ID, Sat, TD.CPMONITOR.TESTSTATION.R, 192.469 References Question Text Do records identify the location of test stations and show a sufficient number of test stations? Assets Covered 90612 Result Notes Maps show test station locations along with a list of written descriptions. 142. Question Result, ID, NA, TD.CPMONITOR.TESTLEAD.R, 192.491(c) (192.471(a), 192.471(b), 192.471(c))

8633 - Solvav Records and Field

accordance with requirements of Subpart I?

Question Text Do records document that pipelines with cathodic protection have electrical test leads installed in

References

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

143. Question Result, ID, NA, TD.CPMONITOR.INTFRCURRENT.R, 192.491(c) (192.473(a))

Question Text Do records document an effective program is in place to minimize detrimental effects of interference currents and that detrimental effects of interference currents from CP systems on other underground metallic structures are minimized?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

144. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) (also presented in: TD.CP, References TD.CPEXPOSED)

Question Text Do records indicate the location of all corrosion control items listed in §192.491(a)?

Assets Covered 90612

Result Notes 1 rectifier, 3 CP test sites, 2 casings. locations listed in maps and records.

TD.CP: External Corrosion - Cathodic Protection

145. Question Result, ID, Sat, TD.CP.POST1971.R, 192.491(c) (192.455(a), 192.457(a), 192.452(a), 192.452(b), 192.455(f), References 192.455(g))

Question Text Do records document that each buried or submerged pipeline installed after July 31, 1971, has been protected against external corrosion with a cathodic protection system within 1 year after completion of construction, conversion to service, or becoming jurisdictional onshore gathering?

Assets Covered 90612

Result Notes Yes, CP was applied to the pipe within 1 year of completion, impressed current is used.

146. Question Result, ID, NA, TD.CP.PRE1971.O, 192.457(b) References

Question Text Are bare or coated pipes in compressor, regulator or meter stations installed before August 1, 1971 (except for cast and ductile iron lines) cathodically protected in areas where active corrosion was found in accordance with Subpart I of Part 192?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

147. Question Result, ID, NA, TD.CP.UNPROTECT.R, 192.491(c) (192.465(e))

Question Text Do records adequately document the re-evaluation of non-cathodically protected buried pipelines for areas of active corrosion?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

148. Question Result, ID, NA, TD.CP.ELECISOLATE.R, 192.491(c) (192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e))

Question Text Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

149. Question Result, ID, NA, TD.CP.ELECISOLATE.O, 192.467(a) (192.467(b), 192.467(c), 192.467(d), 192.467(e))

Question Text Are measures performed to ensure electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?

Assets Covered 90612

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

150. Question Result, ID, References Sat, TD.CP.CASINGINSPECT.R,

Question Text Do records indicate that annual casing inspections have been performed to ensure electrical isolation from the pipeline?

Assets Covered 90612

Result Notes CP checks are done monthly, casings are also. They are isolated.

151. Question Result, ID, Sat, TD.CP.CASINGINSPECT.O,

References

Question Text Are casings electrically isolated from the pipeline?

Assets Covered 90612

Result Notes Casing under SR 432: -440mV CSE, -2080mV CSE pipe

Casing under RR Solvay Side (NE): -460mV CSE, -2080mV CSE pipe

Casing under RR Nippon Side SR 432 (SW): -500mV CSE, -1900mV CSE pipe

152. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) (also presented in: TD.CPMONITOR, References TD.CPEXPOSED)

Question Text Do records indicate the location of all corrosion control items listed in §192.491(a)?

Assets Covered 90612

Result Notes 1 rectifier, 3 CP test sites, 2 casings. locations listed in maps and records.

TD.COAT: External Corrosion - Coatings

153. Question Result, ID, Sat, TD.COAT.NEWPIPE.R, 192.491(c) (192.455(a)(1), 192.461(a), 192.461(b), 192.483(a))

Question Text Do records document that each buried or submerged pipeline installed after July 31, 1971 has been externally coated with a suitable coating material?

Assets Covered 90612

Result Notes Solvay's pipe is a steel FBE coated pipe, above and below ground.

TD.CPEXPOSED: External Corrosion - Exposed Pipe

154. Question Result, ID, NA, TD.CPEXPOSED.EXPOSEINSPECT.R, 192.491(c) (192.459)

Question Text Do records adequately document that exposed buried piping was examined for corrosion and deteriorated coating?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

155. Question Result, ID, NA, TD.CPEXPOSED.EXPOSEINSPECT.O, 192.459 References

Question Text Is exposed buried piping examined for corrosion and deteriorated coating?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

156. Question Result, ID, NA, TD.CPEXPOSED.EXTCORRODREPAIR.R, 192.491(c) (192.485(a), 192.485(b), 192.485(c)) References

Question Text Do records document the repair or replacement of pipe that has been externally corroded to an extent that there is not sufficient remaining pipe wall strength?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

157. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) (also presented in: TD.CPMONITOR, References TD.CP)

Ouestion Text Do records indicate the location of all corrosion control items listed in §192.491(a)?

Assets Covered 90612

Result Notes 1 rectifier, 3 CP test sites, 2 casings. locations listed in maps and records.

TD.ICP: Internal Corrosion - Preventive Measures

8633 - Solvav Records and Field

158. Question Result, ID, NA, TD.ICP.EXAMINE.R, 192.491(c) (192.475(a), 192.475(b))

Question Text Do records document examination of removed pipe for evidence of internal corrosion?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

159. Question Result, ID, NA, TD.ICP.EXAMINE.O, 192.475(a) (192.475(b))

Question Text Is removed pipe examined for evidence of internal corrosion?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

160. Question Result, ID, NA, TD.ICP.EVALUATE.R, 192.491(c) (192.485(c))

Question Text Do records document adequate evaluation of internally corroded pipe?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

161. Question Result, ID, NA, TD.ICP.REPAIRINT.R, 192.485(a) (192.485(b))

Question Text Do records document the repair or replacement of pipe that has been internally corroded to an extent that there is not sufficient remaining strength in the pipe wall?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TQ.PROT9: OQ Protocol 9

162. Question Result, ID, NA, TQ.PROT9.CORRECTION.O, 192.801(a) (192.809(a))

Question Text Have potential issues identified by the OQ plan inspection process been corrected at the operational level?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

163. Question Result, ID, Sat, TQ.PROT9.TASKPERFORMANCE.O, 192.801(a) (192.809(a))

Question Text Verify the qualified individuals performed the observed covered tasks in accordance with the operator's processes or operator approved contractor processes.

Assets Covered 90612

Result Notes Time Blume from Everline consulting performed all OQ covered tasks. Tasks were performed IAW procedures.

164. Question Result, ID, Sat, TQ.PROT9.QUALIFICATIONSTATUS.O, 192.801(a) (192.809(a)) References

Question Text Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

Assets Covered 90612

Result Notes Tim Blume, Everline Consulting, Field Technician OQ requal-4/2025.

165. Question Result, ID, Sat, TQ.PROT9.AOCRECOG.O, 192.801(a) (192.809(a))

Question Text Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

Assets Covered 90612

Result Notes Cognizant

166. Question Result, ID, References Sat, TQ.PROT9.VERIFYQUAL.O, 192.801(a) (192.809(a))

Question Text Observe in the field (job site, local office, etc.) that the foreman/supervisor/manager has verified the qualification of the individual performing the task, that the qualification records are current, and ensure

the personal identification of all individuals performing covered tasks are checked, prior to task performance.

Assets Covered 90612

TQ.OQ: Operator Qualification

167. Question Result, ID, Sat, TQ.OQ.OQCONTRACTOR.R, 192.807(a) (192.807(b))

Question Text Are adequate records containing the required elements maintained for contractor personnel?

Assets Covered 90612

Result Notes Reviewed Tim Blume is the only Everline field tech that performs OQ covered tasks. His qualifications were adequate and up to date.

168. Question Result, ID, References Sat, TQ.OQ.RECORDS.R, 192.807

Question Text Do records document the evaluation and qualifications of individuals performing covered tasks, and can the qualification of individuals performing covered tasks be verified?

Assets Covered 90612

Result Notes Reviewed

169. Question Result, ID, Paferances Sat, TQ.OQ.TRAINING.R, 192.807(a) (192.807(b))

Question Text Does the operator have records for initial qualification, re-training and re-evaluation of individuals performing covered tasks?

Assets Covered 90612

170. Question Result, ID, Sat, TQ.OQ.ABNORMAL.R, 192.807(a) (192.807(b), 192.803)

Question Text Do records document evaluation of qualified individuals for recognition and reaction to AOCs?

Assets Covered 90612

Result Notes Reviewed documentation

TQ.QU: Qualification of Personnel - Specific Requirements

171. Question Result, ID, Sat, TQ.QU.CORROSION.R, 192.453 (192.807(a), 192.807(b))

Question Text Do records indicate qualification of personnel implementing pipeline corrosion control methods? Assets Covered 90612

Result Notes Time Blume from Everline consulting performed all OO covered tasks. Qualifications were adequate.

TQ.QUOMCONST: Qualification of Personnel - Specific Requirements (O and M Construction)

172. Question Result, ID, NA, TQ.QUOMCONST.NDT.R, 192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b))

Question Text Do records indicate the qualification of nondestructive testing personnel?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

173. Question Result, ID, NA, TQ.QUOMCONST.WELDER.R, 192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), References 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))

Question Text Do records indicate that welders are adequately qualified?

Assets Covered 90612

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TQ.TR: Training of Personnel

174. Question Result, ID, Sat, TQ.TR.TRAINING.R, 192.615(b)(2) (192.807(a), 192.807(b))
References

8633 - Solvay Records and Field

Page 24 of 25

Question Text *Is training for emergency response personnel documented?*Assets Covered 90612

Result Notes Solvay uses Longview Fire Department for response in the ROW. Operations can also shut down flow in an emergency.

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

8633 - Solvay Records and Field Report Filters: Results: all

3/17/23, 1:05 PM Forms -

FORM D: Intrastate GT Standard Records & Field 8633

UTC Standard Comprehensive Inspection Report Intrastate GAS Transmission FORM D: State-Specific Requirements

** THIS FORM IS REQUIRED FOR USE FOR ALL INTRASTATE GAS TRANSMISSION OPERATORS. USE IN CONJUNCTION WITH THE "BASELINE RECORDS" and "BASELINE FIELD OBSERVATIONS" MODULES IN THE MOST CURRENT WA-SPECIFIC GT QUESTION SET

Inspector and Operator Information

Inspection Link Inspector - Lead Inspector - Assist

8633 Anderson, Scott

Operator Unit Records Location - City & State

Solvay Chemicals, Inc. Solvay Longview, WA

Inspection Start Date Inspection Exit Interview Date Engineer Submit Date

03-15-2023 03-15-2023 03-17-2023

You must include the following in your inspection summary:

- *Inspection Scope
- *Facilities visited and Total AFOD
- * Summary of Significant Findings

Inspection Scope and Summary

This inspection consisted of a records and field review of Solvay Chemicals, Inc. Solvay operates a 6" hydrogen pipeline for approximately 481 feet across State Highway 432 in Longview, WA. The pipe was installed in 2006. Solvay does not have an IM plan as they do not have any HCAs. There are no jurisdictional valves, relief devices, or compressor stations.

Pipe Specs:

Diameter: 6.625"

Yield Strength (S): X42/X52

Wall Thickness (t): 0.280"

Class Location: 1

MAOP: 150 psig

Facilities visited and Total AFOD

1 AFOD

Summary of Significant Findings

No findings

Primary Operator contacts and/or participants

Pascal Mansy, Engineering and Maintenance Manager, Solvay Chemicals, Inc.

Tim Blume, PNW Field Service, Everline Consulting

Operator executive contact and mailing address for any official correspondence

Robert May

Vice President Industrial, Peroxides NA

3333 Richmond Avenue

Houston, Texas 77098

Instructions and Ratings Definitions

3/17/23, 1:05 PM Forms -

INSTRUCTIONS INSPECTION RESULTS S - Satisfactory Satisfactory Responses Satisfactory Unanswered Unanswered Questions **Questions List** 1,2,4,5, U - Unsatisfactory **Unsatisfactory Responses Unsatisfactory List** Area Of Concern Area of Concern List Area of Concern Responses N/A- Not Applicable (does not apply to this Not Applicable List Not Applicable operator or system) Responses 3,6,7,8, N/C - Not Checked/Evaluated (was not Not Checked / Evaluated Not Checked / Evaluated List inspected during this inspection) Responses

**If an item is marked Unsat, AOC, N/A, or N/C, an explanation must be included in the "Notes" block for that question, and summarized in the appropriate "RECORDS/FIELD OBSERVATION: SUMMARY OF REQUIRED COMMENTS" section at the end of this form.

INTRASTATE GT RECORDS REVIEW

MAPPING RECORDS

REPORTING RECORDS

Question 1

Do records indicate that the operator filed with the commission, not later than March 15 of each year, applicable to the preceding calendar year: a copy of every Pipeline and Hazardous Materials Safety Administration (PHMSA) F-7100.2-1 annual report?

 Q8 Reference
 Q1 Result
 Q1

 WAC 480-93-200(10)
 Satisfactory
 Notes

DAMAGE PREVENTION RECORDS

Question 2

Do records indicate that the operator's locating and excavation practices are in compliance with all RCW 19.122 requirements for facility operators? Does the records sample indicate that locates are made within two business days?

Q9 Reference Q2 Result Q2 Notes

RCW 19.122 Satisfactory No locates requests in the passed 3 years

Question 3

Do records indicate that the operator uses a quality assurance program for monitoring the locating and marking of facilities? Does the operator conduct regular field audits of the performance of locators/contractors and implement appropriate corrective action when necessary?

Q3 Reference Q3 Result Q3 Notes

PHMSA State Program Question Not Applicable Due to the short distance of the line \sim 90% of one call tickets are able to be cleared because

the line crosses one public read

the line crosses one public road.

Question 4

Do records indicate that the operator's (organic or contracted) locator and excavator personel are properly qualified in accordance with the operator's OQ plan and with state OQ requirements?

Q4 Reference Q4 Result Q4 Notes

WAC 480-93-013 Satisfactory

3/17/23, 1:05 PM Forms -

Question 5

Do records indicate that the operator is meeting requirements in RCW 19.122.035 with respect to their duties after notice of excavation? Are examinations of uncovered pipe conducted prior to reburial? Does the operator immediately notify local first respondeers and the commission of any blowing gas leak that has ignited or represents a probable hazard to persons or property?

Q5 Reference Q5 Result Q5 Notes

RCW 19.122.035 Satisfactory

Question 6

Do records indicate that the operator reviews records of accidents and failures caused by excavation damage to ensure the causes of those failures are addressed to minimize the possibility of reoccurrance?

Q6 Reference Q6 Result Q6 Notes

DESIGN/CONSTRUCTION RECORDS

Question 7

Do construction/installation records indicate that the operator is complying with WAC 480-93-115 requirements to seal the casing ends of any transmission line installed in a casing or conduit? If casings are installed, is the operator installing only bare steel casings?

Q21 ReferenceQ7 ResultQ7 NotesWAC 480-93-115Not Applicablecasings are bare and sealed.

CORROSION CONTROL RECORDS

OPERATIONS & MAINTENANCE RECORDS

Question 8

Do odorization records demonstrate appropriate odorization levels, testing, instrumentation, calibration, and adherence to applicable intervals in accordance with WAC 480-93-015? Does the operator retain records of tests performed and equipment calibration for 5 years? Does the operator take prompt action to investigate and remediate odorant concentrations not meeting the minimum requirements (as applicable)?

Q8 Reference Q8 Result Q8 Notes

WAC 480-93-015 Not Applicable you cannot odorize hydrogen

RECORDS: SUMMARY OF REQUIRED COMMENTS

RECORDS REVIEW SUMMARY: Comments are required for any rating other than "Satisfactory". Summarize the "Notes" blocks above, and ensure you annotate the question number for each comment

INTRASTATE GT: FIELD OBSERVATIONS

FIELD: SUMMARY OF REQUIRED COMMENTS

FIELD OBSERVATIONS SUMMARY: Comments are required for any rating other than "Satisfactory". Summarize the "Notes" blocks above and ensure you annotate the question number for each comment.