



STATE OF WASHINGTON  
WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION  
1300 S. Evergreen Park Dr. S.W., P.O. Box 47250 • Olympia, Washington 98504-7250  
(360) 664-1160 • TTY (360) 586-8203

June 25, 2012

L. Dean Williams  
General Manager  
Swissport Fueling, Inc.  
2350 S. 190<sup>th</sup> St.  
Seattle, WA 98188

Dear Mr. Williams:

**RE: 2012 Standard Hazardous Liquid Safety Inspection – SeaTac Fuel Facilities LLC**

Thank you for your letter dated June 21, 2012 requesting an extension of time to complete analysis and remediation of the low cathodic protection (CP) reading on cell 1 for the CP system protecting the bottom of Tank 115.

We accept Swissport's request for an extension to August 21, 2012 to complete this work.

I request that a copy of the final written report including analysis and recommendations as described under Item 7 of your letter be provided to us upon completion.

If you have any questions or need any further assistance, please contact Dennis Ritter at (360) 664-1159.

Sincerely,

David D. Lykken  
Pipeline Safety Director

cc. Mark Norris, Vice President for Consortiums SeaTac Fuel Facilities  
Nestor Soriano, QA/QC & Training Supervisor, Swissport Fueling, Inc.

