



STATE OF WASHINGTON  
WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION  
1300 S. Evergreen Park Dr. S.W., P.O. Box 47250 • Olympia, Washington 98504-7250  
(360) 664-1160 • TTY (360) 586-8203

January 8, 2014

David Barnes  
DOT Compliance  
BP Pipelines (North America) Inc.  
150 W. Warrenville Road  
Naperville, IL 60563

Dear Mr. Barnes:

**RE: 2013 Hazardous Liquid Standard Inspection – BP Pipelines North America- BP  
Cherry Point Refinery**

Thank you for your letter dated December 16, 2013 addressing the findings of our inspection conducted at the BP Pipelines North America (BP), BP Cherry Point Refinery from October 28 - 30, 2013. Staff accepts BP's response regarding monitoring at support locations for the presence of newly formed corrosion product in order to maintain compliance.

Staff would like to thank BP's personnel for their cooperation and assistance during this inspection.

If you have any questions or if we may be of any assistance, please contact Dave Cullom at (360) 664-1141.

Sincerely,

  
David D. Lykken  
Pipeline Safety Director

cc: Steve Pankhurst, President, BP Pipelines North America