



STATE OF WASHINGTON

UTILITIES AND TRANSPORTATION COMMISSION

1300 S. Evergreen Park Dr. S.W., P.O. Box 47250 • Olympia, Washington 98504-7250

(360) 664-1160 • TTY (360) 586-8203

February 9, 2015

David O. Barnes, P.E.
DOT Manager
BP Pipelines (North America) Inc.
150 W. Warrenville Rd
Naperville, IL 60563

Dear Mr. Barnes:

**RE: 2014 Hazardous Liquid Standard Inspection – Olympic Pipe Line Company
Intrastate Laterals – (Insp. No. 5821)**

Thank you for your letter dated February 4, 2015, addressing the findings of our inspection conducted on the Olympic Pipe Line Company's (OPL) Intrastate Laterals from November 17 to 20, 2014.

Staff accepts OPL's proposals to bring these items into compliance. This inspection will be closed as of February 9, 2015.

Staff would like to thank OPL's personnel for their cooperation and assistance during this inspection.

If you have any questions or if we may be of any assistance, please contact Dennis Ritter at (360) 664-1159.

Sincerely,

David D. Lykken
Pipeline Safety Director

cc: Donald W. Porter, President, BP Pipelines (North America) Inc.
Jim Bruen, DOT Team Leader-Programs, BP Pipelines (North America) Inc.