## Inspection Output (IOR)

Generated on 2022. September. 20 13:41

## **Report Filters**

Assets All, and including items not linked to any asset. Results All

### **Inspection Information**

Inspection Name 8414 - Airgas OQ

Start Year 2022
System Type GT

Protocol Set ID GT.2022.01

Operator(s) AIRGAS MERCHANT GAS KALAMA (39624)

Lead Scott Anderson

Team Members David Cullom, Dennis Ritter, Lex Vinsel, Anthony Dorrough, Derek Norwood, Darren Tinnerstet

Observer(s) Deborah Becker, Rell Koizumi

Supervisor Scott Rukke
Director Sean Mayo

Plan Submitted 02/15/2022

Plan Approval 02/16/2022 by Sean

Mayo

All Activity Start 09/19/2022

All Activity End 09/19/2022

Inspection Submitted -Inspection Approval --

#### **Inspection Summary**

**Inspection Scope and Summary** 

This inspection consisted of a procedure and records review of the Airgas Kalama OQ plan.

**Facilities visited and Total AFOD** 

1 AFOD

**Summary of Significant Findings** 

No findings

Primary Operator contacts and/or participants

Scott Moon, Plant Manager, Airgas Kalama

Operator executive contact and mailing address for any official correspondence

Bill Madsen

12800 West Little York Road

Houston, Texas 77041

## Scope (Assets)

							Required
	Asset	Asset	Excluded			Total	%
# Short Name Long Name	Type	IDs	Topics	Planned Re	quired Ins	pected	Complete
1. 88917 (1,850) AIRGAS Merchant Gas Kalama	unit	88917		55	55	55	100.0%

<sup>1.</sup> Percent completion excludes unanswered questions planned as "always observe".

#### **Plans**

#	Plan Assets	Focus Directives	Groups/Subgroups	Qst Type(s)	Extent	Notes
1.	88917 (1,850)		TQ	P, R, O	Detail	

ام مدينا مدينميا

### **Plan Implementations**

											Required
	Activity	SMART	<b>Start Date</b>	Focus	Involved		Qst			Total	%
#	Name	Act#	End Date	Directives	Groups/Subgroups	s Assets	Type(s)	Planned Re	quired Ins	pected	Complete
1.	OQ		09/19/2022		TQ	all	all types	55	55	55	100.0%
			09/19/2022			assets					

- 1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table.
- 2. Percent completion excludes unanswered questions planned as "always observe".

#### **Forms**

No. Entity	Form Name	Status	Date Completed	<b>Activity Name</b>	Asset
1. Attendance List	OQ	COMPLETED	09/20/2022	OQ	88917 (1,850)

## Results (all values, 55 results)

#### TQ.PROT9: OQ Protocol 9

1. Question Result, ID, NA, TQ.PROT9.CORRECTION.O, 192.801(a) (192.809(a)) References

Question Text Have potential issues identified by the OQ plan inspection process been corrected at the operational level?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

2. Question Result, ID, NA, TQ.PROT9.TASKPERFORMANCE.O, 192.801(a) (192.809(a)) References

Question Text Verify the qualified individuals performed the observed covered tasks in accordance with the operator's processes or operator approved contractor processes.

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection. This was observed in the 2021 standard inspection.

3. Question Result, ID, NA, TQ.PROT9.QUALIFICATIONSTATUS.O, 192.801(a) (192.809(a))

Question Text Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection. This was observed in the 2021 standard inspection.

4. Question Result, ID, NA, TQ.PROT9.AOCRECOG.O, 192.801(a) (192.809(a))
References

Question Text Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection. This was observed in the 2021 standard inspection.

5. Question Result, ID, NA, TQ.PROT9.VERIFYQUAL.O, 192.801(a) (192.809(a)) References

Question Text Observe in the field (job site, local office, etc.) that the foreman/supervisor/manager has verified the qualification of the individual performing the task, that the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection.

#### TQ.OQ: Operator Qualification

6. Question Result, ID, Paferones Sat, TQ.OQ.OQPLAN.P, 192.805(a) (192.801(b))

Question Text *Is there an OQ plan that includes covered tasks, and the basis used for identifying covered tasks?*Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 2.0, section 7.3 covered task list.

7. Question Result, ID, Sat, TQ.OQ.REEVALINTERVAL.P, 192.805(g)

Question Text Does the OQ plan establish and justify requirements for reevaluation intervals for each covered task? Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 2.4

8. Question Result, ID, Sat, TQ.OQ.NONQUALIFIED.P, 192.805(c)
References

Question Text Does the OQ plan contain provisions for non-qualified individuals to perform covered tasks while being directed and observed by a qualified individual, and are appropriate restrictions and limitations placed on such activities?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 3.11

9. Question Result, ID, Sat, TQ.OQ.EVALMETHOD.P, 192.805(b) (192.803, 192.809(d), 192.809(e))
References

Question Text Are evaluation methods established and documented appropriate to each covered task?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 3.2

10. Question Result, ID, References Sat, TQ.OQ.OQCONTRACTOR.R, 192.807(a) (192.807(b))

Question Text Are adequate records containing the required elements maintained for contractor personnel?

Assets Covered 88917 (1,850)

Result Notes Contractors are used for CP and leak detection on the Airgas system. Allen Paizs and Mike Wendell perform the CP and Leak detection tasks on the pipeline, they are with GMW Consulting. All elements are up to date and maintained.

11. Question Result, ID, Sat, TQ.OQ.RECORDS.R, 192.807
References

Question Text Do records document the evaluation and qualifications of individuals performing covered tasks, and can the qualification of individuals performing covered tasks be verified?

Assets Covered 88917 (1,850)

Result Notes Reviewed OQ evaluations and qualifications for Scott Moon, Larry Chapman, Mike Wendell, and Allen Paizs. All were up to date and verififed.

12. Question Result, ID, References Sat, TQ.OQ.TRAINING.P, 192.805(h)

Question Text Does the OQ program provide for initial qualification, retraining and reevaluation of individuals performing covered tasks?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 3.3-3.7.1

13. Question Result, ID, Sat, TQ.OQ.TRAINING.R, 192.807(a) (192.807(b)) References

Question Text Does the operator have records for initial qualification, re-training and re-evaluation of individuals performing covered tasks?

Assets Covered 88917 (1,850)

Result Notes Reviewed OQ qualifications for Scott Moon, Larry Chapman, Mike Wendell, and Allen Paizs. No issues.

14. Question Result, ID, Sat, TQ.OQ.OQPLANCONTRACTOR.P, 192.805(b) (192.805(f), 192.805(c))
References

Question Text Does the OQ plan have a process to communicate the OQ plan requirements to contractors and ensure that contractors are following it?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 4.0

15. Question Result, ID, Sat, TQ.OQ.OQCONTRACTOR.P, 192.805(b) (192.805(c), 192.805(d), 192.805(e), 192.805(f))

Question Text Does the OQ plan require other entities that perform covered tasks on behalf of the operator to be qualified?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 4.2

16. Question Result, ID, References Sat, TQ.OQ.OQCONTRACTOREQUIV.P, 192.805(h)

Question Text Does the OQ plan document that the operator has assured that the processes on which an OQ vendor has evaluated qualified personnel are the same or consistent with those used by the operator for employees and contractors in the field?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 4.1, 4.2

17. Question Result, ID, NA, TQ.OQ.OTHERENTITY.R, 192.805(b) (192.805(c), 192.803) References

Question Text If the operator employs other entities to perform covered tasks, such as mutual assistance, are adequate records containing the required elements maintained?

Assets Covered 88917 (1,850)

Result Notes Airgas does not use mutual assistance. Plant employees and GMW consulting are the only employees that perform covered tasks on the pipeline.

18. Question Result, ID, References Sat, TQ.OQ.ABNORMAL.P, 192.803

Question Text Does the OQ Plan contain requirements to assure that individuals performing covered tasks are able to recognize and react to abnormal operating conditions (AOCs)?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 2.5 and 2.6

19. Question Result, ID, Sat, TQ.OQ.ABNORMAL.R, 192.807(a) (192.807(b), 192.803)

Question Text Do records document evaluation of qualified individuals for recognition and reaction to AOCs?

Assets Covered 88917 (1,850)

Result Notes Reviewed AOC evaluations for OQ covered individuals, Scott Moon, Larry Chapman, Mike Wendell, and Allen Paizs.

20. Question Result, ID, NA, TQ.OQ.ABNORMAL.O, 192.803

Question Text Do individuals performing covered tasks have adequate knowledge to recognize and react to abnormal operating conditions?

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection. This was observed in the 2021 standard inspection.

21. Question Result, ID, Sat, TQ.OQ.PERFMONITOR.P, 192.805(d) (192.805(e)) References

Question Text Does the program include provisions to evaluate an individual if there is reason to believe that performance of a covered task contributed to an incident or accident as defined in Parts 192 and 195 or there is reason to believe an individual is no longer qualified to perform a covered task?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section(s) 3.5-3.8

22. Question Result, ID, NA, TQ.OQ.PERFMONITOR.R, 192.805(d) (192.805(e))

Question Text If the operator had an incident/accident where there is reason to believe that an individual contributed to the cause, do records indicate evaluation of the individual following the occurrence?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

23. Question Result, ID, NA, TQ.OQ.OQPLAN.O, 192.805(h) References

Question Text Do individuals performing covered tasks demonstrate adequate skills, knowledge, and ability?

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection. This was observed in the 2021 standard inspection.

24. Question Result, ID, Sat, TQ.OQ.MOC.P, 192.805(f)

Question Text Does the OQ program identify how changes to processes, tools standards and other elements used by individuals in performing covered tasks are communicated to the individuals, including contractor individuals, and how these changes are implemented in the evaluation method(s)?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 1.6

25. Question Result, ID, Paferances Sat, TQ.OQ.CHANGENOTIFY.P, 192.805(i) (192.18)

Question Text Does the process require significant OQ program changes to be identified and the Administrator or State agency notified?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section 1.6

26. Question Result, ID, NA, TQ.OQ.CHANGERECORD.R, 192.805(i) (192.805(f), 192.18) References

Question Text Are records maintained for changes that affect covered tasks and significant OQ plan changes? Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No significant changes.

#### TQ.QU: Qualification of Personnel - Specific Requirements

27. Question Result, ID, Sat, TQ.QU.CORROSION.P, 192.453 (192.805(b)) References

Question Text Does the process require corrosion control processes to be carried out by, or under the direction of, qualified personnel?

Assets Covered 88917 (1,850)

Result Notes Airgas OQ manual section(s) 3.3 and 7.3 Covered Task List

28. Question Result, ID, Sat, TQ.QU.CORROSION.R, 192.453 (192.807(a), 192.807(b))

Question Text Do records indicate qualification of personnel implementing pipeline corrosion control methods? Assets Covered 88917 (1,850)

Result Notes Mike Wendell and Allen Paizs perform CP related tasks on the pipeline. OQs were adequate and up to date.

29. Question Result, ID, NA, TQ.QU.HOTTAPQUAL.P, 192.627 (192.805(b)) References

Question Text Does the process require taps on a pipeline under pressure (hot taps) to be performed by qualified personnel?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No hot taps on a Hydrogen line.

Page 5 of 9

30. Question Result, ID, NA, TQ.QU.HOTTAPQUAL.R, 192.627 (192.807(a), 192.807(b))

Question Text Do records indicate the qualification of personnel performing hot taps?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

31. Question Result, ID, NA, TQ.QU.HOTTAPQUAL.O, 192.627 (192.805(h))

Question Text Do personnel performing hot taps demonstrate adequate skills and knowledge?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No hot taps

32. Question Result, ID, Sat, TQ.QU.EXCAVATE.P, 192.805(b) (ADB-06-01, 192.801, 192.328)

Question Text Does the process require individuals who oversee and perform marking, trenching, and backfilling operations be qualified?

Assets Covered 88917 (1,850)

Result Notes Airgas Task CT 35 for backfilling

33. Question Result, ID, NA, TQ.QU.EXCAVATE.R, 192.807(a) (192.807(b), ADB-06-01, 192.801, 192.328)

Question Text Do records indicate qualification of individuals who oversee marking, trenching, and backfilling operations?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No trenching and backfilling operations.

34. Question Result, ID, NA, TQ.QU.EXCAVATE.O, 192.805(b) (192.805(h), ADB-06-01, 192.801(a), 192.328(a), 192.328(c)) References

Question Text Do individuals who oversee marking, trenching, and backfilling operations demonstrate adequate skills and knowledge?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

#### TQ.QUIM: Qualification of Personnel - Specific Requirements (IM)

35. Question Result, ID, NA, TQ.QUIM.IMREVIEWQUAL.P, 192.915(a) (192.915(b), 192.915(c), 192.935(b), 192.493)

Question Text Does the process require that operator/vendor personnel (including supervisors and persons responsible for preventive and mitigative measures), who review and evaluate results meet acceptable qualification standards?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No IM

36. Question Result, ID, NA, TQ.QUIM.IMREVIEWQUAL.R, 192.947(e) (192.915(a), 192.915(b), 192.915(c), 192.935(b)(1)(i), References 192.947(d), 192.493)

Question Text Do records indicate adequate qualification of integrity management personnel?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No IM

37. Question Result, ID, NA, TQ.QUIM.IMQC.P, 192.805(b) (ASME B31.8S-2004, Section 12.2(b)(4), 192.935(b)(1)(i), References 192.907(b), 192.911(l))

Question Text Does the process require personnel who execute IM program activities to be competent and qualified in accordance with the quality control plan in accordance with ASME B31.8S-2004, Section 12.2(b)(4)?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No IM

## TQ.QUOMCONST: Qualification of Personnel - Specific Requirements (O and M Construction)

8414 - Airgas OQ Page 6 of 9

38. Question Result, ID, Sat, TQ.QUOMCONST.INSPECTOR.P, 192.241(a) (192.241(c), 192.805(b), 192.328(a), 192.328(b)) References Question Text Does the process require welding inspection personnel to be adequately trained and qualified? Assets Covered 88917 (1,850) Result Notes Airgas OQ Task CT 38 39. Question Result, ID, NA, TQ.QUOMCONST.INSPECTOR.R, 192.241(a) (192.241(c), 192.807(a), 192.807(b)) Question Text Do records indicate adequate qualification documentation for personnel who conduct welding inspections? Assets Covered 88917 (1,850) Result Notes No such event occurred, or condition existed, in the scope of inspection review. No welding since 1997 40. Question Result, ID, NA, TQ.QUOMCONST.INSPECTOR.O, 192.241(a) (192.241(c)) References Question Text Does the welding inspector demonstrate adequate skills and knowledge? Assets Covered 88917 (1,850) Result Notes No such activity/condition was observed during the inspection. No welding since install of line in 1997 41. Question Result, ID, NA, TQ.QUOMCONST.NDT.R, 192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b)) References Question Text Do records indicate the qualification of nondestructive testing personnel? Assets Covered 88917 (1,850) Result Notes No such event occurred, or condition existed, in the scope of inspection review. No NDT since 1997 when the pipe was installed 42. Question Result, ID, NA, TQ.QUOMCONST.WELDER.R, 192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), References 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b)) Question Text Do records indicate that welders are adequately qualified? Assets Covered 88917 (1,850) Result Notes No such event occurred, or condition existed, in the scope of inspection review. No welding since 1997 when the pipe was installed. Airgas does have the original OQ welding records, all were adequate. 43. Question Result, ID, Sat, TQ.QUOMCONST.WELDER.P, 192.227(a) (192.225(a), 192.225(b), 192.328(a), 192.328(b), References 192.805(b)) Question Text Does the process require welders to be qualified in accordance with API 1104 or the ASME Boiler & Pressure Vessel Code? Assets Covered 88917 (1,850) Result Notes Airgas OQ Task CT 38, procedure states welders can have either of the certifications. 44. Question Result, ID, NA, TQ.QUOMCONST.WELDERLOWSTRESS.P, 192.227(b) (192.225(a), 192.225(b), 192.805(b)) References Question Text Does the process require welders who perform welding on low stress pipe on lines that operate at < 20% SMYS to be qualified under Section I of Appendix C to Part 192, and are welders who perform welding on service line connection to a main required to be qualified under Section II of Appendix C to Part 192? Assets Covered 88917 (1,850) Result Notes No such relevant facilities/equipment existed in the scope of inspection review. No low stress no services 45. Question Result, ID, NA, TQ.QUOMCONST.WELDER.O, 192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), References 192.229(d), 192.803, 192.328(a), 192.328(b)) Question Text Do welders demonstrate adequate skills and knowledge? Assets Covered 88917 (1,850) Result Notes No such activity/condition was observed during the inspection. No welding since install of line in 1997 46. Question Result, ID, Sat, TQ.QUOMCONST.NDT.P, 192.243(b)(2) (192.803, 192.805(b), 192.805(h), 192.328(a), 192.328(b)) References Question Text Does the process require nondestructive testing of welds to be performed by personnel who are trained and qualified in the established procedures and with the testing equipment employed? Assets Covered 88917 (1,850) Result Notes Airgas OQ task CT 66-68 47. Question Result, ID, NA, TQ.QUOMCONST.NDT.O, 192.243(b)(2) (192.803, 192.328(a), 192.328(b)) References

Question Text Do nondestructive testing personnel demonstrate adequate skills and knowledge?

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection. No welding since install of line in 1997

48. Question Result, ID, NA, TQ.QUOMCONST.PLASTIC.P, 192.285(a) (192.285(d), 192.805(b))

Question Text Does the process require personnel making joints in plastic pipelines be qualified?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No plastic pipe

49. Question Result, ID, NA, TQ.QUOMCONST.PLASTICINSPECT.P, 192.287 (192.805(b))

References

Question Text Does the process require that persons who inspect joints in plastic pipes be qualified?

Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No plastic pipe

50. Question Result, ID, NA, TQ.QUOMCONST.PLASTIC.R, 192.285(a) (192.285(d), 192.287, 192.807(a), 192.807(b)) References

Question Text Do records indicate adequate qualification of personnel making/inspecting joints in plastic pipelines? Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

51. Question Result, ID, NA, TQ.QUOMCONST.PLASTIC.O, 192.285(a) (192.287, 192.803) References

Question Text Do personnel making/inspecting joints in plastic pipelines demonstrate adequate skills and knowledge? Assets Covered 88917 (1,850)

Result Notes No such event occurred, or condition existed, in the scope of inspection review. No plastic pipe

#### TQ.TR: Training of Personnel

52. Question Result, ID, Sat, TQ.TR.TRAINING.P, 192.615(b)(2) (192.805(b))

Question Text Does the process require a continuing training program to be in place to effectively instruct emergency response personnel?

Assets Covered 88917 (1,850)

Result Notes Airgas O&M P-192.615(a)

53. Question Result, ID, Sat, TQ.TR.TRAINING.R, 192.615(b)(2) (192.807(a), 192.807(b))

Question Text Is training for emergency response personnel documented?

Assets Covered 88917 (1,850)

Result Notes Reviewed Airgas Emergency Response drill spreadsheets. Also reviewed LECP meeting attendance sheets.

54. Question Result, ID, NA, TQ.TR.TRAINING.O, 192.615(b)(2) (192.805(b))

Question Text Do emergency response personnel demonstrate adequate skills and knowledge?

Assets Covered 88917 (1,850)

Result Notes No such activity/condition was observed during the inspection.

55. Question Result, ID, Sat, TQ.TR.TRAININGREVIEW.P, 192.615(b)(3)

Question Text Does the process require review of emergency response personnel performance?

Assets Covered 88917 (1,850)

Result Notes Airgas O&M P-192.615(b)

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

8414 - Airgas OQ

Report Filters: Results: all

## **Inspection Results (IRR)**

Generated on 2022. September. 20 13:40

## • 88917 (1,850) (55)

## Inspection Results Report (ALL Non-Empty Results) - Scp\_PK 88917 (1,850)

Ro w	Assets	Resul t	Sub-Group	Qs t #	Question ID	References	Question Text
	88917 (1,850		TQ.PROT9		TQ.PROT9.CORRECTION.O	192.801(a) (192.809(a))	Have potential issues identified by the OQ plan inspection process been corrected at the operational level?
2.	88917 (1,850)	NA	TQ.PROT9	2.	TQ.PROT9.TASKPERFORMANCE.O	192.801(a) (192.809(a))	Verify the qualified individuals performed the observed covered tasks in accordance with the operator's processes or operator approved contractor processes.
3.	88917 (1,850 )	NA	TQ.PROT9	3.	TQ.PROT9.QUALIFICATIONSTATUS.O	192.801(a) (192.809(a))	Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.
4.	88917 (1,850 )	NA	TQ.PROT9	4.	TQ.PROT9.AOCRECOG.O	192.801(a) (192.809(a))	Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.
5.	88917 (1,850)	NA	TQ.PROT9	5.	TQ.PROT9.VERIFYQUAL.O	192.801(a) (192.809(a))	Observe in the field (job site, local office, etc.) that the foreman/supervisor/manag er has verified the qualification of the individual performing the task, that the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.
6.	88917 (1,850 )	Sat	TQ.OQ	1.	TQ.OQ.OQPLAN.P	192.805(a) (192.801(b))	Is there an OQ plan that includes covered tasks, and the basis used for identifying covered tasks?
7.	88917 (1,850 )	Sat	TQ.OQ	2.	TQ.OQ.REEVALINTERVAL.P	192.805(g)	Does the OQ plan establish and justify requirements for reevaluation intervals for each covered task?
8.	88917 (1,850)	Sat	TQ.OQ	3.	TQ.OQ.NONQUALIFIED.P	192.805(c)	Does the OQ plan contain provisions for non-qualified individuals to perform covered tasks while being directed and observed by a qualified individual, and are appropriate restrictions and limitations placed on such activities?

# Inspection Results Report (ALL Non-Empty Results) - Scp\_PK 88917 (1,850) Resul Qs

Ro w	Assets	Resul t	Sub-Group	Qs t #	Question ID	References	Question Text
9.	88917 (1,850 )	Sat	ΤQ.ΟQ	4.	TQ.OQ.EVALMETHOD.P	192.805(b) (192.803, 192.809(d), 192.809(e))	Are evaluation methods established and documented appropriate to each covered task?
10.	88917 (1,850)	Sat	TQ.OQ	5.	TQ.OQ.OQCONTRACTOR.R	192.807(a) (192.807(b))	Are adequate records containing the required elements maintained for contractor personnel?
11.	88917 (1,850)	Sat	TQ.OQ	6.	TQ.OQ.RECORDS.R	192.807	Do records document the evaluation and qualifications of individuals performing covered tasks, and can the qualification of individuals performing covered tasks be verified?
12.	88917 (1,850 )	Sat	TQ.0Q	7.	TQ.OQ.TRAINING.P	192.805(h)	Does the OQ program provide for initial qualification, retraining and reevaluation of individuals performing covered tasks?
13.	88917 (1,850)	Sat	TQ.OQ	8.	TQ.OQ.TRAINING.R	192.807(a) (192.807(b))	Does the operator have records for initial qualification, re-training and re-evaluation of individuals performing covered tasks?
14.	88917 (1,850	Sat	TQ.OQ	9.	TQ.OQ.OQPLANCONTRACTOR.P	192.805(b) (192.805(f), 192.805(c))	Does the OQ plan have a process to communicate the OQ plan requirements to contractors and ensure that contractors are following it?
15.	88917 (1,850)	Sat	TQ.0Q	10.	TQ.OQ.OQCONTRACTOR.P	192.805(b) (192.805(c), 192.805(d), 192.805(e), 192.805(f))	Does the OQ plan require other entities that perform covered tasks on behalf of the operator to be qualified?
16.	88917 (1,850)	Sat	TQ.OQ	11.	TQ.OQ.OQCONTRACTOREQUIV.P	192.805(h)	Does the OQ plan document that the operator has assured that the processes on which an OQ vendor has evaluated qualified personnel are the same or consistent with those used by the operator for employees and contractors in the field?
17.	88917 (1,850)	NA	TQ.OQ	12.	TQ.OQ.OTHERENTITY.R	192.805(b) (192.805(c), 192.803)	If the operator employs other entities to perform covered tasks, such as mutual assistance, are adequate records containing the required elements maintained?
18.	88917 (1,850)	Sat	TQ.0Q	13.	TQ.OQ.ABNORMAL.P	192.803	Does the OQ Plan contain requirements to assure that individuals performing covered tasks are able to recognize and react to abnormal operating conditions (AOCs)?
19.	88917 (1,850 )	Sat	TQ.0Q	14.	TQ.OQ.ABNORMAL.R	192.807(a) (192.807(b), 192.803)	Do records document evaluation of qualified

# Inspection Results Report (ALL Non-Empty Results) - Scp\_PK 88917 (1,850) Resul Qs

Ro w	Assets	Resul t	Sub-Group	Qs t #	Question ID	References	Question Text
							individuals for recognition and reaction to AOCs?
20.	88917 (1,850)	NA	ΤΩ.ΟΩ	15.	TQ.OQ.ABNORMAL.O	192.803	Do individuals performing covered tasks have adequate knowledge to recognize and react to abnormal operating conditions?
21.	88917 (1,850)	Sat	ΤΩ.ΟΩ	16.	TQ.OQ.PERFMONITOR.P	192.805(d) (192.805(e))	Does the program include provisions to evaluate an individual if there is reason to believe that performance of a covered task contributed to an incident or accident as defined in Parts 192 and 195 or there is reason to believe an individual is no longer qualified to perform a covered task?
22.	88917 (1,850)	NA	ΤΩ.ΟΩ	17.	TQ.OQ.PERFMONITOR.R	192.805(d) (192.805(e))	If the operator had an incident/accident where there is reason to believe that an individual contributed to the cause, do records indicate evaluation of the individual following the occurrence?
23.	88917 (1,850 )	NA	TQ.OQ	18.	TQ.OQ.OQPLAN.O	192.805(h)	Do individuals performing covered tasks demonstrate adequate skills, knowledge, and ability?
24.	88917 (1,850)	Sat	ΤΩ.ΟΩ	19.	TQ.OQ.MOC.P	192.805(f)	Does the OQ program identify how changes to processes, tools standards and other elements used by individuals in performing covered tasks are communicated to the individuals, including contractor individuals, and how these changes are implemented in the evaluation method(s)?
25.	88917 (1,850)	Sat	ΤΩ.ΟΩ	20.	TQ.OQ.CHANGENOTIFY.P	192.805(i) (192.18)	Does the process require significant OQ program changes to be identified and the Administrator or State agency notified?
26.	88917 (1,850 )	NA	TQ.OQ	21.	TQ.OQ.CHANGERECORD.R	192.805(i) (192.805(f), 192.18)	Are records maintained for changes that affect covered tasks and significant OQ plan changes?
27.	88917 (1,850 )	Sat	ΤΟ.QU	1.	TQ.QU.CORROSION.P	192.453 (192.805(b))	Does the process require corrosion control processes to be carried out by, or under the direction of, qualified personnel?
28.	88917 (1,850 )	Sat	TQ.QU	2.	TQ.QU.CORROSION.R	192.453 (192.807(a), 192.807(b))	Do records indicate qualification of personnel implementing pipeline corrosion control methods?
29.	88917 (1,850 )	NA	TQ.QU	3.	TQ.QU.HOTTAPQUAL.P	192.627 (192.805(b))	Does the process require taps on a pipeline under

## Inspection Results Report (ALL Non-Empty Results) - Scp\_PK 88917 (1,850)

Ro	Resul		Qs				
W	Assets	t	Sub-Group	t #	Question ID	References	Question Text
							pressure (hot taps) to be performed by qualified personnel?
30.	88917 (1,850 )	NA	TQ.QU	4.	TQ.QU.HOTTAPQUAL.R	192.627 (192.807(a), 192.807(b))	Do records indicate the qualification of personnel performing hot taps?
31.	88917 (1,850	NA	TQ.QU	5.	TQ.QU.HOTTAPQUAL.O	192.627 (192.805(h))	Do personnel performing hot taps demonstrate adequate skills and knowledge?
32.	88917 (1,850)	Sat	TQ.QU	6.	TQ.QU.EXCAVATE.P	192.805(b) (ADB-06-01, 192.801, 192.328)	Does the process require individuals who oversee and perform marking, trenching, and backfilling operations be qualified?
33.	88917 (1,850 )	NA	TQ.QU	7.	TQ.QU.EXCAVATE.R	192.807(a) (192.807(b), ADB-06-01, 192.801, 192.328)	Do records indicate qualification of individuals who oversee marking, trenching, and backfilling operations?
34.	88917 (1,850)	NA	ΤQ.QU	8.	TQ.QU.EXCAVATE.O	192.805(b) (192.805(h), ADB-06-01, 192.801(a), 192.328(a), 192.328(c))	Do individuals who oversee marking, trenching, and backfilling operations demonstrate adequate skills and knowledge?
35.	88917 (1,850)	NA	TQ.QUIM	1.	TQ.QUIM.IMREVIEWQUAL.P	192.915(a) (192.915(b), 192.915(c), 192.935(b), 192.493)	Does the process require that operator/vendor personnel (including supervisors and persons responsible for preventive and mitigative measures), who review and evaluate results meet acceptable qualification standards?
36.	88917 (1,850)	NA	TQ.QUIM	2.	TQ.QUIM.IMREVIEWQUAL.R	192.947(e) (192.915(a), 192.915(b), 192.915(c), 192.935(b)(1)(i), 192.947(d), 192.493)	Do records indicate adequate qualification of integrity management personnel?
37.	88917 (1,850 )	NA	TQ.QUIM	3.	TQ.QUIM.IMQC.P	192.805(b) (ASME B31.8S- 2004, Section 12.2(b)(4), 192.935(b)(1)(i ), 192.907(b), 192.911(l))	Does the process require personnel who execute IM program activities to be competent and qualified in accordance with the quality control plan in accordance with ASME B31.8S-2004, Section 12.2(b)(4)?
38.	88917 (1,850 )	Sat	TQ.QUOMCONS T	1.	TQ.QUOMCONST.INSPECTOR.P	192.241(a) (192.241(c), 192.805(b), 192.328(a), 192.328(b))	Does the process require welding inspection personnel to be adequately trained and qualified?
39.	88917 (1,850 )	NA	TQ.QUOMCONS T	2.	TQ.QUOMCONST.INSPECTOR.R	192.241(a) (192.241(c), 192.807(a), 192.807(b))	Do records indicate adequate qualification documentation for personnel who conduct welding inspections?
40.	88917 (1,850 )	NA	TQ.QUOMCONS T	3.	TQ.QUOMCONST.INSPECTOR.O	192.241(a) (192.241(c))	Does the welding inspector demonstrate adequate skills and knowledge?

# Inspection Results Report (ALL Non-Empty Results) - Scp\_PK 88917 (1,850) Resul Qs

Ro w	Assets	Resul t	Sub-Group	Qs t #	Question ID	References	Question Text
41.	88917 (1,850)	NA	TQ.QUOMCONS T	4.	TQ.QUOMCONST.NDT.R	192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b))	Do records indicate the qualification of nondestructive testing personnel?
42.	88917 (1,850)	NA	TQ.QUOMCONS T	5.	TQ.QUOMCONST.WELDER.R	192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))	Do records indicate that welders are adequately qualified?
43.	88917 (1,850)	Sat	TQ.QUOMCONS T	6.	TQ.QUOMCONST.WELDER.P	192.227(a) (192.225(a), 192.225(b), 192.328(a), 192.328(b), 192.805(b))	Does the process require welders to be qualified in accordance with API 1104 or the ASME Boiler & Pressure Vessel Code?
44.	88917 (1,850)	NA	TQ.QUOMCONS T	7.	TQ.QUOMCONST.WELDERLOWSTRESS .P	192.227(b) (192.225(a), 192.225(b), 192.805(b))	Does the process require welders who perform welding on low stress pipe on lines that operate at < 20% SMYS to be qualified under Section I of Appendix C to Part 192, and are welders who perform welding on service line connection to a main required to be qualified under Section II of Appendix C to Part 192?
45.	88917 (1,850)	NA	TQ.QUOMCONS T	8.	TQ.QUOMCONST.WELDER.O	192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), 192.229(d), 192.803, 192.328(a), 192.328(b))	Do welders demonstrate adequate skills and knowledge?
46.	88917 (1,850)	Sat	TQ.QUOMCONS T	9.	TQ.QUOMCONST.NDT.P	192.243(b)(2) (192.803, 192.805(b), 192.805(h), 192.328(a), 192.328(b))	Does the process require nondestructive testing of welds to be performed by personnel who are trained and qualified in the established procedures and with the testing equipment employed?
47.	88917 (1,850 )	NA	TQ.QUOMCONS T	10.	TQ.QUOMCONST.NDT.O	192.243(b)(2) (192.803, 192.328(a), 192.328(b))	Do nondestructive testing personnel demonstrate adequate skills and knowledge?
48.	88917 (1,850 )	NA	TQ.QUOMCONS T	11.	TQ.QUOMCONST.PLASTIC.P	192.285(a) (192.285(d), 192.805(b))	Does the process require personnel making joints in plastic pipelines be qualified?
49.	88917 (1,850	NA	TQ.QUOMCONS T	12.	TQ.QUOMCONST.PLASTICINSPECT.P	192.287 (192.805(b))	Does the process require that persons who inspect joints in plastic pipes be qualified?

### Inspection Results Report (ALL Non-Empty Results) - Scp\_PK 88917 (1,850)

Ro		Resul		Qs			
w	Assets	t	Sub-Group	t #	Question ID	References	Question Text
50.	88917 (1,850)	NA	TQ.QUOMCONS T	13.	TQ.QUOMCONST.PLASTIC.R	192.285(a) (192.285(d), 192.287, 192.807(a), 192.807(b))	Do records indicate adequate qualification of personnel making/inspecting joints in plastic pipelines?
51.	88917 (1,850)	NA	TQ.QUOMCONS T	14.	TQ.QUOMCONST.PLASTIC.O	192.285(a) (192.287, 192.803)	Do personnel making/inspecting joints in plastic pipelines demonstrate adequate skills and knowledge?
52.	88917 (1,850)	Sat	TQ.TR	1.	TQ.TR.TRAINING.P	192.615(b)(2) (192.805(b))	Does the process require a continuing training program to be in place to effectively instruct emergency response personnel?
53.	88917 (1,850	Sat	TQ.TR	2.	TQ.TR.TRAINING.R	192.615(b)(2) (192.807(a), 192.807(b))	Is training for emergency response personnel documented?
54.	88917 (1,850	NA	TQ.TR	3.	TQ.TR.TRAINING.O	192.615(b)(2) (192.805(b))	Do emergency response personnel demonstrate adequate skills and knowledge?
55.	88917 (1,850	Sat	TQ.TR	4.	TQ.TR.TRAININGREVIEW.P	192.615(b)(3)	Does the process require review of emergency response personnel performance?

Report Parameters: All non-empty Results

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.