Form A- Annual Review 8262

UTC Standard Annual Review Inspection Report Intrastate Operators FORM A: Annual Review

Inspector and Operator Information

Inspection ID	Inspection Link	Inspector - Lead	Inspector - Assist
8262	8262	Anthony Dorrough	
Operator	Unit	Records Location - City	& State
City of Ellensburg	City of Ellensburg	501 North Anderson St	reet, Ellensburg WA
Inspection Start Date	Inspection Exit Interview Date	Engineer Submit Date	

Inspection Summary

You must include the following in your inspection summary:

- *Inspection Scope and Summary *Facilities visited and Total AFOD

- * Summary of Significant Findings
 * Primary Operator contacts and/or participants

Instructions and Ratings Definitions

INSPECTION RESULTS: Annual Review			
Satisfactory Responses	Satisfactory List	Number of Unanswered Questions	Unanswered List
20	1,5,6,9,10,13,14,15,16,21,22,23,24,26,27,31,32,35,37,	0	
Unsatisfactory Responses	Unsatisfactory List		
0			
Area of Concern Responses	Area of Concern List		
0			
Not Applicable Responses	Not Applicable List		
19	3,4,7,8,12,17,18,19,20,25,28,29,30,39,40,41,42,43,44		
Yes Responses	Yes List	No Responses	No List
1	34,	2	36,38,
Not Checked / Evaluated Responses	Not Checked / Evaluated List		
0			

^{**}If an item is marked Unsat, AOC, N/A, or N/C, an explanation must be included in the "Notes" block for that question and also summarized in the "SUMMARY OF REQUIRED COMMENTS" section at the end of this inspection form.

Crew Inspection History

Click Link for Full List of Crew Inspections

more Emiliarion i din Eloc	or oron mopoun	01.10				
Determination crew inspection Date	Inspector	Unit	Type of Work	Foreman Name	Contractor Name	Comments / Observations for Operator
04-22-2021	Anthony Dorrough	City of Ellensburg - 7910	New Service			Staff observed that the work had already been completed.
04-22-2021	Anthony Dorrough	City of Ellensburg - 7910	Main Extension	Mike Ludwig	NW Metal Fab	Staff observed crew in the process of installing 4-inch PE main, and stub for a future housing development, tying into an existing 4-inch PE main as part of the "Bull Road Utility Extension Project". Also on site were COE Gas Engineering-Operations Manager/Darren Larsen; Gas Engineer/Tyler Gillespie.
03-18-2021	Scott Anderson	City of Ellensburg - 7910	Main Install	Logan Graham		
09-24-2020	Scott Anderson	City of Ellensburg - 7910	Relocate/Abandon			
05-28-2020	Scott Anderson	City of Ellensburg - 7910	Main Install			
03-12-2020	Scott Anderson	City of Ellensburg - 7910	Main Install	Mike Helgeson		

Facility Inspection History

Link for Full List of Facility Inspections

Date	Inspection ID	Form A Operator Name	Other Company	Inspector	Type of Inspection	Do you have inspection pictures or file attachments?
06-09-2021	7910	City of Ellensburg		Derek Norwood	Facility	Yes
06-09-2021	7910	City of Ellensburg		Derek Norwood	Facility	Yes
06-09-2021	7910	City of Ellensburg		Derek Norwood	Facility	Yes
06-10-2020	7910	City of Ellensburg		Scott Rukke	Facility	Yes
06-10-2020	7910	City of Ellensburg		Scott Rukke	Facility	Yes

Scheduled Inspection History

Annual Review Inspection History

Year of Inspection	Facility - Operator	Unit Name	Inspection ID	Inspection Type	Inspection Status	Closed Date	Next Inspection Interval	SHAREPOINT
City of Ellensb	urg (14 Inspections)	'	,		'			
2021	City of Ellensburg	City of Ellensburg	8261	PA - Public Awareness	Complete	06-28-2021	06-23-2025	Documents
2021	City of Ellensburg	City of Ellensburg	8262	Standard - Annual Review	Complete	06-28-2021	06-23-2022	Documents
2020	City of Ellensburg	City of Ellensburg	8066	Standard Comprehensive - GD	Complete	01-06-2021	10-29-2023	Documents
2020	City of Ellensburg	City of Ellensburg	8067	DA - Drug & Alcohol	Complete	08-26-2020	08-18-2024	Documents
2020	City of Ellensburg	City of Ellensburg	8068	DIMP - Gas Distribution Integrity Management	Complete	10-22-2020	09-30-2023	Documents
2020	City of Ellensburg	City of Ellensburg	8069	Standard - Annual Review	Complete	06-16-2020	06-11-2021	Documents

Year of Inspection	Facility - Operator	Unit Name	Inspection ID	Inspection Type	Inspection Status	Closed Date	Next Inspection Interval	SHAREPOINT
2019	City of Ellensburg	City of Ellensburg	7755	Technical Assistance - Operator Training	Complete	12-04-2019		Documents
2019	City of Ellensburg	City of Ellensburg	7849	OQ - Operator Qualification	Complete	08-23-2019	07-24-2023	Documents
2019	City of Ellensburg	City of Ellensburg	7850	Standard - Annual Review	Complete	08-23-2019	08-14-2020	Documents
2019	City of Ellensburg	City of Ellensburg	7923	OM PPR GAS - Operations & Maintenance, Plans & Procedures Review	Complete	12-20-2019	08-09-2023	Documents
2017	City of Ellensburg	City of Ellensburg	7250	DIMP - Gas Distribution Integrity Management	Complete	05-23-2017	04-19-2020	Documents
2017	City of Ellensburg	City of Ellensburg	7255	Standard Comprehensive - GD	Complete	11-17-2017	11-01-2020	Documents
2017	City of Ellensburg	City of Ellensburg	7473	PA - Public Awareness	Complete	11-15-2017	10-18-2021	Documents
2015	City of Ellensburg	City of Ellensburg	6191	OM PPR GAS - Operations & Maintenance, Plans & Procedures Review	Complete	08-27-2015	08-03-2019	Documents

GAS System Operations History

Annual Report -	Miles of Main			
Year	SYSTEM TOTAL Miles of Main	Miles of Service	SYSTEM TOTAL NO. of Services	Average Service Length
2020	135.097	75.87	4885	82
2019	133.123	74.98	4828	82
2018	132.638	64.12	4775	70.9
2017	129.626	63.29	4713	70.9
2016	128.312	62.49	4647	71
2015	127.412	61.84	4599	71

Annual Report GA.	o transmission wiles	
YEAR	Total Total Miles	e. Total tool mileage inspected in calendar year using in-line inspection tools
No reports found		

Annual Report - Leaks

Year	Cause of Leak Mains Total	Cause of Leak Mains Hazardous Total	Cause of Leak Services Total	Cause of Leak Services Hazardous Total	NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR
2020	0	0	15	5	0
2019	2	1	20	4	0
2018	1	1	9	1	0
2017	1	1	12	2	0
2016	0	0	11	3	0
2015	2	1	7	3	0

Annual Report - EFV

Operator	Year	Number of EFV's Installed This Calendar Year on Single Family Residential Services:	Estimated Number of EFV's in the system at the End of The Year:	Total Number of Services with EFV Installed During Year:	Estimated Number of Services with EFV In The System At The End of The Year:	* Total Number of Manual Service Line Shut-off Valves Installed During Year:	* Estimated Number of Services with Manual Service Line Shut-off Valves Installed in the System at End of Year:
City of Ellensburg	2020			59	915	3	152
City of Ellensburg	2019			52	856	8	149
City of Ellensburg	2018			71	804	1	137
City of Ellensburg	2017	74	731			1	136
City of Ellensburg	2015	58	591				
City of Ellensburg	2014	51	533				
City of Ellensburg	2013	34	482				
City of Ellensburg	2012	34	448				
City of Ellensburg	2011	47	414				
City of Ellensburg	2010	49	367				
TOT		347	3566	182	2575	13	574

HL System Operations History

HL Annual Report - I	Miles of Pipe by Decade
----------------------	-------------------------

ivo reports	found													
No reports	, ,													
YEAR	Operator	Commodity Group	Part I - Total Miles of Pipe by Decade	Unknown	Pre- 20s	1920- 1929	1930- 1939	1940- 1949	1950- 1959	1960- 1969	1970- 1979	1980- 1989	1990- 1999	2000

YEAR	Operator	Commodity Group	Total Segment Miles	High Population	Other Population	Drinking Water	Ecological Resource	Comm Navigable Water		YΕ
			that							
			Could						l 1	
			A ffoot						ш	No re

HL Annual Report - Breakout Tanks										
YEAR	Operator	Commodity Group	Crude Oil #5	Refined (non HVL) #5	HVL #5	CO2 #5	F Gra			
No reports	found									

No reports found

ANNUAL REPORT: ACCURACY/TRENDS

Question #1.	1. Result
W 11 A 10 1 1 16 11 1216 1 1 1 1 1 1 1 1	C 1: C 1

1. Notes

 $\ensuremath{\mathsf{COE}}$ shows continuing slow and steady growth in miles of main and service.

Access to Complete Distribution Annual Report

Access to C	omplete Transmi	ission Annual Report	Access to Complete Hazardous Liquid Annual Report				
YEAR	Operator	Commodity Group	Total Total Miles		YEAR	Operator	Commodity Group
			Trilles				

Year SYSTEM TOTAL Miles of Main		Miles of Service	SYSTEM TO NO Servi	of	Average Service Length	YEAR	Operato	or Comr	nodity Group			
			Ormani		50111	ccs	Length	No report	s found			
	2020		135.097	75.87		4885	82					
	2019		133.123	74.98		4828	82					
	2018		132.638	64.12		4775	70.9					
	2017		129.626	63.29		4713	70.9					
	2016		128.312	62.49		4647	71					
	2015		127.412	61.84		4599	71					
)		GE PRE		N								
	Au ii luai Ne	port Damage i it	- vendon data									
	Year	Operator	Number of Excavation Tickets	Total Number of Excavation Damages By	Locating Practices Not Sufficient:	One-C Notificati Practic N	on Praces lot Suff	nvation actices Not ficient:	Other:	Number of Services	Total Leaks - Excavation Damage	

YEAR	Operator	Commodity Group
No reports	found	

Total Total

Year	Operator	Number of Excavation Tickets	Total Number of Excavation Damages By Apparent Root Cause:	Locating Practices Not Sufficient:	One-Call Notification Practices Not Sufficient:	Excavation Practices Not Sufficient:	Other:	Number of Services	Total Leaks - Excavation Damage	Total Main Leaks	Miles of Service MAIN	Number of Leaks per Mile of MAIN	Total Leaks Per 1,000 Locates	Number of Hits Per 1,000 Ticket Requests	
2020	City of Ellensburg	1209	3	0	0	2	1	4885	2	0	135.097		1.6542597187758	2.4813895781638	6.1
2019	City of Ellensburg	1093	3	0	0	2	1	4828					0	2.7447392497713	6.2
2018	City of Ellensburg	1223	2	0	2	0	0	4775					0	1.6353229762878	4.1
2017	City of Ellensburg	1142	1	0	1	0	0	4713					0	0.87565674255692	2
2016	City of Ellensburg	1146	2	0	0	2	0	4647					0	1.7452006980803	4.
2015	City of Ellensburg	1030	1	0	0	1	0	4599					0	0.97087378640777	2.1

DIRT data on mismarks for prior year

Damage Cause	Number of Reports
No records found	

DIRT Timeliness - Prior Year Reports must be submitted within 45 days of the damage.

Late	no	yes	Totals
SubmitCompanyID - UTCfinalName	Number of Reports	Number of Reports	Number of Reports
<u>City of Ellensburg</u>	<u>4</u>	<u>3</u>	7
Totals (2 groups)	4	3	7

Question #2.

Review the following damage prevention items:

Q2. Is the damage prevention information in the annual report complete? http://Yes

Q2.b. Is the annual report damages root cause information complete and accurate?

Q2.c. Does the operator have a process to evaluate the cause of "One sufficient" category? Do not have a process established, take each incident on a case by case Q2.f. Is the operator appropriately requalifying locators to address per

Q2.d Does the operator follow a process to evaluate the cause of "Locating practices Q2.e. Is the operator or its contractor qualified and following procedures for locating and not sufficient" category? Q2.e. Is the operator or its contractor qualified and following procedures for locating and marking facilities?

Have not had damage due to locating practices.

Q2.g. What is the number of damages resulting from mismarks?

Located in Section 13 Qualifications and training: Q2.h. What is the number of damages resulting from not locating within the time

No need so far. No known performance deficiencies. Q2.i. Is the operator appropriately addressing discovered mapping en

Q2.j. Are mapping corrections timely and according to written procedures?

Q2.k. Does the operator follow a process to evaluate causes for damages listed "Excavation Practices Not Sufficient"? Do not have a process established, take each incident on a case by case basis.

No mapping errors so far. Q2.L. Is the operator appropriately focusing damage prevention educacauses of excavation damage?

Use leak investigation report and Leak Repair Report

damage?

NPMS SUBMISSIONS/CHANGES

3. Result

3. Notes

2. Notes

No such facilities for this operator.

For transmission operators, has the operator submitted information to the NPMS database, along with changes made after the original submission? Not Applicable

INCIDENT/SRC/AOC REPORTS REVIEW

Question #4 Were there any federally reportable incidents during the previous year? Are there any discernable trends to these incidents? 4. Results Not Applicable

No federally reportable incidents were found.

Q4: Federally reportable incidents

NotificationID Operator Company NRC# Assigned Engineer Date & Time of Incident Street Address of event/incident Incident Address: City Closure Date R

No incident notifications found

Review operator records of previous year's accidents and failures including reported third party damage and leak response. Is the operator ensuring appropriate evaluation and response as required in 192.617 (Gas) or 195.402 (HL) to determine cause of failure? Is the operator taking appropriate steps to minimize the possibility of reoccurrence?

requirements?

5. Result

Satisfactory

5. Notes

Question #6.

Review incident reports for the previous year for accuracy and identify any trends. If any trends discovered please describe. (Please see list of incident data at end of this report)

O6: Incident Per

Qb: Incident Reports	o: incident keports										
NotificationID	Inspector	Company	Street Address of event/incident	Date & Time of Incident	Is 30-Day Report Received?	Reporting Level					
3628	Derek Norwood	City of Ellensburg	400 S Main St	01-14-2020 09:11 AM	~	State					

6. Notes

Question #7.

Were there reportable or unreportable safety related conditions during the previous year? If yes please describe.

6. Result Satisfactory

Q7: Report of SRCs

NotificationID Company Safety-Related SafetyRelatedConditionChoices Reportable? Date & Time of Incident Company Notified Date Report Date Condition

No incident notifications found

7. Notes

No reportable or unreportable safety related conditions were found.

For transmission systems, were there any abnormal operating conditions (as described in 192.605 (c) or 195.402(d)) since the last annual review? If yes please describe.

8. Result Not Applicable

22 Results

7. Result Not Applicable

8. Notes

No such facilties for this operator.

O&M & EMERGENCY PROGRAMS

9. Result Operator Manuals on Sharepoint Is the O&M Manual up to date and were changes made in the previous year? Satisfactory

9. Notes

Question #10. 10. Result If changes to the O&M were made, are changes acceptable? Satisfactory

10. Notes

Question #11. Were emergency plans changed during the previous year?

11. Result Satisfactory

11. Notes No Changes

Question #12.

Were any changes to emergency plans satisfactory?

12. Result

Not Applicable

12. Notes

No changes

INTEGRITY MANAGEMENT PROGRAMS

13. Result Question #13 Were there changes to the Integrity Management programs (TIMP, DIMP or both, as applicable)? Satisfactory

13. Notes

Question #14 14 Result $Is the DIMP/TIMP\ up\ to\ date?\ What\ are\ the\ results\ of\ the\ operator's\ program\ review\ (effectiveness\ evaluation)\ (DIMP\ every\ 5\ years)?$ Satisfactory

14. Notes

Question #15

Are IMP program changes acceptable?

15. Notes

Question #16 16. Results Was appropriate assessment/repair work conducted during the past year? (monitor progress of IMP activities) Satisfactory

16. Notes

Question #17 17. Results Not Applicable

Does the operator's HCA location data correspond to the positional data located in UTC GIS?

Question #18 18. Results

What assessment work is planned for the upcoming year? Not Applicable

18. Notes No assessment work is planned.

19. Results

Within the operator's DIMP, are low pressure systems evaluated for overpressure threats? Not Applicable

19. Notes

20. Results

Did the operator develop and follow specific procedures for low pressure system construction or maintenance projects? (Note: this question is revisited in greater detail in the ADB review section) Not Applicable

20. Notes There is no low pressure system.

Question #21 21. Results Are plastic pipe and components that have shown a record of defects/leaks being mitigated through the DIMP plans? Satisfactory

Compression Fittings in 2015 were removed. Question #22

Has appropriate DIMP remediation work occurred during the past year? (monitor progress of DIMP activities) Satisfactory

Question #23 23. Results What DIMP remediation work is anticipated for upcoming year? Satisfactory

24. Notes	
No.	
	5. Results lot Applicable
25. Notes No changes.	
	6. Results atisfactory

PUBLIC AWARENESS PROGRAM

Is the PA program up to date? And were there changes to the Public Awareness (PA) program within the last year? Satisfactory 27. Notes

Question #28 28. Results Are changes to the PA program satisfactory? Not Applicable 28 Notes

No changes were made as of the last audit.

CONTROL ROOM PROGRAM

Question #29 29. Results Is the CRM program up to date? And were there changes to the Control Room Management (CRM) program within the last year? Not Applicable 29. Notes There are no control rooms 30. Results

Question #30 Are the CRM program changes satisfactory?

30. Notes There are no control rooms.

SAFETY MANAGEMENT SYSTEM API 1173

Question #31 31 Results

Is the operator developing and implementing an API 1173 Safety Management System? Satisfactory

31. Notes

In progress of implementation.

INSPECTOR ASSESSMENT OF INSPECTION UNITS

Question #32 32. Results

Are inspection units broken down appropriately? Do you recommend any changes to inspection units? Satisfactory

32. Notes

33. Notes

Q32: List of current inspection units

Unit Name	Distribution/Transmission	Intrastate or Interstate?	GAS or LIQUID		
City of Ellensburg (1 Unit)					
City of Ellensburg	Distribution	Intrastate	Gas		

OPERATOR'S PUBLIC WEB PAGE

Question #33 33. Results

For informational purposes: Using the drop down selections available in the "Results" block, indicate whether the operator's web page contains the information listed by placing a check in the box adjacent to all items that are present.

Q33.A Pipeline Purpose and Reliability; Q33.B Damage Prevention; Q33.C Pipe Location Information; Q33.D How to get additional information; Q33.H Prevention Measures; Q33.M Emergency Preparedness

ADVISORY BULLETIN REVIEW

Question #34 Is there potential for damage to the operator's pipeline facilities caused by flooding, river scour, or channel migration?

ADB 2019-01 34. Results YES

ADB 2019-01 Flood Mitigation

However, COE has determined that a weather event of the severity to incur even moderate damage to the pipeline system would be extremely rare. COE has addressed the risk in their DIMP

Question #35

34. Notes

If "YES" to Q34, did the operator take appropriate action in accordance with the guidance contained ADB 2019-01? Discuss ADB's guidance with operator's representative, and annotate any

ADB 2019-01 35. Results

ADB 2019-01: Flood Mitigation

Satisfactory

Not Applicable

 $There \ are \ [34] \ river \ crossings, see \ DIMP \ program \ for \ a \ detailed \ explaination \ of the \ risk \ and \ mitigation \ measures.$ Question #36

Is there potential for the operator's system to be damaged by earth movement or other seismic/geological activities?

ADB 2019-02 36. Results ADB 2019-02: Earth Movement/Geological Hazards NO

36. Notes

Question #37 If "YES" to Q36, did the operator take appropriate action according to ADB 2019-02? Discuss suggested actions from ADB with operator's representative and annotate any concerns.

ADB 2019-02 37. Results

ADB 2019-02: Earth Movement/Geological Hazards Satisfactory

37. Notes

\sim	.oction	. #20

Does the operator have any indoor meter sets or regulators in their system?

ADB 2020-01

ADB 2020-01 Inside Meter Sets

38. Notes

38. Results

NO

Question #39

If operator's system has indoor meter sets/regulators, did the operator review ADB 2020-0115? Discuss ADB guidance with operator's representative and annotate any concerns. Particular attention must be given to the operator's plan to conduct leak surveys, AC inspections, and other maintenance activities in locations that are difficult to access, as well as the inclusion of inside meters/regulators within the operator's DIMP plan, as applicable.

ADB 2020-01

ADB 2020-01 Inside Meter Sets

39. Results Not Applicable

There are no indoor meter sets.

Question #40

Does the operator have a detailed record of locations for all indoor meter sets/regulators within their system?

ADB 2020-01

40. Results Not Applicable

ADB 2020-01 Inside Meter Sets

40. Notes Thee are no indoor meter sets.

Question #41

Does the operator have any low pressure systems?

ADB 2020-02

ADB 2020-02 Low Pressure Systems

41. Results

There is no low pressure system.

Question #42

If "YES" to Q41, did the operator review ADB 2020-0025 for Overpressure Protection of Low-Pressure Natural Gas Distribution Systems? Review ADB guidance with operator and annotate any concerns.

ADB 2020-02

ADB 2020-02 Low Pressure Systems

42. Results Not Applicable

42. Notes

There are no low pressure systems.

Question #43

For low pressure construction/maintenance projects, does the operator have a process for review of engineering plans and constructibility reviews that are carried out through all applicable departments? Do all applicable departments review project plans for accuracy, completeness and correctness? How are control procedures developed that could identity system threats that could result in a common failure mode? How is the operator mitigating risk in their low presure system?

ADB 2020-02

43. Results

ADB 2020-02 Low Pressure Systems

Not Applicable

There are no low pressure systems.

Question #44

 $\label{thm:constraints} Does the operator include all low-pressure system risks in their DIMP program appropriately?$

ADB 2020-02 ADB 2020-02 Low Pressure Systems 44. Results

Not Applicable

44. Notes

There are no low pressure systems.

SUMMARY OF REQUIRED COMMENTS

COMMENTS: Required for any ratings other than Satisfactory. Summarize/consolidate entries from the "Notes" blocks above. Ensure you annotate the question number for each comment.