Inspection Output (IOR)

Generated on 2024. September. 30 15:57

Report Filters

Assets All, and including items not linked to any asset. Results All

Inspection Information

Pacific

Standard GT

Status LOCKED

Observer(s) David Cullom, Anthony Dorrough, Start Year 2023

System Type GT Protocol Set ID WA.GT.2023.01

Inspection Name [8587] Georgia Operator(s) GEORGIA-PACIFIC CONSUMER OPERATIONS LLC (31096) Lead Lex Vinsel

Derek Norwood, Scott Anderson, Tom Green

Supervisor Dennis Ritter Director Scott Rukke

Plan Submitted 11/01/2023

Plan Approval 11/01/2023 by Dennis

Ritter

All Activity Start 10/10/2023 All Activity End 10/12/2023

Inspection Submitted 11/15/2023 Inspection Approval 11/16/2023

by Scott Rukke

Inspection Summary

12Sep23 - Note that OPID for GP is 31096 for / per our records. IA is using a different OPID that is 86255 for planning purposes.? End LEV

Inspection Scope and Summary

Gas Transmission Standard Inspection for years 2020-2022

Facilities visited and Total AFOD

Camas WA, Camas Mill

AFOD - 3

Summary of Significant Findings

(DO NOT Discuss Enforcement options)

Primary Operator contacts and/or participants

Kellen Rosales Compliance Program Manager EverLine (720)822-1642

Operator executive contact and mailing address for any official correspondence

Shawn Wood

Vice President Manufacturing

401 Northeast Adams Street

Camas Washington 98607

Scope (Assets)

Short # Name	Long Name	Asset Type	Asset IDs	Excluded Topics	Planned Re	quired Ins	Total spected	Required % Complete
1. 86255	Georgia- Pacific	unit	86255	Compressor Stations Bottle/Pipe - Holders Service Line	152	152	152	100.0%

[8587] Georgia Pacific Standard GT

#	Short Name	Long Name	Asset Type	Asset IDs	Excluded Topics	Total Planned Required Inspected	Required % Complete
					Gas Storage Field (Aboveground) Vault Offshore GOM OCS Cast or Ductile Iron Copper Pipe Aluminum/Amphoteric Plastic Pipe Abandoned CDA AMAOP		

1. Percent completion excludes unanswered questions planned as "always observe".

Plans

Plan # Assets	Focus Directives	Involved Groups/Subgroups	Qst Type(s)	Extent Notes
1. 86255	WUTC Standard Inspection	AR, CR, DC, EP, FS, IM, MO, PD, RPT, SRN, TD, TQ, UNGS, 114 GENERIC	, P, R, O, S	Detail

Plan Implementations

										Required
			Focus	Involved		Qst			Total	%
	SMAR	Start Date	Directive	Groups/Subgroup	Asset	Type(s	Planne	Require	Inspecte	Complet
# Activity Name	T Act#	End Date	s	s	S)	d	d	d	e
1 GP Standard G		10/10/202		all planned		all types	152	152	152	100.0%
		3		questions	assets					
		10/12/202								
		3								

- 1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table
- 2. Percent completion excludes unanswered questions planned as "always observe".

Forms

No. Entity	Form Name	Status	Date Completed	Activity Name	Asset
1. Attendance List	GP Standard GT	COMPLETED	11/01/2023	GP Standard GT	

Results (all values, 152 results)

174 (instead of 152) results are listed due to re-presentation of questions in more than one sub-group.

AR.PTI: Integrity Assessment Via Pressure Test

1. Question Result, ID, NA, AR.PTI.PRESSTESTREVQUAL.R, 192.947(g) (192.915(a), 192.915(b)) References

Question Text Do records demonstrate that operator/vendor personnel, including supervisors, who conduct or review pressure test assessment results are qualified for the tasks they perform?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

Doguinad

Question Result, ID, NA, AR.PTI.PRESSTESTRESULT.R, 192.517(a) (192.505(a), 192.505(b), 192.505(c), 192.505(d), References 192.507(a), 192.507(b), 192.507(c), 192.513(a), 192.513(b), 192.513(c), 192.513(d), 192.517(b), 192.617, 192.619(a), 192.919(e), 192.921(a)(2))

Question Text Do the test records validate the pressure test?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

3. Question Result, ID, NA, AR.PTI.PRESSTESTCOMPLETE.O, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.505(a), References 192.505(b), 192.505(c), 192.505(d), 192.507(a), 192.507(b), 192.507(c), 192.513(a), 192.513(b), 192.513(c), 192.513(d))

Question Text From field operations was the pressure test performed in accordance with Subpart J requirements and the process requirements?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

AR.RMP: Repair Methods and Practices

4. Question Result, ID, NA, AR.RMP.IGNITION.O, 192.751(a) (192.751(b), 192.751(c))

Question Text Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

5. Question Result, ID, NA, AR.RMP.WELDTEST.O, 192.719(a) (192.719(b))

Question Text Does the operator properly test replacement pipe and repairs made by welding on transmission lines?
Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

DC.CO: Construction

6. Question Result, ID, NA, DC.CO.CASING.O, 192.323 (192.467(a), 192.467(b))

Question Text Do field observations confirm railroad or highway casings are being installed as designed and specified, and in accordance with 192.323?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

7. Question Result, ID, NA, DC.CO.REPAIR.R, 192.303 (192.309, 192.493)

Question Text Do records demonstrate that repairs to steel pipe are being made in accordance with §192.309?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.WELDINSP: Construction Weld Inspection

8. Question Result, ID, NA, DC.WELDINSP.WELDVISUALQUAL.R, 192.241 (192.225, 192.227, 192.229, 192.231, 192.233, References 192.243, 192.245)

Question Text Does the operator have records showing that the welding was visually and/or non-destructively tested according to the requirements of 192.241 and the operator's specifications or procedures?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

9. Question Result, ID, NA, DC.WELDINSP.WELDNDT.R, 192.243

Question Text Do records indicate that NDT and interpretation are in accordance with 192.243?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

10. Question Result, ID, NA, DC.WELDINSP.WELDREPAIR.R, 192.245 (192.303)

Question Text Do records indicate that unacceptable welds are removed and/or repaired in accordance with 192.245? Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.WELDPROCEDURE: Construction Welding Procedures

11. Question Result, ID, NA, DC.WELDPROCEDURE.WELD.R, 192.225

Question Text Does the operator have detailed records showing proper qualification of the welding procedures in accordance with 192.225?

Assets Covered 86255

Result Notes No such requirement existed in the scope of inspection review.

12. Question Result, ID, NA, DC.WELDPROCEDURE.WELDERQUAL.R, 192.227 (192.225, 192.229)

Question Text Do the records demonstrate that the welders are qualified in accordance with applicable sections of API Standard 1104 or ASME BPVC, Section IX, and cover the limitations in §192.229?

Assets Covered 86255

Result Notes No such requirement existed in the scope of inspection review.

13. Question Result, ID, NA, DC.WELDPROCEDURE.WELDERQUAL.O, 192.227 (192.225, 192.229)

Question Text Do field observations confirm that the welders are qualified in accordance with applicable sections of API Standard 1104 or ASME BPVC, Section IX, and cover the limitations in §192.229?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

DC.DPCOPP: Design of Pipe - Overpressure Protection

14. Question Result, ID, Sat, DC.DPCOPP.OVERPRESSURE.R, 192.195(a) (192.199(a), 192.199(b), 192.199(c), 192.199(d), References 192.199(e), 192.199(f), 192.199(g), 192.199(h), 192.201(a), 192.201(b), 192.201(c))

Question Text Do records indicate that the pipeline has pressure relieving or pressure limiting devices that are required by 192.195(a), and that they meet the requirements of 192.199 and 192.201?

Assets Covered 86255

Result Notes Reviewed annual tests from Williams (relief on Williams side) for 2020 - 2023. No changes in equipment.

15. Question Result, ID, NA, DC.DPCOPP.OVERPRESSURE.O, 192.195(a) (192.199(a), 192.199(b), 192.199(c), 192.199(d), References 192.199(e), 192.199(f), 192.199(g), 192.199(h), 192.201(a), 192.201(b), 192.201(c))

Question Text Are required pressure relieving or pressure limiting devices being installed, and do they meet the requirements of 192.199 and 192.201?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

16. Question Result, ID, Sat, DC.DPCOPP.PRESSLIMIT.R, 192.199(a) (192.199(b), 192.199(c), 192.199(d), 192.199(e), References 192.199(f), 192.199(g), 192.199(h))

Question Text Do records indicate that pressure relieving or pressure limiting devices meet the requirements of 192.199?

Assets Covered 86255

Result Notes Reviewed test records for 2020 - 2023.

17. Question Result, ID, NA, DC.DPCOPP.PRESSLIMIT.O, 192.199(a) (192.199(b), 192.199(c), 192.199(d), 192.199(e), References 192.199(f), 192.199(g), 192.199(h))

Question Text Do field observations confirm pressure relieving or pressure limiting devices meet the requirements of 192.199?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

18. Question Result, ID, Sat, DC.DPCOPP.PRESSLIMITCAP.R, 192.201(a) (192.201(b), 192.201(c)) References

Question Text Do records indicate that pressure relief or pressure limiting stations being installed comply with 192.201? Assets Covered 86255

Result Notes Reviewed Regulator and Relief inspections for 2020-2023.

19. Question Result, ID, NA, DC.DPCOPP.PRESSLIMITCAP.O, 192.201(a) (192.201(b), 192.201(c))

Question Text Do field observations verify pressure relief or pressure limiting stations comply with the requirements of 192.201?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

20. Question Result, ID, NA, DC.DPCOPP.MULTISTAGE.R, References

Question Text Do records indicate that the operator is installing multistage regulator equipment consistent with the requirements in WAC 480-93-130?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

DC.DPC: Design of Pipe Components

21. Question Result, ID, Sat, DC.DPC.ILIPASS.R, 192.150 (192.150(a), 192.150(c), 192.493)

Question Text Do records indicate that certain transmission pipeline components are designed and constructed to accommodate the passage of instrumented internal inspection devices?

Assets Covered 86255

Result Notes ILI inspections performed 2013.

22. Question Result, ID, Sat, DC.DPC.VALVESPACE.R, 192.179(a) (192.179(a)(1), 192.179(a)(2), 192.179(a)(3), 192.179(a)(4), References 192.179(b), 192.179(c), 192.179(d))

Question Text Do records indicate that transmission line valve spacing is in accordance with 192.179(a)?

Assets Covered 86255

Result Notes Two valves on 10-inch pipeline approximately a mile apart.

23. Question Result, ID, NA, DC.DPC.VALVESPACE.O, 192.141 (192.179(a), 192.179(b), 192.179(c), 192.179(d))

Question Text Are transmission line valves being installed as required by 192.179?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

24. Question Result, ID, Sat, DC.DPC.INTCORRODE.R, 192.476(d) (192.476(b), 192.476(c), 192.476(a))

Question Text Do records demonstrate the transmission line project has features incorporated into its design and construction to reduce the risk of internal corrosion, as required of 192.476?

Assets Covered 86255

Result Notes Reviewed 2007 ICDA for 10-inch pipeline.

25. Question Result, ID, NA, DC.DPC.INTCORRODE.O, 192.476(a) (192.476(b), 192.476(c)) References

Question Text Does the transmission project's design and construction comply with 192.476?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

26. Question Result, ID, NA, DC.DPC.CCPROTCOATLOWER.R, 192.143(b) (192.461(c)) (also presented in: DC.CO) References

Question Text Do records indicate that each pipe segment with external protective coating was inspected just prior to lowering into the ditch and backfilling, and any damage detrimental to effective corrosion control was repaired?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

27. Question Result, ID, NA, DC.DPC.CCELECTRICALISOL.R, 192.467(c) (192.143(b))

Question Text Do operator's records indicate that each pipeline was electrically isolated from metallic casings that are a part of the underground system?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

28. Question Result, ID, NA, DC.DPC.CCELECTRICALISOL.O, 192.467(c) (192.143(b))

Question Text Do field observations confirm that each pipeline was electrically isolated from metallic casings that are a part of the underground system?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

DC.MO: Maintenance and Operations

29. Question Result, ID, NA, DC.MO.ICEXAMINE.R, 192.491(c) (192.475(a), 192.475(b), 192.475(c))

Question Text Do records indicate examination of removed pipe for evidence of internal corrosion?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

30. Question Result, ID, NA, DC.MO.ICEXAMINE.O, 192.475(a) (192.475(b), 192.475(c))

Question Text Is examination of removed pipe conducted to determine any evidence of internal corrosion?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

31. Question Result, ID, NA, DC.MO.MAOPLIMIT.O, 192.605(b)(5)

Question Text During startup or shut-in, is it assured that the pressure limitations on the pipeline were not exceeded?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

32. Question Result, ID, NA, DC.MO.RECORDUPDATE.R, References

Question Text Do records indicate that records, maps, and drawings of gas facilities are updated not later than six months from completion of construction activity and made available to appropriate personnel?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.PT: Pressure Testing

33. Question Result, ID, NA, DC.PT.PRESSTEST.R, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PTLOWPRESS)

Question Text Do records indicate that pressure testing is conducted in accordance with 192.503?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

34. Question Result, ID, NA, DC.PT.PRESSTEST.O, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PTLOWPRESS)

Question Text Is pressure testing conducted in accordance with 192.503?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

35. Question Result, ID, NA, DC.PT.PRESSTESTHIGHSTRESS.R, 192.505(a) (192.143(a), 192.517(a), 192.505(b), 192.505(c), References 192.505(d), 192.143(b), 192.143(c))

Question Text Do records indicate that the sections of a pipeline operating at a hoop stress equal to or greater than 30% of SMYS were strength tested in accordance with the requirements of 192.505?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

36. Question Result, ID, NA, DC.PT.PRESSTESTHIGHSTRESS.O, 192.505(a) (192.143(a), 192.505(b), 192.505(c), 192.505(d), References 192.143(b), 192.143(c))

Question Text Do field observations confirm that sections of a pipeline operating at a hoop stress equal to or greater than 30% of SMYS are strength tested in accordance with the requirements of 192.505?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

37. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.R, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, the test medium disposal was conducted in a manner that minimized damage to the environment?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

38. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.O, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, the test medium was disposed of in an environmentally sound manner?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

39. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.R, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, every reasonable precaution was taken to protect its employees and the general public throughout the testing?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

40. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.O, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, every reasonable precaution is taken to protect its employees and the general public throughout the testing?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

41. Question Result, ID, Sat, DC.PT.PRESSTESTRECORD.R, 192.517(a) (192.517(b)) (also presented in: DC.SPT, References DC.PTLOWPRESS)

Question Text Do records indicate creation and retention of a record for each Subpart J test performed for the required duration?

Assets Covered 86255

Result Notes Aug. 1993 - Original Hydro Reviewed Pressure Chart - No issues

4/14/2010 - Relocate (Hydro) Test - Reviewed Pressure - No issues

42. Question Result, ID, Sat, DC.PT.EQUIPMENTCALIBRATION.R, References

Question Text Do records indicate that pressure testing equipment is maintained and calibrated at appropriate intervals in accordance with the manufacturer's recommendations?

Assets Covered 86255

Result Notes Reviewed certifications for used equipment.

DC.PTLOWPRESS: Pressure Testing - Low Pressure

43. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTESTLOWSTRESS.R, 192.507 (192.505, 192.515, 192.517, ANSI/GPTC References Z380.1-2018 Appendix G-192-9)

Question Text Do records indicate that, as applicable to the project, sections of a pipeline operating at a hoop stress less than 30% of SMYS and at or above 100 psig were tested in accordance with the requirements of 192.507?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

44. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTESTLOWSTRESS.O, 192.507 (192.505, 192.515, ANSI/GPTC Z380.1-2018 References Appendix G-192-9)

Question Text Do field observations confirm that sections of a pipeline operating at a hoop stress less than 30% of SMYS and at or above 100 psig are tested in accordance with the requirements of 192.507?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

45. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTEST100PSIG.R, 192.509 (192.143, 192.517) References

Question Text Do records indicate that the sections of a pipeline operated below 100 psig were leak tested in accordance with the section requirements of 192.509 (except for service lines and plastic pipelines)?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

46. Question Result, ID, NA, DC.PTLOWPRESS.PRESSTEST100PSIG.O, 192.509 (192.143)

Question Text Do field observations confirm that sections of a pipeline operated below 100 psig are leak tested in accordance with the requirements of 192.509 (except for service lines and plastic pipelines)?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

DC.TQ: Training and Qualification

47. Question Result, ID, Sat, DC.TQ.ABNORMAL.R, 192.807(a) (192.803)
References

Question Text Do records show evaluation of qualified individuals for recognition and reaction to AOCs?

Assets Covered 86255

Result Notes All covered tasks have an AOC section as part of the procedure and qualification.

Roy Rogers for Qualifications EWN - 509638

Task 022A Valve Testing & maintenance Last cert 9/17/2023

Task 67, Odorization, Last certification 9/9/2023

Task 001, Conduct Cathodic Protection Survey, 9/10/2023

Steve Ringquist EUW 725326

Ron Simmons EUW 660152

_

Steve Ringquist Emergency related tasks only - Up to date

September

48. Question Result, ID, Sat, DC.TQ.RECORDS.R, 192.807(a) (Operators OQ program manual)

Question Text Are qualification records maintained for operator personnel?

Assets Covered 86255

Result Notes Operator Qualifications are maintained through Energy World Net (EWN)

EP.ERG: Emergency Response

49. Question Result, ID, References Sat, EP.ERG.REVIEW.R, 192.605(a)

Report Filters: Results: all

Question Text Have annual reviews been conducted of the emergency plans and procedures as required, and any updates completed as appropriate?

Assets Covered 86255

Result Notes Annual Reviews of emergency plans and procedures were completed on May 2023 May 2022, May 2021, May & June 2020.

50. Question Result, ID, Sat, EP.ERG.LOCATION.O, 192.615(b)(1) References

Question Text Are supervisors provided the applicable portions of the emergency plan and procedures?

Assets Covered 86255

Result Notes Ron Simmons and Steve Ringquest have copies of emergency plans and procedures

51. Question Result, ID, NA, EP.ERG.POSTEVNTREVIEW.R, 192.605(a) (192.615(b)(1), 192.615(b)(3))

Question Text Do records indicate review of employee activities to determine whether the procedures were effectively followed in each emergency?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

52. Question Result, ID, Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), References 192.616(c), ADB-05-03) (also presented in: PD.PA)

Question Text Do records indicate that liaison has been established and maintained with appropriate fire, police, public officials, and utility owners?

Assets Covered 86255

Result Notes Send out Oct 2020 to Local Fire, Police, Sheriff

Reviewed Mailing labels for send out. 2020 - Sep 2021 - Nov 2022

MO.GC: Conversion to Service

53. Question Result, ID, NA, MO.GC.CONVERSION.R, 192.14(a) (192.14(b), 192.14(c))

Question Text Do records indicate the process was followed for converting any pipelines into Part 192 service? Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

MO.GOABNORMAL: Gas Pipeline Abnormal Operations

54. Question Result, ID, References Sat, MO.GOABNORMAL.ABNORMAL.R, 192.605(a) (192.605(c)(1))

Question Text Did personnel respond to indications of abnormal operations as required by the process?

Assets Covered 86255

Result Notes Abnormal Operations

March 14, 2022 - Loss of phone communication for 4 hours - 7am to 11 am while changing phone providers.

Event documented on AOC form.

No issues during the event.

55. Question Result, ID, Sat, MO.GOABNORMAL.ABNORMALREVIEW.R, 192.605(a) (192.605(c)(4)) References

Question Text Do records indicate periodic review of work done by operator personnel to determine the effectiveness of the abnormal operation processes and corrective action taken where deficiencies are found?

Assets Covered 86255

Result Notes Reviewed records of Quarterly Compliance review - Includes review of AOC's and SRC's.

Reviewed sample of quarterly reports.

MO.GOCLASS: Gas Pipeline Class Location

56. Question Result, ID, Sat, MO.GOCLASS.CLASSLOCATESTUDY.R, 192.605(b)(1) (192.609(a), 192.609(b), 192.609(c), References 192.609(d), 192.609(e), 192.609(f))

Question Text Do records indicate performance of the required study whenever the population along a pipeline increased or there was an indication that the pipe hoop stress was not commensurate with the present class location?

Assets Covered 86255

Result Notes Reviewed HCA Identification report for 10-inch GP Camas Mill Pipeline and Class Location report. Consider all to be class 3.

July 2020

September 2021

Class Location HCA & MCA Analysis - November 30 2022.

MO.GOMAOP: Gas Pipeline MAOP

57. Question Result, ID, Sat, MO.GOMAOP.MAOPDETERMINE.R, 192.709(c) (192.619(a), 192.619(b), 192.619(f), 192.517)

Question Text Do records indicate determination of the MAOP of pipeline segments in accordance with 192.619 and limiting of the operating pressure as required?

Assets Covered 86255

Result Notes MAOP Evaluation - Design Formula for Steel Pipe

Reviewed MAOP determination in 2020, no operational changes since 2020.

MO.GM: Gas Pipeline Maintenance

58. Question Result, ID, Sat, MO.GM.RECORDS.R, 192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c)) (also References presented in: MO.GMOPP)

Question Text Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?

Assets Covered 86255

Result Notes Pipeline records appear adequate.

Reviewed a sample of pipeline patrols and corrosion (with supports) patrols.

59. Question Result, ID, NA, MO.GM.IGNITION.R, 192.709 (192.751(a), 192.751(b), 192.751(c))

Question Text Do records indicate personnel followed processes for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

60. Question Result, ID, References Sat, MO.GM.VALVEINSPECT.R, 192.709(c) (192.745(a), 192.745(b))

Question Text Do records indicate proper inspection and partial operation of transmission line valves that may be required during an emergency as required and prompt remedial actions taken if necessary?

Assets Covered 86255

Result Notes Valve inspections every 6 months.

61. Question Result, ID, References Sat, MO.GM.VALVEINSPECT.O, 192.745(a) (192.745(b))

Question Text Are field inspection and partial operation of transmission line valves adequate?

Assets Covered 86255

Result Notes Partial operation of valves #1 and #2 by Roy R. Qualifications up to date.

MO.GOODOR: Gas Pipeline Odorization

 Question Result, ID, Sat, MO.GOODOR.ODORIZE.R, 192.709(c) (192.625(a), 192.625(b), 192.625(c), 192.625(d), References 192.625(e), 192.625(f))

Question Text Do records indicate appropriate odorization of its combustible gases in accordance with its processes and conduct of the required testing to verify odorant levels met requirements?

Assets Covered 86255

Result Notes Reviewed sample for odorant reads from 2020, 2021, 2022 and 2023.

Readings acceptable and calibration records for instrument were attached.

63. Question Result, ID, NA, MO.GOODOR.ODORIZE.O, 192.625(f)

Question Text Is sampling of combustible gases adequate using an instrument capable of determining the percentage of gas in air at which it becomes readily detectable?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

MO.GO: Gas Pipeline Operations

64. Question Result, ID, Sat, MO.GO.CONTSURVEILLANCE.R, 192.709(c) (192.613(a), 192.613(b), 192.703(b), 192.703(c)) (also References presented in: MO.GOCLASS)

Question Text Do records indicate performance of continuing surveillance of facilities as required, and also the reconditioning, phasing out, or MAOP reduction in any pipeline segment that was determined to be in unsatisfactory condition but on which no immediate hazard existed?

Assets Covered 86255

Result Notes Reviewed Continuing Surveillance Reports of for GP pipeline facilities for December 31, 2020, Dec 31, 2021, Dec 31, 2022.

65. Question Result, ID, NA, MO.GO.CONTSURVEILLANCE.O, 192.613(a) (192.613(b), 192.703(a), 192.703(b), 192.703(c)) (also References presented in: MO.GOCLASS)

Question Text Are unsatisfactory conditions being captured and addressed by continuing surveillance of facilities and the pipeline as required by 192.613?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

66. Question Result, ID, Sat, MO.GO.OMANNUALREVIEW.R, 192.605(a)

Question Text Has the operator conducted annual reviews of the written procedures or processes in the manual as required?

Assets Covered 86255

Result Notes Annual review is scheduled for May. Reviewed records.

67. Question Result, ID, Sat, MO.GO.OMEFFECTREVIEW.R, 192.605(a) (192.605(b)(8))

Question Text Do records indicate periodic review of the work done by operator personnel to determine the effectiveness, and adequacy of the processes used in normal operations and maintenance and modifying the processes when deficiencies are found?

Assets Covered 86255

Result Notes Reviewed O&M Revision Log for 2020, 2021, 2022, and 2023. Many revisions during the first year with annual reviews occurring in May.

68. Question Result, ID, Sat, MO.GO.OMHISTORY.R, 192.605(a) (192.605(b)(3))
References

Question Text Are construction records, maps, and operating history available to appropriate operating personnel? Assets Covered 86255

Result Notes Records and maps are available to Operator personnel.

Reviewed construction drawings.

69. Question Result, ID, Sat, MO.GO.OMHISTORY.O, 192.605(b)(3)

[8587] Georgia Pacific Standard GT

Question Text Are construction records, maps and operating history available to appropriate operating personnel?

Assets Covered 86255

Result Notes Pipeline records and maps are available to Operating personnel.

70. Question Result, ID, Sat, MO.GO.OMLOCATION.O, 192.605(a)

Question Text Are appropriate parts of the manual kept at locations where operations and maintenance activities are conducted?

Assets Covered 86255

Result Notes Manual is available to operating personnel.

71. Question Result, ID, NA, MO.GO.UPRATE.R, 192.553(b) (192.553(a), 192.553(c), 192.553(d))

Question Text Do records indicate the pressure uprating process was implemented per the requirements of 192.553?
Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

MO.GMOPP: Gas Pipeline Overpressure Protection

72. Question Result, ID, Sat, MO.GMOPP.PRESSREGCAP.R, 192.709(c) (192.743(a), 192.743(b), 192.743(c))

Question Text Do records indicate testing or review of the capacity of each pressure relief device at each pressure limiting station and pressure regulating station as required?

Assets Covered 86255

Result Notes Reviewed Records for capacity of the relief devices provided by Williams and reviewed 2020-2023.

73. Question Result, ID, NA, MO.GMOPP.PRESSREGTEST.R, 192.709(c) (192.739(a), 192.739(b))

Question Text Do records indicate inspection and testing of pressure limiting, relief devices, and pressure regulating stations?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

74. Question Result, ID, NA, MO.GMOPP.PRESSREGTEST.O, 192.739(a) (192.739(b), 192.743)

Question Text Are field or bench tests or inspections of regulating stations, pressure limiting stations or relief devices adequate?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

MO.RW: ROW Markers, Patrols, Leakage Survey and Monitoring

75. Question Result, ID, Sat, MO.RW.PATROL.R, 192.709(c) (192.705(a), 192.705(b), 192.705(c)) (also presented in: PD.RW)

Question Text Do records indicate that ROW surface conditions have been patrolled as required?

Assets Covered 86255

Result Notes Reviewed sample of pipeline patrol records for 2020, 2021, 2022, and 2023.

76. Question Result, ID, Sat, MO.RW.ROWMARKER.O, 192.707(a) (192.707(b), 192.707(c), 192.707(d)) (also presented in: References PD.RW)

Question Text Are line markers placed and maintained as required?

Assets Covered 86255

Result Notes Pipeline markers are located adequately and maintained as required.

77. Question Result, ID, Sat, MO.RW.ROWCONDITION.O, 192.705(a) (192.705(c)) (also presented in: PD.RW)

Question Text Are the ROW conditions acceptable for the type of patrolling used?

Assets Covered 86255

Result Notes Right of Way ROW conditions are acceptable. Patrolling is done on foot.

Report Filters: Results: all

78. Question Result, ID, Sat, MO.RW.MARKERSURVEY.R, References

Question Text Do records indicate that pipeline marker surveys were completed in the timeframe specified by WAC 480-93-124?

Assets Covered 86255

Result Notes Patrols are done annually.

Reviewed record of marker surveys for time period as below.

July 9, 2020

July 18, 2021

July 16, 2022

79. Question Result, ID, Sat, MO.RW.LEAKAGE.R, 192.709(c) (192.706, 192.706(a), 192.706(b), 192.935(d))

Question Text Do records indicate leakage surveys conducted as required?

Assets Covered 86255

Result Notes Reviewed records of annual Leakage Survey

140ct 2020

300ct21

210ct22

80. Question Result, ID, NA, MO.RW.CASINGLEAKSURVEY.R, References

Question Text Do records indicate shorted casings were leak surveyed as required?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

81. Question Result, ID, NA, MO.RW.SPECIALLEAKSURVEY.R,

Question Text Do records indicate that special leak surveys have been conducted as required by WAC 480-93-188? Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

82. Question Result, ID, NA, MO.RW.LEAKGRADE.R, References

Question Text Do records indicate that the operator has graded leaks and determined the extent of each leak?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

83. Question Result, ID, NA, MO.RW.LEAKFOLLOWUP.R, References

Question Text Do records indicate that a follow-up inspection was performed not more than thirty days following a repair where residual gas remained in the ground?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

84. Question Result, ID, NA, MO.RW.DOWNGRADELEAKREPAIR.R,

Question Text Do records indicate that leaks that have been downgraded are repaired within twenty-one months?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

85. Question Result, ID, NA, MO.RW.LEAKREPAIRTIME.R, References

Question Text Do records indicate that leaks were repaired and re-evaluated within the timeframes specified in WAC 480-93-18601?

Assets Covered 86255

Result Notes No such requirement existed in the scope of inspection review.

86. Question Result, ID, NA, MO.RW.LEAKRECORDS.R,

References

Question Text Have gas leak records been prepared and maintained as required?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

87. Question Result, ID, Sat, MO.RW.LEAKCALIBRATE.R, References

> Question Text Do records indicate that gas detection equipment has been maintained and calibrated in accordance with the manufacturer's recommendations?

Assets Covered 86255

Result Notes Annual calibration for Leak survey equipment 2020, 2021, 2022, 2023.

Heath DP-III HFI

serial number CPE #2

PD.DP: Damage Prevention

88. Question Result, ID, Sat, PD.DP.ONECALL.O, 192.614(c)(3) References

Question Text Observe operator process a "One Call" ticket.

Assets Covered 86255

Result Notes One call performed for base of new sign to be installed.

89. Question Result, ID, Sat, PD.DP.PDPROGRAM.R, 192.614(c) References

Question Text Does the damage prevention program meet minimum requirements specified in 192.614(c)?

Assets Covered 86255

Result Notes Section 18 of O&M manual.

90. Question Result, ID, Sat, PD.DP.DPINFOGATHER.R, 192.947(b) (192.917(b), 192.935(b)(1)(ii)) References

> Question Text Do records demonstrate that critical damage prevention information is being gathered and recorded during pipeline patrols, leakage surveys, and integrity assessments?

Assets Covered 86255

Result Notes Damaged marker fixed in a timely manner.

91. Question Result, ID, NA, PD.DP.NOTICETOEXCAVATOR.R, References

> Question Text Do records indicate that the operator provides the required information to excavators who damage pipeline facilities?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

92. Question Result, ID, NA, PD.DP.COMMISSIONREPORT.R, References

> Question Text Do records indicate the operator reports to the commission when the operator or its contractor observes or becomes aware of the activities described in WAC 480-93-200(9)?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

PD.PA: Public Awareness

Report Filters: Results: all

93. Question Result, ID, References Sat, PD.PA.LANGUAGE.R, 192.616(g) (API RP 1162 Section 2.3.1)

Question Text Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?

Assets Covered 86255

Result Notes Mailers for public are available in Spanish and English.

PD.SP: Special Permits

94. Question Result, ID, NA, PD.SP.REPAIR.R, 190.341(d)(2)

Question Text If the operator operates a pipeline under a special permit, do records indicate that required repairs were performed?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

RPT.NR: Notices and Reporting

95. Question Result, ID, NA, RPT.NR.CONTACTUPDATE.R, References

Question Text Do records indicate that the operator submits updated name, address, and phone numbers of emergency contacts/responsible officials to the commission and appropriate officials of ALL municipalities in which the company has pipeline facilities?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

96. Question Result, ID, NA, RPT.NR.CONSTRUCTIONREPORT.R, References

Question Text Do records indicate the operator has filed a proposed construction report for construction or replacement of any segment of gas transmission pipeline of at least 100 feet in length?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

97. Question Result, ID, References NA, RPT.NR.PRESSURETESTNOTIFY.R,

Question Text Do records indicate that the operator notified the commission 3 days prior to commencement of any pressure test of a gas pipeline that will have a MAOP that produces a hoop stress of twenty percent or more of the specified minimum yield strength?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

98. Question Result, ID, NA, RPT.NR.PROXIMITYREQUEST.R, References

Question Text Do records demonstrate that the operator is in compliance with the proximity consideration requirements in WAC 480-93-020?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

RPT.RR: Regulatory Reporting (Traditional)

99. Question Result, ID, Sat, RPT.RR.ANNUALREPORT.R, 191.17(a)

Question Text Have complete and accurate Annual Reports utilizing the most recent form F 7 100.2-1 been submitted? Assets Covered 86255

Result Notes Annual Reports were reviewed for 2020, 2021, and 2022

Annual Reports appear accurate and adequate.

100. Question Result, ID, Sat, RPT.RR.CONSTRUCTIONDEFECTS.R, References

Question Text Do records indicate that the operator has submitted timely and complete reports of construction defects and material failures that resulted in leaks?

Assets Covered 86255

Result Notes No findings no issues.

101. Question Result, ID, NA, RPT.RR.IMMEDREPORT.R, 191.5(a) (191.7(a))
References

Question Text Do records indicate immediate notifications of incidents were made in accordance with 191.5?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

102. Question Result, ID, NA, RPT.RR.INCIDENTREPORT.R, 191.15(a) (192.624(a)(1), 192.624(a)(2)) References

Question Text Do records indicate reportable incidents were identified and reports were submitted to DOT on the most recent Form within the required timeframe?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

103. Question Result, ID, NA, RPT.RR.INCIDENTREPORTSUPP.R, 191.15(d)

Question Text Do records indicate accurate supplemental incident reports were filed and within the required timeframe using the most recent Form?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

104. Question Result, ID, NA, RPT.RR.FAILUREANALYSIS.R, References

Question Text Do records indicate that the operator submits failure analysis reports within 5 days of completion for incidents or hazardous conditions due to construction defects or material failures?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

105. Question Result, ID, NA, RPT.RR.SRCR.R, 191.23(a) (191.23(b), 191.25(a), 191.25(b), 191.25(c))

Question Text Do records indicate Safety-Related Condition Reports were filed as required?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

106. Question Result, ID, Sat, RPT.RR.NPMSANNUAL.R, 191.29(a) (191.29(b))

Question Text Do records indicate NPMS submissions were completed each year, on or before March 15, representing all in service, idle and retired assets as of December 31 of the previous year (excludes distribution lines and gathering lines) occurred, and that if no modifications occurred, an email was submitted stating that fact?

Assets Covered 86255

Result Notes Annual reporting of no change to NPMS.

107. Question Result, ID, NA, RPT.RR.PIPELINEMAPPING.R, References

Question Text Do records indicate that accurate maps (or updates) are provided for pipelines operating over 250 PSIG to specifications developed by the commission and sufficient to meet the needs of first responders?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

108. Question Result, ID, Sat, RPT.RR.OPID.R, 191.22(a) (191.22(c), 191.22(d)) References

Question Text Do records indicate appropriate obtaining, and control of, Operator Identification Numbers (OPIDs), including changes in entity, acquisition/divestiture, and construction/update/uprate?

Assets Covered 86255

Result Notes No changes that would effect the OPID 31096.

109. Question Result, ID, NA, RPT.RR.DIRTREPORTS.R, References

[8587] Georgia Pacific Standard GT

Question Text Do records indicate that the operator has submitted reports of damage to the commission using the damage information reporting tool (DIRT) within 45 days?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TD.ATM: Atmospheric Corrosion

110. Question Result, ID, Sat, TD.ATM.ATMCORRODE.R, 192.491(c) (192.479(a), 192.479(b), 192.479(c))

Question Text Do records document the protection of above ground pipe from atmospheric corrosion?

Assets Covered 86255

Result Notes Reviewed annual corrosion reports for the following years.

Jul 10, 2020

Jul 18, 2021

Jul 28, 2023

111. Question Result, ID, Sat, TD.ATM.ATMCORRODEINSP.R, 192.491(c) (192.481(a), 192.481(b), 192.481(c), 192.481(d)) References

Question Text Do records document inspection of aboveground pipe for atmospheric corrosion?

Assets Covered 86255

Result Notes Reviewed annual corrosion reports for the following years.

Jul 10, 2020

Jul 18, 2021

Jul 28, 2023

112. Question Result, ID, Sat, TD.ATM.ATMCORRODEINSP.O, 192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c),

References 192.481(d))

Question Text Is pipe that is exposed to atmospheric corrosion protected?

Assets Covered 86255

Result Notes Exposed pipe is coated adequately.

TD.CPMONITOR: External Corrosion - CP Monitoring

113. Question Result, ID, Sat, TD.CPMONITOR.MONITORCRITERIA.R, 192.491(c) (192.463(a)) References

Question Text Do records document that the CP monitoring criteria used was acceptable?

Assets Covered 86255

Result Notes Reviewed CP monitoring records for

July 9, 2020

July 18, 2021

July 16, 2022

Instrument Multimeter 28130007

Cal date Jan 3, 2023

114. Question Result, ID, Sat, TD.CPMONITOR.MONITORCRITERIA.O, 192.465(a) (192.463(a), 192.463(b), 192.463(c), Part 192, References Appendix D)

Question Text Are methods used for taking CP monitoring readings that allow for the application of appropriate CP monitoring criteria?

[8587] Georgia Pacific Standard GT

Assets Covered 86255

Result Notes Observed Roy R taking Pipe to Soil (P/S) reads at various locations.

References

115. Question Result, ID, Sat, TD.CPMONITOR.TEST.R, 192.491(c) (192.465(a))

Question Text Do records adequately document cathodic protection monitoring tests have occurred as required?

Assets Covered 86255

Result Notes Review of CP surveys

Reviewed CP monitoring records for

July 9, 2020

July 18, 2021

July 16, 2022

Instrument Multimeter 28130007

Cal date Jan 3, 2023

116. Question Result, ID, Sat, TD.CPMONITOR.CURRENTTEST.R, 192.491(c) (192.465(b))

Question Text Do records document details of electrical checks of sources of rectifiers or other impressed current sources?

Assets Covered 86255

Result Notes Reviewed sample of

September 11, 2020

28Nov21

12Mar22

16Jan23

117. Question Result, ID, Sat, TD.CPMONITOR.CURRENTTEST.O, 192.465(b)

Question Text Are impressed current sources properly maintained and are they functioning properly?

Assets Covered 86255

Result Notes Impressed current sources (Rectifier) is in excellent shape and measurement confirmed that it is operating properly.

118. Question Result, ID, NA, TD.CPMONITOR.REVCURRENTTEST.R, 192.491(c) (192.465(c))

Question Text Do records document details of electrical checks interference bonds, diodes, and reverse current switches?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

119. Question Result, ID, NA, TD.CPMONITOR.REVCURRENTTEST.O, 192.465(c) References

> Question Text Are interference bonds, diodes, and reverse current switches properly maintained and are they functioning properly?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

120. Question Result, ID, NA, TD.CPMONITOR.DEFICIENCY.R, 192.491(c) (192.465(d))

Question Text Do records adequately document actions taken to correct any identified deficiencies in corrosion control?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

121. Question Result, ID, Sat, TD.CPMONITOR.TESTSTATION.R, 192.469

References

Ouestion Text Do records identify the location of test stations and show a sufficient number of test stations?

Assets Covered 86255

Result Notes Test station placement appears adequate.

122. Question Result, ID, Sat, TD.CPMONITOR.TESTLEAD.R, 192.491(c) (192.471(a), 192.471(b), 192.471(c))

Question Text Do records document that pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart I?

Assets Covered 86255

Result Notes Cad welded to pipe and coated.

123. Question Result, ID, Sat, TD.CPMONITOR.INTFRCURRENT.R, 192.491(c) (192.473(a)) References

> Question Text Do records document an effective program is in place to minimize detrimental effects of interference currents and that detrimental effects of interference currents from CP systems on other underground metallic structures are minimized?

Assets Covered 86255

Result Notes Program appears adequate for this pipeline.

TD.CP: External Corrosion - Cathodic Protection

124. Question Result, ID, Sat, TD.CP.POST1971.R, 192.491(c) (192.455(a), 192.457(a), 192.452(a), 192.452(b), 192.455(f), References 192.455(g))

Question Text Do records document that each buried or submerged pipeline installed after July 31, 1971, has been protected against external corrosion with a cathodic protection system within 1 year after completion of construction, conversion to service, or becoming jurisdictional onshore gathering?

Assets Covered 86255

Result Notes CP protection was installed during construction.

125. Question Result, ID, NA, TD.CP.PRE1971.0, 192.457(b) References

> Question Text Are bare or coated pipes in compressor, regulator or meter stations installed before August 1, 1971 (except for cast and ductile iron lines) cathodically protected in areas where active corrosion was found in accordance with Subpart I of Part 192?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

126. Question Result, ID, NA, TD.CP.UNPROTECT.R, 192.491(c) (192.465(e)) References

> Question Text Do records adequately document the re-evaluation of non-cathodically protected buried pipelines for areas of active corrosion?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

127. Question Result, ID, Sat, TD.CP.ELECISOLATE.R, 192.491(c) (192.467(a), 192.467(b), 192.467(c), 192.467(d), 192.467(e))

Question Text Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?

Assets Covered 86255

Result Notes Documentation of separation of structures the is on the Cp test records for Isolation flange with Williams pipeline.

128. Question Result, ID, Sat, TD.CP.ELECISOLATE.O, 192.467(a) (192.467(b), 192.467(c), 192.467(d), 192.467(e)) References

Question Text Are measures performed to ensure electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?

Assets Covered 86255

Result Notes Electrical Isolation from Williams to GP Camus was confirmed.

129. Question Result, ID, NA, TD.CP.CASINGINSPECT.R,

References

Question Text Do records indicate that annual casing inspections have been performed to ensure electrical isolation from the pipeline?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

130. Question Result, ID, NA, TD.CP.CASINGINSPECT.O, References

Question Text Are casings electrically isolated from the pipeline?

Assets Covered 86255

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

131. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) (also presented in: TD.CPMONITOR, References TD.CPEXPOSED)

Question Text Do records indicate the location of all corrosion control items listed in §192.491(a)?

Assets Covered 86255

Result Notes Reviewed maps of CP stations and locations.

TD.COAT: External Corrosion - Coatings

132. Question Result, ID, Sat, TD.COAT.NEWPIPE.R, 192.491(c) (192.455(a)(1), 192.461(a), 192.461(b), 192.483(a)) References

Question Text Do records document that each buried or submerged pipeline installed after July 31, 1971 has been externally coated with a suitable coating material?

Assets Covered 86255

Result Notes Manual callout of Fusion Bonded Epoxy be used on all pipelines.

TD.CPEXPOSED: External Corrosion - Exposed Pipe

133. Question Result, ID, NA, TD.CPEXPOSED.EXPOSEINSPECT.R, 192.491(c) (192.459)

References

Question Text Do records adequately document that exposed buried piping was examined for corrosion and deteriorated

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

134. Question Result, ID, NA, TD.CPEXPOSED.EXPOSEINSPECT.O, 192.459 References

Question Text Is exposed buried piping examined for corrosion and deteriorated coating?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

135. Question Result, ID, NA, TD.CPEXPOSED.EXTCORRODREPAIR.R, 192.491(c) (192.485(a), 192.485(b), 192.485(c)) References

Question Text Do records document the repair or replacement of pipe that has been externally corroded to an extent that there is not sufficient remaining pipe wall strength?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TD.ICP: Internal Corrosion - Preventive Measures

136. Question Result, ID, NA, TD.ICP.EXAMINE.R, 192.491(c) (192.475(a), 192.475(b))

Question Text Do records document examination of removed pipe for evidence of internal corrosion?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

137. Question Result, ID, NA, TD.ICP.EXAMINE.O, 192.475(a) (192.475(b))

References

Ouestion Text Is removed pipe examined for evidence of internal corrosion?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

138. Question Result, ID, NA, TD.ICP.EVALUATE.R, 192.491(c) (192.485(c))

Question Text Do records document adequate evaluation of internally corroded pipe?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

139. Question Result, ID, NA, TD.ICP.REPAIRINT.R, 192.485(a) (192.485(b))

References

Question Text Do records document the repair or replacement of pipe that has been internally corroded to an extent that there is not sufficient remaining strength in the pipe wall?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TQ.PROT9: OQ Protocol 9

140. Question Result, ID, NA, TQ.PROT9.CORRECTION.O, 192.801(a) (192.809(a))

Question Text Have potential issues identified by the OQ plan inspection process been corrected at the operational level?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

141. Question Result, ID, Sat, TQ.PROT9.TASKPERFORMANCE.O, 192.801(a) (192.809(a))

Question Text Verify the qualified individuals performed the observed covered tasks in accordance with the operator's processes or operator approved contractor processes.

Assets Covered 86255

Result Notes Roy Rogers performed covered tasks for GP Camus.

142. Question Result, ID, Sat, TQ.PROT9.QUALIFICATIONSTATUS.O, 192.801(a) (192.809(a))

Question Text Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

Assets Covered 86255

Result Notes Certifications reviewed during office portion of inspection for Roy Rogers, Steve Rienquest, Ron Simmons.

143. Question Result, ID, Sat, TQ.PROT9.AOCRECOG.O, 192.801(a) (192.809(a))

Question Text Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

Assets Covered 86255

Result Notes Abnormal Operating Conditions (AOC) were discussed with operators for tasks observed.

144. Question Result, ID, Sat, TQ.PROT9.VERIFYQUAL.O, 192.801(a) (192.809(a))

Question Text Observe in the field (job site, local office, etc.) that the foreman/supervisor/manager has verified the qualification of the individual performing the task, that the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

Assets Covered 86255

Result Notes Certifications reviewed during office portion 110CT23 of inspection for Roy Rogers, Steve Rienquest, Ron

TQ.OQ: Operator Qualification

145. Question Result, ID, Sat, TQ.OQ.OQCONTRACTOR.R, 192.807(a) (192.807(b))

Question Text Are adequate records containing the required elements maintained for contractor personnel?

Assets Covered 86255

Result Notes Adequate documentation of Roy Rogers as contractor personnel.

146. Question Result, ID, Sat, TQ.OQ.RECORDS.R, 192.807

Question Text Do records document the evaluation and qualifications of individuals performing covered tasks, and can the qualification of individuals performing covered tasks be verified?

Assets Covered 86255

Result Notes Adequate documentation of Roy Rogers as contractor personnel.

147. Question Result, ID, Sat, TQ.OQ.TRAINING.R, 192.807(a) (192.807(b))

Question Text Does the operator have records for initial qualification, re-training and re-evaluation of individuals performing covered tasks?

Assets Covered 86255

Result Notes Adequate documentation of Roy Rogers as contractor personnel.

148. Question Result, ID, Sat, TQ.OQ.ABNORMAL.R, 192.807(a) (192.807(b), 192.803)

Question Text Do records document evaluation of qualified individuals for recognition and reaction to AOCs?

Assets Covered 86255

Result Notes Adequate documentation of Roy Rogers as contractor personnel.

TQ.QU: Qualification of Personnel - Specific Requirements

149. Question Result, ID, Sat, TQ.QU.CORROSION.R, 192.453 (192.807(a), 192.807(b))

Question Text Do records indicate qualification of personnel implementing pipeline corrosion control methods? Assets Covered 86255

Result Notes Adequate documentation of Roy Rogers as contractor personnel.

TQ.QUOMCONST: Qualification of Personnel - Specific Requirements (O and M Construction)

150. Question Result, ID, NA, TQ.QUOMCONST.NDT.R, 192.243(b)(2) (192.807(a), 192.807(b), 192.328(a), 192.328(b))

Question Text Do records indicate the qualification of nondestructive testing personnel?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

151. Question Result, ID, NA, TQ.QUOMCONST.WELDER.R, 192.227(a) (192.227(b), 192.229(a), 192.229(b), 192.229(c), References 192.229(d), 192.328(a), 192.328(b), 192.807(a), 192.807(b))

Question Text Do records indicate that welders are adequately qualified?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

TQ.TR: Training of Personnel

152. Question Result, ID, Sat, TQ.TR.TRAINING.R, 192.615(b)(2) (192.807(a), 192.807(b))

Question Text Is training for emergency response personnel documented?

Assets Covered 86255

Report Filters: Results: all

Result Notes Reviewed training of emergency personnel.

DC.CO: Construction

153. Question Result, ID, NA, DC.DPC.CCPROTCOATLOWER.R, 192.143(b) (192.461(c)) (also presented in: DC.DPC)

Question Text Do records indicate that each pipe segment with external protective coating was inspected just prior to lowering into the ditch and backfilling, and any damage detrimental to effective corrosion control was repaired?

Assets Covered 86255

Result Notes No such activity/condition was observed during the inspection.

DC.SPT: Spike Hydrotest

154. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.R, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, the test medium disposal was conducted in a manner that minimized damage to the environment?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

155. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.O, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, the test medium was disposed of in an environmentally sound manner?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

156. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.R, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, every reasonable precaution was taken to protect its employees and the general public throughout the testing?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

157. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.O, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.PTLOWPRESS)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, every reasonable precaution is taken to protect its employees and the general public throughout the testing?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

158. Question Result, ID, Sat, DC.PT.PRESSTESTRECORD.R, 192.517(a) (192.517(b)) (also presented in: DC.PT, DC.PTLOWPRESS)

Question Text Do records indicate creation and retention of a record for each Subpart J test performed for the required duration?

Assets Covered 86255

Result Notes Aug. 1993 - Original Hydro Reviewed Pressure Chart - No issues

4/14/2010 - Relocate (Hydro) Test - Reviewed Pressure - No issues

DC.PTLOWPRESS: Pressure Testing - Low Pressure

159. Question Result, ID, NA, DC.PT.PRESSTEST.R, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PT)

Question Text Do records indicate that pressure testing is conducted in accordance with 192.503?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

160. Question Result, ID, NA, DC.PT.PRESSTEST.O, 192.503(a) (192.503(b), 192.503(c), 192.503(d), 192.503(e)) (also presented References in: DC.PT)

Question Text Is pressure testing conducted in accordance with 192.503?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

161. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.R, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, the test medium disposal was conducted in a manner that minimized damage to the environment?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

162. Question Result, ID, NA, DC.PT.PRESSTESTENVIRON.O, 192.515(b) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, the test medium was disposed of in an environmentally sound manner?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

163. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.R, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do records indicate while conducting tests under Subpart J – Test Requirements, every reasonable precaution was taken to protect its employees and the general public throughout the testing?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

164. Question Result, ID, NA, DC.PT.PRESSTESTSAFETY.O, 192.515(a) (192.629(a), 192.629(b)) (also presented in: DC.PT, References DC.SPT)

Question Text Do field observations confirm while conducting tests under Subpart J – Test Requirements, every reasonable precaution is taken to protect its employees and the general public throughout the testing?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

165. Question Result, ID, Sat, DC.PT.PRESSTESTRECORD.R, 192.517(a) (192.517(b)) (also presented in: DC.PT, DC.SPT)

Question Text Do records indicate creation and retention of a record for each Subpart J test performed for the required duration?

Assets Covered 86255

Result Notes Aug. 1993 - Original Hydro Reviewed Pressure Chart - No issues

4/14/2010 - Relocate (Hydro) Test - Reviewed Pressure - No issues

MO.GOCLASS: Gas Pipeline Class Location

166. Question Result, ID, Sat, MO.GO.CONTSURVEILLANCE.R, 192.709(c) (192.613(a), 192.613(b), 192.703(b), 192.703(c)) (also References presented in: MO.GO)

Question Text Do records indicate performance of continuing surveillance of facilities as required, and also the reconditioning, phasing out, or MAOP reduction in any pipeline segment that was determined to be in unsatisfactory condition but on which no immediate hazard existed?

Assets Covered 86255

Result Notes Reviewed Continuing Surveillance Reports of for GP pipeline facilities for December 31, 2020, Dec 31, 2021, Dec 31, 2022.

167. Question Result, ID, NA, MO.GO.CONTSURVEILLANCE.O, 192.613(a) (192.613(b), 192.703(a), 192.703(b), 192.703(c)) (also References presented in: MO.GO)

Question Text Are unsatisfactory conditions being captured and addressed by continuing surveillance of facilities and the pipeline as required by 192.613?

Assets Covered 86255

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

MO.GMOPP: Gas Pipeline Overpressure Protection

168. Question Result, ID, Sat, MO.GM.RECORDS.R, 192.605(b)(1) (192.243(f), 192.709(a), 192.709(b), 192.709(c)) (also References presented in: MO.GM)

[8587] Georgia Pacific Standard GT

Question Text Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test?

Assets Covered 86255

Result Notes Pipeline records appear adequate.

Reviewed a sample of pipeline patrols and corrosion (with supports) patrols.

PD.PA: Public Awareness

169. Question Result, ID, Sat, EP.ERG.LIAISON.R, 192.605(a) (192.615(c)(1), 192.615(c)(2), 192.615(c)(3), 192.615(c)(4), References 192.616(c), ADB-05-03) (also presented in: EP.ERG)

Question Text Do records indicate that liaison has been established and maintained with appropriate fire, police, public officials, and utility owners?

Assets Covered 86255

Result Notes Send out Oct 2020 to Local Fire, Police, Sheriff

Reviewed Mailing labels for send out. 2020 - Sep 2021 - Nov 2022

PD.RW: ROW Markers, Patrols, Monitoring

170. Question Result, ID, Sat, MO.RW.PATROL.R, 192.709(c) (192.705(a), 192.705(b), 192.705(c)) (also presented in: MO.RW)

Question Text Do records indicate that ROW surface conditions have been patrolled as required?

Assets Covered 86255

Result Notes Reviewed sample of pipeline patrol records for 2020, 2021, 2022, and 2023.

171. Question Result, ID, Sat, MO.RW.ROWMARKER.O, 192.707(a) (192.707(b), 192.707(c), 192.707(d)) (also presented in: References MO.RW)

Question Text Are line markers placed and maintained as required?

Assets Covered 86255

Result Notes Pipeline markers are located adequately and maintained as required.

172. Question Result, ID, Sat, MO.RW.ROWCONDITION.O, 192.705(a) (192.705(c)) (also presented in: MO.RW) References

Question Text Are the ROW conditions acceptable for the type of patrolling used?

Assets Covered 86255

Result Notes Right of Way ROW conditions are acceptable. Patrolling is done on foot.

TD.CPMONITOR: External Corrosion - CP Monitoring

173. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) (also presented in: TD.CP, References TD.CPEXPOSED)

Question Text Do records indicate the location of all corrosion control items listed in §192.491(a)?

Assets Covered 86255

Result Notes Reviewed maps of CP stations and locations.

TD.CPEXPOSED: External Corrosion - Exposed Pipe

174. Question Result, ID, Sat, TD.CP.RECORDS.R, 192.491(a) (192.491(b), 192.491(c)) (also presented in: TD.CP, References TD.CPMONITOR)

Question Text Do records indicate the location of all corrosion control items listed in §192.491(a)?

Assets Covered 86255

Result Notes Reviewed maps of CP stations and locations.

Report Filters: Results: all

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

[8587] Georgia Pacific Standard GT Report Filters: Results: all