

UTC IMP verification Form

Inspector / Date: Al Jones / November 19, 2014

Inspection Dates: October 5-10, 2014

Operator Inspected: Ferndale Pipeline

OPID: 570 Region: Western

Unit Inspected: Ferndale Pipeline system Unit ID: Ferndale Pipeline System

Unit Type: Natural Gas

Unit Address: 4519 Grandview Road, Blaine, WA 98231

Record Location: 150 W. Warrenville Road; Naperville, IL 60563

High Consequence Areas

High Consequence areas in District

Id	High Consequence area	Location	Reason	Mileage	HCA Verified
	HCA	Ferndale		1.8	

New HCA's

High Consequence Area	Location	Reason	Mileage	Assessment Date
	NONE			

Defect Type

HCA ID	Third Party damage	corrosion	Outside force	Manufacturing defects	Construction defects	SCC	Other
	No	Anomalies	Found.				

Amount of low frequency ERW pipe	0%
How is ERW pipe assessed	NA
When was ERW pipe assessed	NA