

UTC IMP verification Form

Inspector / Date: **Dennis Ritter,**

Inspection Dates: **June 15-16, 2015**

Operator Inspected: **Weyerhaeuser Company**

OPID: **22515**

Region: **Western**

Unit Inspected: **Weyerhaeuser-Ostrander**

Unit ID:

Unit Type: **Transmission**

Unit Address: **3401 Industrial Way
PO Box 188
Longview, WA 98632**

Record Location: **Weyerhaeuser Mill, Longview WA**

High Consequence Areas

High Consequence areas in District

Id	High Consequence area	Location	Reason	Mileage	HCA Verified
1	Entire Pipeline	Longview and Kelso, WA	HD, residential, commercial & Areas of congregation	9	Yes, there are Class 1 and 2 areas in HCA
2					
3					
4					
5					
6					
7					
8					
9					
10					

New HCA's N/A-no new HCAs

Amount of low frequency ERW pipe	n/a-no low frequency ERW
How is ERW pipe assessed	
When was ERW pipe assessed	