## OPERATOR QUALIFICATION FIELD INSPECTION PROTOCOL FORM

Inspection Date(s):	September 16-17, 2013
Name of Operator:	Cardinal Glass FG
<b>Operator ID (OPID):</b>	32176
Inspection Location(s):	Winlock, Wa
Supervisor(s) Contacted:	Chuck Miller
# Qualified Employees Observed:	0
# Qualified Contractors Observed:	1

Individual Observed	Title/Organization	Phone Number	Email Address
Kevin O'Hogan	Hogan Operator/Northwest Metal Fabrication		not provided

To add rows, press TAB with cursor in last cell.

PHMSA/State Representative	Region/State	Email Address
Dave Cullom	Western/Wa State	dcullom@utc.wa.gov
Rhonda Shupert	Western/Wa State	rshupert@utc.wa.gov

To add rows, press TAB with cursor in last cell.

#### **Remarks**:

A table for recording specific tasks performed and the individuals who performed the tasks is on the last page of this form. This form is to be uploaded on to the OQBD for the appropriate operator, then imported into the file.

### 9.01 Covered Task Performance

Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

	Aspection Results X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

#### 9.02 Qualification Status

Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

<b>9.02 Inspection Results</b> (type an X in exactly one cell below)		Inspection Notes		
		Checked OQ for PSP reads task 192-0512 (4/6/2011)		
	Potential Issue Identified (explain)	Checked OQ for Transmission Odorizer and Odorant Checks (4/4/2011)		
N/A (explain)		These are on a three year cycle		
	Not Inspected			

#### 9.03 Abnormal Operating Condition Recognition and Reaction

Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

<b>9.03 Inspection Results</b> (type an X in exactly one cell below)		Inspection Notes	
X	No Issue Identified	He seemed very familiar with this system and had the correct set pressures committed to memory at the time of	
	Potential Issue Identified (explain)	· · ·	
	N/A (explain)		
	Not Inspected		

### 9.04 Verification of Qualification

Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

	Aspection Results X in exactly one cell below)	Inspection Notes		
Χ	No Issue Identified	See 9.02		
	Potential Issue Identified (explain)	See 9.02		
	N/A (explain)			
	Not Inspected			

#### 9.05 Program Inspection Deficiencies

Have potential issues identified by the headquarters inspection process been corrected at the operational level?

	spection Results X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

# **Field Inspection Notes**

The following table is provided for recording the covered tasks observed and the individuals performing those tasks.

		Nam	e/ID of Individual Obse	erved	
		Kevin O'Hogan			
		Correct	Correct	Correct	
		Performance	Performance	Performance	
No	Task Name	(Y/N)	(Y/N)	(Y/N)	Comments
1	PSP Reads	Y			
2	Pressure Control Equipment Adjustment and Testing	Y			
3	Odorizer Checks	Y			
4	Odorant Checks (Sniff)	Y			
5					
6					
7					
8					

## **Operations and Maintenance Records Review**

If performing an operations and maintenance records review in the course of your inspection, please review a sample of the qualifications of the individuals performing those O&M tasks that are covered under Operator Qualification and check the records for compliance to 192.807 or 195.507.

192.807	Records supporting an individual's current qualifications shall be maintained	Sat.	Unsat.	Not
or	while the individual is performing the covered task. Records of prior			Checked
195.507	qualification and records of individuals no longer performing covered tasks shall			
	be retained for a period of five years.			
		37		
		v		

Comments:		