S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

A completed **Standard Inspection Checklist, OQ Field Validation Protocol form and Cover Letter/Field Report** are to be submitted to the Chief Engineer within **30 days** from completion of the inspection.

Inspection Report							
Inspection ID/Docket Nu	mber	5926					
Inspector Name & Submit Date		Dennis Ritter, July 31, 2014					
Chief Eng Name & Review/Date		Joe Subsits, August 1, 2014					
		Operator Information					
Name of Operator:	Puget	Sound Energy			22189		
Name of Unit(s):	PSE I	East (Kittitas County)			•		
Records Location:	Records Location: Thorpe Operating Base (Kittitas), PSE Bellevue HQ, Georgetown Operating Base (Seattle)						
Data(s) of Last (unit)		mber 8 – December 2, 2011	Inspection Date(s):	July 14- 22	, 2014		

#### **Inspection Summary:**

The 2014 Std Inspection for PSE East (Kittitas County) Unit was conducted in King (records) and Kittitas Counties. An exit interview was held at PSE's office in Bellevue on July 22, 2014. **No apparent issues were found during the inspection.** 

Field inspections locations are as noted in the Form R Field inspection form. Records were reviewed at PSE's Thorpe and Georgetown Operating Bases, PSE Headquarters in Bellevue and some leak records were reviewed at WUTC's office prior to field visit. Field and OQ assessments were conducted as follows: CP pipe to soil, isolation, casings, rectifier inspections; bridge patrols; pressure regulator and relief lock-up; block valve operation; odorizer station check, odorant concentration testing:

- 4-Regulator stations and associated valves
- 3-Odorant Level (Sniff) testing
- 1-Odorant station
- 1-Rectifiers
- 1-casing
- 3-isolated short sections
- 1-isolation test point
- 3-bridge patrols
- 1-flood patrol (previously flooded area Cove Rd at Manashtash Creek)
- 6 construction projects were reviewed (all were new services, no other construction since last inspection)

The Form 13 PHMSA Drug and Alcohol questionnaire was completed and posted under the CY2014 PSE-Pierce Co inspection.

<b>HQ Address:</b>		System/Unit Name & Address:
355 110th Ave. NE		Kittitas Unit
Bellevue, WA 98004		Thorpe Operating Base (Kittitas County)
		8400 Thorpe Highway South
		Thorpe, WA 98946
Co. Official:	Booga K. Gilbertson	Phone No.: 509-964-2555

Phone No.:	425-462-3843	Fax No.:	
Fax No.:	. 000 005 5770	<b>Emergency Phone No.:</b>	888-225-5773
Emergency Phone No.		The state of the s	DI N
Persons Inter		Title	Phone No.
Darryl Ho	ong Sr. Regu	latory Compliance Analyst	425.462.3911
Robin Han	son	Pressure Control Technician	
Steve Gr	ey	Pressure Control Technician	
Dave Mof	fett	Supervisor Corrosion South	253-476-6216
Gary Swar	son	Maintenance Programs Coordinator	
Scott Hus	ted	Corrosion Control Technician	
Steve Dick	ison	Supervisor Pressure Control	
John Klip	pert	Manager of Gas Systems Operations	206-517-3421
Nancy Wo	ong	Engineer –Gas System Integrity	
Signe Lip	pert	Supervisor of Maintenance Programs	206-716-2630
Stephanie S	Silva	Gas Compliance Program Manager	425-462-3923
Don Frie	ze	Senior Engineer	425-462-3862
Mike Dup	uis	CFS Technician	
Tom Watk	ins	EFR/GFR Kittitas	(509) 201-3037

WU	WUTC staff conducted an abbreviated procedures inspection on 192 O&M and WAC items that changed since the last inspection. This checklist focuses on Records and Field items per a routine standard inspection.  (check one below and enter appropriate date)					
	Team inspection was performed (Within the past five years.) or,	Date:				
$\boxtimes$	Other WUTC Inspector reviewed the O & M Manual (Since the last yearly review of the manual by the operator.) Conducted by Joe Subsits.	Date:	Nov 29, 2010			
	OQ Program Review (PHMSA Form 14) Last Program review was Feb 28-Mar 16, 2004. Next Program review will occur November 6-8, 2014	Date:				

	GAS SYSTEM OPERATIONS							
Gas Supp	plier	Williams						
Services: Residentia		Commercial 135 Industrial 18 Other						
Number o	of reporta	ble safety related conditions last year 0	Number of deferred leaks in sys	tem 0				
Number o	of <u>non-re</u> j	portable safety related conditions last year 0	Number of third party hits last y	ear 5				
Miles of t		ion within inspection unit(total miles and miles in 0	Miles of main within inspection areas) 5	unit(total miles and miles in class 3 & 4				
		Operating Pressure(s):	MAOP (Within last year)	Actual Operating Pressure (At time of Inspection)				
Gate:	RS 25 615	48 Gate Station (Williams) HP inlet 647 outlet	1000 inlet 499 outlet	615.5 inlet 140.3 outlet				
Town		49 Bypass (currently feeds all HP and IP) inlet outlet 54.45	60	54.45				
Gate:	RS 27	26 Cle Elum Limit station	499 inlet 60 outlet	137 inlet 54.3outlet				
Town	RS 25	69 (Thorpe)	499 inlet 60 outlet	137 inlet 54.37outlet				

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

	GAS SYSTEM OPERATIONS					
Does the operator have any transmission pipelines?	No					
Compressor stations? Use Attachment 1.	No					

Pipe Specifications:							
Year Installed (Range)	1999-2014	Pipe Diameters (Range)	5/8" to 16"				
Material Type	MDPE wrapped steel	Line Pipe Specification Used	API 5L, ASTM D2513				
Mileage		SMYS %	< 20% distribution,				

#### **Operator Qualification Field Validation**

**Important:** Per OPS, the OQ Field Inspection Protocol Form (Rev 4, May 2007) shall be used by the inspector as part of this standard inspection. When completed, the inspector will upload this information into the PHMSA OQ Database (OQDB) located at <a href="http://primis.phmsa.dot.gov/oqdb/home.oq">http://primis.phmsa.dot.gov/oqdb/home.oq</a> **Date Completed/Uploaded** 7/31/2014

#### **Integrity Management Field Validation**

**Important:** Per PHMSA, IMP Field Verification Form (**Rev 6/18/2012**) shall be used by the inspector as part of this standard inspection. When completed, the inspector will upload this information into the PHMSA IM Database (IMDB) located at http://primis.phmsa.dot.gov/gasimp/home.gim **Date Completed/Uploaded:** 

PART 199 Drug and Alcohol Testing Regulations and Procedures		S	U	NA	NC
Subparts A - C	Drug & Alcohol Testing & Misuse Prevention Program – Use PHMSA Form #13, Rev 3/19/2010. Do not ask the company to have a drug and alcohol expert available for this portion of your inspection.	X			

		REPORTING RECORDS	S	U	N/A	N/C
1.	49 U.S.C. 60132, Subsection (b)	For Gas Transmission Pipelines and LNG Plants. Submission of Data to the National Pipeline Mapping System Under the Pipeline Safety Improvement Act of 2002  Updates to NMPS: Operators are required to make update submissions every 12 months if any system modifications have occurred. If no modifications have occurred since the last complete submission (including operator contact information), send an email to opsgis@rspa.dot.gov stating that fact. Include operator contact information with all updates. Submitted 2/10/2014 (No change notice)	Х			
2.	RCW 81.88.080	Pipeline Mapping System: Has the operator provided accurate maps (or updates) of pipelines, operating over two hundred fifty pounds per square inch gauge, to specifications developed by the commission sufficient to meet the needs of first responders?	X			
3.	191.5	Immediate Notice of certain incidents to NRC (800) 424-8802, or electronically at <a href="http://www.nrc.uscg.mil/nrchp.html">http://www.nrc.uscg.mil/nrchp.html</a> , and additional report if significant new information becomes available. Operator must have a written procedure for calculating an initial estimate of the amount of product released in an accident. No federal reportables this unit			X	
4.	191.7	Reports (except SRCR and offshore pipeline condition reports) must be submitted electronically to PHMSA at <a href="http://portal.phmsa.dot.gov/pipeline">http://portal.phmsa.dot.gov/pipeline</a> at unless an alternative reporting method is authorized IAW with paragraph (d) of this section.	X			
5.	191.15(a)	30-day follow-up written reports to PHMSA ( <b>Form F7100.2</b> ) Submittal must be electronically to <a href="http://pipelineonlinereporting.phmsa.dot.gov">http://pipelineonlinereporting.phmsa.dot.gov</a>	X			
6.	191.15(c)	Supplemental report (to 30-day follow-up) no supplemental reports			X	
7.	191.17	Complete and submit DOT Form PHMSA F 7100-2.1 by March 15 of each calendar year for the preceding year. ( <i>NOTE: June 15, 2011 for the year 2010</i> ).	X			

		REPORTING RECORDS	S	U	N/A	N/C
8.	191.22	Each operator must obtain an OPID, validate its OPIDs, and notify PHMSA of certain events at http://portal.phmsa.dot.gov/pipeline	X			
9.	191.23	Filing the Safety Related Condition Report (SRCR) no safety related conditions			X	
10.	191.25 49 U.S.C. 60139, Subsection (b)(2)	Filing the SRCR within 5 days of determination, but not later than 10 days after discovery.  no safety related conditions  Note: Operators of gas transmission pipelines that if the pipeline pressure exceeds maximum allowable operating pressure (MAOP) plus the build-up, owner/operator must report the exceedance to PHMSA on or before the fifth day following the date on which the exceedance occurs.  The report should be titled "Gas Transmission MAOP Exceedance" and provide the following information:  • The name and principal address of the operator date of the report, name, job title, and business telephone number of the person submitting the report.  • The name, job title, and business telephone number of the person who determined the condition exists.		X	X	
		<ul> <li>The date the condition was discovered and the date the condition was first determined to exist.</li> <li>The location of the condition, with reference to the town/city/county and state or offshore site, and as appropriate, nearest street address, offshore platform, survey station number, milepost, landmark, and the name of the commodity transported or stored.</li> <li>The corrective action taken before the report was submitted and the planned follow-up or future corrective action, including the anticipated schedule for starting and concluding such action.</li> </ul>				
11.	.605(d)	Instructions to enable operation and maintenance personnel to recognize potential <b>Safety</b> Related Conditions no safety related conditions			X	
12.	191.27	Offshore pipeline condition reports – filed within 60 days after the inspections no offshore pipelines-Gulf of Mexico condition			X	
13.	192.727(g)	Abandoned facilities offshore, onshore crossing commercially navigable waterways reports  No abandoned facilities			X	
14.	480-93-200(1)	Telephonic Reports to <b>UTC Pipeline Safety Incident Notification 1-888-321-9144</b> (Within <b>2 hours</b> ) for events which results in;				
15.	480-93-200(1)(a)	A fatality or personal injury requiring hospitalization; No fatalities or injuries			X	
16.	480-93-200(1)(b)	Damage to property of the operator and others of a combined total exceeding fifty thousand dollars; none in this unit			X	
17.	480-93-200(1)(c)	The evacuation of a building, or high occupancy structures or areas; Cle Elum 2013, Eb urg 2014	X			
18.	480-93-200(1)(d)	The unintentional ignition of gas; none since last unit inspection			X	
19.	480-93-200(1)(e)	The unscheduled interruption of service furnished by any operator to twenty five or more distribution customers; none since last unit inspection			X	
20.	480-93-200(1)(f)	A pipeline pressure exceeding the MAOP plus ten percent or the maximum pressure allowed by proximity considerations outlined in WAC 480-93-020; none since last unit inspection			X	
21.	480-93-200(1)(g)	Is significant, in the judgment of the operator, even though it does not meet the criteria of (a) through (f) of this subsection; None in this unit			X	
22.	480-93-200(2)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9146 (Within 24 hours) for;				
23.	480-93-200(2)(a)	The uncontrolled release of gas for more than two hours; None since last unit inspection			X	
24.	480-93-200(2)(b)	The taking of a high pressure supply or transmission pipeline or a major distribution supply gas pipeline out of service; None since last unit inspection			X	
25.	480-93-200(2)(c)	A gas pipeline operating at low pressure dropping below the safe operating conditions of attached appliances and gas equipment; or No low pressure in this unit			X	
26.	480-93-200(2)(d)	A gas pipeline pressure exceeding the MAOP No low pressure in this unit			X	
27.	480-93-200(4)	Did written incident reports (within 30 days of telephonic notice) include the following				

		REPORTING RECORDS	S	U	N/A	N/C
28.	480-93-200(4)(a)	Name(s) and address(es) of any person or persons injured or killed, or whose property was damaged; No injury or fatality incidents since last unit inspection			X	
29.	480-93-200(4)(b)	The extent of injuries and damage; No injury or fatality incidents since last unit inspection			X	
30.	480-93-200(4)(c)	A description of the incident or hazardous condition including the date, time, and place, and reason why the incident occurred. If more than one reportable condition arises from a single incident, each must be included in the report;	X			
31.	480-93-200(4)(d)	A description of the gas pipeline involved in the incident or hazardous condition, the system operating pressure at that time, and the MAOP of the facilities involved;	X			
32.	480-93-200(4)(e)	The date and time the gas pipeline company was first notified of the incident;	X			
33.	480-93-200(4)(f)	The date and time the ((operators')) gas pipeline company's first responders arrived on-site;	X			
34.	480-93-200(4)(g)	The date and time the gas ((facility)) pipeline was made safe;	X			
35.	480-93-200(4)(h)	The date, time, and type of any temporary or permanent repair that was made;	X			
36.	480-93-200(4)(i)	The cost of the incident to the ((operator)) gas pipeline company;	X			
37.	480-93-200(4)(j)	Line type;	X			
38.	480-93-200(4)(k)	City and county of incident; and	X			
39.	480-93-200(4)(1)	Any other information deemed necessary by the commission.	X			
40.	480-93-200(5)	Supplemental report if required information becomes available after 30 day report submitted	X			
41.	480-93-200(6)	Written report within 5 days of receiving the <b>failure analysis</b> of any incident or hazardous condition due to <b>construction defects or material failure None in this unit</b>			X	
42.	480-93-200(7)	Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form)				
43.	480-93-200(7)(a)	Does the operator report to the commission the requirements set forth in RCW 19.122.053(3) (a) through (n)	X			
44.	480-93-200(7)(b)	Does the operator report the name, address, and phone number of the person or entity that the company has reason to believe may have caused damage due to excavations conducted without facility locates first being completed?	X			
45.	480-93-200(7)(c)	Does the operator retain all damage and damage claim records it creates related to damage events reported under 93-200(7)(b), including photographs and documentation supporting the conclusion that a facilities locate was not completed?  Note: Records maintained for two years and made available to the commission upon request.	X			
46.	480-93-200(8)	Does the operator provide the following information to excavators who damage gas pipeline facilities?				
47.	480-93-200(8)(a)	Notification requirements for excavators under RCW 19.122.050(1)	X			
48.	480-93-200(8)(b)	A description of the excavator's responsibilities for reporting damages under RCW 19.122.053; and	X			
49.	480-93-200(8)(c)	<ul> <li>Information concerning the safety committee referenced under RCW 19.122.130, including committee contact information, and the process for filing a complaint with the safety committee.</li> </ul>	X			
50.	480-93-200(9)	Reports to the commission only when the operator or its contractor observes or becomes aware of the following activities  • An excavator digs within thirty-five feet of a transmission pipeline, as defined by RCW 19.122.020(26) without first obtaining a facilities locate; (200(9)(a)  • A person intentionally damages or removes marks indicating the location or presence of gas pipeline facilities. 200(9)(b)	X			
51.	480-93-200(10)	Annual Reports filed with the commission no later than March 15 for the proceeding calendar year				
52.	480-93-200(10)(a)	A copy of PHMSA F-7100.1-1 and F-7100.2-1 annual report required by U.S. Department of Transportation, PHMSA/Office of Pipeline Safety	X			

		REPORTING RECORDS	S	U	N/A	N/C
53.	480-93-200(10)(b)	Reports detailing all construction defects and material failures resulting in leakage.  Categorizing the different types of construction defects and material failures. The report must include the following:  (i) Types and numbers of construction defects; and  (ii) Types and numbers of material failures.	Х			
54.	480-93-200(11)	Providing updated emergency contact information to the commission and appropriate officials of all municipalities where gas pipeline companies have facilities Cle Elum, Kittitas County, Kittitas	X			
55.	480-93-200(12)	Providing by email, reports of daily construction and repair activities no later than 10:00 a.m.	X			
56.	480-93-200(13)	Submitting copy of DOT Drug and Alcohol Testing MIS Data Collection Form when required	X			

Comments:	

	those service lines not maintained by the operator  Does the excess flow valve meet the performance standards prescribed under §192.381  UMAC Series 2600 GasBreaker				N/A	N/C
57.	192.16	<b>Customer notification</b> - Customers notified, within <b>90 days</b> , of their responsibility for those service lines not maintained by the operator	X			
58.	Does the excess flow valve meet the performance standards prescribed under §192.381?		X			
59.			X			

ĺ	Comments:	

		CONSTRUCTION RECORDS	S	U	N/A	N/C
60.	PSE re-qualifies all pipe joiners annually.					
61.	192.225	Test Results to Qualify Welding Procedures	X			
62.	2. 192.227 Welder Qualification No welding since last inspection					
63.						
64.	480-93-080(2)	Plastic pipe joiners re-qualified 1/Yr (15 Months) Annually	X			
65.	480-93-080(2)(b)	Plastic pipe joiners re-qualified if no production joints made during any 12 month period <b>PSE re-qualifies all pipe joiners annually.</b>			X	
66.	480-93-080(2)(c)	Tracking Production Joints or Re-qualify joiners 1/Yr (12Months) PSE requalifies all pipe joiners annually.			X	
67.					X	
68.	480-93-115(3)	Sealing ends of casings or conduits on transmission lines and mains No transmission casing construction this unit			X	_

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		CONSTRUCTION RECORDS	S	U	N/A	N/C
69.	480-93-115(4)	Sealing ends (nearest building wall) of casings or conduits on services Standard note on construction docs, but did not observed during this inspection	X			
70.	192.241(a)	Visual Weld Inspector Training/Experience No steel welding since last inspection			X	
71.	192.243(b)(2)	Nondestructive Technician Qualification No steel welding since last inspection			X	
72.	192.243(c)	NDT procedures No steel welding since last inspection			X	
73.	192.243(f)	Total Number of Girth Welds No steel welding since last inspection			X	
74.	192.243(f)	Number of Welds Inspected by NDT No steel welding since last inspection			X	
75.	192.243(f)	Number of Welds Rejected None rejected No steel welding since last inspection			X	
76.	192.243(f)	Disposition of each Weld Rejected None rejected No steel welding since last inspection			X	
77.	.273/.283	Qualified Joining Procedures Including Test Results	X			
78.	192.303	Construction Specifications PSE procedures	X			
79.	192.325 WAC 480-93- 178(4)(5)	Underground Clearances	X			
80.	192.327	Amount, location, cover of each size of pipe installed	X			
81.	480-93-160(1)	Report filed <b>45 days</b> prior to construction or replacement of transmission pipelines ≥ <b>100</b> feet in length No transmission construction in this unit			X	
82.	480-93-160(2)	Did report describe the proposed route and the specifications for the pipeline and must include, but is not limited to the following items: No transmission construction in this unit			X	
83.	480-93-160(2)(a)	Description and purpose of the proposed pipeline; No transmission construction in this unit			X	
84.	480-93-160(2)(b)	Route map showing the type of construction to be used throughout the length of the line, and delineation of class location as defined in 49 CFR Part 192.5, and incorporated boundaries along the route. No transmission construction in this unit			X	
85.	480-93-160(2)(c)	Location and specification of principal valves, regulators, and other auxiliary equipment to be installed as a part of the pipeline system to be constructed No transmission in this unit			X	
86.	480-93-160(2)(d)	MAOP for the gas pipeline being constructed; No transmission construction in this unit			X	
87.	480-93-160(2)(e)	Location and construction details of all river crossings or other unusual construction requirements encountered en route. No transmission construction in this unit			X	
88.	480-93-160(2)(f)	Proposed corrosion control program to be followed inc specs for coating and wrapping, and method to ensure the integrity of the coating using holiday detection equipment;			X	
89.	480-93-160(2)(g)	Welding specifications; and No transmission construction in this unit			X	
90.	480-93-160(2)(h)	Bending procedures to be followed if needed. No transmission construction n in this unit			X	
91.	480-93-170(1)	Commission notified 2 days prior to pressure testing pipelines with an MAOP producing a hoop stress ≥ 20% SMYS? No transmission construction in this unit			X	
92.	480-93-170(7)	Pressure tests records at a minimum include required information listed under 480-93-170(a-h)	X			
93.	480-93-170(9)	Individual pressure test records maintained for single installations where multiple pressure tests were performed?	X			
94.	480-93-170(10)	Pressure Testing Equipment checked for accuracy/intervals (Manufacturers Rec or Operators schedule)	X			
95.	480-93-175(2)	Study prepared and approved prior to moving and lowering of metallic pipelines > 60  psig None since last unit inspection			X	
96.	480-93-175(4)	Leak survey within 30 days of moving or lowering pipelines ≤ 60 psig None since last unit inspection			X	

**Comments:** 

		OPERATIONS and MAINTENANCE RECORDS	S	U	N/A	N/C
97.	192.517(a)	Pressure Testing (operates at or above 100 psig) – useful life of pipeline or 5-yr window for pre-code pipelines—Checked 16" and 12" steel line to Cle Elum	X			
98.	192.517(b)	Pressure Testing (operates below 100 psig, service lines, plastic lines) – <b>5 years</b>	X			
99.	192.605(a)	192.517(a) Pressure Testing (operates at or above 100 psig) – useful life of pipeline or 5-yr window for pre-code pipelines—Checked 16" and 12" steel line to Cle Elum 192.517(b) Pressure Testing (operates below 100 psig, service lines, plastic lines) – 5 years 192.605(a) Procedural Manual Review – Operations and Maintenance (1 per yr/15 months) 192.605(b)(3) Availability of construction records, maps, operating history to operating personnel 180-93-018(3) Records, including maps and drawings updated within 6 months of completion of construction activity? 192.605(b)(8) Periodic review of personnel work – effectiveness of normal O&M procedures PSE in house gas site audits for contractors, and QC audits for PSE personnel 192.609 Periodic review of personnel work – effectiveness of abnormal operation procedures Transmission covered in separate inspection 192.611 Confirmation or revision of MAOP No revisions to MAOP in this unit since last inspection.  Damage Prevention (Operator Internal Performance Measures) Does the operator have a quality assurance program in place for monitoring the locating and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices v. 6.0, Bes Practice 4-18. Recommended only, not required) Does operator including performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties? Do locate contractors address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing levels? Does the operator locating and excavation procedures for compliance with state law and regulations.  Are locating and excavating personnel properly qualified in accordance with the operator's Operator Qualification plan and with federal and state requirements? Follow-up inspection performed on the pipeline where there is reason to believe the pipeline could be damaged .614(c) (6)  I. Is				
100.	192.605(b)(3)	Availability of construction records, maps, operating history to operating personnel  Records, including maps and drawings updated within <b>6 months</b> of completion of				
101.	480-93-018(3)	Pressure Testing (operates at or above 100 psig) – useful life of pipeline or 5-yr window for pre-code pipelines—Checked 16" and 12" steel line to Cle Elum  Pressure Testing (operates below 100 psig, service lines, plastic lines) – 5 years  Procedural Manual Review – Operations and Maintenance (1 per yr/15 months)  Note: Including review of OQ procedures as suggested by PHMSA - ADB-09-03 dated 277/09  Availability of construction records, maps, operating history to operating personnel Records, including maps and drawings updated within 6 months of completion of construction activity?  Periodic review of personnel work – effectiveness of normal O&M procedures PSE in house gas site audits for contractors, and QC audits for PSE personnel  Periodic review of personnel work – effectiveness of abnormal operation procedures Transmission covered in separate inspection  192.609  Class Location Study (If applicable) No class location study since last inspection  Confirmation or revision of MAOP No revisions to MAOP in this unit since last inspection.  Damage Prevention (Operator Internal Performance Measures)  Does the operator have a quality assurance program in place for monitoring the locating and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices v. 6.0, Best Practice 4-18. Recommended only, not required)  Does operator including performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties?  Do locate contractors address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing levels?  Does the operator periodically review the Operator Qualification plan criteria and methods used to qualify personnel to perform locates?				
102.	192.605(b)(8)		X			
103.	192.605(c)(4)				X	
104.	192.609	Class Location Study (If applicable) No class location study since last inspection			X	
105.	192.611				X	
106.		Damage Prevention (Operator Internal Performance Measures)				
107.		and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices v. 6.0, Best	X			
108.			X			
109.		Do locate contractors address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing	X			
110.	192.614		X			
111.			X			
112.		Are locates are being made within the timeframes required by state law and regulations? Examine record sample.	X			
113.		operator's Operator Qualification plan and with federal and state requirements?	X			
114.		Follow-up inspection performed on the pipeline where there is reason to believe the pipeline could be damaged .614(c) (6)  1. Is the inspection the done as frequently as necessary during and after the activities to verify the integrity of the pipeline?  2. In the case of blasting, does the inspection include leakage surveys?	X			

Comments:		

115.		Emergency 1	Response Plans	S	U	N/A	N/C
116.	192.603(b)	Prompt and effective response to each type Note: Review operator records of previous damage and leak response		X			
117.	192.615(b)(1)	Location Specific Emergency Plan None in	this unit			X	
118.	192.615(b)(2)	Emergency Procedure training, verify effec	tiveness of training	X			
119.	192.615(b)(3)	Employee Emergency activity review, deter	rmine if procedures were followed.	X			
120.	192.615(c)	Liaison Program with Public Officials		X			
121.	192.616	Public Awar	Public Awareness Program				
122.	192.616(e&f)	Documentation properly and adequately reflects implementation of operator's Public Awareness Program requirements - Stakeholder Audience identification, message type and content, delivery method and frequency, supplemental enhancements, program evaluations, etc. (i.e. contact or mailing rosters, postage receipts, return receipts, audience contact documentation, etc. for emergency responder, public officials, school superintendents, program evaluations, etc.). See table below:					
123.		Operators in existence on June 20, 2005, must have completed their written programs no later than June 20, 2006. See 192.616(a) and (j) for exceptions.					
124.		API RP 1162 Baseline* Reco	ommended Message Deliveries				
125.		Stakeholder Audience (LDC's)	Baseline Message Frequency (starting from effective date of Plan)				
		Residence Along Local Distribution System	Annual				
		LDC Customers	Twice annually				
		One-Call Centers	As required of One-Call Center				
		Emergency Officials	Annual				
		Public Officials	3 years				
		Excavator and Contractors	Annual				
		Stakeholder Audience (Transmission line operators)  Residence Along Local Distribution	Baseline Message Frequency (starting from effective date of Plan) 2 years				
		System One-Call Centers Emergency Officials	As required of One-Call Center Annual				
		Public Officials  Excavator and Contractors	3 years Annual				
126.		* Refer to API RP 1162 for additional requi	irements, including general program nts, recordkeeping, program evaluation, etc.				
127.	192.616(g)	significant number of the population in the		X			
128.	.616(h)	IAW API RP 1162, the operator's program four years of the date the operator's program existence on June 20, 2005, who must have than June 20, 2006, the first evaluation is do	completed their written programs no later	X			

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

129.	192.616(j)	Operators of a Master Meter or petroleum gas system – public awareness messages 2 times annually: PSE does operate gas distribution system  (1) A description of the purpose and reliability of the pipeline; (2) An overview of the hazards of the pipeline and prevention measures used; (3) Information about damage prevention; (4) How to recognize and respond to a leak; and (5) How to get additional information.		X	
130.	192.617	Review operator records of accidents and failures including laboratory analysis where appropriate to determine cause and prevention of recurrence .617  Note: Including excavation damage and leak response records (PHMSA area of emphasis) (NTSB B.10)	X		

Comments:			

131.	192.619/621/623	Maximum Allowable Operating Pressure ( <b>MAOP</b> ) Note: New PA-11 design criteria is incorporated into 192.121 & .123 (Final Rule Pub. 12/24/08) 16" and 12" Cle Elum Line	X		
132.	480-93-015(1)	Odorization of Gas – Concentrations adequate	X		
133.	480-93-015(2)	Monthly Odorant Sniff Testing	X		
134.	480-93-015(3)	Prompt action taken to investigate and remediate odorant concentrations not meeting the minimum requirements None since last inspection		Х	
135.	480-93-015(4)	Odorant Testing Equipment Calibration/Intervals (Annually or Manufacturers Recommendation)	X		
136.	480-93-124(3)	Pipeline markers attached to bridges or other spans inspected? 1/yr(15 months)	X		
137.	480-93-124(4)	Markers reported missing or damaged replaced within 45 days?	X		
138.	480-93-140(2)	Service regulators and associated safety devices tested during initial turn-on	X		
139.	480-93-155(1)	Up-rating of system MAOP to >60 psig? Procedures and specifications submitted 45 days prior	X		
140.	480-93-185(1)	Reported gas leaks promptly investigated? Graded in accordance with 480-93-186? Records retained?	Х		
141.	480-93-185(3)(a)	Leaks originating from a foreign source. Take appropriate action to protect life and property regarding the pipeline company's own facilities, and;	X		
142.	480-93-185(3)(b)	Leaks originating from a foreign source reported promptly/notification by mail. Records retained? PSE has not needed to send any letters as required by this regulation		X	
143.	480-93-186(3)	Leak evaluations: Are follow-up inspections performed within <b>30 days</b> of a leak repair?	X		
144.	480-93-186(4)	Leak evaluations: Grade 1 and 2 leaks (if any), downgraded once to a grade 3 without physical repair?	X		
145.	480-93-187	Gas leak records: at a minimum include required information listed under 480-93-187(1-13)	X		
146.	480-93-188(1)	Gas leak surveys	X		
147.	480-93-188(2)	Gas detection instruments tested for accuracy/intervals (Mfct recommended or monthly not to exceed 45 days)	X		
148.	480-93-188(3)	Leak survey frequency (Refer to Table Below) leak survey same interval as atmos 1/3 yr	X		

		Busin	ess Districts (implement	by 6/02/07)	1/yr (15	months)			
			High Occupancy Struct	ures	1/yr (15	months)			
			Pipelines Operating ≥ 250		1/yr (15				
		Other N	Iains: CI, WI, copper, unp	rotected steel	2/yr (7.5	months)			
1.10	T		T					1	
149.	480-93-	188(4)(a)	repairs or other related of	construction None				X	
150.	480-93-	188(4)(b)	underground gas faciliti	es, and damage co	ucture construction occurs adjould have occurred Cle Elum	2013	X		
151.	480-93-	188(4)(c)	since last inspection		where active gas lines could			X	
152.	480-93-	188(4)(d)	Special leak surveys - an and explosions None sir		of unusual activity, such as ea	rthquake, floods,		X	
153.	480-93-	188(4)(e)	migration into nearby buildings.PSE performs this as part of normal response to leak call						
154.	480-93	-188(5)	Gas Survey Records (M under 480-93-188 (5) (a						
155.	led 35 Ted(s) Zean program Sen Tadata					X			
156.	192	.709	Patrolling (Transmission separate inspection	n Lines) ( <b>Refer to</b>	Table Below) .705 Transm	ission covered in		X	
			Class Location	At Highway	and Railroad Crossings	At All Other I	Places		
			1 and 2		r (7½ months)	1/yr (15 mon			
			3	4/y	r (4½ months) r (4½ months)	2/yr (7½ mor 4/yr (4½ mor	nths)		
			<u> </u>	3	( - , )	-, 3- (-,	,		
157.	192	.709	Leak Surveys (Tran		Refer to Table Below) .706 separate inspection	Transmission		X	
			Class Location		Required	Not Excee	d		
			1 and 2		1/yr	15 month	S		
			3		2/yr	7½ month	ıs		
			4		4/yr	4½ month	IS		
158.	192.603(t	o)	Patrolling Business Dist	rict (4 per yr/4½	<b>months</b> ) .721(b)(1)		X		
159.	192.603(t	p)	Patrolling Outside Busin	ness District (2 pe	er yr/7½ months) 192.721(b)	0(2)	X		
160.	192.603(t	p)	Leakage Survey - Outsi	de Business Distri	ict ( <b>5 years</b> ) 192 .723(b)(1) 1	3 yrs with atmos	X		
161.	192.603(t	p)		ess District (5 year	ars) bution lines (3 years)		Х		
162.	192.603(t	p)	Tests for Reinstating Se					X	
163.	192.603(t	o)/.727(g)	Abandoned Pipelines; U	Inderwater Facilit	y Reports 192.727 None in the	nis unit		X	
164.	192.709		Pressure Limiting and R	egulating Station	s (1 per yr/15 months) .739		X		
165.	192.709		Pressure Limiting and R	egulator Stations	- Capacity (1 per yr/15 mon	<b>ths</b> ) .743	X		
166.	192.709		in separate inspection		r yr/15 months) .745 Trans	mission covered		X	
167.	192.709		Valve Maintenance – D	istribution (1 per	yr/15 months) .747		X		
168.	480-93-10	00(3)	Service valve maintenar	nce (1 per yr/15 r	months)		X		
169.	192.709		Vault maintenance (≥20 regulation	0 cubic feet)(1 p	er yr/15 months) .749 No v	aults meeting		X	

170.	192. 603(b)	Prevention of Accidental Ignition (hot work permits) .751PSE does not use hot work permits—procedures cover this		X	
171.	192. 603(b)	Welding – Procedure 192.225(b)	X		
172.	192. 603(b)	Welding – Welder Qualification 192.227/.229	X		
173.	192. 603(b)	NDT – NDT Personnel Qualification .243(b)(2)	X		
174.	192.709	NDT Records ( <b>pipeline life</b> ) .243(f) Transmission covered in separate inspection		X	
175.	192.709	Repair: pipe ( <b>pipeline life</b> ); Other than pipe ( <b>5 years</b> ) Transmission covered in separate inspection		X	
176.	192.905(c)	Periodically examining their transmission line routes for the appearance of newly identified area's (HCA's) Transmission covered in separate inspection		X	

Comments:		

CORROSION CONTROL RECORDS						N/C
177.	192.455(a)(1)	Pipeline coatings meet requirements of 192.461 (for buried pipelines installed after 7/31/71)	X			
178.	192.455(a)(2)	CP system installed on and operating within 1 yr of completion of pipeline construction (after 7/31/71)	X			
179.	192.465(a)	Annual Pipe-to-soil Monitoring (1 per yr/15 months) for short sections (10% per year; all in 10 years)	X			
180.	192.491	Test Lead Maintenance .471	X			
181.	192.491	Maps or Records .491(a)	X			
182.	192.491	Examination of Buried Pipe when exposed .459 None since last inspection			X	
183.	480-93-110(8)	CP test reading on all exposed facilities where coating has been removed None since last inspection			X	
184.	192.491	Annual Pipe-to-soil monitoring (1 per yr/15 months) .465(a)	X			
185.	192.491	Rectifier Monitoring (6 per yr/2½ months) .465(b)	X			
186.	192.491	Interference Bond Monitoring – Critical (6 per yr/2½ months) .465(c)None in this unit			X	
187.	192.491	Interference Bond Monitoring – Non-critical (1 per yr/15 months) .465(c) None in this unit			X	
188.	480-93-110(2)	Remedial action taken within 90 days (Up to 30 additional days if other circumstances. Must document) .465(d) None in this unit			X	
189.	480-93-110(3)	CP equipment/ instrumentation maintained, tested for accuracy, calibrated, and operated in accordance with manufactures recommendations, or at appropriate schedule determined by gas company if no recommendation.	X			
190.	192.491	Unprotected Pipeline Surveys, CP active corrosion areas (1 per 3 cal yr/39 months) .465(e) no unprotected pipe or areas of active corrosion			X	
191.	192.491	Electrical Isolation (Including Casings) .	X			
192.	480-93-110(5)	Casings inspected/tested annually not to exceed <b>fifteen months</b>	X			
193.	480-93-110(5)(a)	Casings w/no test leads installed prior to 9/05/1992. Demonstrate other acceptable test methods all casings have test lead in this unit			X	
194.	480-93-110(5)(b)	Possible shorted conditions – Perform confirmatory follow-up inspection within 90 days no shorted casings since last inspection			X	
195.	480-93-110(5)(c)	Casing shorts cleared when practical No casing shorts cleared-on list for leak survey			X	

 $S-Satisfactory \quad U-Unsatisfactory \quad N/A-Not\ Applicable \quad N/C-Not\ Checked$  If an item is marked U, N/A, or N/C, an explanation must be included in this report.

	CORROSION CONTROL RECORDS					N/C
196.	480-93-110(5)(d)	Shorted conditions leak surveyed within 90 days of discovery. <b>Twice annually/7.5 months</b> No shorted casings			X	
197.	192.491	Interference Currents .473No interference currents			X	
198.	192.491	Internal Corrosion; Corrosive Gas Investigation .475(a) PSE has no internal corrosion issues—Williams does not supply corrosive gas			X	
199.	192.491	Internal Corrosion; Internal Surface Inspection; Pipe Replacement .475(b)			X	
200.	192.491	Internal Corrosion Control Coupon Monitoring (2 per yr/7½ months) .477 PSE has no internal corrosion issues—Williams does not supply corrosive gas			X	
201.	192.491	Atmospheric Corrosion Control Monitoring (1 per 3 cal yr/39 months onshore; 1 per yr/15 months offshore) .481	X			
202.	192.491	Remedial: Replaced or Repaired Pipe; coated and protected; corrosion evaluation and actions .483/.485 No repaired or replaced pipe			X	

Comments:			

		S	U	N/A	N/C	
203.	192.161	Supports and anchors	X			
204.	480-93-080(1)(d)	Welding procedures located on site where welding is performed? No welding witnessed during field inspection			X	
205.	480-93-080(1)(b)	Use of testing equipment to record and document essential variables No welding witnessed during field inspection			X	
206.	480-93-080(2)(a)	Plastic procedures located on site where welding is performed? No fusion witnessed during field inspection			X	
207.	480-93-080(3)	Identification and qualification cards/certificates w/name of welder/joiner, their qualifications, date of qualification and operator whose qualification procedures were followed. No fusion witnessed during field inspection			X	
208.	480-93-013	Personnel performing "New Construction" covered tasks OQ qualified? No construction crews witnessed during field inspection			X	
209.	480-93-015(1)	Odorization	X			
210.	480-93-018(3)	Updated records, inc maps and drawings made available to appropriate operations personnel?	X			
211.	192.179	Valve Protection from Tampering or Damage	X			
212.	192.455	Pipeline coatings meet requirements of 192.461 (for buried pipelines installed after 7/31/71)	X			
213.	192.463	Levels of cathodic protection	X			
214.	192.465	Rectifiers	X			
215.	192.467	CP - Electrical Isolation	X			
216.	192.476	Systems designed to reduce internal corrosion PSE has no internal corrosion issues— Williams does not supply corrosive gas			X	
217.	192.479	Pipeline Components exposed to the atmosphere	X			
218.	192.481	Atmospheric Corrosion: monitoring	X			
219.	192.491	Test Stations – Sufficient Number .469	X			
220.	480-93-115(2)	Casings – Test Leads (casings w/o vents installed after 9/05/1992)	X			
221.	480-93-115(2)	Mains or transmission lines installed in casings/conduit. Are casing ends sealed? Did not witness installation in casing or conduit.			X	
222.	480-93-115(4)	Service lines installed in casings/conduit. Are casing ends nearest to building walls sealed? Did not witness installation in casing or conduit.			X	

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C - Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		PIPELINE INSPECTIO	ON (Field)	S	U	N/A	N/C
223.	192.605(a)	Appropriate parts of manuals kept at	locations where O&M activities are conducted	X			
224.	192.605	Knowledge of Operating Personnel		X			
225.	480-93-124	Pipeline markers	Pipeline markers				
226.	480-93-124(4)	Markers reported missing or damaged	d replaced within 45 days?	X			
227.	192.719	Pre-pressure Tested Pipe (Markings	and Inventory) no pretested pipe			X	
228.	192.195	Overpressure protection designed and	d installed where required?	X			
229.	192.739/743	Pressure Limiting and Regulating De	vices (Mechanical/Capacities)	X			
230.	192.741	Telemetering, Recording Gauges		X			
231.	192.751	Warning Signs		X			
232.	192.355	Customer meters and regulators. Pro	tection from damage	X			
233.	192.355(c)		cular traffic where anticipated. No regulated vaults			X	
234.	480-93-140	Service regulators installed, operated manufacturers recommended practice	and maintained per state/fed regs and es?	X			
235.	480-93-178(2)		mum Exposure to Ultraviolet Light (2yrs)	X			
236.	480-93-178(4)	Minimum Clearances from other utilities. For parallel lines a minimum of twelve inches. Where a minimum twelve inches of separation is not possible, must take adequate precautions, such as inserting the plastic pipeline in conduit, to minimize any potential hazards. Did not witness construction in trench with other utilities				X	
237.	480-93-178(5)	Minimum Clearances from other utilities. For perpendicular lines a minimum of six inches of separation from the other utilities. Where a minimum six inches of separation is not possible, must take adequate precautions, such as inserting the plastic pipeline in conduit, to minimize any potential hazards Did not witness construction in trench crossing other utilities				X	
238.	480-93-178(6)	Are there Temporary above ground P	PE pipe installations currently? Yes No X				
239.	480-93-178(6)(a)	If yes, is facility monitored and prote installed	cted from potential damage? No temporary PE			X	
240.	480-93-178(6)(b)	If installation exceeded 30 days, was deadline? No temporary PE installed	commission staff notified prior to exceeding the			X	
241.	192.745	Valve Maintenance (Transmission) T	Transmission covered in separate inspection			X	
242.	192.747	Valve Maintenance (Distribution)		X			
Facility	y Sites Visited:						
Facility	у Туре	Facility ID Number	Location				
Regulat	or station	RS 2548	Vantage Hwy, Kittitas County				
Regulat	or station	RS 2549	Vantage Hwy, Kittitas County				
Regulat	Regulator station RS 2560 Kilmore Rd at Thorpe Hwy, Thorpe						
Regulat	or station	RS 2726	Sunset Hwy, Cle Elum				
Rectifie	r	PS 333	Sunset Hwy, Cle Elum				
Odorize	er and Storage Tank	OD 031	Vantage Hwy, Kittias County				
Casing			Sunset Hwy near RR tracks, Cle Elum				
Isolation	n Test Point	RS 2548	Vantage Hwy, Kittitas County				
Odorani	t Test Site	OT-0189	Tumble Creek Drive, Cle Elum				
Odorani	t Test Site	OT-0202	Cottage Café, Cle Elum				
Odorant Test Site OT-0202 Cottage Café, Cle Elum  Odorant Test Site OT-0104 Thorpe School, Thorpe							

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

PIPELINE INSPECTION (Field)					N/A	N/C
Bridge Crossing	PBS-	KRD Canal Crossing at Thorpe Prairie Rd.				
Bridge Crossing	Bridge Crossing PBS- Thrall Rd at Wilson Creek E. of I-82					
Bridge Crossing	Bridge Crossing PBS- Thrall Rd. at Wilson Creek W. of I-82					

Comments:			

### Recent Gas Pipeline Safety Advisory Bulletins: (Last 2 years)

<u>Number</u>	<u>Date</u>	<u>Subject</u>
ADB-2013-07	July 12, 13	Potential for Damage to Pipeline Facilities Caused by Flooding
ADB-2012-10	Dec 5, 12	Using Meaningful Metrics in Conducting Integrity Management Program Evaluations
ADB-2012-09	Oct 11, 12	Communication During Emergency Situations
ADB-2012-08	Jul 31, 12	Inspection and Protection of Pipeline Facilities After Railway Accidents
ADB-12-07	Jun 11, 12	Mechanical Fitting Failure Reports
ADB-12-06	May 7, 12	Verification of Records establishing MAOP and MOP
ADB-12-05	Mar 23, 12	Cast Iron Pipe (Supplementary Advisory Bulletin)
ADB -12-04	Mar 21, 12	Implementation of the National Registry of Pipeline and Liquefied Natural Gas Operators
ADB-12-03	Mar 6, 12	Notice to Operators of Driscopipe 8000 High Density Polyethylene Pipe of the Potential for Material Degradation
ADB-11-05	Sep 1, 11	Potential for Damage to Pipeline Facilities Caused by the Passage of Hurricanes

 $S-Satisfactory \quad U-Unsatisfactory \quad N/A-Not\ Applicable \quad N/C-Not\ Checked$  If an item is marked U, N/A, or N/C, an explanation must be included in this report.

For more PHMSA Advisory Bulletins, go to <a href="http://phmsa.dot.gov/pipeline/regs/advisory-bulletin">http://phmsa.dot.gov/pipeline/regs/advisory-bulletin</a>

### **Attachment 1**

 $\begin{array}{c} \textbf{Distribution Operator Compressor Station Inspection} \\ \textbf{Unless otherwise noted, all code references are to 49CFR Part 192.} & S-Satisfactory & U-Unsatisfactory & N/A-Not Applicable \\ \textbf{If an item is marked U, N/A, or N/C, an explanation must be included in this report.} \end{array}$ 

N/C - Not Checked

243.	.605(b)	COMPRESSOR STATION PROCEDURES No compressor stations	S	U	N/A	N/C
244.		.605(b)(6) Maintenance procedures, including provisions for isolating units or sections of pipe and for purging before returning to service				
245.	]	.605(b)(7) Starting, operating, and shutdown procedures for gas compressor units				
246.		.731 Inspection and testing procedures for remote control shutdowns and pressure relieving devices (1 per yr/15 months), prompt repair or replacement				
247.		.735 (a) Storage of excess flammable or combustible materials at a safe distance from the compressor buildings				
248.	]	(b) Tank must be protected according to NFPA #30				
249.		.736 Compressor buildings in a compressor station must have fixed gas detection and alarm systems ( <b>must be performance tested</b> ), unless:				
250.		• 50% of the upright side areas are permanently open, or				
251.		It is an unattended field compressor station of 1000 hp or less				

Comments:		

COMPRESSOR STATION O&M PERFORMANCE AND RECORDS					U	N/A	N/C
252.	.709	.731(a)	Compressor Station Relief Devices (1 per yr/15 months)				
253.	]	.731(c)	Compressor Station Emergency Shutdown (1 per yr/15 months)				
254.		.736(c)	Compressor Stations – Detection and Alarms ( <b>Performance Test</b> )				

Comments:			

			COMPRESSOR STATIONS INSPECTION (Field) (Note: Facilities may be "Grandfathered")	S	U	N/A	N/C
255.	.163	(c)	Main operating floor must have (at least) two (2) separate and unobstructed exits				
256.			Door latch must open from inside without a key				
257.			Doors must swing outward				
258.		(d)	Each fence around a compressor station must have (at least) 2 gates or other facilities for emergency exit				
259.			Each gate located within 200 ft of any compressor plant building must open outward				
260.			When occupied, the door must be opened from the inside without a key				
261.		(e)	Does the equipment and wiring within compressor stations conform to the <b>National Electric Code</b> , <b>ANSI/NFPA 70?</b>				
262.	.165	(a)	If applicable, are there liquid separator(s) on the intake to the compressors?				
263.		(b)	Do the liquid separators have a manual means of removing liquids?				
264.			If slugs of liquid could be carried into the compressors, are there automatic dumps on the separators, Automatic compressor shutdown devices, or high liquid level alarms?				
265.	.167	(a)	ESD system must:				

### **Attachment 1**

 $\begin{array}{c} \textbf{Distribution Operator Compressor Station Inspection} \\ \textbf{Unless otherwise noted, all code references are to 49CFR Part 192.} & S-Satisfactory & U-Unsatisfactory & N/A-Not Applicable \\ \textbf{If an item is marked U, N/A, or N/C, an explanation must be included in this report.} \end{array}$ 

N/C - Not Checked

			COMPRESSOR STATIONS INSPECTION (Field)	S	U	N/A	N/C
			(Note: Facilities may be "Grandfathered")	3		IVA	14/0
266.			- Discharge blowdown gas to a safe location				
267.			- Block and blow down the gas in the station				
268.			- Shut down gas compressing equipment, gas fires, electrical facilities in compressor building and near gas headers				
269.			- Maintain necessary electrical circuits for emergency lighting and circuits needed to protect equipment from damage				
270.			ESD system must be operable from at least two locations, each of which is:				
271.	.167		- Outside the gas area of the station				
272.			- Not more than 500 feet from the limits of the station				
273.			- ESD switches near emergency exits?				
274.		(b)	For stations supplying gas directly to distribution systems, is the ESD system configured so that the LDC will not be shut down if the ESD is activated?				
275.		(c)	Are ESDs on platforms designed to actuate automatically by				
276.			- For unattended compressor stations, when:				
277.			• The gas pressure equals MAOP plus 15%?				
278.			An uncontrolled fire occurs on the platform?				
279.			- For compressor station in a building, when				
280.			An uncontrolled fire occurs in the building?				
281.			• Gas in air reaches 50% or more of LEL in a building with a source of ignition (facility conforming to <b>NEC Class 1, Group D</b> is not a source of ignition)?				
282.	.171	(a)	Does the compressor station have adequate fire protection facilities? If fire pumps are used, they must not be affected by the ESD system.				
283.		(b)	Do the compressor station prime movers (other than electrical movers) have over-speed shutdown?				
284.		(c)	Do the compressor units alarm or shutdown in the event of inadequate cooling or lubrication of the unit(s)?				
285.		(d)	Are the gas compressor units equipped to automatically stop fuel flow and vent the engine if the engine is stopped for any reason?				
286.		(e)	Are the mufflers equipped with vents to vent any trapped gas?				
287.	.173		Is each compressor station building adequately ventilated?				
288.	.457		Is all buried piping cathodically protected?				
289.	.481		Atmospheric corrosion of aboveground facilities				
290.	.603		Does the operator have procedures for the start-up and shut-down of the station and/or compressor units?				
291.			Are facility maps current/up-to-date?				
292.	.615		Emergency Plan for the station on site?				
293.	.619		Review pressure recording charts and/or SCADA				
294.	.707		Markers				
295.	.731		Overpressure protection – relief's or shutdowns				
296.	.735		Are combustible materials in quantities exceeding normal daily usage, stored a safe distance from the compressor building?				
297.			Is aboveground oil or gasoline storage tanks protected in accordance with <b>NFPA standard No. 30?</b>				
298.	.736		Gas detection – location				

Comments
----------

### **Attachment 1**

N/C - Not Checked

Comments:			