OPERATOR QUALIFICATION FIELD INSPECTION PROTOCOL FORM

Inspection Date(s):	July 20 – 23, 2015 (field portion)
Name of Operator:	Puget Sound Energy
Operator ID (OPID):	22189
Inspection Location(s):	Seattle, WA and surrounding locales in West King County
Supervisor(s) Contacted:	Chuck Smythe and Debbie Larson
# Qualified Employees Observed:	8
# Qualified Contractors Observed:	0

Individual Observed Title/Organization		Phone Number	Email Address			
Brian Barnett	PC Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	brian.barnett@pse.com			
Clipper Edwards	PC Tech- PSE 42 (Coordinate)		clipper.edwards@pse.com			
David Handyside	PC Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	david.handyside@pse.com			
Mike Cowin	CC Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	mike.cowin@pse.com			
David Montgomery	CC Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	david.montgomery@pse.c om			

Field Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	david.decker@pse.com
Field Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	augustus.banks@pse.com
Field Tech- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	leisa.hawkins@pse.com
PC Lead- PSE	425.462.3911 (Compliance contact phone number- Darryl Hong)	chuck.smythe@pse.com
	Field Tech- PSE Field Tech- PSE	(Compliance contact phone number- Darryl Hong) Field Tech- PSE 425.462.3911 (Compliance contact phone number- Darryl Hong) Field Tech- PSE 425.462.3911 (Compliance contact phone number- Darryl Hong) PC Lead- PSE 425.462.3911 (Compliance contact phone number- Darryl Hong) PC Lead- PSE 425.462.3911 (Compliance contact phone number- Darryl Hong)

To add rows, press TAB with cursor in last cell.

PHMSA/State Representative	Region/State	Email Address
Dave Cullom	Western/ WA State	dcullom@utc.wa.gov
Derek Norwood	Western/ WA State	dnorwood@utc.wa.gov

To add rows, press TAB with cursor in last cell.

Remarks:

A table for recording specific tasks performed and the individuals who performed the tasks is on the last page of this form. This form is to be uploaded on to the OQBD for the appropriate operator, then imported into the file.

9.01 Covered Task Performance

Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

	Aspection Results X in exactly one cell below)	Inspection Notes
X	No Issue Identified	Procedures were on hand and followed.
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.02 Qualification Status

Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

9.02 Inspection Results (type an X in exactly one cell below)		Inspection Notes			
X	No Issue Identified	We verified all covered task qualifications for the work they were about to perform in the field.			
	Potential Issue Identified (explain)				
	N/A (explain)				
	Not Inspected				

9.03 Abnormal Operating Condition Recognition and Reaction

Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

9.03 Inspection Results (type an X in exactly one cell below)		Inspection Notes	
X	No Issue Identified Potential Issue Identified (explain)	All field technicians were cognizant of AOCs encounted at the time of inspection and aware of potential AOCs that may occur.	
	N/A (explain)		
	Not Inspected		

9.04 Verification of Qualification

Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

	spection Results X in exactly one cell below)	Inspection Notes			
X	No Issue Identified	We verified all covered task qualifications for the work they were about to perform in the field.			
	Potential Issue Identified (explain)	ane, were accurate perform in the field.			
	N/A (explain)				
	Not Inspected				

9.05 Program Inspection Deficiencies

Have potential issues identified by the headquarters inspection process been corrected at the operational level?

	Aspection Results X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

Field Inspection Notes

The following table is provided for recording the covered tasks observed and the individuals performing those tasks.

		Name/ID of Individual Observed				
		Brian Barnett	Mike Cowin Dave Decker		Leisa Hawkins	
		Clipper Edwards	David Montgomery	Augustus (Gus) Banks		
		David Handyside				
		Chuck Smythe				
		Correct	Correct	Correct	Correct	
No	Task Name	Performance (Y/N)	Performance (Y/N)	Performance (Y/N)	Performance (Y/N)	
1	Bridge and slide inspections	Y	(-7.7)	Y	(2.17)	
2	Pressure control (Lock-up, stroke, and relief operation)	Y				
3	Rectifier Checks		Y			
4	PSP Readings		Y			
5	Odorant Checks				Y	
6						
7						
8						

Operations and Maintenance Records Review

If performing an operations and maintenance records review in the course of your inspection, please review a sample of the qualifications of the individuals performing those O&M tasks that are covered under Operator Qualification and check the records for compliance to 192.807 or 195.507.

PHMSA (OQ) Field Inspection Form 15 (Rev. 4) May 17, 2007)

192.807	Records supporting an individual's current qualifications shall be maintained	Sat.	Unsat.	Not
or	while the individual is performing the covered task. Records of prior			Checked
195.507	qualification and records of individuals no longer performing covered tasks shall			
	be retained for a period of five years.			
		37		
		·		
	Comments:			