Inspection ID:	7240						
Name of Operator:	Northwe	est Natural Gas Company					
OPID No. 13840			Unit ID No.				
HQ Address:			System/Unit Name & Address:				
220 NW Second Ave	enue						
Portland, OR 97209							
·							
Operator No	Operator Northwest Natural Gas Company						
Official: Gr	ant M. Yosl	hihara					
Title: Vi	ce Presiden	t of Utility Operations					
Phone: 50	3-226-4211	x2374	Zip Code:				
Emergency							
Phone/Cell:							
Persons Interviewed		Title		Phone No.			
Samantha Burt		Compliance Specialist		503-226-4211 x4366			
Margaret Locke		Compliance Engineer		503-226-4211 x4306			
Kenneth Reed							
Brooks Bamforth							
Michael Frilot							
Kelly Beller							
Darin Yost							
David Maynard							
State Representative(s): Inspection Date(s) April 27-28, 2017							
Records Location :		Portland, O	R				

3.5 miles of transmission line in Camas, WA, 8" Steel pipe installed in 1956
Portion of Unit Inspected:
Camas Transmission Line – P04

 $Sat + \textbf{-} Exceeds \ requirements/exemplary \ performance$

Sat – Meets requirements

 $Con-"Concern"\ meets\ requirements, but\ is\ an\ area\ of\ recommendation\ and/or\ area\ that\ if\ not\ addressed\ may\ lead\ to\ non-compliance$

Unsat – Does not meet requirements

N/A – Not Applicable

N/C - Not Checked

Unit Description:

Training and Qualification – OQ Protocol 9 (OQ Field Inspection)

192.801(a) (192.809(a))	Sat+	Sat	Concern	Unsat	NA	N
() ()		X				
Notes						
2. Qualification Status (de qualified to perform the covered tasks. (TQ.PRC	tail) Verify the individuals	performi	ng the observe	ed covered i	tasks are o	curren
192.801(a) (192.809(a))	Sat+	Sat	Concern	Unsat	N A	N
		Χ				
3. Abnormal Operating Con						
3. Abnormal Operating Conceptorming covered tasks are cognizant of the A	OCs that are applicable to t	he tasks o	bserved. (TQ.	PROT9.AOC	CRECOG.O) (deta
3. Abnormal Operating Conceptorming covered tasks are cognizant of the A		he tasks o				
3. Abnormal Operating Concerforming covered tasks are cognizant of the A	OCs that are applicable to t	Sat	Concern	PROT9.AOC	N A) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the Appendix (192.809(a)) Notes Crew performing regulator station inspe	Sat+ ction recognized AOC when	Sat	Concern	PROT9.AOC	N A) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the Appendix (192.809(a)) Notes Crew performing regulator station inspe	Sat+ ction recognized AOC when	Sat	Concern	PROT9.AOC	N A) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the Appendix (192.809(a)) Notes Crew performing regulator station inspe	Sat+ ction recognized AOC when	Sat	Concern	PROT9.AOC	N A) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the Alega.801(a) (192.809(a)) Notes Crew performing regulator station inspe	Sat+ ction recognized AOC when	Sat	Concern	PROT9.AOC	N A) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the Adnosmostic (192.809(a)) Notes Crew performing regulator station insperaccordingly and corrected the AOC by replacing	Sat+ ction recognized AOC when the boot of the regulator. con (detail) Verify the q	Sat X the regula	Concern ator failed to lo	Unsat Ockup. Crew	N A responde) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the Appearance of	Sat+ ction recognized AOC when the boot of the regulator. con (detail) Verify the q	Sat X the regula	Concern ator failed to lo	Unsat Ockup. Crew	N A responde) (deta
3. Abnormal Operating Convertorming covered tasks are cognizant of the Apple 2.801(a) (192.809(a)) Notes Crew performing regulator station insperance accordingly and corrected the AOC by replacing the according to the a	Sat+ ction recognized AOC when the boot of the regulator. con (detail) Verify the q	Sat X the regula	Concern ator failed to lo	Unsat Ockup. Crew	N A responde) (deta
3. Abnormal Operating Concertorming covered tasks are cognizant of the App. 192.801(a) (192.809(a)) Notes Crew performing regulator station insperaccordingly and corrected the AOC by replacing accordingly and corrected the AOC by replacing the sersonal identification of all individuals performing the personal identification i	ction recognized AOC when the boot of the regulator. ion (detail) Verify the quing covered tasks are checkers.	Sat X the regular	Concern Ator failed to loo	Unsat Ockup. Crew	N A responde d ensure to) (deta
Notes Crew performing regulator station insperaccordingly and corrected the AOC by replacing	ction recognized AOC when the boot of the regulator. ion (detail) Verify the quing covered tasks are checkers.	Sat X the regular ualification ed, prior to	Concern Ator failed to loo	Unsat Ockup. Crew	N A responde d ensure to) (det

PHMSA Form 15 Question Set (IA Equivalent) PHMSA (OQ) FIELD INSPECTION FORM

5. Program Inspection Deficiencies (detail) Have potential issues identified by the headquarters inspection process been corrected at the operational level? (TQ.PROT9.CORRECTION.O) (detail)							
192.801(a) (192.809(a))	Sat+	Sat	Concern	Unsat	NA	NC	
		X					
Notes							

Acceptable Use: Inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.