

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

NOTES-FIELD INSPECTION

Company: City of Enumclaw

Date(s): 8/29-8/31-2017

Unit: City of Enumclaw

Insp. No. 7254

Field Readings									
Line & Location	Line		CP Volts		Rectifier		Pressures		Remarks
	Size	In.	P/S	Casing	Volts	Amps	Set	Actual	
Meat Market Rectifier					7.61 V output				Taps set at C1 F3, 50-5 shunt, 1.35mV
Warner Rd Regulator							Worker set at 38 psi	Worker Lock up 37.6 psi	Monitor set at 40 locked up at 39.7
Meat Market Regulator R-21							34 psi	34 psi	Has a Reliance 50-55 psi snap disk
Hwy 164 farm tap 49							34 psi	34 psi	Has a Reliance 50-55 psi snap disk
188 th Ave SE & SR 164 Casing			-1.692 mV on -0.948 mV off	-0.354 mV					
228 th Ave SE & SR 164 Casing			-1.720 mV on -0.949 mV	-0.432 mV					
2726 Griffin CP test station 66			-1.136 mV on -1.098 mV off						
2971 Initial Ave CP test station 100			-1.358 mV on -0.831 mV off						Off reading did not meet -0.85mV criteria. The native potential that was taken in 2011 was 0.622 mV. This meets the 100 millivolt criteria which is a criteria that Enumclaw lists as a procedure they can use.
Valve operation on emergency valve 225 at 2820 Griffin Ave									Valve operated OK
929 Natalie CP test station 65			-1.417 mV on -0.929						

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

1624 Pioneer CP test station 52			mV off -1.381 mV on -0.901 mV off						
2541 Kibler CP test station 71			-1.524 mV on -0.994 mV off						
1942 Railroad CP test station 01									No longer a CP test station
Valve operation on valve 156 at Washington Ave & Garrett									Valve operated OK
1516 Davis Ave CP test station 90			-1.516 mV on -0.879 mV off						
Valve operation on valve 156 at 1553 Kibler									Valve operated OK
363 Rainier CP test station 31									No longer a CP test station
1426 Marion CP test station 41			-1.387 mV on -0.910 mV off						
276 th Ave SE & SE 456 th St CP test station 18			-1.362 mV on -0.924 mV off						
Valve operation 276 th Ave SE & SE 456 th St									Valve operated OK
PSE-Enumclaw isolation on Buckley-Enumclaw Rd									-1.178mV on -1.120mV off for PSE side of valve -1.839mV on -1.107 off for Enumclaw side of valve
Odorant check at City Shop									Performed by Mark VanWieringen OQ re-qualify date 3/3/19. A reading of 0.43%. Heath Consultants Odorator 2 serial #SN-2101724004