S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

A completed **Standard Inspection Checklist, Cover Letter and Field Report** is to be submitted to the Chief Engineer within 30 days from completion of the inspection.

		Inspection Report			
Inspection ID/Docket number	,	7549			
Inspector Name & Submit Date		David Cullom 6/26/2018			
Chief Eng Name & Review Date		Joe Subsits 6/27/2018			
		Operator Information			
Name of Operator:	Pug	et Sound Energy		OP ID #:	22189
Name of Unit(s):	Tra	nsmission			
Records Location:	Geo	orgetown and Bellevue			
Date(s) of Last (unit) Inspection:	Sep	t 22-25, Oct 1 and 29, 2015	Inspection Date(s):	June 11-14	and June 19

Inspection Summary:

There were no probable violations or areas of concern noted during this inspection.

This review consisted of records verification and field validation. Several facilities were visited in the field from Edmonds to Tumwater, WA to verify proper pressure regulation, cathodic protection, and odorant levels.

Many programs are managed at the corporate level, such as OQ, damage prevention, and public awareness. If additional detail on a specific compliance program is needed, one should reference other inspections, such as the West King County and Snohomish inspections, conducted during this inspection year.

HQ Address:			System/Unit Name & Addres	SS:
PO Box 97034 M/S	: PSE-12N		Transmission System	
Bellevue, WA 9800	9-9734			
Co. Official:	Booga K Gilb	ertson, Sr. VP Operations	Phone No.:	
Phone No.:	425-462-3843	erison, or. vi operations	Fax No.:	
Fax No.:	.20 .02 00 10		Emergency Phone No.:	
Emergency Phone	No.:			
Persons In	terviewed	Т	itle	Phone No.
Angela	Wingate	QC Proje	ct Manager	(425)449-7411
Signe I	Lippert	Supervisor Mair	itenance Programs	(253)395-6830
Gary S	wanson	Program Coordinator,	Maintenance Programs	(206)517-3432
Stephan	ie Silva	Pipeline Complianc	e Program Supervisor	(425)462-3923
Argentina	Stefanescu	Regulatory Con	mpliance Analyst	(425)457-5752
Don H	Frieze	Senior	Engineer	(425)462-3862
Lee Maxwell		Sr. Regulatory C	ompliance Analyst	(425)462-3575
Michelle	Gallardo	Corrosio	n Engineer	(425)462-3859

Form D – Intrastate Gas Transmission Records and Field Insp. (Rev. July 2017)

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/ \dot{C} – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

UTC staff conducted abbreviated procedures inspection on 192 O&M and WAC items that changed since the last inspection. This checklist focuses on Records and Field items per a routine standard inspection. (check one below and enter appropriate date)

	Team inspection was performed (Within the past five years.) or,	Date:	
\boxtimes	Other UTC Inspector reviewed the O & M Manual (Since the last yearly review of the manual by the operator.)	Date:	10/29/2015

		GAS SYST	EM OPERATIONS						
Gas Supp	lier	Williams, King County Waste Treatment Plant, and	d Cedar Hills Landfill						
Number of	f reporta	ble safety related conditions last year 0	Number of deferred leaks in syste	em 0					
Number of	f <u>non-re</u>	portable safety related conditions last year 0	Number of third party hits last ye	ear 0					
Miles of transmission pipeline within unit (total miles and miles in class 3 & 4 areas) Total mileage 28.4 per GSI TIMP Annual Report									
8.2 miles a classified a		e distribution system the rest of the mileage is tate.							
		Operating Pressure(s):	MAOP (Within last year)	Actual Operating Pressure (At time of Inspection)					
Feeder:	Please	e review field notes for additional detail.	Please review field notes for additional detail.	Please review field notes for additional detail.					
Town:	Please	e review field notes for additional detail.	Please review field notes for additional detail.	Please review field notes for additional detail.					
Other:	Please	e review field notes for additional detail.	Please review field notes for additional detail.	Please review field notes for additional detail.					
Does the o	perator	have any transmission pipelines? Yes							
Compresso	or statio	ns? Use Attachment 4.							
Have incid	lent repo	orts and the annual report been reviewed for accuracy	v and analyzed for trends and opera	tor issues? Yes \boxtimes No \square					
	Comments: Having mixed intra and interstate data on the annual report is a bit cumbersome, but you can cross reference to the GSI TIMP Annual Report for clarification.								

Pipe Specifications:			
Year Installed (Range)	1960 - 2010	Pipe Diameters (Range)	<=20"
Material Type	STW	Line Pipe Specification Used	API5L
Mileage	~8.2	SMYS %	Various Please review GSI TIMP Annual Report

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Supply Company	Williams, King County Waste	Class Locations	Not used per PSE. Additionally,
	Treatment Plant, and Cedar		HCA determination is performed
	Hills Landfill (Repeated data		using Method 2.
	field)		

		REPORTING RECORDS	S	U	N/A	N/C
1.	RCW 81.88.080	Pipeline Mapping System: Has the operator provided accurate maps (or updates) of pipelines, operating over two hundred fifty pounds per square inch gauge, to specifications developed by the commission sufficient to meet the needs of first responders?	x			
2.	480-93-200(1)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 2 hours) for events which (regardless of cause);				
3.	480-93-200(1)(a)	Result in a fatality or personal injury requiring hospitalization;			Х	
4.	480-93-200(1)(b)	Results in damage to property of the operator and others of a combined total exceeding fifty thousand dollars; Note: Report all damages regardless if claim was filed with pipeline company or not.			x	
5.	480-93-200(1)(c)	Results in the evacuation of a building, or high occupancy structures or areas;			Х	
6.	480-93-200(1)(d)	Results in the unintentional ignition of gas;			Х	
7.	480-93-200(1)(e)	Results in the unscheduled interruption of service furnished by any operator to twenty five or more distribution customers;			х	
8.	480-93-200(1)(f)	Results in a pipeline or system pressure exceeding the MAOP plus ten percent or the maximum pressure allowed by proximity considerations outlined in WAC 480-93-020;			х	
9.	480-93-200(1)(g)	Is significant, in the judgment of the operator, even though it does not meet the criteria of (a) through (e) of this subsection; or			х	
10.	480-93-200(2)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 24 hours) for;			х	
11.	480-93-200(2)(a)	The uncontrolled release of gas for more than two hours;			X	
12.	480-93-200(2)(b)	The taking of a high pressure supply or transmission pipeline or a major distribution supply pipeline out of service;			х	
13.	480-93-200(2)(c)	A pipeline operating at low pressure dropping below the safe operating conditions of attached appliances and gas equipment; or			х	
14.	480-93-200(2)(d)	A pipeline pressure exceeding the MAOP			Х	

Comments:

Questions 1-14 - This condition or event did not occur within the inspection time period.

15.	480-93-200(5)	Written incident reports (within 30 days) including the following;	S	U	N/A	N/C
16.	480-93-200(4)(a)	Name(s) and address(es) of any person or persons injured or killed, or whose property was damaged;			Х	
17.	480-93-200(4)(b)	The extent of injuries and damage;			Х	
18.	480-93-200(4)(c)	A description of the incident or hazardous condition including the date, time, and place, and reason why the incident occurred. If more than one reportable condition arises from a single incident, each must be included in the report;			X	
19.	480-93-200(4)(d)	A description of the gas pipeline involved in the incident or hazardous condition, the system operating pressure at that time, and the MAOP of the facilities involved;			Х	
20.	480-93-200(4)(e)	The date and time the gas pipeline company was first notified of the incident;			Х	
21.	480-93-200(4)(f)	The date and time the ((operators')) gas pipeline company's first responders arrived on-site;			Х	
22.	480-93-200(4)(g)	The date and time the gas ((facility)) pipeline was made safe;			Х	

Form D – Intrastate Gas Transmission Records and Field Insp. (Rev. July 2017)

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

23.	480-93-200(4)(h)	The date, time, and type of any temporary or permanent repair that was made;		Х	
24.	480-93-200(4)(i)	The cost of the incident to the ((operator)) gas pipeline company;		Х	
25.	480-93-200(4)(j)	Line type;		Х	
26.	480-93-200(4)(k)	City and county of incident; and		Х	
27.	480-93-200(4)(1)	Any other information deemed necessary by the commission.		Х	
28.	480-93-200(5)	Submit a supplemental report if required information becomes available		Х	
29.	480-93-200(6)	Written report within 45 days of receiving the failure analysis of any incident or hazardous condition due to construction defects or material failure		х	

Comments:

Questions 15-29 – This condition or event did not occur within the inspection time period.

30.	480-93-200(7)	Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013)				
	· · · · · · · · · · · · · · · · · · ·	(Via the commission's Virtual DIRT system or on-line damage reporting form)				
31.	480-93-200(7)(a)	Does the operator report to the commission the requirements set forth in RCW 19.122.053(3) (a) through (n)	Х			
32.	480-93-200(7)(b)	Does the operator report the name, address, and phone number of the person or entity that the company has reason to believe may have caused damage due to excavations conducted <u>without facility locates</u> first being completed?	х			
33.	480-93-200(7)(c)	Does the operator retain all damage and damage claim records it creates related to damage events reported under 93-200(7)(b), including photographs and documentation supporting the conclusion that a facilities locate was not completed? Note: Records maintained for two years and made available to the commission upon request.	x			
34.	480-93-200(8)	Does the operator provide the following information to excavators who damage gas pipeline facilities?				
35.	480-93-200(8)(a)	• Notification requirements for excavators under RCW 19.122.050(1)	Х			
36.	480-93-200(8)(b)	 A description of the excavator's responsibilities for reporting damages under RCW 19.122.053; and 	Х			
37.	480-93-200(8)(c)	 Information concerning the safety committee referenced under RCW 19.122.130, including committee contact information, and the process for filing a complaint with the safety committee. 	x			
38.	480-93-200(9)	 Reports to the commission only when the operator or its contractor observes or becomes aware of the following activities An excavator digs within thirty-five feet of a transmission pipeline, as defined by RCW 19.122.020(26) without first obtaining a facilities locate; (200(9)(a) A person intentionally damages or removes marks indicating the location or presence of gas pipeline facilities. 200(9)(b) 	х			
39.	480-93-200(7)	Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form)	Х			
40.	480-93-200(10)	Annual Reports filed with the commission no later than March 15 for the proceeding calendar year. (<i>NOTE: PHMSA extension to June 15, 2013 for the year 2012</i>).	S	U	N/A	N/C
41.	480-93-200(10)(a)	A copy of PHMSA F-7100.1-1 and F-7100.2-1 annual report required by U.S. Department of Transportation, PHMSA/Office of Pipeline Safety ***Notes – This report was reviewed prior and during the inspection ***	x			

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

42.	480-93-200(10)(b)	Reports detailing all construction defects and material failures resulting in leakage. Categorizing the different types of construction defects and material failures. The report must include the following: (i) Types and numbers of construction defects; and (ii) Types and numbers of material failures.	x		
43.	480-93-200(11)	Providing updated emergency contact information to the commission and appropriate officials of all municipalities where gas pipeline companies have facilities	Х		
44.	480-93-200(12)	Providing by email, reports of daily construction and repair activities no later than 10:00 a.m. ***Notes – This operator has been providing accurate daily reports of job locations***	x		
45.	480-93-200(13)	Submitting copy of DOT Drug and Alcohol Testing MIS Data Collection Form when required	X		

Comments:

		CONSTRUCTION RECORDS	S	U	N/A	N/C
46.	480-93-080(1)(b)	Use of testing equipment to record and document essential variables			Х	
47.	480-93-115(2)	Test leads on casings (without vents) installed after 9/05/1992			Х	
48.	480-93-115(3)	Sealing ends of casings or conduits on transmission pipelines and main			Х	
49.	480-93-115(4)	Sealing ends (nearest building wall) of casings or conduits on services			Х	
50.	480-93-160(1)	Detailed report filed 45 days prior to construction or replacement of transmission pipelines \geq 100 feet in length			Х	
51.	480-93-170(3)	Pressure Tests Performed on new and replacement pipelines			Х	
52.	480-93-170(10)	Pressure Testing Equipment checked for Accuracy/Intervals (Manufacturers recommendation or operators schedule)			Х	
53.	480-93-175(1)	Study prepared and approved prior to moving and lowering of metallic pipelines > 60 psig			Х	

Comments:

Questions 46-53 - This condition or event did not occur within the inspection time period.

		OPERATIONS and MAINTENANCE RECORDS	S	U	N/A	N/C
54.		Damage Prevention Program				
55.	480-93-250(3)	Are locates are being made within the timeframes required by RCW 19.122? Examine record sample. ***Notes - This is also reviewed in the records portion of the distribution unit inspection***	х			
56.	480-93-015(1)	Odorization of Gas – Concentrations adequate?	Х			
57.	480-93-015(2)	Monthly Odorant Sniff Testing ***Notes – I reviewed records for the past three years***	Х			
58.	480-93-015(3)	Prompt action taken to investigate and remediate odorant concentrations not meeting the minimum requirements ***Notes - This condition or event did not occur within the inspection time period. ***			x	

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

OPERATIONS and MAINTENANCE RECORDS S					U	N/A	N/0	
59.	480-93-	015(4)	Odorant Testing Equipment Calibration/Inte Recommendation) *** Notes - I checked the field portion of the inspection***	ervals (Annually or Manufacturers calibration records of several units used for	x			
60.	480-93-	124(3)	Pipeline markers attached to bridges or othe This is conducted during the PBS patrols	r spans inspected? 1/yr(15 months) ***Notes – ***	х			
61.	480-93-	124(4)	Markers reported missing or damaged repla		Х			
62.	480-93-			aded/record retained. ***Notes- This condition			х	
63.	480-93-	480-93-185(3) Leaks originating from a foreign source reported promptly/notification by mail/record retained ***Notes- This condition or event did not occur within the inspection time period.***				x		
64.	480-93	3-187	Gas Leak records - Content		Х			1
65.	480-93-188(1)		Gas Leak surveys – Coverage ***Notes– Numerous maps were selected and reviewed – no issues noted.***		x			
66.	480-93-188(2)			y/intervals (Mfct rec or monthly not to exceed d records for several units I checked from ecords.***	x			
67.	480-93-	188(3)	Leak survey frequency (Refer to Table Be	low)	Х			<u> </u>
					1	1		4
	-		Business Districts (By 6/02/07)	1/yr (15 months)				
	-		High Occupancy Structures	1/yr (15 months)				
	-		Pipelines Operating ≥ 250 psig	1/yr (15 months)		_		
		Other I	Mains: CI, WI, copper, unprotected steel	2/yr (7.5 months)				
68.	480-93-1	88(4)(a)		resurfacing, following street alterations or repairs not occur within the inspection time period.***			x	
69.	480-93-188(4)(b)		Special leak surveys - areas where substructure construction occurs adjacent to underground gas facilities, and damage could have occurred ***Notes- This condition or event did not occur within the inspection time period.***				x	
70.	480-93-188(4)(c)		Special leak surveys - Unstable soil areas where active gas lines could be affected ***Notes- This condition or event did not occur within the inspection time period.***				x	
71.	480-93-188(4)(d)		and explosions **** Notes - No earthq				х	
72.	480-93-188(4)(e)			ccavation damage, operators must perform a gas multiple leaks and underground migration into ition or event did not occur within the			x	
73.	480-93-1	88(5)	Gas survey records: Retention/Content		Х			<u> </u>
74.	1	480-93-188(6) Leak Survey Program/Self Audits ***Notes - QC and QM performs the leak survey self-audits.***		х		1		

Comments:

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

CORROSION CONTROL RECORDS			S	U	N/A	N/C
75.	480-93-110(8)	CP test reading on all exposed facilities where coating has been removed	Х			
76.	480-93-110(2)	Remedial action taken within 90 days (Up to 30 additional days if other circumstances. Must document) .465(d)	х			
77.	480-93-110(3)	CP Test Equipment and Instruments checked for Accuracy/Intervals (Mfct Rec or Opr Sched)	X			
78.	480-93-110(5)	Casings inspected/tested annually not to exceed fifteen months	Х			
79.	480-93-110(5)(a)	Casings w/no test leads installed prior to 9/05/1992. Demonstrate other acceptable test methods	X			
80.	480-93-110(5)(b)	Possible shorted conditions – Perform confirmatory follow-up inspection within 90 days	Х			
81.	480-93-110(5)(c)	Casing shorts cleared when practical	Х			
82.	480-93-110(5)(d)	Shorted conditions leak surveyed within 90 days of discovery. Twice annually/7.5 months	Х			

Comments:

Notes - 75-82 - No issues. I reviewed CP records for the past three years.

PIPELINE INSPECTION (Field)			S	U	N/A	N/C
83.	480-93-015(1)	Odorization levels	Х			
84.	480-93-115(2)	Casings – Test Leads (Casings w/o vents installed after 9/05/1992) ***Notes– This condition or event did not occur within the inspection time period.***			х	

Comments:

EXIT INTERVIEW

Exit Interview Conducted? 6/19/2018 Items Covered: no NOPVs or AOCs

Date: 6/26/2018

Recent Gas Pipeline Safety Advisory Bulletins: (Last 2 years)

NumberDateSubjectADB-2013-07July 12, 13Potential for Damage to Pipeline Facilities Caused by Flooding

Form D – Intrastate Gas Transmission Records and Field Insp. (Rev. July 2017)

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

ADB-2012-10	Dec 5, 12	Using Meaningful Metrics in Conducting Integrity Management Program Evaluations
ADB-2012-09	Oct 11, 12	Communication During Emergency Situations
ADB-2012-08	Jul 31, 12	Inspection and Protection of Pipeline Facilities After Railway Accidents
ADB-12-07	Jun 11, 12	Mechanical Fitting Failure Reports
ADB-12-06	May 7, 12	Verification of Records establishing MAOP and MOP
ADB-12-05	Mar 23, 12	Cast Iron Pipe (Supplementary Advisory Bulletin)
ADB -12-04	Mar 21, 12	Implementation of the National Registry of Pipeline and Liquefied Natural Gas Operators
ADB-12-03	Mar 6, 12	Notice to Operators of Driscopipe 8000 High Density Polyethylene Pipe of the Potential for Material Degradation
ADB-11-05	Sep 1, 11	Potential for Damage to Pipeline Facilities Caused by the Passage of Hurricanes
ADB-11-04	Jul 27, 11	Potential for damage to pipeline facilities caused by severe flooding.

For more PHMSA Advisory Bulletins, go to http://phmsa.dot.gov/pipeline/regs/advisory-bulletin