

UTC IMP Verification Form

Inter/Intra

Inspector / Date: **D. Ritter** **September 10, 2013**

Inspection Dates: **September 10-11, 2018**

Operator Inspected: **Targa Sound Terminal**

OPID: **38921** Region:

Unit Inspected: **Targa Sound Terminal** Unit ID:

Unit Type:

Unit Address: **2628 Marine View Dr**

Record Location: **Tacoma WA**

High Consequence Areas

High Consequence areas in District

Id	High Consequence area	Location	Reason	Mileage	HCA Verified
1	Entire line	F St to Marine View Dr	Hi Pop Drinking Water Eco Sensitive	2.65	Yes 9/2018
2					
3					
4					
5					
6					
7					
8					
9					
10					

New HCA's

High Consequence	Location	Reason	Mileage	Assessment Date
-------------------------	-----------------	---------------	----------------	------------------------

Area				

Assessments

ILI

HCA ID	Tool(s), or assessment method(s)	Assessment review results	Prior Assessment date	Assessment date	Next Assessment date
	Pressure test	Passed	n/a	12/2012	12/2017
	ILI-Geo and MFL	No anomalies	n/a	9/22/15	9/2020

Do assessments address unit threats?	Yes
Earth Movement threat addressed if applicable?	n/a

HCA ID	Immediate repairs	One year condition (gas) 180 Day condition(liquid)	Monitored Condition (gas) Other condition (liquid)

Amount of low frequency ERW pipe	0
How is ERW pipe assessed	
When was ERW pipe assessed	