S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/ $\bar{C}$  – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

A completed **Standard Inspection Checklist, Cover Letter and Field Report** is to be submitted to the Chief Engineer within 30 days from completion of the inspection.

	Inspection Report								
Inspection ID/Docket number		7576							
Inspector Name & Submit Date		Derek Norwood/July 19, 2018							
Chief Eng Name & Review Date		Joe Subsits/July 23, 2018							
		Operator Information							
Name of Operator:	Akz	to Nobel Pulp and Performance Chemicals		OP ID #:	32358				
Name of Unit(s):	Akz	to Nobel Pulp and Performance Chemicals							
<b>Records Location:</b>	Mo	ses Lake, WA							
Date(s) of Last (unit) Inspection:	9/1:	5/2015-9/16/2015	<b>Inspection Date(s):</b>	6/27/2018 a	and 7/11/2018				

### **Inspection Summary:**

Akzo Nobel operates 0.45 miles of 8" PE pipeline. The pipeline transports unodorized hydrogen gas from Akzo Nobel's chemical plant to JR Simplot's boiler. I reviewed records of leak survey, patrolling, pressure logs, compressor curve, valve inspections, construction drawing, emergency response training activities and operator qualifications. The field inspection consisted of walking the right of way, marker survey, leak survey at casing vent, and valve inspection operation/inspection during JR Simplot planned shutdown.

HQ Address:			System/Unit Name & Addre	ess:
4374 Nashville Ferry Roa	ad East		2701 Road N NE	
Columbus, MS 39702			Moses Lake, WA 98837	
Co. Official:	Lind Bingham		Phone No.:	
Phone No.:	509-764-1502		Fax No.:	
Fax No.:			Emergency Phone No.:	
<b>Emergency Phone No.:</b>	509-764-1500			
Persons Intervi	ewed	T	itle	Phone No.
Lind Bingha	m	SHE/Q	Manager	509-764-1502
Bob Cosentii	no	Principal	Consultant	360-200-4959
		•		

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		conducted abbreviated procedures in a last inspection. This checklist focuse in	-			_	
			and enter appropriate date)				
X	Team ins	spection was performed (Within the past five ye	ears.) or,		Date:	2/3/2015	
	Other UTC Inspector reviewed the O & M Manual (Since the last yearly review of the manual by						
		GAS SYST	TEM OPERATIONS				
Gas S	upplier	Akzo Nobel					
Numb	er of repor	able safety related conditions last year 0	Number of deferred leaks in syst	em 0			
Numb	er of <u>non-r</u>	eportable safety related conditions last year 0	Number of third party hits last year 0				
	of transmis	sion pipeline within unit (total miles and miles in 0.45					
		Operating Pressure(s):	MAOP (Within last year)		Actual Operating Pressure (At time of Inspection)		
Feede	r:		30 psig	12.5 psig			
Town:							
Other:							
	•	r have any transmission pipelines?	Yes				
Comp	ressor stati	ons? Use Attachment 4.					
Have i	incident rep	ports and the annual report been reviewed for accuracy	ey and analyzed for trends and oper	ator issues?	Yes ⊠	No□	
		erator changed miles of transmission pipe from ( cy and in order to match the miles of transmission		17 annual rep	oort. The	change was made to	

Pipe Specifications:			
Year Installed (Range)	1995	Pipe Diameters (Range)	8"
Material Type	HDPE 3408	Line Pipe Specification	ASTM D2513
		Used	
Mileage	0.45	SMYS %	N/A
Supply Company	Akzo Nobel	Class Locations	1

		REPORTING RECORDS	S	U	N/A	N/C
1.	RCW 81.88.080	Pipeline Mapping System: Has the operator provided accurate maps (or updates) of pipelines, operating over two hundred fifty pounds per square inch gauge, to specifications developed by the commission sufficient to meet the needs of first responders?			X	
2.	480-93-200(1)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 2 hours) for events which (regardless of cause);				
3.	480-93-200(1)(a)	Result in a fatality or personal injury requiring hospitalization;			X	
4.	480-93-200(1)(b)	Results in damage to property of the operator and others of a combined total exceeding fifty thousand dollars;  Note: Report all damages regardless if claim was filed with pipeline company or not.			X	
5.	480-93-200(1)(c)	Results in the evacuation of a building, or high occupancy structures or areas;			X	

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		REPORTING RECORDS	S	U	N/A	N/C
6.	480-93-200(1)(d)	Results in the unintentional ignition of gas;			X	
7.	480-93-200(1)(e)	Results in the unscheduled interruption of service furnished by any operator to twenty five or more distribution customers;			X	
8.	480-93-200(1)(f)	Results in a pipeline or system pressure exceeding the MAOP plus ten percent or the maximum pressure allowed by proximity considerations outlined in WAC 480-93-020;			X	
9.	480-93-200(1)(g)	Is significant, in the judgment of the operator, even though it does not meet the criteria of (a) through (e) of this subsection; or			X	
10.	480-93-200(2)	Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 24 hours) for;			X	
11.	480-93-200(2)(a)	The uncontrolled release of gas for more than two hours;			X	
12.	480-93-200(2)(b)	The taking of a high pressure supply or transmission pipeline or a major distribution supply pipeline out of service;			X	
13.	480-93-200(2)(c)	A pipeline operating at low pressure dropping below the safe operating conditions of attached appliances and gas equipment; or			X	
14.	480-93-200(2)(d)	A pipeline pressure exceeding the MAOP			X	

#### **Comments:**

Item 1 – No pipelines operating over 250 psig

Items 2-14 – No reportable incidents occurred since the last inspection

15.	480-93-200(5)	Written incident reports (within 30 days) including the following;	S	U	N/A	N/C
16.	480-93-200(4)(a)	Name(s) and address(es) of any person or persons injured or killed, or whose property was damaged;			X	
17.	480-93-200(4)(b)	The extent of injuries and damage;			X	
18.	480-93-200(4)(c)	A description of the incident or hazardous condition including the date, time, and place, and reason why the incident occurred. If more than one reportable condition arises from a single incident, each must be included in the report;			X	
19.	480-93-200(4)(d)	A description of the gas pipeline involved in the incident or hazardous condition, the system operating pressure at that time, and the MAOP of the facilities involved;			X	
20.	480-93-200(4)(e)	The date and time the gas pipeline company was first notified of the incident;			X	
21.	480-93-200(4)(f)	The date and time the ((operators')) gas pipeline company's first responders arrived on-site;			X	
22.	480-93-200(4)(g)	The date and time the gas ((facility)) pipeline was made safe;			X	
23.	480-93-200(4)(h)	The date, time, and type of any temporary or permanent repair that was made;			X	
24.	480-93-200(4)(i)	The cost of the incident to the ((operator)) gas pipeline company;			X	
25.	480-93-200(4)(j)	Line type;			X	
26.	480-93-200(4)(k)	City and county of incident; and			X	
27.	480-93-200(4)(1)	Any other information deemed necessary by the commission.			X	
28.	480-93-200(5)	Submit a supplemental report if required information becomes available			X	
29.	480-93-200(6)	Written report within 45 days of receiving the failure analysis of any <b>incident or hazardous condition</b> due to <b>construction defects or material failure</b>			X	

### **Comments:**

Items 15-28 – No reportable incidents occurred since the last inspection

Item 29 – No construction defects or material failures have occurred on this line

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

30.	100.02.200/5	Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013)				
	480-93-200(7)	(Via the commission's Virtual DIRT system or on-line damage reporting form)				
31.	480-93-200(7)(a)	Does the operator report to the commission the requirements set forth in RCW 19.122.053(3) (a) through (n)			X	
32.	480-93-200(7)(b)	Does the operator report the name, address, and phone number of the person or entity that the company has reason to believe may have caused damage due to excavations conducted without facility locates first being completed?			X	
33.	480-93-200(7)(c)	Does the operator retain all damage and damage claim records it creates related to damage events reported under 93-200(7)(b), including photographs and documentation supporting the conclusion that a facilities locate was not completed?  Note: Records maintained for two years and made available to the commission upon request.			X	
34.	480-93-200(8)	Does the operator provide the following information to excavators who damage gas pipeline facilities?				
35.	480-93-200(8)(a)	Notification requirements for excavators under RCW 19.122.050(1)			X	
36.	480-93-200(8)(b)	<ul> <li>A description of the excavator's responsibilities for reporting damages under RCW 19.122.053; and</li> </ul>			X	
37.	480-93-200(8)(c)	<ul> <li>Information concerning the safety committee referenced under RCW 19.122.130, including committee contact information, and the process for filing a complaint with the safety committee.</li> </ul>			Х	
38.	480-93-200(9)	Reports to the commission only when the operator or its contractor observes or becomes aware of the following activities  • An excavator digs within thirty-five feet of a transmission pipeline, as defined by RCW 19.122.020(26) without first obtaining a facilities locate; (200(9)(a)  • A person intentionally damages or removes marks indicating the location or presence of gas pipeline facilities. 200(9)(b)			X	
39.	480-93-200(7)	Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form)			X	
40.	480-93-200(10)	<b>Annual Reports</b> filed with the commission no later than <b>March 15</b> for the proceeding calendar year. ( <i>NOTE: PHMSA extension to June 15, 2013 for the year 2012</i> ).	S	U	N/A	N/C
41.	480-93-200(10)(a)	A copy of PHMSA F-7100.1-1 and F-7100.2-1 annual report required by U.S. Department of Transportation, PHMSA/Office of Pipeline Safety Reviewed annual reports for 2015, 2016 and 2017, all were submitted by March 15 the following year	X			
42.	480-93-200(10)(b)	Reports detailing all construction defects and material failures resulting in leakage.  Categorizing the different types of construction defects and material failures. The report must include the following:  (i) Types and numbers of construction defects; and  (ii) Types and numbers of material failures.  No defects or material failures but reports for 2015, 2016 and 2017 were received by March 15 the following year	Х			
43.	480-93-200(11)	Providing updated emergency contact information to the commission and appropriate officials of all municipalities where gas pipeline companies have facilities			X	
44.	480-93-200(12)	Providing by email, reports of daily construction and repair activities no later than 10:00 a.m.			X	
45.	480-93-200(13)	Submitting copy of DOT Drug and Alcohol Testing MIS Data Collection Form when required			Х	

### **Comments:**

Items 30-39 - Operator has had no damages to the pipeline since the last inspection

Item 43 – No updates since last inspection

Item 44 – No construction has occurred since last inspection

 $Item\ 45-Not\ required\ to\ submit\ MIS\ Data\ Collection\ Form,\ less\ than\ 50\ covered\ employees$ 

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		CONSTRUCTION RECORDS	S	U	N/A	N/C
46.	480-93-080(1)(b)	Use of testing equipment to record and document essential variables			X	
47.	480-93-115(2)	Test leads on casings (without vents) installed after 9/05/1992			X	
48.	480-93-115(3)	Sealing ends of casings or conduits on transmission pipelines and main  Seals on ends of casings were visible from construction drawings	X			
49.	480-93-115(4)	Sealing ends (nearest building wall) of casings or conduits on services			X	
50.	480-93-160(1)	Detailed report filed 45 days prior to construction or replacement of transmission pipelines $\geq$ 100 feet in length			X	
51.	480-93-170(3)	Pressure Tests Performed on new and replacement pipelines			X	
52.	480-93-170(10)	Pressure Testing Equipment checked for Accuracy/Intervals (Manufacturers recommendation or operators schedule)			X	
53.	480-93-175(1)	Study prepared and approved prior to moving and lowering of metallic pipelines > 60 psig			X	

### **Comments:**

Item 46 – No welding performed on pipeline, entire pipeline is PE

Item 47 – Operator has no metallic pipelines inside of casings

Item 49 – Operator has no services

Item 50 – No construction or replacement of transmission pipeline

Items 51-52 – No pressure tests performed during this inspection period

Item 53 – No metallic pipelines

		OPERATIONS and MAINTENANCE RECORDS	S	U	N/A	N/C
54.		Damage Prevention Program				
55.	480-93-250(3)	Are locates are being made within the timeframes required by RCW 19.122? Examine record sample.  One road crossing, Akzo Nobel has "permanent" locates and they refresh the paint annually	X			
56.	480-93-015(1)	Odorization of Gas – Concentrations adequate?			X	
57.	480-93-015(2)	Monthly Odorant Sniff Testing			X	
58.	480-93-015(3)	Prompt action taken to investigate and remediate odorant concentrations not meeting the minimum requirements			X	
59.	480-93-015(4)	Odorant Testing Equipment Calibration/Intervals (Annually or Manufacturers Recommendation)			X	
60.	480-93-124(3)	Pipeline markers attached to bridges or other spans inspected? 1/yr(15 months)			X	
61.	480-93-124(4)	Markers reported missing or damaged replaced within 45 days?  Put new stickers on markers in 2015 as a part of annual patrol, no markers reported damaged	X			
62.	480-93-185(1)	Reported gas leaks investigated promptly/graded/record retained			X	
63.	480-93-185(3)	Leaks originating from a foreign source reported promptly/notification by mail/record retained			X	
64.	480-93-187	Gas Leak records - Content			X	
65.	480-93-188(1)	Gas Leak surveys – Coverage Reviewed records of leak survey for 2015, 2016, 2017 and through June 2018, Survey performed monthly with calibrated 4-gas monitor	X			
66.	480-93-188(2)	Gas detection instruments tested for accuracy/intervals (Mfct rec or monthly not to exceed 45 days) Calibrated before each use	X			
67.	480-93-188(3)	Leak survey frequency (Refer to Table Below)	X			

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

		OPERATIONS and MAINTENANCE	RECORDS	S	U	N/A	N/C
		Business Districts (By 6/02/07)	1/yr (15 months)		1		
		High Occupancy Structures	1/yr (15 months)		-		
		Pipelines Operating ≥ 250 psig	1/yr (15 months)				
	Other I	Mains: CI, WI, copper, unprotected steel	2/yr (7.5 months)				
					_		
68.	480-93-188(4)(a)	Special leak surveys - Prior to paving or resur Leak surveys performed monthly	facing, following street alterations or repairs	X			
69.	480-93-188(4)(b)	Special leak surveys - areas where substructur underground gas facilities, and damage could				X	
70.	480-93-188(4)(c)	Special leak surveys - Unstable soil areas whe	ere active gas lines could be affected			X	
71.	480-93-188(4)(d)	Special leak surveys - areas and at times of un and explosions	usual activity, such as earthquake, floods,			Х	
72.	480-93-188(4)(e)	Special leak surveys - After third-party excava- leak survey to eliminate the possibility of mul- nearby buildings.				X	
73.	480-93-188(5)	Gas survey records: Retention/Content All required information is present		X			
74.	480-93-188(6)	Leak Survey Program/Self Audits Cosentino reviews records every 180 days		X			

#### **Comments:**

Items 56-59 - Pipeline is unodorized

Item 60 – No bridge crossing or spans

Items 62-64 – No leaks on pipeline during this inspection period

Items 69-72 - None of these events have occurred near Akzo Nobel's pipeline

	CORROSION CONTROL RECORDS  480-93-110(8) CP test reading on all exposed facilities where coating has been removed  480-93-110(2) Remedial action taken within 90 days (Up to 30 additional days if other circumstances. Must document) .465(d)  480-93-110(3) CP Test Equipment and Instruments checked for Accuracy/Intervals (Mfct Rec or Opr Sched)  480-93-110(5) Casings inspected/tested annually not to exceed fifteen months  480-93-110(5)(a) Casings w/no test leads installed prior to 9/05/1992. Demonstrate other acceptable test methods			U	N/A	N/C
<i>75.</i>	480-93-110(8)	CP test reading on all exposed facilities where coating has been removed			X	
76.	480-93-110(2)				X	
77.	480-93-110(3)				X	
78.	480-93-110(5)	Casings inspected/tested annually not to exceed fifteen months			X	
79.	480-93-110(5)(a)	,			X	
80.	480-93-110(5)(b)	Possible shorted conditions – Perform confirmatory follow-up inspection within 90 days			X	
81.	480-93-110(5)(c)	Casing shorts cleared when practical			X	
82.	480-93-110(5)(d)	Shorted conditions leak surveyed within 90 days of discovery. Twice annually/7.5 months			X	

#### **Comments:**

Items 75-82 – Operator has no metallic pipelines

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

PIPELINE INSPECTION (Field)			S	U	N/A	N/C
83.	480-93-015(1)	Odorization levels			X	
84.	480-93-115(2)	Casings – Test Leads (Casings w/o vents installed after 9/05/1992)			X	

### **Comments:**

Item 83 – Gas is unodorized hydrogen

Item 84 – No metallic pipe inside casings

EXIT INTERVIEW				
Exit Interview Conducted? Yes Items Covered: Discussed results of inspection, told them that there are no areas of concern or probable violations.	Date:	July 11, 2018		

### **Recent Gas Pipeline Safety Advisory Bulletins: (Last 2 years)**

Number	<u>Date</u>	Subject
ADB-2013-07	July 12, 13	Potential for Damage to Pipeline Facilities Caused by Flooding
ADB-2012-10	Dec 5, 12	Using Meaningful Metrics in Conducting Integrity Management Program Evaluations
ADB-2012-09	Oct 11, 12	Communication During Emergency Situations
ADB-2012-08	Jul 31, 12	Inspection and Protection of Pipeline Facilities After Railway Accidents
ADB-12-07	Jun 11, 12	Mechanical Fitting Failure Reports
ADB-12-06	May 7, 12	Verification of Records establishing MAOP and MOP
ADB-12-05	Mar 23, 12	Cast Iron Pipe (Supplementary Advisory Bulletin)
ADB -12-04	Mar 21, 12	Implementation of the National Registry of Pipeline and Liquefied Natural Gas Operators
ADB-12-03	Mar 6, 12	Notice to Operators of Driscopipe 8000 High Density Polyethylene Pipe of the Potential for Material Degradation
ADB-11-05	Sep 1, 11	Potential for Damage to Pipeline Facilities Caused by the Passage of Hurricanes
ADB-11-04	Jul 27, 11	Potential for damage to pipeline facilities caused by severe flooding.

For more PHMSA Advisory Bulletins, go to <a href="http://phmsa.dot.gov/pipeline/regs/advisory-bulletin">http://phmsa.dot.gov/pipeline/regs/advisory-bulletin</a>