FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

NOTES-FIELD INSPECTION

Company: **Akzo Nobel Pulp & Performance Chemicals** **Date(s):** **6/26/2018 and 7/11/2018**

Unit: **Moses Lake** **Insp. No.:** **7576**

Field Readings									
Line & Location	**Line**		**CP Volts**		**Rectifier**		**Pressures**		**Remarks**
	Size	**In.**	**P/S**	**Casing**	**Volts**	**Amps**	**Set**	**Actual**	
6” PE, Pipeline Markers									Walked pipeline right-of-way, there appeared to be sufficient amount of pipeline markers
Leak Survey									Leak detection performed with 4-gas monitor at casing vents by Lind Bingham, no gas detected
Valve Inspection/Operation									Both valves inspected and partially operated by Lind Bingham, valves turned freely and position indicator was functioning properly