Inspection Output (IOR)

Generated on 2019.March.08 16:51

Inspection Information

Inspection Name 7824-NOURYON(Akzo)-PA Status PLANNED Start Year 2019 System Type GT Protocol Set ID GT.2018.02 Operator(s) NOURYON PULP AND PERFORMANCE CHEMICALS LLC (32358) Lead Lex Vinsel Supervisor Joe Subsits Director Sean Mayo Plan Submitted 01/10/2019 Plan Approval 01/11/2019 by Joe Subsits All Activity Start 01/16/2019 All Activity End 01/17/2019 Inspection Submitted --Inspection Approval --

Inspection Summary

Inspection Scope and Summary

Akzo Nobel operates 0.45 miles of 8" PE pipeline. The pipeline transports unodorized hydrogen gas from Akzo Nobel's chemical plant to JR Simplot's boiler.

visited and Total AFOD

< 2 AFOD >

Summary of Significant Findings

(DO NOT Discuss Enforcement options)

<No significant findings during this inspection.>

Primary Operator contacts and/or participants

Lind Bingham NOURYON (Akzo)		HSE & S Manager	509-764-1502	
Bob Cosentino	Cosentino Consultants	Primary Contact	360-200-4959	

Operator executive contact and mailing address for any official correspondence

Lind Bingham NOURYON (Akzo) HSE & S Manager 509-764-1502	Lind Bingham	NOURYON (Akzo)	HSE & S Manager	509-764-1502
--	--------------	----------------	-----------------	--------------

NOURYON

2701 Road N NE

Moses Lake, WA 98837

< enter text here >

Scope (Assets)

# Short Label Long Label	Asset Type	Asset IDs	Excluded Topics	Planned Re	quired Ins	Total spected %	Required Complete
1. 86235 (1852) NOURYON(Akzo Nobel)	unit	86235	Storage Fields Bottle/Pipe - Holders Vault Service Line Offshore GOM OCS Cast or Ductile Iron CDA AMAOP Abandoned Copper Pipe Aluminum pipe Plastic pipe	27	27	27	100.0%

1. Percent completion excludes unanswered questions planned as "always observe".

Plans

# Plan Assets	Focus Directives	Involved Groups/Subgroups	Qst Type(s)	Extent Notes
1. 86235 (1852)	n/a	PD.RW, PD.PA.ASSETS.P, PD.PA.MESSAGEFREQUENCY.R, PD.PA.LANGUAGE.P, PD.PA.LANGUAGE.R, PD.PA.EVALPLAN.P, PD.PA.EVALIMPL.R, PD.PA.AUDITMETHODS.R, PD.PA.PROGRAMIMPROVE.R, PD.PA.EVALEFFECTIVENESS.R, PD.PA.MEASUREOUTREACH.R, PD.PA.AUDIENCEID.P, PD.PA.MEASUREUNDERSTANDABILITY.R, PD.PA.MEASUREBEHAVIOR.R, PD.PA.MEASUREBOTTOM.R, PD.PA.CHANGES.R, PD.PA.MGMTSUPPORT.P, PD.PA.PROGRAM.P, PD.PA.AUDIENCEID.R, PD.PA.MESSAGES.P, PD.PA.SUPPLEMENTAL.P, PD.PA.EDUCATE.R, PD.PA.LOCATIONMESSAGE.R	P, R, O, S	Detail

Plan Implementations

Activity # Name	Start Date End Date	Involved Groups/Subgroups	Assets	Qst Type(s)	Planned Red	quired Ins	Total	Required % Complete
1. Nouryon PA	 01/16/2019 01/18/2019	PD.PA, PD.RW	all assets	all types	27	27	27	100.0%

1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table.

2. Percent completion excludes unanswered questions planned as "always observe".

Forms

No. Entity	Form Name	Status	Date Completed	Activity Name	Asset
1. Attendance List	Nouryon PA	COMPLETED	02/19/2019	Nouryon PA	86235 (1852)

Results (Unsat, Concern values, 0 results)

This inspection has no matching Results.

Report Parameters: Results: Unsat, Concern

Inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.