

UTC IMP Verification Form

Inter/Intra

Inspector / Date: Lex Vinsel / 11-14-2017
Inspection Dates: 10/17/2017
Operator Inspected: Georgia-Pacific Consumer Products (Camas)
OPID: 31096 **Region: Western**
Unit Inspected: Camas Mill **Unit ID: GP Camas Pipeline**
Unit Type: Transmission
Unit Address: 401 NE Adams Street, Camas, WA
Record Location: 401 NE Adams Street, Camas WA

High Consequence Areas

High Consequence areas in District

Id	High Consequence area	Location	Reason	Mileage	HCA Verified
1	001	Entire Pipeline		1.0	
2					
3					
4					
5					
6					
7					
8					
9					
10					

New HCA's

High Consequence Area	Location	Reason	Mileage	Assessment Date
None	None			

Assessments

ILI

HCA ID	Tool(s), or assessment method(s)	Assessment review results	Prior Assessment date	Assessment date	Next Assessment date
001	ILI	No corrosion or metal loss indicated.		2013	

Do assessments address unit threats?	Yes
Earth Movement threat addressed if applicable?	Yes

HCA ID	Immediate repairs	One year condition (gas) 180 Day condition(liquid)	Monitored Condition (gas) Other condition (liquid)
001	None	None	None

Were anomalies evaluated in timely manner?	Yes, S14 anomaly was determined to be an imperfection.
Were repairs appropriate?	Composite repair sleeve at S14 location.

Repair Summary

